

200/200

ASS. REC. BY:

REF: CSI CT1 20002447/R15302 | Special Instruction:

Survivor: Rosu |

ASSIGNMENT (Office)

From (Person): Tan Kah Leong of CTC Date/Time: 13.2.2020 14:38 PM

Estimated Cost: _____ Bill to: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SME 252 Insured: SKG 1456U

at Workshop m/s Performance Tel: 6390174

of 303 Alexandra Road

Policy No: DMDCSA 30336919055 Claim No: SUM 201 20070102

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 5/2/2020
(Client's Record)

CA / REV / REP. / REV 24 HRS ^{14/2/20} H.O.D. Endorsement: _____

Date/Time: 12/2/2020 2:46 PM Person Contacted: Carolin Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SME 252 - MBA / INC 2000244614 DON - 4/12/2020
	SKG 1456U - MBA / INC 2000244614 DEN - 05/01/2020


Waiman

ASSIGNMENT

From: _____ Date: 18/11/2020
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SME 252
 at Workshop m/s Performance
 of 303 Alexandra Road
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: 4.0000 own way

Veh No: SME 252 Yr Regn: 2018 / 04
 Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: B.M.W X3 DRIVE 20I c.c. 1998
 Colour: Brown A/C: Insured / Std / NI / NA
 Sp. Reading: 12994 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: NBATA12030LC94451
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 245/50R19
 R: _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS np
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT



BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 05/02/2020 D.O.I. 18/02/2020
 Survey held at PERFORMANCE
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
REAR O/S
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Result Confirmed P/P \$ 10,413.35 @ 5 days with Sharon. (\$ 6,440.35 Red 38%)</u>
	<u>RECEIVED 18 MAR 2020</u>
	<u>Sharon Ho 18/3/2020</u>

Date/Time, File Pass to? 18/03/20
 1) Typist : Prell. Report : Final Report
 Date/Time, File Return to? _____
 2) _____
 Report Format: _____
 Lump Sum / P/P: (\$ 10,413.35 P/P)

Days Of Repair: 5
 Resurvey No. of Trip: 1
 Add Fee: : Site Insp (\$) : Interview (\$) : Tech. Invs (\$) : Weekend (\$)
 Survey Fee: 220
 Transportation: _____ \$ + RS. \$
 Photos _____
 Others _____
 TOTAL 220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Created	First Submitted	Last Submitted	Policy No.	ACI Sub-Header	File Number	Status
Main	12 Feb 2020		12 Feb 2020 14:38 Assign				New Assignment Cancel Case

[Home](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	NG TZEN IAN, JEREMY, ID: S7910447G		
Vehicle Reg. No.:	SME25Z	Date of Loss:	05/02/2020 20:00 - :59
Claim Type:	TP / SNM20D200701C02	Policy/Cover Note No.:	DMPCSN30336919055
Vehicle Reg. No. (Insured):	SKG1456U	Policy No. (Claimant):	5113061461
		Excess:	S\$2,000.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/02/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Name	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Sharon Heng L K <sharon.heng.leekun@simedarby.com.sg>
Sent: Tuesday, 17 March 2020 4:30 pm
To: Rasul (LKKAuto)
Cc: Shirley Hiew (LKK Auto)
Subject: RE: DIRECT SETTLEMENT FINAL REPORT - SME25Z - YOUR REF : SNM20D200701.

Dear Rasul

Thanks very much,

Sharon Heng
Admin Executive
Bodyshop

BMW
Performance Motors

DDI: +65 6319 0123
FAX: +65 6474 3229
Address : 303 Alexandra Road, Singapore 159941
EMail: sharon.heng.leekun@simedarby.com.sg

www.bmw.com.sg

Sime Darby Motors
A member of the Sime Darby Group

-----Original Message-----

From: Rasul (LKKAuto) [mailto:Rasul@lkkauto.com]
Sent: Tuesday, 17 March, 2020 4:25 PM
To: Sharon Heng L K
Cc: Shirley Hiew (LKK Auto)
Subject: RE: DIRECT SETTLEMENT FINAL REPORT - SME25Z - YOUR REF : SNM20D200701.

[External Mail] This email originated from outside of the organisation; be careful with requests, attachments and links.

Hi Sharon,

Finalised amount of \$ 10,418.35 / 5 days of repair is confirmed

Best Regards,
Rasul | Assessor
LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Save the Earth. Print only when necessary.

-----Original Message-----

From: Sharon Heng L K [mailto:sharon.heng.leekun@simedarby.com.sg]

Sent: Tuesday, 17 March, 2020 7:58 AM

To: Rasul (LKKAuto)

Subject: FW: DIRECT SETTLEMENT FINAL REPORT - SME25Z - YOUR REF : SNM20D200701.

Dear Rasul

For your perusal :

Labor	\$ 5849.00
Parts	\$ 4569.35
Total	\$10418.35

Owner is claiming CAR RENTAL - \$480.00 (4 DAYS).
GIA SEARCH FEE - \$2.00

Note : 5 working days.

Sharon Heng
Admin Executive
Bodyshop

BMW
Performance Motors

DDI: +65 6319 0123
FAX: +65 6474 3229
Address : 303 Alexandra Road, Singapore 159941
EMail: sharon.heng.leekun@simedarby.com.sg

www.bmw.com.sg

Sime Darby Motors
A member of the Sime Darby Group

-----Original Message-----

From: service.pml@simedarby.com.sg [mailto:service.pml@simedarby.com.sg]

Sent: Friday, 13 March, 2020 7:34 PM

To: Sharon Heng L K

Subject: Message from KM_C458

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	06/02/2020 10:22
Date Of Accident	05/02/2020 20:15
Exact Location Of Accident	CAVENAGH RAOD (EXITING TOWARDS BUKIT TIMAH ROAD)
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SME25Z
Insured/Policyholder	
Name Of Registered Owner	NG TZEN IAN, JEREMY
NRIC No	SXXX447G
Email Address	JEREMYNG.SG@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96810080
Alternative Phone No	OTHERS-96810080

Vehicle Particulars

Manufacturer	BMW
Model	X3
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5113061461
Cover Note Number	

Driver

Name of Driver	NG TZEN IAN, JEREMY
NRIC No	SXXX447G
Date Of Birth	21/04/1979
Occupation	INDOOR
Date Of Driving Pass	06/03/1999
Driving Experience	20 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96810080
Fax Number	
Contact Number	OTHERS-96810080
EEmail Address	JEREMYNG.SG@GMAIL.COM

Address	21 BALMORAL PARK #05-07
Postcode	259850
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKG1456U
Vehicle Make/Model/Colour	AUDI
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	BALWANT RAO JAIN
NRIC/Passport Number	SXXXX395H
Contact Number	96186175
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

B. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders;

Policyholder's Signature

Date & Time: 06/01/2020
11:2 AM

Driver's Signature

(if driver is not the policyholder)
Date & Time: 06/01/2020

Reporting Centre Personnel Signature

Name: [Signature]
NIC/PIN No. [Signature]

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AT APPROXIMATELY 2:58PM ON 05/02/2020 I WAS DRIVING ALONG
(ALLENBY) ROAD HEADING TOWARDS BUILT TOWER ROAD
AS I APPROACHED THE JUNCTION I WAS PREPARING TO ENTER THE
THE FILTER LANE TO TURN LEFT ONTO BUILT TOWER ROAD
THERE WERE A FEW CARS AHEAD OF ME AND I STOPPED BEHIND
AS THEY TOOK THEIR TURN TO EXIT (ALLENBY) ROAD
FINALLY IT CAME TO MY TURN TO EXIT. BUT THERE WAS
ON COMING TRAFFIC AND I HAD TO COME TO A FULL STOP
A BEHIND OR TWO AFTER I STOPPED THERE WAS AN IMPACT
ONTO MY CAR FROM THE REAR
A SILVER AUDI PALSON HAD LANDED INTO THE BACK OF MY
GREY BMW X3 AND CAUSED DAMAGE TO MY BUMPER,
REAR AND EXHAUST AMONGST OTHER THINGS
WE GOT OFF THE CARS AND WENT TO HEAD TO THE
NEAREST POLICE STATION TO EXCHANGE DETAILS
THE DRIVER OF THE CAR THAT HIT ME WAS MR
BALAJANT RAO JAIN (VIC S2063295H) AND THE LICENSE
PLATE OF HIS CAR IS SKG 1456U
NONE OF US HAD SUFFERED ANY INJURY FROM THE
ACCIDENT

DECLARATION

(We declare the foregoing particulars are true in every respect)

Policyholder's Signature

Date & Time: 05/02/2020
10:20 AM

Driver's Signature

(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature

Name: [Signature]
NRC/CM No: [Signature]

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401539W GST Reg. No. M2-0020081-X
Toll-Free Number (1900-2288269)

103, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

119, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



- 18/2/20
@ 4pm

GST REG. NO : M2 - 0020081 - X

11 FEB 2020

ESTIMATE

Estimate No. : b1 54386 Page No. : 1 of 5
Date Estimated : 06/02/2020
Prepared By : Joseph Yaguel

- ESTIMATE REPAIR FOR -

Ng Tzen Ian, Jeremy
21 Balmoral Park
#05-07

Singapore 259850

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SME25Z	WBATR12030LC94451	31/10/2018	X3 sDrive20i	0

DESCRIPTION

Replacing rear bumper panel and attachments, bootlid,
rework tail panel ✓

To replace rear windscreen glass.

To conduct water leak tests.

To supply and install rear windscreen solar film.

To replace rear exhaust silencer including alignment
system and conduct checks for leak.

Spray rear bumper, bootlid and tailpanel ✓

To check electrical wiring systems and lightings at the
rear section for proper function.

To carry out body cavity preservation.
(Per panel).

Sundries

Total Labour 1: 8,305.00

DESCRIPTION

DESCRIPTION	QTY	PRIC	VALUE
CLAMPING BUSH ? see ✓	1	60.90	60.90
RR SILENCER BRACKET ? see ✓	1	24.80	24.80
SWING SUPPORT ? see ✓	1	44.00	44.00
TAILPIPE TRIM CHROME D=90MM ? see ✓	1	122.20	122.20
REAR SILENCER ? see ✓	1	1,346.70	1,346.70
TRUNK LID repair ? see ✓	1	1,973.35	1,973.35
REAR BUMPER CARRIER ? see ✓	1	743.50	743.50
RH SIDE GUIDE FOR BUMPER ? see ✓	1	58.25	58.25
RH BUMPER GUIDE ? see ✓	1	70.30	70.30
REAR BUMPER BOTTOM REINFORCEMENT ? see ✓	1	78.85	78.85

2536 1700 3400.00

X17 ? 574.00

X17 ? 75.00

X17 ? 531.00

451 531.00

2548 1805 2749.00

150 177.00

X17 ? 118.00

150.00

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 54386
Date Estimated : 06/02/2020
Prepared By : Joseph Yaguel

Page No. : 2 of 5

REGN. NO. CHASSIS NO. REGN. DATE MODEL MILEAGE
SME25Z WBATR12030LC94451 31/10/2018 X3 sDrive20i 0

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER TOWING LUG COVER (M) <i>at X30c</i>	1	76.15	76.15
REAR BUMPER PANEL PRIMED (M/PMA) <i>dy-</i>	1	1,555.40	1,555.40
REAR BUMPER BOTTOM TRIM PANEL (M) <i>de-</i>	1	370.35	370.35
EMBLEM GROMMET <i>new</i>	2	0.85	1.70
PLAQUE 82MM <i>new</i>	1	71.60	71.60
LETTERING X3 <i>new</i>	1	64.45	64.45
LETTERING S DRIVE 20i <i>new</i>	1	96.65	96.65
BUMP STOP ? <i>xan</i>	10	4.15	41.50
REAR WINDOW GREEN ? <i>xan</i>	1	1,121.75	1,121.75
REAR SILENCER RH INSULATION ? <i>xan</i>	1	70.75	70.75
TRUNK LID GASKET ? <i>xan</i>	1	170.20	170.20
RH REFLECTOR <i>cm</i>	1	38.85	38.85
DECOUPLING RING PDC TORQUE CONVERTER ? <i>xan</i>	4	5.10	20.40
(DG) CLEANER R1 (100ML) ? <i>xan</i>	1	26.15	26.15
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) ? <i>xan</i>	2	131.55	263.10
(DG/SL)ADHESIVE PRIMER VP 206 (30ML) ? <i>xan</i>	1	27.85	27.85

Total Parts : 8,539.70

Claims OD (red circle) Uninsured losses / Direct Settlement

Regs No. _____ Claim No. _____

Date & Time 18/02/2020 @ 1610 Excess S\$ _____

Surveyor's Name Rafael Sign _____

Surveyor's Tel 90010068 Authorised Yes / No _____

Authorized Date _____ Time _____

RE-SURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommended 5 days

UKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To resurvey damaged parts before/after repair
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Time: _____

Labour 1	:	8,305.00
Parts	:	8,539.70
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,179.13
Grand Total	:	18,023.83



** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

16853.70

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg No. 197401559W, GST Reg No. M2-0020081-X



Supplementary

Estimate No. : **b1 54386**
Date Estimated : **06/02/2020**
Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -
Ng Tzen Ian, Jeremy
21 Balmoral Park
#05-07

Singapore 259850

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SME25Z	WBATR12030LC94	31/10/2018	X3 sDrive20i	0

DESCRIPTION	ACCOUNT:		DISC. %	NETT
	ORIGINAL PRICE			

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING RIVET BLACK <i>me</i>	1.40	10	0	14.00 <i>A</i>

SUPPLEMENTARY ITEMS

Total Labour :	
Total Parts :	14.00
Total Labour & Parts :	14.00

Performance Motors Limited

A member of the Sime Darby Group
 Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



Final Report

Estimate No. : **b1 54386**
 Date Estimated : **06/02/2020**
 Prepared By : **Joseph Yaguel**

- ESTIMATE REPAIR FOR -
Ng Tzen Ian, Jeremy
21 Balmoral Park
#05-07

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Singapore 259850

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SME25Z	WBATR12030LC94	31/10/2018	X3 sDrive20i	0

DESCRIPTION	ACCOUNT: ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments etc including to make good rear boot lid, tail end panel and knock out dented area caused by the accident. To remove and install body parts in order to carry out painting job.	2,550.00	0	2,550.00 ✓
To replace rear exhaust silencer, chrome pipe and clamping bush including to align system and conduct checks for leak.	451.00	0	451.00 ✓
To respray rear bumper, rear boot lid and tail end panel.	2,548.00	0	2,548.00 ✓
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0	150.00 ✓
Sundries	150.00	0	150.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# CLAMPING BUSH	60.90	1	0	60.90 ✓
RR SILENCER BRACKET	24.80	1	0	24.80 ✓
TAILPIPE TRIM CHROME D=90MM	122.20	1	0	122.20 ✓
REAR SILENCER	1,346.70	1	0	1,346.70 ✓
REAR BUMPER CARRIER	743.50	1	0	743.50 ✓
RH SIDE GUIDE FOR BUMPER	58.25	1	0	58.25 ✓
REAR BUMPER PANEL PRIMED (M/PMA)	1,555.40	1	0	1,555.40 ✓
REAR BUMPER BOTTOM TRIM PANEL (M)	370.35	1	0	370.35 ✓
EMBLEM GROMMET	0.85	2	0	1.70 ✓
PLAQUE 82MM	71.60	1	0	71.60 ✓
LETTERING X3	64.45	1	0	64.45 ✓
LETTERING S DRIVE 20I	96.65	1	0	96.65 ✓
# EXPANDING RIVET BLACK	1.40	10	0	14.00 ✓ (54/11)
RH REFLECTOR	38.85	1	0	38.85 ✓

SUPPLEMENTARY ITEMS

Performance Motors Limited

A member of the Sino-Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



Final Report

Total Labour :	5,849.00
Total Parts :	4,569.35
Total Labour & Parts :	10,418.35
GST @7%:	729.28
<u>Grand Total :</u>	<u>11,147.63</u>

STEVE
LH 13/7/20 5

CAR RENTAL - \$480.00 (4 DAYS)
GIA SEARCH FEE - \$2.00

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	12 Feb 2020		12 Feb 2020 14:38 Edit Adj Rpt	S\$10,418.35 Edit Estimates	S\$10,418.35 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	-, Co. Reg. No.: -	
Main Claimant:	NG TZEN IAN, JEREMY , ID: S7910447G	
Vehicle Reg. No.:	SME25Z	Date of Loss: 05/02/2020 20:00 - :59 [15 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / SNM20D200701C02	Policy/Cover Note No.: DMPCSN30336919055
Vehicle Reg. No. (Insured):	SKG1456U	Policy No. (Claimant): 5113061461
		Excess: S\$2,000.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174	
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]	
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 21/02/2020]	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SME25Z (SNM20D200701C02)**
[SKG1456U]
TP
NG TZEN IAN, JEREMY
Feb 5 2020 8:00PM
[-]
Performance Motors Limited

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser
Video						1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	National Assessment Centre Services (Bukit Merah)		Thumbnail	Print			
1	06/02/20 10:47	Video - Accident [Linked Accident Report Documents]		Load MP4	<input checked="" type="checkbox"/>			
Assessment Reports						1 per page	<input checked="" type="checkbox"/>	
No	Finalized On	National Assessment Centre Services (Bukit Merah)		Thumbnail	Print			
1	06/02/20 11:19	Accident Statement		Load HTM	<input checked="" type="checkbox"/>			
Photos/Images						3 per page	<input checked="" type="checkbox"/>	
No	Finalized On	National Assessment Centre Services (Bukit Merah)		Thumbnail	Print			
1	06/02/20 10:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
2	06/02/20 10:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
3	06/02/20 10:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
4	06/02/20 10:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
5	06/02/20 10:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
6	06/02/20 10:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
7	06/02/20 10:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
8	06/02/20 10:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
9	06/02/20 10:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
10	06/02/20 10:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
11	06/02/20 10:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
12	06/02/20 10:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
13	06/02/20 10:46	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	18/03/20 11:43	General View		Load JPG	<input checked="" type="checkbox"/>			
2	18/03/20 11:43	General View		Load JPG	<input checked="" type="checkbox"/>			
3	18/03/20 11:43	General View		Load JPG	<input checked="" type="checkbox"/>			
4	18/03/20 11:43	General View		Load JPG	<input checked="" type="checkbox"/>			
5	18/03/20 11:43	General View		Load JPG	<input checked="" type="checkbox"/>			
6	18/03/20 11:43	General View		Load JPG	<input checked="" type="checkbox"/>			
7	18/03/20 11:43	General View		Load JPG	<input checked="" type="checkbox"/>			
8	18/03/20 11:43	General View		Load JPG	<input checked="" type="checkbox"/>			
9	18/03/20 11:43	General View		Load JPG	<input checked="" type="checkbox"/>			
10	18/03/20 11:43	General View		Load JPG	<input checked="" type="checkbox"/>			
11	18/03/20 11:43	General View		Load JPG	<input checked="" type="checkbox"/>			
12	18/03/20 11:43	General View		Load JPG	<input checked="" type="checkbox"/>			

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
				<input checked="" type="checkbox"/>
13	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
14	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
15	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
16	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
17	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
18	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
19	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
20	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
21	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
22	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
23	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
24	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
25	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
26	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
27	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
28	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
29	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
30	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
31	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
32	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
33	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
34	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
35	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
36	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
37	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
38	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
39	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
40	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
41	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
42	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
43	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
44	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
45	18/03/20 11:43	General View	Load JPG	<input checked="" type="checkbox"/>
46	18/03/20 11:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	18/03/20 11:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	18/03/20 11:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	18/03/20 11:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	18/03/20 11:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	18/03/20 11:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	18/03/20 11:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	18/03/20 11:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
54	18/03/20 11:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
55	18/03/20 11:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
56	18/03/20 11:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
57	18/03/20 11:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
58	18/03/20 11:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
59	18/03/20 11:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
60	18/03/20 11:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
61	18/03/20 11:44	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
62	18/03/20 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	18/03/20 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	18/03/20 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	18/03/20 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	18/03/20 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	18/03/20 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	18/03/20 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	18/03/20 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	18/03/20 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	18/03/20 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	18/03/20 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	18/03/20 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	18/03/20 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	18/03/20 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	18/03/20 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	18/03/20 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	18/03/20 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	18/03/20 11:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	12/02/20 14:38	Pre-Repair Survey	 Load PDF	
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	06/02/20 11:16	Sketch Plan <small>[Linked Accident Report Documents]</small>	 Load JPG	<input checked="" type="checkbox"/>
2	06/02/20 11:16	Sketch Plan #2 <small>[Linked Accident Report Documents]</small>	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/03/20 16:51	Supplementary	 Load PDF	

Linked Accident Report Documents

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	06/02/20 10:47	Video - Accident	 Load MP4	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	06/02/20 11:19	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	06/02/20 10:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	06/02/20 10:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	06/02/20 10:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	06/02/20 10:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	06/02/20 10:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	06/02/20 10:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	06/02/20 10:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	06/02/20 10:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	06/02/20 10:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	06/02/20 10:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	06/02/20 10:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
12	06/02/20 10:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
13	06/02/20 10:46	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	06/02/20 11:16	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	06/02/20 11:16	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199807198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT120002447/R1SF3E2

Date: 23/03/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMPCSN30336919055	
Claimant Vehicle No: SME25Z	Insured Vehicle No: SKG1456U	
Date of Loss: 05/02/2020	Nature of Claim: TP	Claim No: SNM20D200701C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SME25Z				
Make & Model:	BMW X3 XDRIVE20I, 2.0 M SPORT HID SR NAV (A)	Engine No:	H4153070B48B20A		
Reg. Date:	31/10/2018 (Man. Year: 2018)	Chassis No:	WBATR12030LC94451		
Colour:	Brown	Odometer:	12994 km		
Engine Capacity:	1998 cc				
Market Value/New Car Price:	N/A				
Sum Insured (S\$):	Market Value/New Car Price				

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/50 R19	Rear Tyre Size:	245/50 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,234.70	4,719.35	4,515.35	48.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,624.00	5,699.00	1,925.00	25.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,858.70	10,418.35	6,440.35	38.20
+ GST 7.00/7.00% (S\$)	1,180.11	729.28	450.83	38.20
Nett Amount (S\$)	18,038.81	11,147.63	6,891.18	38.20

INSPECTION

Date of Assignment:	12/02/2020	
Date Inspected:	18/02/2020 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 23 Mar 2020)	
Parts: M1-SUV	BMW X3 XDRIVE20I 2.0 M SPORT HID SR NAV (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SME25Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR WINDSCREEN SOLAR FILM	Not Necessary	531.00 FS	*- FS	
2	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS	
3	1		*CLAMPING BUSH	Necessary	60.90 FS	*60.90 FS	
4	1		*RR SILENCER BRACKET	Necessary	24.80 FS	*24.80 FS	
5	1		*SWING SUPPORT	Serviceable	44.00 FS	*- FS	
6	1		*TAILPIPE TRIM CHROME D=90MM	Scratched	122.20 FS	*122.20 FS	
7	1		*REAR SILENCER	Bent	1,346.70 FS	*1,346.70 FS	
8	1		*TRUNK LID	Repair	1,973.35 FS	*- FS	
9	1		*REAR BUMPER CARRIER	Bent	743.50 FS	*743.50 FS	
10	1		*RH SIDE GUIDE FOR BUMPER	Cracked	58.25 FS	*58.25 FS	
11	1		*RH BUMPER GUIDE	Serviceable	70.30 FS	*- FS	
12	1		*REAR BUMPER BOTTOM REINFORCEMENT	Serviceable	78.85 FS	*- FS	
13	1		*REAR BUMPER PANEL PRIMED (M/PMA)	Deformed	1,555.40 FS	*1,555.40 FS	
14	1		*REAR BUMPER BOTTOM TRIM PANEL (M)	Deformed	370.35 FS	*370.35 FS	
15	2		*EMBLEM GROMMET	Necessary	1.70 FS	*1.70 FS	
16	1		*PLAQUE 82MM	Necessary	71.60 FS	*71.60 FS	
17	1		*LETTERING X3	Necessary	64.45 FS	*64.45 FS	
18	1		*LETTERING S DRIVE 20I	Necessary	96.65 FS	*96.65 FS	
19	10		*BUMP STOP	Not Necessary	41.50 FS	*- FS	
20	1		*REAR WINDOW GREEN	Not Necessary	1,121.75 FS	*- FS	
21	1		*REAR SILENCER RH INSULATION	Not Necessary	70.75 FS	*- FS	
22	1		*TRUNK LID GASKET	Not Necessary	170.20 FS	*- FS	
23	1		*RH REFLECTOR	Cracked	38.85 FS	*38.85 FS	
24	4		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	20.40 FS	*- FS	
25	1		*(DG) CLEANER R1 (100ML)	Not Necessary	26.15 FS	*- FS	
26	2		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Not Necessary	263.10 FS	*- FS	
27	1		*(DG/SL) ADHESIVE PRIMER VP 206 (30ML)	Not Necessary	27.85 FS	*- FS	
28	10		*EXPANDING RIVET BLACK	Necessary	14.00 FS	*14.00 FS	
29	1		*REAR BUMPER TOWING LUG COVER (M)	Serviceable	76.15 FS	*- FS	
					Total Parts (S\$)	9,234.70	4,719.35

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REPLACING REAR BUMPER PANEL AND ATTACHMENTS, BOOTLID, REWORK TAIL PANEL	New	3,400.00	2,550.00
2	TO REPLACE REAR WINDSCREEN GLASS	New	574.00	0.00
3	TO CONDUCT WATER LEAK TESTS	New	75.00	0.00
4	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK	New	531.00	451.00
5	SPRAY REAR BUMPER, BOOTLID AND TAILPANEL	New	2,749.00	2,548.00
6	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
7	TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL)	New	118.00	0.00
Gross Labour Cost (S\$)			7,624.00	5,699.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >