

|                |                   |
|----------------|-------------------|
| Vehicle number | GBF3460E          |
| Make / Model   | NISSAN NV200      |
| Chassis number | JN1YBAM20U0003111 |
| Accident date  | 4/2/20            |
| Reference      | 2002-08           |

Qty Particulars Unit Price - SGD \$

| PARTS REPLACEMENT - LIST ITEMS         |                                                 |             |
|----------------------------------------|-------------------------------------------------|-------------|
| 1                                      | REAR BUMPER                                     | 805.92      |
| 1                                      | REAR BUMPER RETAINER                            | 96.30       |
| 1                                      | REAR RH FENDER X R                              | 1979.67     |
| 1                                      | REAR RH FENDER MOULDING X NN                    | 159.30      |
| 1                                      | REAR RH FENDER INNER SHIELD X NN                | 127.40      |
| 1                                      | TAILLAMP RH / RM                                | 659.69      |
| 1                                      | RH SLIDING DOOR X R                             | 1711.43     |
| 1                                      | RH SLIDING DOOR HINGE X NN                      | 86.00       |
| 1                                      | RH SLIDING DOOR CHECKER X NN                    | 121.10      |
| 1                                      | REAR AXLE BEAM X NN                             | 2417.03     |
| 1                                      | REAR RH WHEEL HUB WITH BEARING X NN             | 293.50      |
| 1                                      | REAR RH SHOCK ABSORBER X NN                     | 592.20      |
|                                        |                                                 | 9049.54     |
|                                        | Less 10%                                        | 904.95      |
|                                        |                                                 | 8144.59     |
| PARTS REPLACEMENT - SPECIAL NETT ITEMS |                                                 |             |
| 1                                      | RIM X NN                                        | 600.00      |
| 1 SET                                  | REAR BUMPER CLIP / NK                           | 40.00 30    |
| 1 SET                                  | REAR FENDER INNER SHIELD CLIP X NN              | 60.00       |
|                                        | Subtotal                                        | 700.00      |
|                                        | Balance C/F                                     | 8844.59     |
| LABOUR AND MISCELLANEOUS CHARGES       |                                                 |             |
|                                        | Balance B/F                                     | 8844.59     |
| 1                                      | CHECK WIRING AND LIGHTNING SYSTEM               | 60.00 30    |
| 2                                      | COMPUTERISED AND CHECK FRONT WHEEL ALIGNMENT    | 200.00 60   |
| 3                                      | REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS    | 150.00 X    |
| 4                                      | TRANSFER PARTS, ATTACHMENT FROM OLD DOOR TO NEW | 200.00 X    |
| 5                                      | REMOVE AND REFIT REAR QUARTER GLASS             | 200.00 100  |
| 6                                      | PANEL BEATING ON AFFECTED AREAS                 | 1200.00 800 |
| 7                                      | SPRAY PAINTING ON AFFECTED AREAS                | 1200.00 100 |
| 8                                      | APPLY ANTI-RUST ON AFFECTED AREAS               | 150.00 30   |
|                                        | Subtotal                                        | 3360.00     |
|                                        | Grand total                                     | 12204.59    |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "No Fault" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

too high