

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	19 May 2020 Edit Reg		11 Feb 2020 00:00 Edit Adj Rpt	S\$7,300.00 Edit Estimates	S\$7,300.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R		
Main Claimant:	YEO KWEE TECK		
Vehicle Reg. No.:	SLJ1425G	Date of Loss:	11/02/2020 07:00 - :59 [38 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT20020199	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHA1634P	Policy No. (Claimant):	
		Excess:	
Repairer:	N-51 Automotive Pte Ltd (kaki Bukit Autohub) (HQ) KAKI BUKIT AUTOHUB 2 KAKI BVUKIT AVE 2 #01-18, 417921 Kaki Bukit - Tel:		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Bhargavi Purushothaman Dhanya]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 21/02/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- III_SG (01/10/2020): **Alert - Adj Mandate Approved (S\$8818.45) - SLJ1425G - Claim Handler: Bhargavi Pu...**
- III_SG (21/05/2020): **Alert - Adj Mandate Approved (S\$0.00) - SLJ1425G - Claim Handler: Bhargavi Purus...**
- III_SG (20/05/2020): **Alert - Adj Mandate Approved (S\$0.00) - SLJ1425G - Claim Handler: Bhargavi Purus...**

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***SLJ1425G (MCT20020199)**
[SHA1634P]
TP
YEO KWEE TECK
Feb 11 2020 7:00AM
[COMFORT TRANSPORTATION PTE LTD]
N-51 Automotive Pte Ltd (kaki Bukit Autohub)

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Video				1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
1	19/05/20 10:51	Video - Accident-IV		Load MP4	
2	21/05/20 12:35	Video - Accident-TP		Load MP4	
Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	02/06/20 14:57	General View		Load JPG	☒
2	02/06/20 14:57	General View		Load JPG	☒
3	02/06/20 14:57	General View		Load JPG	☒
4	02/06/20 14:57	General View		Load JPG	☒
5	02/06/20 14:57	General View		Load JPG	☒
6	02/06/20 14:57	General View		Load JPG	☒
7	02/06/20 14:57	General View		Load JPG	☒
8	02/06/20 14:57	General View		Load JPG	☒
9	02/06/20 14:57	General View		Load JPG	☒
10	02/06/20 14:57	General View		Load JPG	☒
11	02/06/20 14:57	General View		Load JPG	☒
12	02/06/20 14:57	General View		Load JPG	☒
13	02/06/20 14:57	General View		Load JPG	☒
14	02/06/20 14:57	General View		Load JPG	☒
15	02/06/20 14:57	General View		Load JPG	☒
16	02/06/20 14:57	General View		Load JPG	☒
17	02/06/20 14:57	General View		Load JPG	☒
18	02/06/20 14:57	General View		Load JPG	☒
19	02/06/20 14:57	General View		Load JPG	☒
20	02/06/20 14:57	General View		Load JPG	☒
21	02/06/20 14:57	General View		Load JPG	☒
22	02/06/20 14:57	General View		Load JPG	☒
23	02/06/20 14:57	General View		Load JPG	☒
24	02/06/20 14:57	General View		Load JPG	☒
25	02/06/20 14:57	General View		Load JPG	☒
26	02/06/20 14:57	General View		Load JPG	☒
27	02/06/20 14:57	General View		Load JPG	☒
28	02/06/20 14:57	General View		Load JPG	☒
29	02/06/20 14:57	General View		Load JPG	☒
30	02/06/20 14:57	General View		Load JPG	☒
31	02/06/20 14:57	General View		Load JPG	☒

Video			1 per page ▾	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
32	02/06/20 14:57	General View	 Load JPG	☒
33	02/06/20 14:57	General View	 Load JPG	☒
34	02/06/20 14:57	General View	 Load JPG	☒
35	02/06/20 14:57	General View	 Load JPG	☒
36	02/06/20 14:57	General View	 Load JPG	☒
37	02/06/20 14:57	General View	 Load JPG	☒
38	02/06/20 14:57	General View	 Load JPG	☒
39	02/06/20 14:57	General View	 Load JPG	☒
40	02/06/20 14:57	General View	 Load JPG	☒
41	02/06/20 14:57	General View	 Load JPG	☒
42	02/06/20 14:57	General View	 Load JPG	☒
43	02/06/20 14:57	General View	 Load JPG	☒
44	02/06/20 14:57	General View	 Load JPG	☒
45	02/06/20 14:57	General View	 Load JPG	☒
46	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
47	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
48	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
49	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
50	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
51	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
52	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
53	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
54	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
55	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
56	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
57	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
58	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
59	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
60	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
61	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
62	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
63	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
64	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
65	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
66	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
67	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
68	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
69	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
70	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
71	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
72	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
73	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
74	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
75	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
76	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
77	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
78	02/06/20 14:58	Reinspection Photo	 Load JPG	☒
79	02/06/20 14:58	Reinspection Photo	 Load JPG	☒

Video				1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print
80	02/06/20 14:58	Reinspection Photo		Load JPG	☒
81	02/06/20 14:58	Reinspection Photo		Load JPG	☒
82	02/06/20 14:58	Reinspection Photo		Load JPG	☒
83	02/06/20 14:58	Reinspection Photo		Load JPG	☒
84	02/06/20 14:58	Reinspection Photo		Load JPG	☒
85	02/06/20 14:58	Reinspection Photo		Load JPG	☒
86	02/06/20 14:58	Reinspection Photo		Load JPG	☒
87	02/06/20 14:58	Reinspection Photo		Load JPG	☒
88	02/06/20 14:58	Reinspection Photo		Load JPG	☒
89	02/06/20 14:58	Reinspection Photo		Load JPG	☒
90	02/06/20 14:58	Reinspection Photo		Load JPG	☒
91	02/06/20 14:58	Reinspection Photo		Load JPG	☒
92	02/06/20 14:58	Reinspection Photo		Load JPG	☒
93	02/06/20 14:58	Reinspection Photo		Load JPG	☒
94	02/06/20 14:58	Reinspection Photo		Load JPG	☒
95	02/06/20 14:58	Reinspection Photo		Load JPG	☒
96	02/06/20 14:58	Reinspection Photo		Load JPG	☒
97	02/06/20 14:58	Reinspection Photo		Load JPG	☒
98	02/06/20 14:58	Reinspection Photo		Load JPG	☒
99	02/06/20 14:58	Reinspection Photo		Load JPG	☒
100	02/06/20 14:58	Reinspection Photo		Load JPG	☒
101	02/06/20 14:58	Reinspection Photo		Load JPG	☒
102	02/06/20 14:58	Reinspection Photo		Load JPG	☒
103	02/06/20 14:58	Reinspection Photo		Load JPG	☒
104	02/06/20 14:58	Reinspection Photo		Load JPG	☒
105	02/06/20 14:58	Reinspection Photo		Load JPG	☒
106	02/06/20 14:58	Reinspection Photo		Load JPG	☒
107	02/06/20 14:58	Reinspection Photo		Load JPG	☒
108	02/06/20 14:58	Reinspection Photo		Load JPG	☒
109	02/06/20 14:58	Reinspection Photo		Load JPG	☒
110	02/06/20 14:58	Reinspection Photo		Load JPG	☒
111	02/06/20 14:58	Reinspection Photo		Load JPG	☒
112	02/06/20 14:58	Reinspection Photo		Load JPG	☒
113	02/06/20 14:58	Reinspection Photo		Load JPG	☒
114	02/06/20 14:58	Reinspection Photo		Load JPG	☒
115	02/06/20 14:58	Reinspection Photo		Load JPG	☒
116	02/06/20 14:58	Reinspection Photo		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	12/02/20 15:48	ACKNOWLEDGEMENT EMAIL TO INDIA DD11022020		Load PDF	
2	12/02/20 15:48	EMAIL FROM INDIA DD11022020		Load PDF	
3	12/02/20 15:48	TP GIA REPORT		Load PDF	
4	21/05/20 11:54	EMAIL TO III DD 210520		Load PDF	
5	03/06/20 08:45	TP ESTIMATE_MARKED		Load PDF	
6	30/09/20 08:36	LOD		Load PDF	
7	30/09/20 08:36	Authorisation to Act		Load PDF	
8	30/09/20 08:36	Workshop Invoice		Load PDF	
9	30/09/20 08:36	Rental Receipt & Agreement		Load PDF	
10	30/09/20 08:36	LTA Search Receipt		Load PDF	

Video			1 per page ▾	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail Print
11	30/09/20 08:36	Towing Receipt		Load PDF
12	21/10/20 10:30	DISCHARGE VOUCHER		Load PDF
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail Print
1	11/05/20 16:38	Singapore Accident Statement		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20002450/APS3S2**Date:** 21/10/2020REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SLJ1425G	Insured Vehicle No :	SHA1634P
Date of Loss:	11/02/2020	Nature of Claim:	TP
		Claim No:	MCT20020199

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ1425G	Engine No:	HR12214614B
Make & Model:	NISSAN NOTE, 1.2 DIG-S CVT (A)	Chassis No:	JN1TBAE12Z0982888
Reg. Date:	29/11/2016 (Man. Year: 2016)	Odometer:	66685 km
Colour:	Grey		
Engine Capacity:	1198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,414.49	6,265.19	5,149.30	45.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,720.00	3,020.00	1,700.00	36.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,134.49	9,285.19	6,849.30	42.45
Approved Total (Overridden) (S\$)		7,300.00		
(S\$)	16,134.49	7,300.00	8,834.49	54.76
+ GST 7.00/7.00% (S\$)	1,129.41	511.00	618.41	54.76
Nett Amount (S\$)	17,263.90	7,811.00	9,452.90	54.76
+ Car Rental (9.0 x S\$100.00/day) (S\$)		900.00		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		100.00		
Nett Liability (S\$)		8,818.45		
Global Sum Settlement (S\$)		8,800.00		

INSPECTION

Date of Assignment: 11/02/2020

Date Inspected: 12/02/2020 Inspected At:

N-51 Automotive Pte Ltd (kaki Bukit Autohub) (HQ)
 KAKI BUKIT AUTOHUB 2 KAKI BUKIT AVE 2 #01-17
 Singapore 417921

10/21/2020

Adjuster Report

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Oct 2020)
Parts:	144	NISSAN NOTE 1.2 DIG-S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ1425G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER	Distorted	460.00 FL	*460.00 FL
2	1	*REAR BUMPER CENTRE BRACKET	Not Necessary	179.60 FL	*- FL
3	2	*REAR BUMPER SIDE RETAINER L/R	Necessary	98.00 FL	*98.00 FL
4	1	*REAR BUMPER SPONGE	Cracked	125.30 FL	*125.30 FL
5	1	*REAR END PANEL	Dented	552.80 FL	*552.80 FL
6	1	*REAR END PANEL INNER TOP GARNISH	Deformed	68.80 FL	*68.80 FL
7	2	*REAR END PANEL NOSE BRACKET L/R	Dented	192.60 FL	*192.60 FL
8	1	*REAR FENDER INNER SHIELD L/R	N/s Torn	96.00 FL	*48.00 FL
9	2	*REAR FENDER INNER TRIM BOARD L/R	N/s Cracked / O/s Deformed	792.80 FL	*792.80 FL
10	1	*REAR FLOOR PANEL	Buckled	611.00 FL	*611.00 FL
11	1	*REAR FLOOR PANEL COMPARTMENT TRAY	Deformed	143.00 FL	*143.00 FL
12	1	*REAR FLOOR PANEL TOP BOARD COVER	Torn	443.70 FL	*258.00 FL
13	2	*REAR FLOOR SIDE TOP PANEL L/R	Necessary	131.60 FL	*131.60 FL
14	1	*REAR LH FENDER	Repair	909.00 FL	*- FL
15	1	*REAR TAILGATE	Distorted	1,018.20 FL	*1,018.20 FL
16	1	*REAR TAILGATE DIG-S EMBLEM	Necessary	64.90 FL	*64.90 FL
17	1	*REAR TAILGATE LOGO EMBLEM	Necessary	64.90 FL	*64.90 FL
18	1	*REAR TAILGATE NOTE EMBLEM	Necessary	79.90 FL	*79.90 FL
19	2	*REAR TAILGATE DAMPER L/R	Not Necessary	395.40 FL	*- FL
20	2	*REAR TAILGATE HINGE L/R	Not Necessary	138.60 FL	*- FL
21	1	*REAR TAILGATE INNER PULL GARNISH	Deformed	35.00 FL	*35.00 FL
22	2	*REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R	Not Necessary	40.00 FL	*- FL
23	1	*REAR TAILGATE INNER TRIM BOARD	Cracked	132.00 FL	*132.00 FL
24	1	*REAR TAILGATE LOCK STRIKER	Not Necessary	34.80 FL	*- FL
25	1	*REAR TAILGATE MECHANISM LOCK	Damaged	128.40 FL	*128.40 FL
26	2	*REAR TAILGATE NUMBER PLATE LAMP L/R	Not Necessary	160.40 FL	*- FL
27	1	*REAR TAILGATE OUTER HANDLE	Not Necessary	243.50 FL	*- FL
28	1	*REAR TAILGATE WEATHERSTRIP	Cut	68.20 FL	*68.20 FL
29	1	*REAR TAILGATE WINDSCREEN MOULDING	Necessary	69.50 FL	*69.50 FL
30	2	*REAR TAILLAMP INNER PANEL L/R	Repair	94.00 FL	*- FL
31	2	*REAR TAILLAMP L/R	N/s Cracked / O/s Cut	646.20 FL	*646.20 FL
32	1	*SET REAR BUMPER	Necessary	80.00 FS	*30.00 FS
33	1	*SET REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
34	1	*SET REAR END PANEL INNER TOP GARNISH CLIPS	Necessary	50.00 FS	*10.00 FS
35	2	*SET REAR FENDER INNER SHIELD CLIPS L/R	Necessary	100.00 FS	*20.00 FS
36	2	*SET REAR FENDER INNER TRIM BOARD CLIPS L/R	Necessary	100.00 FS	*30.00 FS
37	1	*REAR FLOOR PANEL INSULATOR MAT	Necessary	300.00 FS	*200.00 FS
38	1	*REAR LH FENDER GLASS SEALANT	Not Necessary	80.00 FS	*- FS
39	1	*REAR LH FENDER GLASS WITH MOULDING	Not Necessary	1,342.00 FS	*- FS
40	1	*REAR TAILGATE CAMERA	Damaged	800.00 FS	*400.00 FS
41	1	*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*30.00 FS
42	1	*REAR TAILGATE LOCK OPENER SWITCH	Not Necessary	73.40 FS	*- FS

Report was unsubmitted during this print-out.

10/21/2020			Adjuster Report		
No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
43	1	*REAR TAILGATE NUMBER PLATE	Bent	25.00 FS	*25.00 FS
44	1	*REAR TAILGATE NUMBER PLATE HOLDER	Deformed	50.00 FS	*30.00 FS
45	1	*SET REAR TAILGATE OUTER HANDLE CLIPS	Not Necessary	50.00 FS	*- FS
46	1	*REAR TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
47	1	*REAR TAILGATE WIPER MOTOR	Not Necessary	427.80 FS	*- FS
48	2	*SET REAR TAILLAMP CLIPS L/R	Necessary	60.00 FS	*20.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.					
				Sub Total (\$)	12,236.30
				6,844.10	
				- List Item Discount on L Items 10.00/10.00% (\$)	821.81
				578.91	
				Total Parts (\$)	11,414.49
				6,265.19	
Report was unsubmitted during this print-out.					

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING, AND REWIRE FOR PARKING SENSOR.	New	100.00	80.00
2	TO REMOVE, REINSTALL TAILGATE WINDSCREEN.	New	150.00	120.00
3	TO REMOVE, REINSTALL FENDER GLASS.	New	150.00	0.00
4	TO REMOVE, REINSTALL PETROL TANK. (TO FR)	New	80.00	0.00
5	TO REMOVE, REINSTALL ROOF TOP TRIM UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET. (TO FR)	New	140.00	80.00
6	TO RE-SPRAY PAINTING ON THE REAR BOOTLID, REAR END PANEL, REAR FENDER (L/R), SPARE TYRE PANEL AND REAR BUMPER.	New	1,400.00	1,200.00
7	TO REMOVE AND REINSTALL EXHAUST PIPE.	New	80.00	0.00
8	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.	New	2,400.00	1,400.00
9	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	New	140.00	60.00
10	TO REMOVE, REINSTALL TAILGATE MECHANISM AND CHECK FOR FUNCTION.	New	80.00	80.00
Gross Labour Cost (\$\$)			4,720.00	3,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >