

# N-51 AUTOMOTIVE PTE LTD

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

MR. YEO KWEE TECK  
BLK 931 JURONG WEST ST 92 #13-205  
SINGAPORE 640931

TPM  
Xiao Tong

## ESTIMATE

Repair Code : CLM16038

Date in : 11/02/2020

Vehicle Num. : SLJ1425G

Model : NISSAN NOTE 1.2 DIG-S CVT 2WD LED

Chassis/Eng# : JN1TBAE12Z0982888/HR12214614B

### Parts and Labour Assesment

| Description of part                                    | Qty | Unit Price | Amount     |
|--------------------------------------------------------|-----|------------|------------|
| REAR BUMPER Distorted                                  | 1   | 460.00     | ✓ 460.00   |
| REAR BUMPER CENTER BRACKET All new                     | 1   | 179.60     | ✓ 179.60   |
| REAR BUMPER SIDE RETAINER L/R New                      | 2   | 49.00      | ✓ 98.00    |
| REAR BUMPER SPONGE Caused                              | 1   | 125.30     | ✓ 125.30   |
| REAR END PANEL Dented                                  | 1   | 552.80     | ✓ 552.80   |
| REAR END PANEL INNER TOP GARNISH Behind                | 1   | 68.80      | ✓ 68.80    |
| REAR END PANEL NOSE BRACKET L/R Dented                 | 2   | 96.30      | ✓ 192.60   |
| REAR FENDER INNER SHIELD L/R LH torn                   | 2   | 48.00      | 48 96.00   |
| REAR FENDER INNER TRIM BOARD L/R LH cracked, RH Behind | 2   | 396.40     | ✓ 792.80   |
| REAR FLOOR PANEL Buckled                               | 1   | 611.00     | ✓ 611.00   |
| REAR FLOOR PANEL COMPARTMENT TRAY Behind               | 1   | 143.00     | ✓ 143.00   |
| REAR FLOOR PANEL TOP BOARD COVER torn                  | 1   | 443.70     | 258 443.70 |
| REAR FLOOR SIDE TOP PANEL L/R New                      | 2   | 65.80      | ✓ 131.60   |
| REAR LH FENDER Reps                                    | 1   | 909.00     | ✓ 909.00   |
| REAR TAILGATE Distorted                                | 1   | 1018.20    | ✓ 1,018.20 |
| REAR TAILGATE 'DIG-S' EMBLEM                           | 1   | 64.90      | ✓ 64.90    |
| REAR TAILGATE 'LOGO' EMBLEM                            | 1   | 64.90      | ✓ 64.90    |
| REAR TAILGATE 'NOTE' EMBLEM                            | 1   | 79.90      | ✓ 79.90    |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

# **N-51 AUTOMOTIVE PTE LTD**

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

MR. YEO KWEE TECK

BLK 931 JURONG WEST ST 92 #13-205

SINGAPORE 640931

Contact : 96245879

## ESTIMATE

Repair Code : CLM16038

Date in : 11/02/2020

Vehicle Num. : SLJ1425G

Model : NISSAN NOTE 1.2 DIG-S CVT 2WD LED

Chassis/Eng# : JN1TBAE12Z0982888/HR12214614B

|                                              |                         |   |        |   |        |
|----------------------------------------------|-------------------------|---|--------|---|--------|
| REAR TAILGATE DAMPER L/R                     | <i>2 H/m</i>            | 2 | 197.70 | X | 395.40 |
| REAR TAILGATE HINGES L/R                     |                         | 2 | 69.30  | X | 138.60 |
| REAR TAILGATE INNER PULL GARNISH             | <i>2 H/m</i>            | 1 | 35.00  | ✓ | 35.00  |
| REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R | <i>2 H/m</i>            | 2 | 20.00  | X | 40.00  |
| REAR TAILGATE INNER TRIM BOARD               | <i>1 C/L</i>            | 1 | 132.00 | ✓ | 132.00 |
| REAR TAILGATE LOCK STRIKER                   | <i>1 H/m</i>            | 1 | 34.80  | X | 34.80  |
| REAR TAILGATE MECHANISM LOCK                 | <i>1 Dmgd</i>           | 1 | 128.40 | ✓ | 128.40 |
| REAR TAILGATE NUMBER PLATE LAMP L/R          | <i>2 H/m</i>            | 2 | 80.20  | X | 160.40 |
| REAR TAILGATE OUTER HANDLE                   | <i>1 H/m</i>            | 1 | 243.50 | X | 243.50 |
| REAR TAILGATE WEATHER STRIP                  | <i>1 C/L</i>            | 1 | 68.20  | ✓ | 68.20  |
| REAR TAILGATE WINDSCREEN MOULDING            | <i>1 H/m</i>            | 1 | 69.50  | ✓ | 69.50  |
| REAR TAILLAMP INNER PANEL L/R                | <i>2 R/S</i>            | 2 | 47.00  | X | 94.00  |
| REAR TAILLAMP L/R                            | <i>2 H C/L, R H C/L</i> | 2 | 323.10 | ✓ | 646.20 |

Subtotal before discount

8,218.10

Percentage discount 10%

821.81

**Sub-total 1**

7,396.29

|                                  |                |   |        |     |                   |
|----------------------------------|----------------|---|--------|-----|-------------------|
| REAR BUMPER CLIPS - SET          | <i>1 H/m</i>   | 1 | 80.00  | 30  | <del>80.00</del>  |
| REAR BUMPER REVERSE SENSOR - SET | <i>1 Dmgd.</i> | 1 | 350.00 | 200 | <del>350.00</del> |

\*\*\* This is a computer-generated document which requires no signature. \*\*\*

# N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

MR. YEO KWEE TECK  
BLK 931 JURONG WEST ST 92 #13-205  
SINGAPORE 640931

Contact : 96245879

## ESTIMATE

Repair Code : CLM16038

Date in : 11/02/2020

Vehicle Num. : SLJ1425G

Model : NISSAN NOTE 1.2 DIG-S CVT 2WD LED

Chassis/Eng# : JN1TBAE12Z0982888/HR12214614B

|                                                         |   |         |                       |
|---------------------------------------------------------|---|---------|-----------------------|
| REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>Nec</i> | 1 | 50.00   | 10 <del>50.00</del>   |
| REAR FENDER INNER SHIELD CLIPS L/R - SET <i>Nec</i>     | 2 | 50.00   | 20 <del>100.00</del>  |
| REAR FENDER INNER TRIM BOARD CLIPS L/R - SET <i>Nec</i> | 2 | 50.00   | 30 <del>100.00</del>  |
| REAR FLOOR PANEL INSULATOR MAT <i>Nec</i>               | 1 | 300.00  | 200 <del>300.00</del> |
| REAR LH FENDER GLASS SEALANT <i>Nec</i>                 | 1 | 80.00   | 1 <del>80.00</del>    |
| REAR LH FENDER GLASS WITH MOULDING <i>Nec</i>           | 1 | 1342.00 | 1 <del>1,342.00</del> |
| REAR TAILGATE CAMERA <i>Damaged</i>                     | 1 | 800.00  | 400 <del>800.00</del> |
| REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>Nec</i>   | 1 | 50.00   | 30 <del>50.00</del>   |
| REAR TAILGATE LOCK OPENER SWITCH <i>Nec</i>             | 1 | 73.40   | 1 <del>73.40</del>    |
| REAR TAILGATE NUMBER PLATE <i>Best</i>                  | 1 | 25.00   | 1 <del>25.00</del>    |
| REAR TAILGATE NUMBER PLATE HOLDER <i>Replaced</i>       | 1 | 50.00   | 30 <del>50.00</del>   |
| REAR TAILGATE OUTER HANDLE CLIPS - SET                  | 1 | 50.00   | 1 <del>50.00</del>    |
| REAR TAILGATE WINDSCREEN SEALANT <i>Nec</i>             | 1 | 80.00   | 60 <del>80.00</del>   |
| REAR TAILGATE WIPER MOTOR <i>Nec</i>                    | 1 | 427.80  | 1 <del>427.80</del>   |
| REAR TAILLAMP CLIPS L/R - SET <i>Nec</i>                | 2 | 30.00   | 20 <del>60.00</del>   |
| Subtotal before discount                                |   |         | 4,018.20              |
| Percentage discount 0%                                  |   |         | 0.00                  |
| Sub-total 2                                             |   |         | 4,018.20              |
| Parts-total                                             |   |         | 11,414.49             |

\*\*\* This is a computer-generated document which requires no signature. \*\*\*

# N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

MR. YEO KWEE TECK  
BLK 931 JURONG WEST ST 92 #13-205  
SINGAPORE 640931

Contact : 96245879

## ESTIMATE

Repair Code : CLM16038

Date in : 11/02/2020

Vehicle Num. : SLJ1425G

Model : NISSAN NOTE 1.2 DIG-S CVT 2WD LED

Chassis/Eng# : JN1TBAE12Z0982888/HR12214614B

## LABOUR

|                                                                                                                                                                                 |      |                  |
|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------|------------------|
| To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.                                                                                  | 80   | 100.00           |
| To remove, reinstall tailgate windscreen                                                                                                                                        | 120  | 150.00           |
| To remove, reinstall fender glass                                                                                                                                               | X    | 150.00           |
| To remove, reinstall petrol tank. (to FR)                                                                                                                                       | X    | 80.00            |
| To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)                                                                           | 80   | 140.00           |
| To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.                                                                  | 1200 | 1,400.00         |
| To remove and reinstall exhaust pipe.                                                                                                                                           | X    | 80.00            |
| To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident. | 1400 | 2,400.00         |
| To apply anti-rust chemical on repaired and replaced panel.                                                                                                                     | 60   | 140.00           |
| To remove, reinstall tailgate mechanism and check for function                                                                                                                  | ✓    | 80.00            |
| <b>Labour Total</b>                                                                                                                                                             |      | <b>4,720.00</b>  |
| <b>Parts &amp; Labour Total</b>                                                                                                                                                 |      | <b>16,134.49</b> |

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

page 4

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 9171.39

h/s: 7.31C

08 Days.

7.31C