

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Feb 2020 Edit Reg		12 Feb 2020 00:00 Edit Adj Rpt	S\$3,100.00 Edit Estimates	S\$3,100.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: PUA BENG BOON (PAN LINGWEN) , ID: S1805532E									
Main Claimant: LACHLAN WILLIAM BARNES , Co. Reg. No.: G5186753Q									
Vehicle Reg. No.: SMK403J		Date of Loss: 06/02/2020 18:00 - :59 [20 Months and 13 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 2944997838SG		Policy/Cover Note No.: (Comprehensive) Coverage: 16/07/2019 - 15/07/2020							
Vehicle Reg. No. (Insured): SJK6800S		Policy No. (Claimant): Excess:							
Repairer: Sin Ming Autocare BFG Pte Ltd (HQ) 176, Sin Ming Drive #02-05, Sin Ming Autocare Complex, 575721 Sin Ming - Tel: 64550600									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 21/02/2020]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG_EXPRESS (14/04/2020): Alert - Adj Mandate Approved (S\$2000.00) - SMK403J - Claim Handler: MdNoor, Nors...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMK403J (2944997838SG)**
[SJK6800S]
TP
LACHLAN WILLIAM BARNES
Feb 6 2020 6:00PM
[PUA BENG BOON (PAN LINGWEN)]
Sin Ming Autocare BFG Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
Video			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/02/20 11:02	FRONT VIDEO	Load MP4	
2	20/02/20 11:02	REAR VIDEO	Load MP4	
Letters/Correspondences			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	Edit	
Assessment Reports			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/03/20 11:02	Adjuster Immediate Advice	Load HTM	
Photos/Images			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/03/20 10:59	General View	Load JPG	☒
2	26/03/20 10:59	General View	Load JPG	☒
3	26/03/20 10:59	General View	Load JPG	☒
4	26/03/20 10:59	General View	Load JPG	☒
5	26/03/20 10:59	General View	Load JPG	☒
6	26/03/20 10:59	General View	Load JPG	☒
7	26/03/20 10:59	General View	Load JPG	☒
8	26/03/20 10:59	General View	Load JPG	☒
9	26/03/20 10:59	General View	Load JPG	☒
10	26/03/20 10:59	General View	Load JPG	☒
11	26/03/20 10:59	General View	Load JPG	☒
12	26/03/20 10:59	General View	Load JPG	☒
13	26/03/20 10:59	General View	Load JPG	☒
14	26/03/20 10:59	Chassis Number	Load JPG	☒
15	26/03/20 10:59	Odometer Reading	Load JPG	☒
16	26/03/20 10:59	Reinspection Photo	Load JPG	☒
17	26/03/20 10:59	Reinspection Photo	Load JPG	☒
18	26/03/20 10:59	Reinspection Photo	Load JPG	☒
19	26/03/20 10:59	Reinspection Photo	Load JPG	☒
20	26/03/20 10:59	Reinspection Photo	Load JPG	☒
21	26/03/20 10:59	Reinspection Photo	Load JPG	☒
22	26/03/20 10:59	Reinspection Photo	Load JPG	☒
23	26/03/20 10:59	Reinspection Photo	Load JPG	☒
24	26/03/20 10:59	Reinspection Photo	Load JPG	☒
25	26/03/20 10:59	Reinspection Photo	Load JPG	☒
Documentation			1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/02/20 16:08	ACKNOWLEDGEMENT EMAIL TO AIG DD11022020	Load PDF	
2	12/02/20 16:08	EMAIL FROM AIG DD11022020	Load PDF	
3	12/02/20 16:08	TP GIA REPORT	Load PDF	

Video				1 per page ▼	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
4	18/02/20 13:13	TP ESTIMATE-MARKED		Load PDF	
5	19/03/20 14:30	LETTER TO OI		Load PDF	
6	26/03/20 11:07	TP ESTIMATE - MARKED (FINAL)		Load PDF	
7	27/04/20 11:31	Authorisation to Act		Load PDF	
8	27/04/20 11:31	GIA SEARCH		Load PDF	
9	27/04/20 11:31	LOD		Load PDF	
10	27/04/20 11:31	Release Voucher		Load PDF	
11	27/04/20 11:31	WORKSHOP INVOICE		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	13/02/20 15:27	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJK6800S (Insd veh)	Model:	TOYOTA HARRIER 2.0 G
	SMK403J (TP veh)		GRADE (A)
Date of Accident:	06/02/2020		

Global Sum Settlement	:	[X]	Yes	[]	No	
Repair Estimate	:	\$				9,209.27
Final Repair Cost	:	\$				1,860.00
Loss of Use	:	\$				4.00 days at \$100.00 per day
Rental (if any)	:	\$				days
LTA / GIA Search Fee	:	\$				
Others:	:	\$				
	:	\$				
Final Settlement Sum (GLOBAL SUM)	:	\$				1,860.00

Is Third Party Workshop GIA Registered?				[]	YES	[X]	NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:				Agreed Liability _____ 50 _____ (%)				
B) For GIA Registered Workshop:				BOLA Applicable: Yes/ No BOLA Scenario No: _____				
BOLA Liability: _____ (%)				Assessed Liability (*): _____ (%)				
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.								
Remarks _____								

Payment Instruction: Payee's Breakdown			
1)	Sin Ming Autocare BFG Pte Ltd	: \$	1,860.00
2)		: \$	
3)		: \$	

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

27 Apr
2020

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20002453/KES3S2**Date:** 27/04/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SMK403J**Insured Vehicle No :** SJK6800S

Date of Loss: 06/02/2020

Nature of Claim: TP

Claim No: 2944997838SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMK403J**

Make & Model: TOYOTA HARRIER, 2.0 G GRADE (A)

Engine No: 8ARZ118452

Reg. Date: 24/05/2018 (Man. Year: 2018)

Chassis No: JTEKB3GH00J001946

Colour: Metallic Pearl White

Odometer: 23802 km

Engine Capacity: 1998 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 235/60 R18

Rear Tyre Size:

235/60 R18

Front Left Side: Michelin 7 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 7 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,296.79	2,655.37	3,641.42	57.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,310.00	1,230.00	1,080.00	46.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,606.79	3,885.37	4,721.42	54.86
Approved Total (Overridden) (S\$)		3,100.00		
(S\$)	8,606.79	3,100.00	5,506.79	63.98
+ GST 7.00/7.00% (S\$)	602.48	217.00	385.48	63.98
Nett Amount (S\$)	9,209.27	3,317.00	5,892.27	63.98
+ Loss of Use (4.0 x S\$100.00/day) (S\$)		400.00		
(S\$)		3,717.00		
Liabe Amount (50.00%) (S\$)		1,858.50		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,860.50		
Global Sum Settlement (S\$)		1,860.00		

INSPECTION

Date of Assignment: 12/02/2020

Date Inspected: 13/02/2020 Inspected At:

Sin Ming Autocare BFG Pte Ltd (HQ)

176, Sin Ming Drive #02-05, Sin Ming Autocare Complex

Singapore 575721

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	1,218.45 FL	*- FL
2	1		*REAR BUMPER RETAINER L/H	Serviceable	132.40 FL	*- FL
3	1		*REAR FENDER - LH	Repair	1,891.10 FL	*- FL
4	1		*REAR FENDER INNER SHIELD (LH)	Serviceable	191.60 FL	*- FL
5	1		*REAR DOOR - LH	Bent	1,685.90 FL	*1,685.90 FL
6	1		*REAR DOOR LOWER CHROME	Necessary	285.60 FL	*285.60 FL
7	4		*REAR BUMPER CLIPS	Not Necessary	22.00 FS	*- FS
8	1		*SET REVERSE SENSOR	Serviceable	280.00 FS	*- FS
9	4		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	22.00 FS	*- FS
10	1		*REAR TYRE	Serviceable	350.00 FS	*- FS
11	1		*REAR RIM LH	Dented	1,569.00 FS	*1,176.75 FS
					Sub Total (\$)	7,648.05 3,148.25
					- List Item Discount on L Items 25.00/25.00% (\$)	1,351.26 492.88
					Total Parts (\$)	6,296.79 2,655.37

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR SPRAY PAINT ALL AFFECTED AREAS.	New	1,100.00	480.00
2	LABOUR FOR PANEL BEATING ALL AFFECTED AREAS.	New	800.00	600.00
3	TO APPLY ANTI-RUST.	New	80.00	30.00
4	LABOUR FOR REMOVE & TRANSFER ALL INNER PARTS AND DOOR GLASS TO NEW DOOR.	New	250.00	60.00
5	TO WHEEL ALIGNMENT.	New	80.00	60.00
Gross Labour Cost (\$\$)			2,310.00	1,230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >