

# 振明摩托

## CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883  
Tel: 6747-4810 Fax: 6745-5018  
cmmotors@singnet.com.sg

### ESTIMATE

Our Ref: EST027/20/TP

Your Ref: TP claim against SMF4315E

11-Feb-20

**AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#08-16

Singapore 409179

**Attn: Motor Claims Department**

Dear Sir/Ms,

**Re: Estimated cost of repair to Mitsubishi Lancer EX no: SLL4382R**

Date of accident: 08-02-2020

Parts supply (Nett)

1 pc Rear boot emblem - Logo		S\$	55.60 ✓
1 pc Rear boot emblem - LANCER			65.80 ✓
1 pc Rear boot emblem - SPORT			55.20 ✓
1 pc Rear boot emblem - C&C			62.50 ✓
1 pc Rear boot emblem - MIVEC			54.50 ✓
1 pc Rear boot inner lock			233.50 +
1 pc Rear bumper			815.50 ✓
1 pc Rear bumper reinforcement			266.30 ✓
2 pcs Rear bumper retainer @\$45.80			91.60 ✓
2 pcs Rear bumper brackets @\$89.50			179.00 +
1 pc Rear bumper tow cover			28.50 ✓
2 pcs Rear bumper reflectors @\$45.80			91.60 +
1 pc Rear bumper pad (top)			113.50 ✓
1 pc Rear end panel			489.50 +
1 pc Rear end panel garnish			115.80 ✓
			<u>2,718.40</u>
		Less 10%:	(271.84)

S/Nett Items

1 pc Rear no. plate with cover (S/Nett)			45.00 ✓
1 set Rear reverse sensor (S/Nett)			250.00 ✓
1 pc Rear exhaust pipe cover (S/Nett)			120.00 +

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc.

To apply underseal

To remove and refit rear reverse sensor

To respray affected part.

To check wirings.

Adrian L  
4/5 11/02/20  
04 Days  
Total: 2827.32  
c/s: 2250

S\$ 4,151.56

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: