

Case Details

Case Reference Number : TAX/02/20/2029
Type of Repair : Accident Repair
Vehicle Registration Number : SHB1005A

Company Type : SMRT Taxis Pte Ltd
Estimation ID : EST-10431-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd
Accident Date and Time : 08/02/2020 12:20 PM
Vehicle Age(In Months) : 69

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	0.00	Repair	X R
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	0	0.00	Not Give	X Svc
One Time Key In	Main			BUMPER SUPPORT F/RH	1	76.40	76.40	25.00	57.30	Replace	0	0.00	Not Give	X Svc
One Time Key In	Main			BUMPER SUPPORT F/LH	1	76.40	76.40	25.00	57.30	Replace	0	0.00	Not Give	X Svc
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0.00	Not Give	X Svc
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0.00	Not Give	X Svc
One Time Key In	Main			ARM SUB-ASSY,FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0.00	Not Give	X Svc
One Time Key In	Main			ARM SUB-ASSY,FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	0	0.00	Not Give	X Svc
One Time Key In	Main			BUMPER GRILLE SUB-ASSY,LOWER	1	311.10	311.10	25.00	233.33	Replace	0	0.00	Not Give	X Svc
One Time Key In	Main			LENS & BODY,FR TURN LH	1	511.80	511.80	10.00	460.62	Replace	0	0.00	Not Give	X Svc
One Time Key In	Main			BUMPER LIP FRT	1	139.60	139.60	25.00	104.70	Replace	0	0.00	Not Give	X Svc

Total Spare Part Cost 6,543.58

Lump Sum Discount (%) 20.00

Final Spare Part Cost 5,234.86

Surveyor Total 167.69

Lump Sum Dis (%) 20.00

Final Sur Total 134.15

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace Remarks
One Time Key In	Main			BUMPER FRT ABSORBER LOWER	1	127.70	127.70	25.00	95.78	Replace	0	0.00	Not Give ✕ Svc
One Time Key In	Main			UNDER COVER CENTER	1	448.30	448.30	25.00	336.23	Replace	0	0.00	Not Give ✕ Svc
One Time Key In	Main			HEAD LAMP LH	1	945.20	945.20	10.00	850.68	Replace	0	0.00	Not Give ✕ Svc
One Time Key In	Main			FENDER FRT/LH	1	723.40	723.40	25.00	542.55	Replace	1	0.00	Repair ✕ R
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace ✓ Nec
One Time Key In	Main			FENDER PROTECTOR FRT/LH UPPER	1	46.10	46.10	25.00	34.58	Replace	0	0.00	Not Give ✕ Svc
One Time Key In	Main			PROTECTOR, FRONT FENDER SIDE PANEL LH	1	114.50	114.50	25.00	85.88	Replace	0	0.00	Not Give ✕ Svc
One Time Key In	Main			FENDER LINER FRT/LH	1	171.70	171.70	25.00	128.77	Replace	1	128.77	Replace ✓ cuf
One Time Key In	Main			FENDER LINER PAD, FR WHEEL. LH	1	49.30	49.30	25.00	36.97	Replace	0	0.00	Not Give ✕ Svc
One Time Key In	Main			WHEEL DISC. FRONT	1	1,484.20	1,484.20	25.00	1,113.15	Replace	0	0.00	Not Give ✕ Svc
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0.00	Not Give ✕ Svc
One Time Key In	Main			MIRROR ASSY, LH	1	1,224.90	1,224.90	25.00	918.68	Replace	0	0.00	Not Give ✕ Svc
One Time Key In	Main			MIRROR LAMP LH	1	65.30	65.30	10.00	58.77	Replace	0	0.00	Not Give ✕ Svc
One Time Key In	Main			COVER, OUTER MIRROR, LH	1	107.40	107.40	25.00	80.55	Replace	0	0.00	Not Give ✕ Svc
Total Spare Part Cost									6,543.58	Surveyor Total		167.69	
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20.00	
Final Spare Part Cost									5,234.86	Final Sur Total		134.15	

10,401.04#

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT LH PORTION	507.00	200	✓
Total:			507.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200.00	✓
2	Main	TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0.00	
3	Main	TO RESPRAY FRONT FENDER LH	378.00	200.00	✓
4	Main	TO RESPRAY RIM	180.00	0.00	
5	Main	RESPRAY MIRROR COVER LH	180.00	0.00	
Total:			1,296.00	400.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00	
2	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00	
3	Main	TO REMOVE AND REFIX WING MIRROR	120.00	0.00	
4	Main	TO REPLACE SUNDRY PARTS	100.00	0.00	
5	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00	
6	Main	TO WASH AND VACUUM	60.00	0.00	
Total:			600.00	0.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	5,234.86	134.15
Total Labour Cost	507.00	200.00
Total Spray Painting	1,296.00	400.00
Other	600.00	0.00
Overall Total	7,637.86	734.15
Lump Sum Repair Option		✓
Lump Sum Total	7,650.00	750.00
Surveyor Approved Amount		750.00
No of Repair Days*	5	2 2 days

Estimator Assessment(\$)

Surveyor Assessment(\$)

Remarks

Lump Sum repair, after paint photo.

Surveyor Name

Sun Pin (LKK)

Signature



Survey Date

11/02/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: