

k



TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : GBH3119G  
Date of Accident : 11 February 2020

*Not Authorized  
after  
12/1/20  
5 days.  
To help the other rep  
2/5 \$7650/*

Messrs BIS Motoring Pte Ltd

Date : 14 February 2020

Estimate To Repair SMK7021G - Renault Grand Scenic IV 1.5 DCI AT EU6  
Chassis No : VF1RFA00662476759

S/No	Quantity	Description	Amount
<b>LIST ITEMS</b>			
01	1 pc	rear bumper	\$ 1,081.32 ✓
02	1 pc	rear bumper centre pad	\$ 480.00 ✓
03	1 pc	rear bumper lower	\$ 684.50 ✓
04	2 ps	rear bumper reflector @ \$434.20 <i>205</i>	\$ 868.40 <i>o/scre</i>
05	2 ps	rear bumper side retainer @ \$337.30	\$ 674.60 X
06	2 ps	rear bumper lower bracket @ \$103.60	\$ 207.20 <i>o/scre</i>
07	2 ps	rear bumper centre pad lower bracket @ \$325.10	\$ 650.20 X
08	2 ps	rear bumper centre pad splash guide @ \$372.70	\$ 745.40 X
09	4 ps	rear bumper parking sensor @ \$244.60	\$ 978.40 <i>shold</i>
10	1 pc	rear bumper parking sensor wire harness	\$ 446.50 X
11	1 pc	rear bumper beam	\$ 625.60 <i>best</i>
12	1 pc	rear end panel	\$ 797.60 ✓
13	1 pc	rear end panel inner trim	\$ 595.00 X
14	1 pc	rear end panel top garnish	\$ 245.60 X
15	1 pc	rear end panel under plastic <i>\$25.00</i>	\$ 1,169.90 ✓
16	1 pc	tailgate lid	\$ 2,292.70 ✓
17	1 pc	tailgate lid centre emblem	\$ 151.20 ✓
18	1 pc	tailgate lid Scenic emblem	\$ 119.60 ✓
19	1 pc	tailgate lid Renault emblem	\$ 138.10 ✓
20	1 pc	tailgate lid lamp	\$ 546.50 X
21	2 ps	rear number plate lamp @ \$35.80	\$ 71.60 X
22	1 pc	rear keyless switch	\$ 124.80 X
23	1 pc	rear keyless switch antenna	\$ 0.00 X
24	1 pc	rear reverse camera	\$ 458.50 X
25	1 pc	rear exhaust heat shield - outer	\$ 160.30 ✓
26	1 pc	rear exhaust heat shield - end	\$ 235.10 X
Less 10 %			\$ 14,518.82
			\$ 1,451.86
			\$ 13,066.76
<b>SPECIAL NETT ITEMS</b>			
27	1 pc	rear number plate w/holder	\$ 50.00 <i>best</i> 40
28	1 pc	rear windscreen sealant	\$ 80.00 <i>nu</i> 40
29	1 pc	rear windscreen inner seal	\$ 50.00 <i>nu</i> 40
			\$ 180.00
<b>LABOUR &amp; MISC. CHARGES</b>			
01		To rust-proofing of the affected areas.	\$ 300.00 30
02		To reinstall of rear bumper parking sensor.	\$ 80.00 50

*434.20 1 pc*

*103.60 1 pc*

*489.20 2 pcs*

*7843.72*



陳林際嗎私人有限公司  
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : GBH3119G  
Date of Accident : 11 February 2020

Messrs BIS Motoring Pte Ltd

Date : 14 February 2020

Estimate To Repair SMK7021G - Renault Grand Scenic IV 1.5 DCI AT EU6

Chassis No : VF1RFA00662476759

S/No	Quantity	Description	Amount
		<b>LABOUR &amp; MISC. CHARGES</b>	
03		To reinstall of rear reverse camera	\$ 11 80.00 X
04		To check electrical lighting concerned.	\$ 60.00 20
05		To repair and realign rear exhaust box.	\$ 11 100.00 X
06		To perform water seepage test, windnoise and test-drive.	\$ 11 80.00 X
07		To transfer of bootlid fittings, attachments and perform water seepage test.	\$ 200.00 100
08		To remove and refit rear windscreen glass.	\$ 120.00 ✓
09		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ 100.00 80
10		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,200.00 680
11		Putty and spray painting of the affected portion.	\$ 1,200.00 800
			\$ 3,520.00
		<b>Total</b>	\$ 16,766.76

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



陳林峰有限公司  
**TAN LIM MOTOR PTE LTD**

1 Defu Lane 6 Singapore 539365  
 Tel : 68685151 ( 24 Hours ) Fax : 68580877  
 GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : GBH3119G  
 Date of Accident : 11 February 2020

Messrs BIS Motoring Pte Ltd

Date : 14 February 2020

Supplementary To Repair SMK7021G - Renault Grand Scenic IV 1.5 DCI AT EU6  
 Chassis No : VF1RFA00662476759

S/No	Quantity	Description	Amount
<b>LIST ITEMS</b>			
01	1 pc	o/s tailamp <i>C/A</i>	\$ 443.40 ✓
02	1 pc	o/s rear bumper beam top bracket <i>C/A</i>	\$ 116.00 ✓
		Less 10 %	\$ 559.40
			\$ 55.94
		Total	\$ 503.46
			\$ 503.46

  

~~parts - \$ 9287.22~~

~~- 10%~~

---

~~\$ 8258.49~~

SN - \$ 120.00 ✓

LB - \$ 1880.00 ✓

---

~~\$ 10358.49~~

~~- 20%~~

---

~~\$ 8286.79~~

---

LS \$ 8250.00 x 5 days

~~9-8413.12~~

~~102~~

---

~~9-7571.80~~

~~S.V-120.00~~

~~L-1880.00~~

---

~~9571.80~~

~~22~~

---

~~7657~~