

LTC
FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50
AUTOBAY @ KAKI BUKIT SINGAPORE 417883
TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg
GST:200712509E RCB NO:201004495R

No of Affidavits
13/2/20
1/5 \$13,000/
13 days.

M/S : LONPAC INSURANCE

Estimate No: M001010

Date: 11-Feb-20

Veh Reg No: SJR4343X

ATTN: Motor Claim Department

Make/Model: MITSUBISHI LANCER

Your Ref No: **SJR4343X**

Chassis No: JMYSRCY2A9U004317

Claim Type: Third Party

Engine No: 4A910125980

Accident Date: 07/02/2020

Reg. Date : 30/09/2009

Estimate Repair Cost to Vehicle No : SJR4343X

PAGE:1/5

S/N	Description	Quantity	Unit	Price	Amount
	<u>NETT PRICE</u>			<u>S\$</u>	<u>S\$</u>
1	Front Bonnet	1	PCS	622.00 Bul	622.00 ✓
2	Front Bonnet Hinges	2	PCS	54.00 Serf	108.00 ✓
3	Front Bonnet Lock	1	PCS	49.00 tw	49.00 ✓
4	Front Bonnet Gasket Rubber	1	PCS	25.00 ny	25.00 ✓
5	Front Bonnet Lock Cable	1	PCS	42.00 crm	42.00 ✓
6	Front Bonnet Insulator	1	PCS	110.00 noqul	110.00 ✓
7	Front Bonnet insulator Clips	8	SET	5.50 11	44.00 X
8	Front Support Panel	1	PCS	586.00 Bul	586.00 ✓
9	Front Support Panel Top Garnish	1	PCS	85.00 DUS	85.00 ✓
10	Front Support Panel Top Garnish Clips	6	PCS	5.50 11	33.00 X
11	Front Fender - RH	1	PCS	468.00 R	468.00 X
12	Front Fender Dust Cover - RH	6	PCS	104.00 11	624.00 X
13	Front Fender Dust Cover Clips - RH	2	PCS	5.50 11	11.00 X
14	Front HeadLamps	2	PCS	616.00 cm	1232.00 ✓
15	Front HeadLamps Lower Bracket	2	PCS	19.00 NS	38.00 X
16	Front Bumper	1	PCS	810.00 DUS	810.00 ✓
17	Front Bumper Reinforcement	1	PCS	313.00 DUS	313.00 ✓
18	Front Bumper Lower Cover	2	PCS	18.00 NS	36.00 X
19	Front Bumper Lower Grille	1	PCS	120.00 Dis	120.00 ✓
20	Front Bumper Lower Grille Cover	2	PCS	6.00 NS	12.00 X
21	Front Bumper Fog lamp	2	PCS	350.00 cm	700.00 ✓
22	Front Bumper Fog Lamp Cover	2	PCS	36.00 tw	72.00 ✓
TOTAL				4449.50	6140.00
LESS 10%					5,526

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50
 AUTOBAY @ KAKI BUKIT SINGAPORE 417883
 TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg
 GST:200712509E RCB NO:201004495R

M/S : LONPAC INSURANCE**Estimate No: M001010**

Date: 11-Feb-20

Veh Reg No: SJR4343X

ATTN: Motor Claim Department

Make/Model: MITSUBISHI LANCER

Your Ref No: **SJR4343X**

Chassis No: JMYSRCY2A9U004317

Claim Type: Third Party

Engine No: 4A910125980

Accident Date: 07/02/2020

Reg. Date : 30/09/2009

Estimate Repair Cost to Vehicle No : SJR4343X

PAGE:2/5

S/N	Description	Quantity	Unit	Price S\$	Amount S\$
<u>NETT PRICE</u>					
23	Front Bumper side Spoiler	2	PCS	289.00 <i>11</i>	578.00 <i>X</i>
24	Front Bumper Under Dust Cover	1	PCS	140.00 <i>thin</i>	140.00 <i>✓</i>
25	Front Grille	1	PCS	247.00 <i>dis</i>	247.00 <i>✓</i>
26	Front Grille Emblem	1	PCS	45.00 <i>scr</i>	45.00 <i>✓</i>
27	Front Air Cleaner Air Duct	1	PCS	89.00 <i>89</i>	89.00 <i>X</i>
28	Front Air Cleaner Box Joint	1	PCS	50.00 <i>ena</i>	50.00 <i>✓</i>
29	Front Air Con Condenser	1	PCS	640.00 <i>dis</i>	640.00 <i>✓</i>
30	Front Air Con Pipe	1	PCS	246.00 <i>11</i>	246.00 <i>X</i>
31	Front Radiator	1	PCS	760.00 <i>ben/pun</i>	760.00 <i>✓</i>
32	Front Radiator Fan <i>cosin/ing</i>	1	PCS	240.00 <i>one</i>	240.00 <i>✓</i>
33	Front Radiator Fan Blade	1	PCS	110.00 <i>bul</i>	110.00 <i>✓</i>
34	Front Radiator Fan Motor	1	PCS	298.00 <i>Jm</i>	298.00 <i>✓</i>
35	Front Horn	1	PCS	80.00 <i>ena</i>	80.00 <i>✓</i>
36	Front Bumper Top Beam	1	PCS	89.00 <i>dis</i>	89.00 <i>✓</i>
37	Rear Boot	1	PCS	620.00 <i>bul</i>	620.00 <i>✓</i>
38	Rear Boot Lock	1	PCS	85.00 <i>twi</i>	85.00 <i>✓</i>
39	Rear Boot Emblem (Lancer)	1	PCS	43.00 <i>ner</i>	43.00 <i>✓</i>
40	Rear Boot Emblem (Miver)	1	PCS	38.00 <i>ner</i>	38.00 <i>✓</i>
41	Rear Boot Reflector	2	PCS	194.00 <i>11</i>	388.00 <i>X</i>
42	Rear Boot 3rd Bradke light	1	PCS	290.00 <i>11</i>	290.00 <i>X</i>
43	Rear Boot Inner Cover	1	PCS	182.00 <i>del/am</i>	182.00 <i>✓</i>
44	Rear Boot Inner Cover Clips	7	PCS	5.50 <i>11</i>	38.50 <i>X</i>
TOTAL				4780.50	5296.50
LESS 10%					4.766.85

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

GST:200712509E RCB NO:201004495R

M/S : LONPAC INSURANCE**Estimate No: M001010**

Date: 11-Feb-20

Veh Reg No: SJR4343X

ATTN: Motor Claim Department

Make/Model: MITSUBISHI LANCER

Your Ref No: **SJR4343X**

Chassis No: JMYSRCY2A9U004317

Claim Type: Third Party

Engine No: 4A910125980

Accident Date: 07/02/2020

Reg. Date : 30/09/2009

Estimate Repair Cost to Vehicle No : SJR4343X

PAGE:3/5

S/N	Description	Quantity	Unit	Price S\$	Amount S\$
<u>NETT PRICE</u>					
45	Rear Boot Centre Logo	1	PCS	48.00 <i>mu</i>	48.00 ✓
46	Rear Boot Hinges	2	PCS	120.00 <i>17</i>	240.00 X
47	Rear Boot Shock Absorber	2	PCS	98.00 <i>17</i>	196.00 X
48	Rear Boot Rubber	1	PCS	185.00 <i>twi</i>	185.00 ✓
49	Rear Spare Tyre Cover Board	1	PCS	240.00 <i>to 1</i>	240.00 ✓
50	Rear Spare Tyre panel	<i>crumpled</i> 1/	PCS	638.00 <i>by c</i>	638.00 ✓
51	Rear End Panel	2	PCS	435.00 <i>5.50</i>	870.00 <i>1pc</i>
52	Rear End panel Top Garnish	1	PCS	144.00 <i>twi</i>	144.00 ✓
53	Rear Fender Inner Side Garnish	2	PCS	252.00 <i>Defrom</i>	504.00 ✓
54	Rear Fender Inner Side Garnish Clipse	6	PCS	5.50 <i>17</i>	33.00 X
55	Rear Tail lamp	2	PCS	298.00 <i>o/sou</i>	596.00 <i>1pc</i>
56	Rear Tail Lamp Panel	2	PCS	98.00 <i>u</i>	196.00 X
57	Rear Bumper	1	PCS	747.00 <i>Dis</i>	747.00 ✓
58	Rear Bumper Top Beam	1	PCS	98.00 <i>Dis</i>	98.00 ✓
59	Rear Bumper Reinforcement	1	PCS	290.00 <i>Dis</i>	290.00 ✓
60	Rear Bumper Side Retainer	2	PCS	18.00 <i>Beel</i>	36.00 ✓
61	Rear Bumper Towing Cover	1	PCS	20.00 <i>to 1</i>	20.00 ✓
62	Rear Bumper Reflector	2	PCS	19.00 <i>BNo</i>	38.00 ✓
63	Rear Bumper Side Dust Cover	2	PCS	52.00 <i>17</i>	104.00 X
64	Rear Bumper Side Dust Cover Clips	6	PCS	5.50 <i>17</i>	33.00 X
65	Rear Bumper Cover Clips	4	PCS	5.50 <i>mu</i>	22.00 ✓
66	Rear Number Plate Lamp	2	PCS	38.00 <i>17</i>	76.00 X
TOTAL				3854.50	5354.00
LESS 10%					4818.60

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50

AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg

GST:200712509E RCB NO:201004495R

M/S : LONPAC INSURANCE

Estimate No: M001010

Date: 11-Feb-20

Veh Reg No: SJR4343X

ATTN: Motor Claim Department

Make/Model: MITSUBISHI LANCER

Your Ref No: SJR4343X

Chassis No: JMYSRCY2A9U004317

Claim Type: Third Party

Engine No: 4A910125980

Accident Date: 07/02/2020

Reg. Date : 30/09/2009

Estimate Repair Cost to Vehicle No : SJR4343X

PAGE:4/5

S/N	Description	Quantity	Unit	Price	Amount
<u>NETT PRICE</u>				<u>S\$</u>	<u>S\$</u>
67	Rear Exhaust Silencer	1	PCS	468.00	468.00 ✓
68	Rear Exhaust Rubber	2	PCS	28.00	56.00 ✓
69	Rear Exhaust Top Head Cover Plate	1	PCS	210.00	210.00 ✓
70	Rear Smart Sensor	1	PCS	90.00	90.00 ✓
71	Rear Sound Buzzer	1	PCS	85.00	85.00 X
TOTAL				881.00	909.00
LESS 10%				792.90	818.10
<u>SPECIAL NET</u>					
72	Front Number Plate	1	PCS	40.00	40.00 /5
73	Rear Spare Tyre Panel Top Sound Proof	2	PCS	150.00	300.00 /50
74	Rear Bumper Lower Spoiler	1	PCS	650.00	650.00 480
75	Rear Bumper Sensor	1	PCS	300.00	300.00 200
76	Rear number Plate	1	PCS	40.00	40.00 ✓
77	Rear Exhaust Chrome Pipe	1	PCS	150.00	150.00 X
TOTAL				1330.00	1480.00

13108
11797.2

FOCUS AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50
AUTOBAY @ KAKI BUKIT SINGAPORE 417883
TEL: 6886 9097 FAX: 6844 4625 Email: claims@focusauto.com.sg
GST:200712509E RCB NO:201004495R

M/S : LONPAC INSURANCE

Estimate No: M001010

Date: 11-Feb-20

Veh Reg No: SJR4343X

Make/Model: MITSUBISHI LANCER

Chassis No: JMYSRCY2A9U004317

Engine No: 4A910125980

Reg. Date : 30/09/2009

ATTN: Motor Claim Department

Your Ref No: SJR4343X

Claim Type: Third Party

Accident Date: 07/02/2020

Estimate Repair Cost to Vehicle No : SJR4343X

PAGE:5/5

S/N	Description	Quantity	Unit	Price	Amount
	<u>LABOUR</u>			<u>S\$</u>	<u>S\$</u>
78	Towing			100.00	50
79	Panel Beating			2400.00	1800
80	Check Wiring			100.00	30
81	Rust Proofing			100.00	✓
82	To Remove & Replace Air Con Condenser and Charger Gas			160.00	100
83	To Remove & Replace Bumper Sensor			80.00	50
84	To Remove & Replace Exhaust Silencer			120.00	60
85	To Spray Paint			1600.00	✓
TOTAL				4660.00	
OVERALL TOTAL					22,069.55

SINGAPORE DOLLAR FIFTEEN THOUSAND SIX HUNDRED TWELVE DOLLARS
AND FOURTY ONE CENTS ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR FOCUS AUTO PTE LTD

16472.2
13177.

AUTHORISE SIGNATURE