

ASS. REC. BY:

REF: CSICT 20002466/Ksf3

Special Instruction:

Surveyor: Ben Tang

ASSIGNMENT (Office)

From (Person): Ben Tang of CTL Date/Time: 12.2.2000 3:43p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKR 1353A Insured: SLG 8146 Gat Workshop m/s Yee Auto Tel: 64575768of Bik 160 on Ming Ave #02-17Policy No: _____ Claim No: SUM 2017 200757 / SLG 8146 G / BEN

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 2.10.2020

(Client's Record)

CA / REV / REP. / REV 24 HRS api' H.O.D. Endorsement: _____Date/Time: 12.2.2000 4:01p.m Person Contacted: ms Phang Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>SLR 1353A - X</u>
	<u>SLG 8146G - X</u>
<u>25/2</u>	<u>L1 Pr 832506 Confirmed</u>
	<u>(\$ 7,421.50 Red - 70%)</u>

ASS. REC. BY: Kenneth

REF:

41

ASSIGNMENT

From:

Date:

13/07/20

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKR 1353A

at Workshop m/s

Yee Auto

of

Blk 160 Sin Ming Drive # 02-17

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1wp

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SKR 1353A

Yr Regn:

01 / 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mer

B180

C.C

1595

Colour

M. Gray

A/C:

Insured / Std / NI / NA

Sp. Reading

60870

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD 24624 22J289599

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

225 / 40 R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

7 mm

R/Bal.

7 mm

L/Bal.

7 mm

L/Bal.

7 mm

D.O.A.

10/2/20

D.O.I.

13/2/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 25 FEB 2020

Date/Time, File Pass to?

25/02/20

1)

Type

Date/Time, File Return to?

2)



Preli. Report



Final Report

Days Of Repair:

3

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$)



Interview (\$)



Tech. Invs (\$)



Week end (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

220

Report Format:

Lump Sum / L.B.E. (\$)

\$ 3,250/- 45

Nivitha (LKK Auto)

From: Ben Tang <Ben.Tang@sg.cntaiping.com>
Sent: Wednesday, 12 February 2020 3:43 PM
To: 'assignments'
Subject: FW: OUR REF : SNM20D200759/SLG8146G/BEN - Your Vehicle: SLG 8146 G; Our Ref: YeeAuto-SKR 1353 A; Accident Involving SKR 1353 A & SLG 8146 G on 10 February 2020

Dear Sirs

We refer to above matter.

Please assist to arrange for PRS survey of TP vehicle SKR1353A.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: bonnie kwok <litigation@bonniekwok.com>
Sent: Wednesday, February 12, 2020 2:19 PM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; yeeauto pteltd <yeeautopteltd@gmail.com>
Subject: Re: OUR REF : SNM20D200759/SLG8146G/BEN - Your Vehicle: SLG 8146 G; Our Ref: YeeAuto-SKR 1353 A; Accident Involving SKR 1353 A & SLG 8146 G on 10 February 2020

Dear Sirs,

Our client agrees to LKK Auto Consultants Pte Ltd as the Single Joint Expert (SJE).

Please let us have their report in due course.

Kindly request for the SJE to contact the repairers, M/s Yee Auto Pte Ltd at 6457 5768 to make the necessary arrangements.

Regards,
ST

veh in
7: 12/02/2020 4.01 PM
C: ang phang
E: ✓

BONNIE KWOK LLC

Advocates & Solicitors
101A Upper Cross Street
#08-12 People's Park Centre
Singapore 058358
TEL: 6536 6026
FAX: 6536 2279
email : litigation@bonniekwok.com
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 8.45 a.m. to 5.45 p.m. and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Wed, 12 Feb 2020 at 11:44, Ben Tang <Ben.Tang@sg.cntaiping.com> wrote:

WITHOUT PREJUDICE

Dear Sir,

We refer to your email dated 11 February 2020.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

LKK / LBS / STA

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

Thank you.

Best Regards

Ben Tang

Executive

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #XX-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI

Sent: Wednesday, February 12, 2020 11:36 AM

To: Ben Tang <Ben.Tang@sg.cntaiping.com>; 'bonnie kwok' <litigation@bonniekwok.com>

Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: OUR REF : SNM20D200759/SLG8146G/BEN - Your Vehicle: SLG 8146 G; Our Ref: YeeAuto-SKR 1353 A; Accident Involving SKR 1353 A & SLG 8146 G on 10 February 2020

Dear Ben,

Please conduct PRS for SKR1353A.

Note : officer in charge – Ben Tang 63896175

*** *Kindly quote our reference number when replying.*

Thank You.

Regards,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

TEL: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: bonnie kwok <litigation@bonniekwok.com>

Sent: Tuesday, February 11, 2020 5:02 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Subject: Urgent: Pre-Repair Inspection: Your Vehicle: SLG 8146 G; Our Ref: YeeAuto-SKR 1353 A; Accident Involving SKR 1353 A & SLG 8146 G on 10 February 2020

Urgent

Dear Sirs,

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle no. SKR 1353 A at M/s Yee Auto Pte Ltd, Block 160 Sin Ming Drive #02-17 Sin Ming Autocity Singapore 575722.

Regards,

ST

--

BONNIE KWOK LLC

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : litigation@bonniekwok.com

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 8.45 a.m. to 5.45 p.m. and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
 Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
 Email: yeeautopte ltd@gmail.com
 Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd
 3 Anson Road
 #16-00 Springleaf Tower
 Singapore 079909

ATTN: Motor Claim Department

Your Ref No: -
 Claim Type: Third Party
 Accident Date: 10/02/2020
 TP Veh Reg No: SLG8146G

Estimate No: ES2000012
 Date: 12 Feb 2020
 Policy No:
 Veh Reg No: SKR1353A
 Make/Model: MERCEDES BEN B180 (R16 BI)
 Chassis No: WDD246242J289599
 Engine No: 27091030510960
 Reg. Date: 20/01/2015

Estimate Repair Cost to Vehicle No :SKR1353A

Description	U/Price	Quantity	List Price SS	Amount SS
Net Price				
1 REVERSE SENSOR CENTRE - LH	368.00	1 PC	368.00	X
2 REVERSE SENSOR CENTRE - RH	368.00	1 PC	368.00	265.00
			736.00	736.00
Spare Parts				
3 REAR BUMPER	1,780.00	1 PC	1,780.00	✓
4 REAR BUMPER SIDE RETAINER - LH	98.00	1 PC	98.00	X
5 REAR BUMPER SIDE RETAINER - RH	98.00	1 PC	98.00	X
6 REAR BUMPER CLIPS	40.00	1 SET	40.00	✓
7 REAR BUMPER INNER GARNISH	268.00	1 PC	268.00	✓
8 REAR BUMPER LOWER BRACKET - LH	48.50	1 PC	48.50	X
9 REAR BUMPER LOWER BRACKET - RH	48.50	1 PC	48.50	✓
10 REAR BUMPER LOWER GARNISH	475.00	1 PC	475.00	✓
11 REAR BUMPER REINFORCEMENT	804.00	1 PC	804.00	✓
12 REAR BUMPER SIDE MOULDING - LH	195.00	1 PC	195.00	✓
13 REAR BUMPER SIDE MOULDING - RH	195.00	1 PC	195.00	✓
14 TAIL LAMP LH	770.00	1 PC	770.00	X
15 TAIL LAMP RH	770.00	1 PC	770.00	X
16 REAR END PANEL	860.50	1 PC	860.50	X
17 REAR BUMPER CHROME STEP PROTECTOR	355.00	1 PC	355.00	✓
			6,805.50	6,805.50
Labour				
18 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,500.00	1 JOB	1,500.00	500
19 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,500.00	1 JOB	1,500.00	400
20 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	80.00	1 JOB	80.00	X
21 TO CHECK WIRING FUNCTIONS.	50.00	1 JOB	50.00	15
			3,130.00	3,130.00

YEE Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company.

Acknowledged by Repairer
 Signature:
 Date:



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopte ltd@gmail.com
Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 10/02/2020
TP Veh Reg No: SLG8146G

Estimate No: ES2000012
Date: 12 Feb 2020
Policy No:
Veh Reg No: SKR1353A
Make/Model: MERCEDES BEN B180
(R16 BI)
Chassis No: WDD2462422J289599
Engine No: 27091030510960
Reg. Date: 20/01/2015

Estimate Repair Cost to Vehicle No :SKR1353A

Description	U/Price	Quantity	List Price	Amount
			SS	SS
			Total	S\$ 10,671.50
			Add GST @ 7%	747.01
			Total Amount Payable	S\$ 11,418.51

TOTAL: SINGAPORE DOLLAR ELEVEN THOUSAND FOUR HUNDRED EIGHTEEN AND CENTS FIFTY ONE ONLY

For Yee Auto Pte Ltd


AUTHORISED SIGNATURE

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20002466/KSF3N2
Date: 26/02/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00005222003
Claimant Vehicle No: SKR1353A Insured Vehicle No: SLG8146G
Date of Loss: 10/02/2020 Nature of Claim: TP Claim No: SNM20D200759

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKR1353A
Make & Model: MERCEDES-BENZ B180, 1.6 (R16 BI) (A) Engine No: 27091030510960
Reg. Date: 20/01/2015 (Man. Year: 2014) Chassis No: WDD2462422J289599
Colour: Metallic Grey Odometer: 60670 km
Engine Capacity: 1595 cc
Market Value/New Car Price: N/A
Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40R18 Rear Tyre Size: 225/40R18
Front Left Side: Continental 7 mm Rear Left Side: Continental 7 mm
Front Right Side: Continental 7 mm Rear Right Side: Continental 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,541.50	3,221.95	4,319.55	57.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,130.00	915.00	2,215.00	70.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	10,671.50	4,136.95	6,534.55	61.23
Approved Total (Overridden) (\$\$)		3,250.00		
(\$\$)	10,671.50	3,250.00	7,421.50	69.55
+ GST 7.00/7.00% (\$\$)	747.01	227.50	519.51	69.55
Nett Amount (\$\$)	11,418.51	3,477.50	7,941.01	69.55

INSPECTION

Date of Assignment: 25/02/2020
Date Inspected: 13/02/2020 Inspected At: Yee Auto Service (HQ)
Estimated Period of Repair: 3.0 days 160 Sin Ming Drive #02-17 Sin Ming Autocity
Singapore 575722

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Feb 2020)
Parts:	144	MERCEDES-BENZ B180 1.6 (R16 BI) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKR1353A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	1,780.00 F	*1,520.00 FL
2	1		*REAR BUMPER SIDE RETAINER-LH	Serviceable	98.00 F	*- FL
3	1		*REAR BUMPER SIDE RETAINER-RH	Serviceable	98.00 F	*- FL
4	1		*SET REAR BUMPER CLIPS	Necessary	40.00 F	*40.00 FL
5	1		*REAR BUMPER INNER GARNISH	Cracked	268.00 F	*268.00 FL
6	1		*REAR BUMPER LOWER BRACKET-LH	Serviceable	48.50 F	*- FL
7	1		*REAR BUMPER LOWER BRACKET-RH	Distorted	48.50 F	*48.50 FL
8	1		*REAR BUMPER LOWER GARNISH	Buckled	475.00 F	*381.00 FL
9	1		*REAR BUMPER REINFORCEMENT	Bent	804.00 F	*525.00 FL
10	1		*REAR BUMPER SIDE MOULDING-LH	Necessary	195.00 F	*129.00 FL
11	1		*REAR BUMPER SIDE MOULDING-RH	Necessary	195.00 F	*129.00 FL
12	1		*TAIL LAMP LH	Serviceable	770.00 F	*- FL
13	1		*TAIL LAMP RH	Serviceable	770.00 F	*- FL
14	1		*REAR END PANEL	Repair	860.50 F	*- FL
15	1		*REAR BUMPER CHROME STEP PROTECTOR	Necessary	355.00 F	*245.00 FL
16	1		*REVERSE SENSOR CENTRE-LH	Serviceable	368.00 FS	*- FS
17	1		*REVERSE SENSOR CENTRE-RH	Shorted	368.00 FS	*265.00 FS
					Sub Total (\$\$)	7,541.50 3,550.50
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 328.55
					Total Parts (\$\$)	7,541.50 3,221.95

F=Franchise part, S=SpcNett, L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE & REPLACE DAMAGED PARTS,PANEL BEAT WHERE NECESSARY	New	1,500.00	500.00
2	TO PUTTY,APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION	New	1,500.00	400.00
3	TO APPLY RUST-PROOFING ON REPAIRED,REPLACED PANEL	New	80.00	0.00
4	TO CHECK WIRING FUNCTIONS	New	50.00	15.00
Gross Labour Cost (\$\$)			3,130.00	915.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >