

CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
TEH ENG KENG BLK 422 FAJAR RD #08-499 SINGAPORE 670422 Contact No 83220932MsTeh	Cust No/Name	KCV14189/TEH ENG KENG
	Reg No/Reg Date	SKX73186 / 28/12/201
	Date In/Mileage	/ 0
	Chassis No	MMBSTA13AFH018828
	Engine No	3A92UCT8057
	Make/Model	MIT/ATTRAGE 1.2 CVT MIVEC
	Colour/Trim	U01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KCV14189	CRDVCH	10/02/2020/ 15:38	QUD	247 / DonBong	50896			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2200.00
RENEW ACCIDENT, DAMAGED PARTS ON REAR BUMPER FACE, REPAIR REAR END PANEL, REPAIR LH REAR FENDER								825 / 2200.00
E PNT88000								100.00
REMOVE AND INSTALL PARKING ASSIST								180 / 250.00
E PNT88000								
REMOVE AND INSTALL REAR BOOT CABIN , SIDE TRIM TO FACILITATE REPAIR WORK								840 / 1680.00
E PNT98000								
PAINT WORK SPRAY REAR END PANEL, REAR BUMPER, LH REAR FENDER AND AFFECTED PORTION								80.00
M SUNDRY								30 / 50.00
PERFORM RUST PREVENTION								220.00
A 54900099								200.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								50.00
M SUNDRY								
SUPPLY PARKING SENSOR								
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								
M SUNDRY								
SUNDRIES								
M DUCT,RR VENTILATOR					1.00	30.00	00.00	30.00
M COVER,RR VENTILATOR					1.00	40.00	00.00	40.00
M CLIP,GEARSHIFT CONTROL LIN					4.00	3.00	00.00	12.00
M BRACKET,RR BUMPER,LH					1.00	28.00	00.00	28.00
M BRACKET,RR BUMPER,RH					1.00	28.00	00.00	28.00
M CLIP,RR BUMPER					6.00	4.00	00.00	24.00
M FACE,RR BUMPER					1.00	748.00	00.00	748.00

Estimate

?

X

MM

?

X

MM

?

X

MM

BR

BR

BR

Steve CLKK

WIL MAIL

SURVEYOR NAME :

SURVEYOR SIGNATURE :

SURVEYOR NAME: Steve CLKK

SURVEYOR SIGNATURE: [Signature]

Confirm & accepted by

DATE: 19/2/20, 2.00pm

REMARKS:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Authorized signatory and company stamp

Third party survey is on a "Without Prejudice" basis

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Date:

Page 1 of 1



Exceptional Journeys

Surveyor : STEVE LKK
Claim : TP MS FIRST CAP
DOA : 09.02.2020
Emailed : 28.02.2020, 7.15pm
Date survey : 19.02.2020

VEHICLE NO : SKX 7318 G
MODEL : MIT ATTRAGE 1.2
WIP : 50896

Material	:	\$	828.00
Labour	:	\$	2,195.00
Sub-Total	:	\$	3,023.00
	:		-
Less Excess	:	\$	-
Total	:	\$	3,023.00
GST 7%	:	\$	211.61
Grand Total	:	\$	3,234.61
Finalise By/Date	:	LOI / 28/02/2020	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☒ REPAIR TOOK 4 WORKING DAYS + 2 Days (1) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 6


☒ TP claim SHC 3240 T

☐ Claim GIA / LTA fee

☒ Claim Loss of ☐ Use / ☒ Rental

☒ Claim Medical Fee / Others claim luggage

☐ Third Party Report -



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
MS FIRST CAPITAL INSURANCE LIMITED MOTOR CLAIMS DEPARTMENT 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877 Contact No 19/02/2020	Cust No/Name	KCV14189/TEH ENG KENG
	Reg No/Reg Date	SKX7318G / 28/12/2015
	Date In/Mileage	19/02/2020/ 95878
	Chassis/Package	MMBSTA13AFH01882E /DC17RP
	Engine No	3A92UCT8057
	Make/Model	MIT/ATTRAGE 1.2 CVT MIVEC
	Colour/Trim	U01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CTP00040	Cash	28/02/2020/ 15:57	TLD	260 / AiTing	50896			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E	PNT88000	REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, REPAIR REAR END PANEL, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME						✓ 825.00
E	PNT88000	REMOVE AND INSTALL PARKING ASSIST TO FACILITATE REPAIR						✓ 100.00
E	PNT88000	REMOVE AND INSTALL REAR BOOT CABIN , SIDE TRIMS TO FACILITATE REPAIR						✓ 180.00
E	PNT98000	RESPRAY ON REAR END PANEL, REAR BUMPER, AND ALL OTHER AFFECTED AREAS TO THE SAME						✓ 840.00
A	54900099	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM						✓ 30.00
A	10028901	CONDUCT DIAGNOSTIC CHECK USING MUT TESTER AND CLEAR TROUBLE CODE						✓ 200.00
M	SUNDRY	SUNDRIES						✓ 20.00
X	BRACKET,RR BUMPER,LH				1.00	✓ 28.00	00.00	28.00
X	BRACKET,RR BUMPER,RH				1.00	✓ 28.00	00.00	28.00
X	CLIP,RR BUMPER				6.00	✓ 4.00	00.00	24.00
X	FACE,RR BUMPER				1.00	✓ 748.00	00.00	748.00
Z	TEXT	TP CLAIM FIRST CAPITAL SHC3240T DOA : 09.02.2020 SURVEYOR STEVE (LKK) 19.02.2020 REPAIR 04 DAYS						
Guarantee Your Warranty, Maintain with Cycle & Carriage!								

Parts	828.00	Nett	3,023.00
Labour	2,175.00	7% GST on	3023.00
Standard Menu	0.00		211.61
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	3,234.61
Sundry/Others	20.00		
Total(w/o GST)	3,023.00		

This is not an official tax invoice.
This is a computer generated document, no signature is required.