



TeamWork Garage Pte Ltd
 53 Ubi Avenue 1 #01-23/24 Spore 408934
 Paya Ubi Industrial Park
 Tel : 6844 2475
 E-mail : claims@teamworkgarage.com
 ROC number : 201015366H
REPAIR PERFORMA INVOICE

AIG Singapore

78 Shenton Way

Singapore 0799120

- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
 Third party survey is on a "Without Prejudice" basis
 Legal confirmation(s) is allowed
 Supplier item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vehicle number SLT7916P
 Make / Model TOYOTA/FORTUNER 2.7
 Chassis number MROZX69G100102415
 Accident date 07 February 2020
 Reference 2002-22

Qty Particulars

Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS

- | Qty | Particulars | Unit Price - SGD \$ |
|-----|-------------------------------|---------------------|
| 1 | REAR RH BUMPER OUTER GARNISH | 309 409.74 cut✓ |
| 1 | REAR RH FENDER OUTER GARNISH | 358 458.28 cut✓ |
| 1 | REAR RH DOOR OUTER GARNISH | 353 453.24 cut✓ |
| 1 | REAR RH DOOR PANEL | 757.62 bt✓ |
| 1 | REAR RH DOOR TAPE | 145.32 neu✓ |
| 1 | FRONT RH DOOR PANEL | 758.70 bt✓ |
| 1 | FRONT RH DOOR TAPE | 145.32 neu✓ |
| 1 | RH SIDE BOARD | 449.34 cut✓ |
| 1 | REAR AXLE BEAM | 2054.76 x NN |
| 1 | REAR RH WHEEL BEARING AND HUB | 698.28 x NN |
| 1 | REAR RH SHOCK ABSORBER | 277.62 x NN |

Less 25 %

Subtotal

Balance C/F

PARTS REPLACEMENT - SPECIAL NETT ITEMS

- | | | |
|---|----------------|----------------------|
| 1 | BOT BRAKE FULD | 50.00 xnn |
| 1 | RIM | 800.00 450 cut✓ 450. |

Subtotal

Balance C/F

LABOUR AND MISCELLANEOUS CHARGES

Balance B/F

- | | | |
|---|---|--------------|
| 1 | CHECK WIRING AND LIGHTNING SYSTEM | 60.00 30 |
| 2 | COMPUTERISED AND CHECK REAR WHEEL ALIGNMENT | 150.00 80 |
| 3 | REMOVE AND REPLACE FRONT UNDERCARRIAGE PARTS | 200.00 100 |
| 4 | TRANSFER PARTS, ATTACHMENT FROM FRONT OLD DOOR TO | 200.00 x nn. |
| 5 | TRANSFER PARTS, ATTACHMENT FROM REAR OLD DOOR TO | 200.00 120 |
| 6 | PANEL BEATING ON AFFECTED AREAS | 800.00 500 |
| 7 | SPRAY PAINTING ON AFFECTED AREAS | 800.00 500 |
| 8 | APPLY ANTI RUST ON AFFECTED AREAS | 150.00 40. |

Subtotal

Grand total

Taufik 97495749 - wp' 11/2/20

04 days Lumpsum.

Resurvey after repair.

taufik@lkkauto.com.

3276.30
2457.22.

450.

1370.

4277.22

1153400

04 days.

#