

Vision Autowork Pte.Ltd.

(ROC / GST Reg. No. 201500371E)
8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875
Tel : 6341 6789 Fax: 6341 6778
E-mail:visionautowork@gmail.com

DATE : 17.02.20

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMH3830E**
MODEL : **TOYOTA VOXY**
DATE OF ACCIDENT : 07.02.20
TIME OF ACCIDENT : 09:00HRS

Aches ZWR80035020

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>reld</i>	1	\$ 1,404.70	\$ 1,404.70
2	FRONT BUMPER FOG LAMP COVER C/W CHROME LH <i>new</i>	1	\$ 220.40	\$ 220.40
3	FRONT BUMPER LOWER GRILLE <i>new</i>	1	\$ 279.40	\$ 279.40
4	FRONT BUMPER SIDE RETAINER <i>LH new</i>	2	\$ 102.50	\$ 205.00
5	FRONT BUMPER SPONGE <i>reld</i>	1	\$ 179.70	\$ 179.70
6	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 438.60	\$ 438.60
7	FRONT BUMPER UNDER COVER GARNISH <i>new</i>	1	\$ 396.10	\$ 396.10
8	FRONT UPPER GRILLE <i>new</i>	1	\$ 787.90	\$ 787.90
9	HEADLAMP LH (HID) <i>reld</i>	1	\$ 3,382.40	\$ 3,382.40
10	FRONT SUPPORT PANEL <i>Reis</i>	1	\$ 1,650.50	\$ 1,650.50
11	AIR CON CONDENSER SIDE GARNISH <i>new</i>	2	\$ 60.10	\$ 120.20
12	FRONT FENDER LH <i>Derfed</i>	1	\$ 978.60	\$ 978.60
13	FRONT FENDER EMBLEM 'HYBRIC' LH <i>new</i>	1	\$ 98.10	\$ 98.10
14	FRONT FENDER INNER COWLING <i>new</i>	2	\$ 291.20	\$ 582.40
15	FVFRONT FENDER SUPPORT PANEL LH <i>new</i>	1	\$ 67.30	\$ 67.30
16	FRONT WHEEL RIM LH <i>lit</i>	1	\$ 1,465.20	\$ 1,465.20
17	FRONT ABS SENSOR LH <i>new</i>	1	\$ 498.30	\$ 498.30
18	FRONT DRIVESHAFT <i>2m</i>	1	\$ 1,521.10	\$ 1,521.10
19	FRONT CROSSMEMBER <i>new</i>	1	\$ 2,351.40	\$ 2,351.40
20	FRONT STEERING RACK AND PINION <i>new</i>	1	\$ 1,667.30	\$ 1,667.30
21	FRONT KNUCKLE ARM BEARING LH <i>new</i>	1	\$ 197.40	\$ 197.40
22	FRONT STABILIZER BAR LINKAGE LH <i>new</i>	1	\$ 173.70	\$ 173.70
23	FRONT SHOCK ABSORBER LH <i>new</i>	1	\$ 721.60	\$ 721.60
24	FRONT KNUCKLE ARM LH <i>new</i>	1	\$ 565.70	\$ 565.70
25	FRONT LOWER ARM LH <i>Best</i>	1	\$ 997.60	\$ 997.60

8500.30

TOTAL PRICE \$ 20,950.60
LESS 25% \$ 5,237.65
SUB TOTAL PRICE \$ 15,712.95

6375.22

S.N: 550

579.80

TO : AIG MOTOR CLAIMS DEPTS
 VEHICLE NO : SMH3830E
 MODEL : TOYOTA VOXY
 DATE OF ACCIDENT : 07.02.20
 TIME OF ACCIDENT : 09:00HRS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
3	FRONT BUMPER UNDER COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
4	FRONT UPPER GRILLE CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
5	FRONT SUPPORT PANEL SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
6	FRONT SUPPORT PANEL COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00
7	AIR CON CONDENSER SIDE GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
8	FRONT FENDER COWLING CLIPS (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
9	FRONT WHEEL TYRE LH <i>new</i>	1	\$ 650.00	\$ 650.00
10	BRAKE OIL <i>new</i>	1	\$ 30.00	\$ 30.00
11	RADIATOR COOLANT <i>new</i>	1	\$ 60.00	\$ 60.00

30

TOTAL \$ 1,230.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,600.00	1600 800
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	1600 800
3	TUFF COAT	\$ 250.00	250 30
4	WIRING CHECK	\$ 80.00	80 30
5	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 120.00	X
6	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 80.00	X
7	REFOCUS HEADLAMP BEAM	\$ 60.00	X
8	REMOVE AND REFIX STEERING RACK PINION	\$ 350.00	X
9	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	650 350
10	FOUR WHEEL ALIGNMENT	\$ 120.00	120 80
11	RESET ABS LIGHT	\$ 350.00	X
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 5,440.00

1890

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMH3830E**
MODEL : **TOYOTA VOXY**
DATE OF ACCIDENT : 07.02.20
TIME OF ACCIDENT : 09:00HRS

TOTAL PARTS COST : \$ 16,942.95
TOTAL LABOUR COST : \$ 5,440.00
TOTAL REPAIR COST : \$ 22,382.95

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY

SERVICE ADVISOR
ABBY
HP : 9856 4815

Adrian L
L/S 17/02/20.

OS Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 884522

L/S: 7K