

Surveyor:

STEVE

DOI: 12/02/2020

Date / Time: 11/02/2020

Registered in Merimen: 12/02/2020

Pre-assign / CCU / FTE:



Insured Vehicle No. : SKJ 5006T

Claim No. : 5480072292SG

X

Name of Insured : RYUJI NAGANO

Policy No. : 2100336441

Insured Tel No. : HP:

Make / Model : VOLVO V40-1.6 V40 CROSS COUNTRY T4 (A)

Excess Sec II : \$

D.O.A : 22/01/2020 09:40

Place of Accident : ALONG NICOLL HIGHWAY

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability : % Final ? Yes / No

FBK 2648L

INSRS:
WSP: SOUTHERN
Tel: MOTOR
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time	STAGE	DATE / PIC
	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA :	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	
PRELIMINARY ADVICE Date/Time:	Sent By:	
FINALIZATION Date/Time:	Confirm with:	Confirm by:
Repair Cost: \$	(days) Reduction: %	Email ☐ Call ☐
FINAL SETTLEMENT Date/Time: 10/3/2020	Confirm with: Mr Lim	Email ☒ Call ☐
Final Liability: % 100	(Agreed / Assessed) BOLA S/N No.: 15	If NO or B 28, Ass. Lia:
Repair Cost: (w/ LTA) \$ 1926.00		of charge for
Loss of Rental (LOR): \$ -	(days)	
Loss of Use (LOU): \$ 40.00	(\$ 20 x 2 days)	
Loss of Income (LOI): \$ -	(\$ x days)	
LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐	(Tick only one)	
GIA/LTA Search: \$ -		
Medical: \$ -		
Disbursement: \$ -	(e.g. Tow/ Independent)	
Legal Cost: \$ -		
Total: \$ 1966.00	Global Sum \$:	
FINAL PAYMENT Date/Time:	Confirm with:	Email ☐ Call ☐
Payee 1: \$ 1966.00	Name 1: Southern Motor	
Payee 2: (Strike if N.A.) \$	Name 2:	
Payee 3: (Strike if N.A.) \$	Name 3:	

ASSIGNMENT

From:

Date:

12.2.2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

FBK 2648L

at Workshop m/s

Southern motor

of

Blk 1006 Bukit Merah Lane 2 #01-10

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res:

Yes or No

Lum Sum:

20

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

imp'

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FBK 2648L

Yr Regn:

5/6/15

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda CB400

c.c

399

Colour:

Black

A/C:

Insured / Std / NI / NA

Sp Reading:

79528

T/Radio:

Insured / Std / NI / NA

Eng No:

C/No:

NIC421603395

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

120/62R17

R:

160/60R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

5

mm

R/Bal:

5

mm

L/Bal:

mm

L/Bal:

mm

D.O.A:

22/1/20

D.O.I:

12/2/20

Survey held at

Southern Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

MV-13K

L/S - \$1800 (Red \$1407.50 / 447.)

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS: \$

Photo:

Other:

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Insp (\$



: Wheel end (\$

Report Format:

Lump Sum / LBJ: (\$



南方摩哆

Business Reg. No: 234147/00L
Block 1006, Bukit Merah Lane 2, #01-10, Singapore 159762
Tel: 6273-0369 (3 Lines) Fax: 6274-6614

07th February 2020
AIG Asia Pacific Insurance Pte Ltd
78 Shanton Way #07-16
AIG Building
Singapore (079120)

Dear Sirs,

RE: Cost of repair to Honda CB400 - FBK2648L

1pc of Exhaust Pipe	✓ DD	S\$	1,150.00 ✓
1pc of Engine Guard	✓ BT		225.00 ✓
1pc of Rear GIVI Box	✓ MT		680.00 ✓
1pc of Rear Absorber	✗ NN		950.00 ✓
1pc of Handle Balancer	✓ MT		35.00 ✓
1pc of Handle Bar	✓ BT		120.00 ✓
1pc of Mirror (RH)	✓ MT		115.00 ✓
			3,275.00
Less 10%			327.50
Nett			2,947.50
Alignment Rear Rim			80.00 ✗
Labor			180.00 150 ✓
			<u>S\$3,207.50</u>

2325
-10%
2092.50 ✓

2942.50

L/S - 1794
= 1800

Yours Faithfully,
Southern Motor

Steve (LKK) wil A/L
8322 8813 12/2/20, 11:30am
2 days
L/S
Ry AL SJ

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



南方摩哆

Business Reg. No: 234147/00L
Block 1006, Bukit Merah Lane 2, #01-10, Singapore 159762
Tel: 6273-0369 (3 Lines) Fax: 6274-6614

07th February 2020

AIG Asia Pacific Insurance Pte Ltd

78 Shanton Way #07-16

AIG Building

Singapore (079120)

Dear Sirs,

RE: Cost of repair to Honda CB400 – FBK2648L

1pc of Exhaust Pipe / <i>OD</i>	S\$	1,150.00
1pc of Engine Guard / <i>BT</i>		225.00
1pc of Rear GIVI Box / <i>CM</i>		680.00
1pc of Rear Absorber <i>X</i>		950.00
1pc of Handle Balancer / <i>CM</i>		35.00
1pc of Handle Bar / <i>BT</i>		120.00
1pc of Mirror (RH) / <i>CM</i>		115.00
		3,275.00
Less 10%		327.50
Nett		2,947.50
Alignment Rear Rim		80.00 <i>X</i>
Labor		180.00 <i>150</i>
		<u>\$3,207.50</u>

Yours Faithfully,
Southern Motor

Steve (LKK) wil Myo L
8322 8813 12/2/20, 11:30am
2 days
L/S
Ry AL Syj

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____



Figure 1

[illegible]

1000

— **SEE SUBJECT**

© 2005 Blackwell Publishing Ltd

Abstract:

© 2004 Blackwell Publishing Ltd
Journal of Internal Medicine 255: 101–108

2000

2000

100

1999

0986

TABLE 5

1999a,b).


References

1999

10000

1

1

[illegible][illegible]

Keywords: child sexual abuse; disclosure; social support

Want to have a healthy free promotion? Our Minimum Auction (<https://www.gigamonster.com/gig/auction/>) has one of the smartest ways to sell off your bids immediately. We have our network of entrepreneurs able to buy off your bids, just as the highest price offered, except we let go how you selling the products.

Our images are available for use on digital devices. To learn more, visit www.gettyimages.com. All images are provided for personal use only. For more information, please contact your local office. © 2014 Getty Images. All rights reserved.

[illegible]

Need to visit a marketplace? This business opportunity isn't specific to the amount of language you use. It is a commercial base for through-out for of the marketplace available for

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	058D
Vehicle Details	
Vehicle No.:	FBK2648L
Vehicle to be Exported:	No
Intended Deregistration Date:	12 Feb 2020
Vehicle Make:	HONDA
Vehicle Model:	CB400SF MANUAL
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	NC42E1203294
Chassis No.:	NC421603295
Maximum Power Output:	-
Open Market Value:	\$7,067.00
Original Registration Date:	05 Jun 2015
First Registration Date:	05 Jun 2015
Transfer Count:	0
Actual ARF Paid:	\$1,061.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	04 Jun 2025
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$6,501.00
COE Rebate Amount:	\$3,453.00
Total Rebate Amount:	\$3,453.00

The information contained herein is correct as at 12 Feb 2020

OK

• PRE-REPAIR INSPECTION REQUEST – FBK2648L vs SKJ5006T (OI) on D.O.A.: 22/01/2020

From: Subramaniam, Divyashni
To: assignments@lkkauto.com, 'Admin A'
Cc: Lim, Kok-Chong, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Hor, Yinrul, Subramaniam, Divyashni, Teo, Ericweihong, soumotor@hotmail.com
Sent: 2/11/2020 9:53:30 AM
Attachments:  20200207130656.pdf

Hi,

Please refer to the enclosed request from **Southern Motor**.

Claim no : 5480072292SG003
Case Owner : Chan Kian Meng

If you have any queries/concerns, please let us know.
*Kindly assist to assign **Mohammed Rasul** as Single Joint Expert as requested.*

Thanks & Regards,

Divyashni Subramaniam
AIG
FNOL Adjuster I
Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.

Tel: 8001206556 | Ext: 1012103
Divyashni.Subramaniam@aig.com | www.aig.sg

From: soumotor@hotmail.com <soumotor@hotmail.com>
Sent: Monday, February 10, 2020 4:07 PM
To: Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKJ5006T AND FBK2648L ON 22/01/2020

Dear Divyashni Subramaniam,

We choose Mohammed Rasul from LKK Auto Consultants Pte Ltd

as the surveyor. Thank you.

From Southern Motor

From: Subramaniam, Divyashni
Sent: Mon, 10 Feb 2020 06:17:45 +0000
To: Southern Motor
Cc: Lim, Kok-Chong, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Hor, Yinrul, Subramaniam, Divyashni, Teo, Ericweihong
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKJ5006T AND FBK2648L ON 22/01/2020

Without Prejudice

Your Reference : FBK2648L
Our Reference : 5480072292SG003

Dear Sir/Madam,

resul / de3

P. Lim
T. 11.34am 11/2/2020
V. Out
E. ✓

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Divyashni Subramaniam
AIG
FNOL Adjuster I
Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.

Tel: 8001206556 | Ext: 1012103
Divyashni.Subramaniam@aig.com | www.aig.sg

From: Southern Motor <soumotor@hotmail.com>
Sent: Friday, February 7, 2020 2:04 PM
To: ClaimsDocManagement <ClaimsDocManagement@aig.com>
Subject: [EXTERNAL] FBK2648L

This message is from an external sender; be cautious with links and attachments.

From: Divyashni.Subramaniam@aig.com
To: soumotor@hotmail.com
Cc: Kok-Chong.Lim@aig.com ,Lee-Ying.Chin@aig.com ,NoorMariesa.AbuKassim@aig.com ,Yinrul.Hor@aig.com ,Divyashni.Subramaniam@aig.com ,Ericweihong.Teo@aig.com
Subject: aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKJ5006T AND FBK2648L ON 22/01/2020
Date: Mon, 10 Feb 2020 06:17:45 +0000
Without Prejudice

Your Reference : FBK2648L
Our Reference : 5480072292SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Divyashni Subramaniam
AIG
FNOL Adjuster I
Auto Claims | AIG Asia Pacific Insurance Pte, Ltd.

Tel: 8001206556 | Ext: 1012103
Divyashni.Subramaniam@aig.com | www.aig.sg

From: Southern Motor <soumotor@hotmail.com>
Sent: Friday, February 7, 2020 2:04 PM
To: ClaimsDocManagement <ClaimsDocManagement@aig.com>
Subject: [EXTERNAL] FBK2648L

This message is from an external sender; be cautious with links and attachments.

View Received Message

This mail is associated with :

*FBK2648L (5480072292SG)

[SKJ5006T]

TP

CHAN YIAW CHEE

Jan 22 2020 9:00AM

[RYUJI NAGANO]

Southern Motor

Reply

Reply All

Mark as Unread

Print Message

Delete Message

Forward

From

AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 06/03/2020 16:06 PM.

To

LKK_HQ

Subject

Alert - Adj Mandate Approved (S\$1966.00) - FBK2648L - Claim Handler: Chan, Kian-Meng

Approved:1966.00.

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)
Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Jan 2020 Edit Reg		11 Feb 2020 00:00 Edit Adj Rpt	S\$1,800.00 Edit Estimates	S\$1,800.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	RYUJI NAGANO, ID: S27416163		
Main Claimant:	CHAN YIAW CHEE		
Vehicle Reg. No.:	FBK2648L	Date of Loss:	22/01/2020 09:00 - :59 [55 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 5480072292SG	Policy/Cover Note No.:	(Comprehensive)
Vehicle Reg. No. (Insured):	SKJ5006T	Policy No. (Claimant):	5071758734-04
		Excess:	
Repairer:	Southern Motor (HQ) BLK 1006 BUKIT MERAH LANE 2, #01-10, 159762 Bukit Merah - Tel: 62730369		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 21/02/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (06/03/2020): Alert - Adj Mandate Approved (S\$1966.00) - FBK2648L - Claim Handler: Chan, Kian-...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*FBK2648L (5480072292SG)
[SKJ5006T]
TP
CHAN YIAW CHEE
Jan 22 2020 9:00AM
[RYUJI NAGANO]
Southern Motor

Upload Documents			Upload Photos		Compose New Letter		Upload Video		Upload Audio		View		View in Browser	
Letters/Correspondences											1 per page		☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
1	(Draft)	Third Party Express Settlement – Payment Breakdown									1	Edit		
Photos/Images											3 per page		☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print	
1	12/02/20 19:25	General View									1	Load JPG	☒	
2	12/02/20 19:25	General View									1	Load JPG	☒	
3	12/02/20 19:25	Odometer Reading									1	Load JPG	☒	
4	12/02/20 19:25	Chassis Number									1	Load JPG	☒	
5	12/02/20 19:25	General View									1	Load JPG	☒	
6	12/02/20 19:25	General View									1	Load JPG	☒	
7	12/02/20 19:25	General View									1	Load JPG	☒	
8	12/02/20 19:25	General View									1	Load JPG	☒	
9	12/02/20 19:25	General View									1	Load JPG	☒	
10	12/02/20 19:25	General View									1	Load JPG	☒	
11	12/02/20 19:25	General View									1	Load JPG	☒	
12	12/02/20 19:25	General View									1	Load JPG	☒	
13	12/02/20 19:25	General View									1	Load JPG	☒	
14	12/02/20 19:25	General View									1	Load JPG	☒	
15	12/02/20 19:25	General View									1	Load JPG	☒	
16	12/02/20 19:25	General View									1	Load JPG	☒	
17	12/02/20 19:25	General View									1	Load JPG	☒	
18	12/02/20 19:25	General View									1	Load JPG	☒	
19	12/02/20 19:25	General View									1	Load JPG	☒	
20	12/02/20 19:25	General View									1	Load JPG	☒	
21	12/02/20 19:25	General View									1	Load JPG	☒	
22	12/02/20 19:25	General View									1	Load JPG	☒	
23	12/02/20 19:25	General View									1	Load JPG	☒	
24	12/02/20 19:25	General View									1	Load JPG	☒	
25	12/02/20 19:25	General View									1	Load JPG	☒	
26	12/02/20 19:25	General View									1	Load JPG	☒	
27	12/02/20 19:25	General View									1	Load JPG	☒	
28	12/02/20 19:25	General View									1	Load JPG	☒	
29	12/02/20 19:25	General View									1	Load JPG	☒	
30	12/02/20 19:25	General View									1	Load JPG	☒	
31	12/02/20 19:25	General View									1	Load JPG	☒	
32	12/02/20 19:25	General View									1	Load JPG	☒	
33	12/02/20 19:25	General View									1	Load JPG	☒	
34	12/02/20 19:25	General View									1	Load JPG	☒	
35	28/02/20 17:34	After Repair Photo									1	Load JPG	☒	
36	28/02/20 17:34	After Repair Photo									1	Load JPG	☒	
37	28/02/20 17:34	After Repair Photo									1	Load JPG	☒	
38	28/02/20 17:34	After Repair Photo									1	Load JPG	☒	
39	28/02/20 17:34	After Repair Photo									1	Load JPG	☒	
40	28/02/20 17:34	After Repair Photo									1	Load JPG	☒	

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
41	28/02/20 17:34	After Repair Photo		☒
			Load JPG	
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/02/20 18:24	ACKNOWLEDGEMENT EMAIL TO AIG DD 11.02.2020		Load PDF
2	12/02/20 18:24	EMAIL FROM AIG DD 11.02.2020		Load PDF
3	12/02/20 18:24	TP ESTIMATE + TP GIA REPORT		Load PDF
4	16/02/20 23:24	TP ESTIMATE - MARKED		Load PDF
5	05/03/20 16:56	LETTER TO OI		Load PDF
6	05/03/20 16:56	LOD		Load PDF
7	16/03/20 10:42	WORKSHOP INVOICE		Load PDF
8	16/03/20 10:42	AUTHORISATION TO ACT FORM		Load PDF
9	16/03/20 10:42	Release Voucher		Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	13/02/20 13:40	OI GIA REPORT		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)

Vehicle No:	SKJ5006T (Insd veh)	Model:	HONDA CB400SF 399CC
	FBK2648L (TP veh)		
Date of Accident:	22/01/2020		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	3,432.03
Final Repair Cost	:	\$	1,926.00
Loss of Use	:	\$	40.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	1,966.00

Is Third Party Workshop GIA Registered?	☐ YES	☒ NO	(Kindly indicate below)
A) For <u>Non GIA Registered Workshop</u> :	Agreed Liability ____100____(%)		
B) For <u>GIA Registered Workshop</u> :	BOLA Applicable: Yes/ No BOLA Scenario No: _____		
	BOLA Liability: _____(%) Assessed Liability (*): _____(%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Southern Motor	:	\$ 1,966.00
2)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

16 Mar
2020

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any)

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20002481/EDA3Q2

Date: 16/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant

Vehicle No : FBK2648L

Insured Vehicle No : SKJ5006T

Date of Loss: 22/01/2020

Nature of Claim: TP

Claim No: 5480072292SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: FBK2648L

Make & Model: HONDA CB400SF, 399cc

Engine No: NC42E1203294

Reg. Date: 05/06/2015 (Man. Year: 2015)

Chassis No: NC421603295

Colour: Black

Odometer: 79528 km

Engine Capacity: 399 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 120/60Z R17

Rear Tyre Size: 160/60 R17

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: 0 mm

Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,947.50	2,092.50	855.00	29.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	260.00	150.00	110.00	42.31
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,207.50	2,242.50	965.00	30.09
Approved Total (Overridden) (S\$)		1,800.00		
(S\$)	3,207.50	1,800.00	1,407.50	43.88
+ GST 7.00/7.00% (S\$)	224.53	126.00	98.53	43.88
Nett Amount (S\$)	3,432.03	1,926.00	1,506.03	43.88
+ Loss of Use (2.0 x S\$20.00/day) (S\$)		40.00		
Nett Liability (S\$)		1,966.00		

INSPECTION

Date of Assignment: 11/02/2020

Date Inspected: 12/02/2020 Inspected At:

Southern Motor (HQ)
BLK 1006 BUKIT MERAH LANE 2,
#01-10
Singapore 159762

Estimated Period of Repair: 2.0 days

Adjuster: CHEN TSUE YEE

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*EXHAUST PIPE	Dented	1,150.00 FL	*1,150.00 FL
2	1		*ENGINE GUARD	Bent	225.00 FL	*225.00 FL
3	1		*REAR GIVI BOX	Cut	680.00 FL	*680.00 FL
4	1		*REAR ABSORBER	Not Necessary	950.00 FL	*- FL
5	1		*HANDLE BALANCER	Cut	35.00 FL	*35.00 FL
6	1		*HANDLE BAR	Bent	120.00 FL	*120.00 FL
7	1		*MIRROR (RH)	Cut	115.00 FL	*115.00 FL
					Sub Total (\$\$)	3,275.00 2,325.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	327.50 232.50
					Total Parts (\$\$)	2,947.50 2,092.50

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	ALIGNMENT REAR RIM	New	80.00	0.00
2	LABOR	New	180.00	150.00
Gross Labour Cost (\$\$)			260.00	150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >