

Speed Auto Works
(Co Reg. No. 5321801E)
Blk 90 Bedok North Street 4
#13-1537 Singapore 460090
Tel: 6789 5155 Fax : 6783 5155

TO	: AXA	DATE	: 6-Feb-20
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SJY5766R
ADDRESS	:	MODEL	: KIA CERATO
TEL. NO.	:	CHASSIS NO	:
OWNER'S INSURANCE	:		
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>		DATE	:
		TIME	:
THIRD PARTY REQUESTOR / CONTACT : DAUD/93911482			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER ✓ CNA	1	\$ 895.20	\$ 895.20
2	REAR BUMPER LOWER ✓ SEN	1	\$ 325.00	\$ 325.00
3	REAR BUMPER REINFORCEMENT ✓ CNA	1	\$ 489.00	\$ 489.00
4	REAR BUMPER REINFORCEMENT SPONGE ✓ CNA	1	\$ 240.70	\$ 240.70
5	REAR BUMPER REINFORCEMENT BRACKET X (WV)	5	\$ 32.00	\$ 160.00
6	REAR BUMPER SIDE RETAINER X (SVC)	2	\$ 68.60	\$ 137.20
7	BOOT LID X (R)	1	\$ 1,259.00	\$ 1,259.00
8	BOOT LID CHROME MOULDING X (SVC)	1	\$ 375.60	\$ 375.60
9	BOOT LID WEATHERSTRIP X (SVC)	1	\$ 254.00	\$ 254.00
10	BOOT LID INNER LOCK ✓ Jm	1	\$ 187.60	\$ 187.60
11	BOOT LID STRIKER X (SVC)	1	\$ 47.60	\$ 47.60

520.80

185.80

304.80

160.30

12	REAR END PANEL X (R)	1	\$ 658.20	\$ 658.20
13	REAR END PANEL TOP GARNISH ✓ CRU	1	\$ 227.80	\$ 227.80
14	REAR FLOOR PANEL TOP BOARD X SVC	1	\$ 578.00	\$ 578.00
15	REAR FENDER SIDE INNER TRIM X (SVC)	2	\$ 437.80	\$ 875.60
16	REAR WHEELHOUSE LINER X SVC	2	\$ 98.30	\$ 196.60
17	TAILLAMP X (SVC)	2	\$ 659.40	\$ 1,318.80

TOTAL PRICE \$ 8,225.90
LESS 10% \$ 822.59
SUB TOTAL PRICE \$ 7,403.31

160.30

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BUMPER CLIP SET ✓ nec	1	\$ 65.00	\$ 65.00
2	REAR BUMPER LOWER SPOILER CLIP SET X SVC	1	\$ 55.00	\$ 55.00
3	REVERSE SENSOR ✓ short	1	\$ 250.00	\$ 250.00
5	BOOT LID EMBLEM X SVC	1	\$ 200.00	\$ 200.00
6	BOOTLID SEALANT X SVC	1	\$ 80.00	\$ 80.00
7	BOOTLID INNER TRIM CLIP SET ✓ CRU	1	\$ 65.00	\$ 65.00
8	BOOTLID STICKER ✓ nec	1	\$ 800.00	\$ 800.00
9	REAR END PANEL TOP GARNISH CLIP SET ✓ nec	1	\$ 45.00	\$ 45.00
10	REAR FENDER SIDE INNER TRIM CLIP SET X SVC	1	\$ 120.00	\$ 120.00
11	REAR WHEELHOUSE LINER CLIP SET X SVC	1	\$ 90.00	\$ 90.00
12	REAR END PANEL SEALANT ✓ CRU	1	\$ 90.00	\$ 90.00

SUB TOTAL PRICE \$ 1,860.00

25

200

25

250.00

15

20

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	CUT OFF AND REPLACE REAR END PANEL, FLOOR PANEL AND REAR LHS FRAME. STRAIGHTEN, REALIGN REAR CHASSIS FRAME AND RENEW OTHER DAMAGE PARTS.	\$ 1,200.00	600	
2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA.	\$ 1,200.00	600	
3	DISMENTLE AND INSTALL EXHAUST PIPE SYSTEM TO ENABLE REPAIRS.	X nn \$ 120.00		
4	REMOVE AND INSTALL REAR PARKING SENSOR AND WIRING HARNESS. PERFORM DISTANCE SENSORY TESTING.	✓ \$ 120.00	30	

5	RENEW REAR FLOOR INSULATOR. <i>X</i>	<i>nn</i> \$ 180.00		
8	REMOVE AND INSTALL REAR MULTI-VIEW CAMERA ASSY. PERFORM AIMING AND ADJUST TO POSITION. <i>X</i>	<i>nn</i> \$ 250.00		
9	CONDUCT WATER LEAKAGE ON WELDING JOINT AREA. <i>✓</i>	\$ 100.00	50	
10	TRANSFER REAR BOOTLID ATTACHMENT AND MECHANISM INTO NEW TAILGATE ASSY. <i>X</i>	<i>nn</i> \$ 200.00		

TOTAL \$ 3,370.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 9,263.31
TOTAL LABOUR COST : \$ 3,370.00
TOTAL REPAIR COST : \$ 12,633.31

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

*2/5 repair
with preparation
4 day 3.30 pm*

*13/2/20
Hock Burr
LKK*

*85312883
Hock ANN@lkk Auto.com
Reamy after print*

*Reamy taken
Hock Burr
13/2/20 4:00 pm*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: