

























...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Feb 2020		13 Feb 2020 12:55 Edit Adj Rpt	S\$4,400.00 Edit Estimates	S\$4,400.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	NORHISHAM BIN MOHD KAMSIN , ID: S75007291								
Vehicle Reg. No.:	SJT9132U	Date of Loss:	07/02/2020 17:00 - :59 [123 Months and 1 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM20D200700C02	Policy/Cover Note No.:	DMB1SN16757219033						
Vehicle Reg. No. (Insured):	PC57G	Policy No. (Claimant):	DMPCSN3067261900						
		Excess:	S\$0.00						
Repairer:	SK Automobile Pte Ltd (HQ) 23 Kaki Bukit Avenue 4, #03-01 Vicom Inspection Centre, 415933 Kaki Bukit - Tel: 67895155								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]								
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 24/02/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJT9132U (SNM20D200700C02)
[PC57G]
TP
NORHISHAM BIN MOHD KAMSIN
Feb 7 2020 5:00PM
[-]
SK Automobile Pte Ltd








Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Assessment Reports									1 per page		<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)							Thumbnail	Print	
1	10/02/20 12:41	Accident Statement								Load HTM	
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)							Thumbnail	Print	
1	10/02/20 12:24	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
2	10/02/20 12:24	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
3	10/02/20 12:24	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
4	10/02/20 12:24	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
5	10/02/20 12:24	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
6	10/02/20 12:24	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
7	10/02/20 12:24	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
8	10/02/20 12:24	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
9	10/02/20 12:24	Accident Photo [Linked Accident Report Documents]								Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail	Print	
1	14/02/20 11:03	Chassis Number								Load JPG	<input checked="" type="checkbox"/>
2	14/02/20 11:03	Odometer Reading								Load JPG	<input checked="" type="checkbox"/>
3	14/02/20 11:04	General View								Load JPG	<input checked="" type="checkbox"/>
4	14/02/20 11:04	General View								Load JPG	<input checked="" type="checkbox"/>
5	14/02/20 11:04	General View								Load JPG	<input checked="" type="checkbox"/>
6	14/02/20 11:04	General View								Load JPG	<input checked="" type="checkbox"/>
7	14/02/20 11:04	General View								Load JPG	<input checked="" type="checkbox"/>
8	14/02/20 11:04	General View								Load JPG	<input checked="" type="checkbox"/>
9	14/02/20 11:04	General View								Load JPG	<input checked="" type="checkbox"/>
10	14/02/20 11:04	General View								Load JPG	<input checked="" type="checkbox"/>
11	14/02/20 11:04	General View								Load JPG	<input checked="" type="checkbox"/>
12	14/02/20 11:04	General View								Load JPG	<input checked="" type="checkbox"/>
13	14/02/20 11:04	General View								Load JPG	<input checked="" type="checkbox"/>
14	14/02/20 11:04	General View								Load JPG	<input checked="" type="checkbox"/>
15	14/02/20 11:04	General View								Load JPG	<input checked="" type="checkbox"/>
16	14/02/20 11:04	General View								Load JPG	<input checked="" type="checkbox"/>
17	14/02/20 11:04	General View								Load JPG	<input checked="" type="checkbox"/>
18	14/02/20 11:04	General View								Load JPG	<input checked="" type="checkbox"/>
19	14/02/20 11:04	General View								Load JPG	<input checked="" type="checkbox"/>
20	14/02/20 11:04	General View								Load JPG	<input checked="" type="checkbox"/>
21	14/02/20 11:04	General View								Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
22	14/02/20 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
23	14/02/20 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
24	14/02/20 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
25	14/02/20 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
26	14/02/20 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
27	14/02/20 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
28	14/02/20 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
29	14/02/20 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
30	14/02/20 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
31	14/02/20 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
32	14/02/20 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
33	14/02/20 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
34	14/02/20 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
35	14/02/20 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
36	14/02/20 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
37	14/02/20 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
38	14/02/20 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
39	14/02/20 11:04	General View	 Load JPG	<input checked="" type="checkbox"/>
40	14/02/20 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
41	14/02/20 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
42	14/02/20 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
43	14/02/20 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
44	14/02/20 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
45	14/02/20 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
46	14/02/20 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
47	14/02/20 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
48	14/02/20 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
49	14/02/20 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
50	14/02/20 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
51	14/02/20 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
52	14/02/20 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
53	14/02/20 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
54	14/02/20 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
55	14/02/20 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
56	14/02/20 11:05	General View	 Load JPG	<input checked="" type="checkbox"/>
57	14/02/20 11:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	14/02/20 11:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	14/02/20 11:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	14/02/20 11:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	14/02/20 11:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	14/02/20 11:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	14/02/20 11:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	14/02/20 11:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	14/02/20 11:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	14/02/20 11:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	14/02/20 11:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	14/02/20 11:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	14/02/20 11:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	14/02/20 11:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	14/02/20 11:05	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
72	14/02/20 11:05	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
73	14/02/20 11:05	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
74	14/02/20 11:05	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
75	14/02/20 11:05	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
76	14/02/20 11:05	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
77	14/02/20 11:05	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
78	14/02/20 11:05	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
79	14/02/20 11:05	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
80	14/02/20 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
81	14/02/20 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
82	14/02/20 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
83	14/02/20 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
84	14/02/20 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
85	14/02/20 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
86	14/02/20 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
87	14/02/20 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
88	14/02/20 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
89	14/02/20 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
90	14/02/20 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
91	14/02/20 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
92	14/02/20 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
93	14/02/20 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
94	14/02/20 11:06	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
95	13/03/20 10:22	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
96	13/03/20 10:22	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
97	13/03/20 10:22	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
98	13/03/20 10:22	After Repair Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	10/02/20 12:39	Accident Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	10/02/20 12:39	Accident Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	10/02/20 12:39	POLICE REPORT [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	10/02/20 12:39	POLICE REPORT [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	10/02/20 12:41	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)	Thumbnail	Print
1	10/02/20 12:24	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	10/02/20 12:24	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	10/02/20 12:24	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	10/02/20 12:24	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	10/02/20 12:24	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	10/02/20 12:24	Accident Photo	Load JPG	

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)		Thumbnail	Print
					<input checked="" type="checkbox"/>
7	10/02/20 12:24	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	10/02/20 12:24	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	10/02/20 12:24	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	National Assessment Centre Services (Bukit Merah)		Thumbnail	Print
1	10/02/20 12:39	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
2	10/02/20 12:39	Accident Sketch Plan		Load JPG	<input checked="" type="checkbox"/>
3	10/02/20 12:39	POLICE REPORT		Load JPG	<input checked="" type="checkbox"/>
4	10/02/20 12:39	POLICE REPORT		Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT120002530/HQD3E2

Date: 02/04/2020

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMB1SN16757219033

Claimant Vehicle
No: SJT9132UInsured Vehicle
No: PC57G

Date of Loss: 07/02/2020

Nature of Claim: TP

Claim
No: SNM20D200700C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJT9132U

Make & Model: TOYOTA WISH, 2.0 (A)

Reg. Date: 06/11/2009 (Man. Year: 2009)

Colour: Grey

Engine Capacity: 1987 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 3ZRA390400

Chassis No: JTDGJ20W505001062

Odometer: 133294 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size: 195/65 R15

Front Left Side: Bridgestone 5 mm

Rear Left Side: Yokohama 3 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Yokohama 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,157.92	3,657.22	6,500.70	64.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,540.00	1,820.00	2,720.00	59.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,697.92	5,477.22	9,220.70	62.73
Approved Total (Overridden) (S\$)		4,400.00		
(S\$)	14,697.92	4,400.00	10,297.92	70.06
+ GST 7.00/7.00% (S\$)	1,028.85	308.00	720.85	70.06
Nett Amount (S\$)	15,726.77	4,708.00	11,018.77	70.06

INSPECTION

Date of Assignment: 13/02/2020

Date Inspected: 13/02/2020 Inspected At:

8 KAKI BUKIT AVE 4# 08-46 PREMIER

Repairer : SK Automobile Pte Ltd (HQ)

Estimated Period of Repair: 5.0 days

Adjuster: LEE HOCK ANN**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 02 Apr 2020)
Parts:	N/A TOYOTA WISH 2.0 (A) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJT9132U)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	689.00 FL	*565.70 FL
2	2		*REAR BUMPER SIDE RETAINER	Necessary	119.60 FL	*119.60 FL
3	1		*TAILGATE	Bent	1,245.00 FL	*1,070.80 FL
4	1		*TAILGATE CHROME MOULDING	Scratched	245.00 FL	*245.00 FL
5	2		*TAILGATE HINGE	Serviceable	156.40 FL	*- FL
6	2		*TAILGATE DAMPER	Serviceable	308.00 FL	*- FL
7	1		*TAILGATE WEATHERSTRIP	Cracked	184.00 FL	*184.00 FL
8	2		*TAILGATE STOPPER	Serviceable	75.80 FL	*- FL
9	1		*TAILGATE LOCK ASSY	Jammed	354.00 FL	*270.80 FL
10	1		*TAILGATE STRIKER	Serviceable	73.40 FL	*- FL
11	1		*REAR WINDSCREEN MOULDING	Necessary	125.00 FL	*78.80 FL
12	1		*REAR END PANEL	Bent	548.00 FL	*470.80 FL
13	1		*REAR END PANEL MEMBER	N/S Bent	195.60 FL	*97.80 FL
14	2		*REAR WHEELHOUSE LINER	Serviceable	196.60 FL	*- FL
15	1		*REAR END PANEL TOP GARNISH	Cracked	184.00 FL	*184.00 FL
16	1		*REAR CARGO TOP BOARD	Crumpled	450.80 FL	*260.80 FL
17	2		*REAR CARGO SIDE BOARD	Serviceable	526.40 FL	*- FL
18	1		*TAILGATE INNER TRIM HANDLE	Serviceable	98.00 FL	*- FL
19	2		*REAR FENDER INNER TRIM	Serviceable	1,398.00 FL	*- FL
20	1		*SPARE TYRE CARRIER	Serviceable	245.60 FL	*- FL
21	1		*TAILGATE LAMP	N/S Scratched	1,308.00 FL	*387.40 FL
22	2		*TAILLAMP PANEL	Repair	1,041.40 FL	*- FL
23	1		*EXHAUST PIPE SILENCER	Serviceable	763.80 FL	*- FL
24	1		*EXHAUST HEAT SHIELD	Serviceable	70.60 FL	*- FL
25	1		*SET REAR BUMPER CLIP	Necessary	70.00 FS	*25.00 FS
26	2		*SET REAR FENDER SIDE INNER TRIM CLIP	Serviceable	90.00 FS	*- FS
27	1		*SET TAILGATE INNER TRIM CLIP	Necessary	70.00 FS	*25.00 FS
28	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	45.00 FS	*20.00 FS
29	2		*SET REAR WHEELHOUSE LINER CLIP	Serviceable	130.00 FS	*- FS
30	1		*REAR WINDSCREEN INNER SEAL	Necessary	110.00 FS	*30.00 FS
31	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
32	1		*REAR END PANEL SEALANT	Necessary	90.00 FS	*50.00 FS
33	1		*REAR FLOOR PANEL SEALANT	Serviceable	90.00 FS	*- FS
34	1		*REAR FLOOR PANEL INSULATOR	Serviceable	250.00 FS	*- FS
35	1		*REVERSE CAMERA	Serviceable	450.00 FS	*- FS
36	1		*REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS
37	1		*TAILGATE INNER TRIM BOARD	Cracked	604.90 FL	*420.80 FL
38	2		*EXHAUST MOUNTING	Serviceable	77.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				Sub Total (S\$)	12,978.90	4,746.30
				- List Item Discount on L Items 25.00/25.00% (S\$)	2,820.98	1,089.08
				Total Parts (S\$)	10,157.92	3,657.22

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CUT OFF AND REPLACE REAR END PANEL, FLOOR PANEL AND REAR LHS FRAME, STRAIGHTEN, REALIGN REAR CHASSIS FRAME AND RENEW OTHER DAMAGE PARTS	New	1,500.00	800.00
2	SPRAY PAINTING ON DAMAGE AND AFFECTED AREA	New	1,200.00	750.00
3	DISMENTLE AND INSTALL EXHAUST PIPE SYSTEM TO ENABLE REPAIRS	New	120.00	0.00
4	REMOVE AND INSTALL REAR PARKING SENSOR AND WIRING HARNESS. PERFORM DISTANCE SENSORY TESTING	New	150.00	20.00
5	RENEW REAR FLOOR INSULATOR	New	80.00	0.00
6	REMOVE AND REPLACE SMART KEYLESS ANTENNA AND BUZZER. RESET SMART ENTRY SYSTEM	New	250.00	0.00
7	PERFORM REAR LIGHTING WIRING CHECK AND TEST FUNCTION	New	80.00	30.00
8	REMOVE AND INSTALL REAR MULTI-VIEW CAMERA ASSY. PERFORM AIMING AND ADJUST TO POSITION	New	200.00	0.00
9	CONDUCT WATER LEAKAGE ON WELDING JOINT AREA	New	100.00	40.00
10	TRANSFER REAR TAILGATE ATTACHMENT AND MECHANISM INTO NEW TAILGATE ASSY	New	180.00	80.00
11	REMOVE AND INSTALL REAR WINDSCREEN GLASS	New	180.00	100.00
12	DISMENTLE AND INSTALL REAR COMPARTMENT TRIMMING	New	200.00	0.00
13	APPLY TUFF COATING TREATMENT	New	300.00	0.00
Gross Labour Cost (\$\$)			4,540.00	1,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >