

ASS. REC. BY:

REF: CS/AIG 2000 2533/K903<sup>82</sup>

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

Meinmen

From (Person): chin lee ying

of

A19

Date/Time: 13/2/2020 @ 8.48am

Estimated Cost:

Bill to:

OF / F / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBD 6912J

Insured:

at Workshop m/s

Tong Luck Auto

Tel: 6250 0088

of

160 Sin Ming Drive # 07-01

Policy No:

0999993937

Claim No:

485355825694

Sum Insured:

Excess:

~~1400~~ 1400 19/2/2020

Make of Veh:

D.O.A 13/01/2020

(Client's Record)

CA / REV REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 9.11am @ 13/2/2020

Person Contacted:

Tennree

Vehicle: IN/OUT

Date/Time

Action/Instruction

13/2/2020 3.10pm

GBD 6912J-X

13/2/2020 3.10pm revert to Victor via Meinmen.

19/2/2020 4.20pm Victor informed c/a via Meinmen. (LH rear door not consistent).

19/2/2020 5pm informed Candy c/a &amp; Ex: \$1400 by email.

20/2/2020 10.30am Kenneth already informed Candy that the LH rear door not consistent &amp; will not replace it.

REF:

AIG (SIAIG 20002533/ E9A3

ASS. REC. BY:

## ASSIGNMENT

From: \_\_\_\_\_ Date: 13/02/2020

Estimated Cost: \_\_\_\_\_

☒ OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBD 6912J

at Workshop m/s Tong Luck

of 160 Sin Ming Drive # 07-01/06

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: TBA

(Client's Record)

Make of Veh: vehicle In

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: 2448.80

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 06 days Res.: Yes or No

Lum Sum: 13.1 % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: GBD 6912J Yr Regn: 03/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Citroen <sup>ch</sup> Dispatch C.C. 1997

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 125323 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: VF 7XSAH 8888012466

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F: Yokohama

R: 205/65R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 0 mm R/Bal. 9 mm

L/Bal. 0 mm L/Bal. 9 mm

D.O.A. 13/1/20 D.O.I. 13/2/20

Survey held at \_\_\_\_\_

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

28/2/20 @ 10.12am According to repairer, Candy that Victor already informed them to repair RH rear door after wksp provided the damaged photo (see email).

12/3 2448.80 Cashmere (lead 5187, 54%)

RECEIVED 12 MAR 2020

Date/Time, File Pass to?

☐

: Preli. Report

1) 12/3 12/3/20

☐

: Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

Report Format:

MER-07

Lump Sum / L.B.E (\$)

4488.80

**Estimated cost of repair for repairing of vehicle no.: GBD6912J -- OD Claim**

From: Chin, Lee-Ying  
To: assignments, Admin-D (LKKAUTO)  
Cc: Lim, Kok-Chong  
Sent: 2/13/2020 8:48:35 AM  
Attachments:  GBD6912J--Estimate.pdf

---

Hi LKK,

Kindly assist to survey today.

Thanks.

Best Regards  
Lee Ying, Chin  
AIG  
Claims | AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way #08-16 Singapore 079120  
Tel +(65) 6419 1947  
[Lee-Ying.Chin@aig.com](mailto:Lee-Ying.Chin@aig.com) | [www.aig.sg](http://www.aig.sg)

---

**From:** Operation / Candy Ong [<mailto:operation@tlauto.com.sg>]  
**Sent:** Wednesday, February 12, 2020 3:17 PM  
**To:** Chin, Lee-Ying  
**Subject:** [EXTERNAL] Estimated cost of repair for repairing of vehicle no.: GBD6912J -- OD Claim

**This message is from an external sender; be cautious with links and attachments.**

Dear Lee Ying,

Please find attached documents for your information and necessary action

The vehicle is now garage at our workshop

Kindly arrange your surveyor to inspect the vehicle at an earlier date

Thanks & regards,  
Candy Ong



**Tong Luck Auto Pte Ltd**  
160 Sin Ming Drive  
#07-01/06 Sin Ming Autocity  
Singapore 575722  
Tel: 6250 0088 Fax: 6250 5545

Email: [operation@tlauto.com.sg](mailto:operation@tlauto.com.sg)

## Shiau Chan (LKKAUTO)

---

**From:** Operation / Candy Ong <operation@tlauto.com.sg>  
**Sent:** Friday, 28 February 2020 10:12 AM  
**To:** Shiau Chan (LKKAUTO)  
**Subject:** FW: FW: OD VEHICLE GBD6912J (DOA: 13/01/2020)

Dear Shiau Chan,

Please find below email as per your request

Best Regards,  
Candy Ong  
Tong Luck Auto Pte Ltd

-----Original Message-----

From: Koh, Victor-CK [mailto:Victor-CK.Koh@aig.com]  
Sent: Thursday, February 27, 2020 2:16 PM  
To: Operation / Candy Ong <operation@tlauto.com.sg>  
Subject: RE: FW: OD VEHICLE GBD6912J (DOA: 13/01/2020)

Hi Candy,

RH rear door to repair.

Thanks & Regards

Victor Koh  
AIG  
Claims Technical Controller  
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120  
Tel +65 6419 1785 | Fax +65 68357416  
Victor-ck.koh@aig.com | www.aig.com

-----Original Message-----

From: Operation / Candy Ong [mailto:operation@tlauto.com.sg]  
Sent: Thursday, February 27, 2020 11:42 AM  
To: Koh, Victor-CK  
Subject: [EXTERNAL] FW: OD VEHICLE GBD6912J (DOA: 13/01/2020)

This message is from an external sender; be cautious with links and attachments.

Dear Victor,

We received an email from LKK Auto Consultants Pte Ltd on 25/2/2020 that the

RH rear door is not consistent to the accident

Please find attached photos showing that the tail lamp and the rear door have the same scratches marks, the door pillar and door hinge was also badly dented

Therefore the RH rear door is related to the accident

We are still pending for your approval to proceed with the repair

Kindly revert soonest as the owner is chasing for the vehicle

Best Regards,  
Candy Ong  
Tong Luck Auto Pte Ltd

## Shiau Chan (LKKAUTO)

---

**From:** Operation / Candy Ong <operation@tlauto.com.sg>  
**Sent:** Wednesday, 26 February 2020 10:38 AM  
**To:** Shiau Chan (LKKAUTO)  
**Cc:** SUR  
**Subject:** OD VEHICLE GBD6912J (DOA: 13/01/2020)  
**Attachments:** P1400413.jpg; P1400414.jpg; P1400415.jpg; P1400416.jpg; P1400417.jpg; P1400418.jpg; P1400419.jpg; P1400420.jpg; P1400421.jpg; P1400422.jpg; P1400423.jpg; P1400424.jpg; P1400425.jpg; P1400426.jpg; P1400427.jpg; P1400428.jpg; P1400429.jpg; P1400430.jpg; P1400431.jpg; P1400432.jpg; P1400433.jpg; P1400434.jpg; P1400435.jpg; P1400436.jpg; P1400437.jpg; P1400438.jpg; P1400439.jpg; P1400440.jpg

Dear Shiau Chan,

Refer to your email dated 25/2/2020

Please note that the vehicle was surveyed by your surveyor only on 13/2/2020

We are only told on 21/2/2020 that the RH rear door was not consistent

Please find attached photos showing that the tail lamp and the rear door have the same scratches marks, the door pillar and door hinge is badly dented

Therefore the RH rear door is related to the accident

Kindly revert soonest

Best Regards,  
Candy Ong  
Tong Luck Auto Pte Ltd

## Shiau Chan (LKKAuto)

---

**From:** Koh, Victor-CK <Victor-CK.Koh@aig.com>  
**Sent:** Wednesday, 19 February 2020 4:18 PM  
**To:** Shiau Chan (LKKAuto)  
**Cc:** Fong, Andy-SY  
**Subject:** RE: PENDING FOR MANDATE AND RE-MANDATE APPROVAL

Hi Shiau Chan,



RH rear door dent (circle in yellow) not consistent. To amend parts and labour accordingly. Mandate approve and authorize repair.

Thanks & Regards

Victor Koh  
AIG  
Claims Technical Controller  
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore 079120  
Tel +65 6419 1785 | Fax +65 68357416  
[Victor-ck.koh@aig.com](mailto:Victor-ck.koh@aig.com) | [www.aig.com](http://www.aig.com)



## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Wednesday, 19 February 2020 5:00 PM  
**To:** tlauto@singnet.com.sg  
**Cc:** SUR  
**Subject:** OD VEHICLE GBD 6912J (DOA: 13/01/2020)

Dear Candy,

As instructed by our client, please proceed to repair the insured vehicle **GBD 6912J (Excess \$1,400/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Claim Audit

AUDIT TRAIL				By
No.	On	Audit	Remarks	
1	14 Jan 2020 18:05	Clim Veh Model Changed		[ ] Merimen Administrator
2	14 Jan 2020 18:05	Clim Created	Reg No: GBD6912J. Policy No: 999995580. Acct Date: 2020/01/13. Claim Type: SC. Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG). Ins.Status => Notification. Created from SAS:MBHH20006444	[I] Merimen Administrator
3	20 Jan 2020 10:32	Clim Registration Init. Est.:->5,000 - 6,000. Modified		[I] Lim, Sheng Yang
4	04 Feb 2020 09:02	Clim Registration Modified	Acct Time:22:30:00->22:00:00. Pol No:999995580->0999993937.	[I] Hor, Yinrul
5	13 Feb 2020 14:39	Clim Registration Setl.Type:3->0. Claim Type:SC->OD. Modified		[ ] Nivitha Govindasamy
6	13 Feb 2020 14:39	Adj Clim Retrieved	Adj: LKK Auto Consultants Pte Ltd (HQ)	[ ] Nivitha Govindasamy
7	13 Feb 2020 14:39	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):	[A] Nivitha Govindasamy
8	13 Feb 2020 14:39	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2020/02/24	[A] Nivitha Govindasamy
9	13 Feb 2020 14:39	Adj Mandate Set	Approved:8000.00.Reinsp:Adj decides.	[A] Nivitha Govindasamy
10	13 Feb 2020 14:39	Clim Registration Modified	Rep:1137->200237.	[A] Nivitha Govindasamy
11	13 Feb 2020 14:39	Clim Veh Model Changed	(204857) CITROEN DISPATCH 2.0 D I HDI AT (M).	[A] Nivitha Govindasamy
12	13 Feb 2020 14:39	Adj Adjuster Assigned	[None] -> KENNETH KONG	[A] Nivitha Govindasamy
13	13 Feb 2020 15:07	Adj Rpt Initiated		[A] SHIAU CHAN
14	13 Feb 2020 15:07	Clim Dtl Modified	Claim Conclusion: -> 3.	[A] SHIAU CHAN
15	13 Feb 2020 15:07	Clim Dtl Modified	JPJ Reg. Date: -> 2015/03/26.	[A] SHIAU CHAN
16	13 Feb 2020 15:07	Clim Details Notified		[A] SHIAU CHAN
17	13 Feb 2020 15:09	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2020/02/24	[A] SHIAU CHAN
18	13 Feb 2020 15:10	Adj Mandate Request	Cur.Req:8235.80:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
19	19 Feb 2020 13:52	Clim Registration Modified	Excess: -> 1400.00. 2F Remarks: -> Not Applicable. GST: -> 7.00.	[I] Chan, Yoke Shi
20	19 Feb 2020 13:52	Label Added (20226):Coverage Confirmed.		[A] Merimen Administrator
21	19 Feb 2020 16:20	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2020/02/24. Mandate Remarks: Authorise repair. RH rear door dent not consistent. To amend parts and labour accordingly. Re-inspection to be done for damage check and supplementary items / labour with clear photos.	[I] Koh, Victor-CK
22	19 Feb 2020 16:20	Adj Mandate Set	Approved:5951.80:Authorise repair. RH rear door dent not consistent. To amend parts and labour accordingly. Re-inspection to be done for damage check and supplementary items / labour with clear photos. Reinsp:Yes.	[I] Koh, Victor-CK

Date From



Date To



Audit Type None

Go

### ACTIVITY

No record

### Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Bill Type	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
2437820	13 Feb 2020 15:07:50	OD/TP Case (Adjuster)	Motor	LKK Auto Consultants	LKK Auto Consultants	GBD6912J		11.77

Note: This document has not been finalised.

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building  
78 Shenton Way #08-16  
Singapore 079120

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Azlan, Syazairdina

Date: 13 Feb 2020

**Preliminary Advice**

Vehicle No	: GBD6912J	Accident Date	: 13/01/2020
Make	: CITROEN DISPATCH	Policy No.	: 0999993937
Assignment Date	: 13/02/2020	Excess	: S\$0.00
Date of Inspection	: 13/02/2020	Est. Duration of Repair	: 6.00
Inspection At	: TONG LUCK AUTO PTE LTD (HQ) 160 SIN MING DRIVE, #07-01 SIN MING AUTOCITY SINGAPORE 575722		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,675.80
Revised Amount	:S\$	5,951.80
Check Items (Estimated)	:S\$	2,284.00
Total	:S\$	8,235.80

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	41,000.00
COE / PARF Rebate	:S\$	30,693.00
Salvage Value	:S\$	
Margin for Repair	:S\$	10,307.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	14/01/2020 17:52
Date Of Accident	13/01/2020 22:30
Exact Location Of Accident	PIE TOWARDS CHANGI NEAR EXIT 20
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBD6912J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD
Co Reg No	1XXXXX778Z
Email Address	BENNY.CHONG@DAIMLER.COM
Mobile Phone No	
Alternative Phone No	OFFICE-92203185

### Vehicle Particulars

Manufacturer	CITROEN
Model	DISPATCH 2.0 HDI MT6
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995580
Cover Note Number	N.A

### Driver

Name of Driver	MOHAMED ALI MUHAMMAD FAISAL
NRIC No	SXXXX382E
Date Of Birth	14/11/1990
Occupation	OUTDOOR
Date Of Driving Pass	05/01/2016
Driving Experience	4 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96563758
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode


Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO ATTACHED STATEMENT.

A large rectangular area with horizontal lines for writing. Two diagonal lines are drawn across the area, from the bottom left to the top right, forming a large 'X' shape.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

VERIFY BY AJAX MARS (ARC)  
REPORTING OFFICER  
AIZAM BIN ATAN

Reporting Centre Personnel's Signature  
Name:  
NRIC/VIN No.:



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Hong Kah South NPP  
510 Jurong West Street 52 #01-90  
SINGAPORE 640510  
Tel No: 1800-5648999



T/20200114/2043

1 of 3

Report No: T/20200114/2043

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made:  
14/01/2020 12:53

Video Report No.:

Station Diary No.:  
12

**Informant's Particulars**

Name of Informant:  
MOHAMED ALI MUHAMMAD  
FAISAL

Address:  
APT BLK 511 JURONG WEST STREET 52 #06-78  
SINGAPORE 640511

ID Type / ID No.:  
NRIC NO / S9082382E

Contact No.:  
Home/Office: Mobile: 96563758

Nationality:  
INDIAN

Email:

Sex: Age: Date of Birth:  
Male 29 14/11/1990

Type of Informant:  
Driver

Race:  
Indian

Language:  
English

Institution / School Name:

Occupation:  
driver

Driving Licence Information:  
Class: 2B.3

Date of Expiry:

**General Information of the Accident**

Type of Accident: Non-Injury  
Hit and Run

Drink  
Drive:  
No

Date/Time of  
Accident:  
13/01/2020 22:30

Type of Location:  
Straight Road

Location:  
Along Road 1  
PAN ISLAND EXPRESSWAY

towards Changi Airport near exit 20

Weather:  
Clear

Road Surface:  
Dry

Road Speed Limit:  
90 Km/h

Traffic Flow:

Traffic Control:

Traffic Volume:  
Light

Type of Collision:  
Between Moving Vehicles - Head To Rear

Anyone conveyed by  
ambulance:  
No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBD5912J	Van				Slightly Damaged	1

**Details of Person Involved**

Any Pedestrian Involved: No

No. of Pedestrians Injured: NIL

Use of Pedestrian Crossing: NA



Sketch Plan #5



SINGAPORE  
POLICE FORCE

Police Station Of Origin:  
Hong Kah South NPP  
510 Jurong West Street 52 #01-90  
SINGAPORE 640510  
Tel No: 1800-5648999



T/20200114/2043

3 of 3

Report No: T/20200114/2043

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Sr Staff Sgt YAP HOW KIAT MICHAEL

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

14/01/2020 12:53

Officer In Charge Of Case:

TP / HRT /

Staff Sgt MUHAMMAD KHAIRIL BIN KAMAL

Contact No.: 65476368

Classification Of Case:

Authentication Stamp



NP168





HOTLINE TEL: (65) 6419-3000


## COVER NOTE

<b>Cover Note No.</b> 100880287		<b>Date</b> 14 Jan 2020	
The following risk described in the Schedule is hereby HELD COVERED in the terms of the applicable Company's policy issued to the Policyholder.			
<b>SCHEDULE</b>			
<b>Policyholder</b>	Daimler Fleet Management Singapore Pte Ltd		
<b>Age Condition</b>	N/A	<b>Registration No</b>	GBD6912J
<b>Policy Type</b>	COMPREHENSIVE COMMERCIAL MOTOR	<b>Make/Model</b>	Citroen Dispatch 2.0 HDI
<b>Effective Date</b>	1 Jan 2020	<b>CC/Tonnage</b>	1.00
<b>Expiry Date</b>	31 Dec 2020	<b>Engine No</b>	10DYZG4090357
<b>Hire Purchase Company</b>	NA	<b>Chassis No</b>	VF7XSAHZ8EZ012466
		<b>Year of Registration</b>	2015
			
<p>This policy is subject to driver's age condition. The policy will indemnify the insured or any authorised driver only if he/she meets the age condition. Please refer to policy terms and conditions.</p> <p>Usage of vehicle only for the following purposes:</p> <ol style="list-style-type: none"><li>1. Use only for social, domestic and pleasure purposes and for the Policyholder's business.</li><li>2. Use in connection with the Policyholder's business. Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business and use for social, domestic or pleasure purposes.</li></ol> <p>Please note that acceptance of the risk is subject to our final acceptance and terms and conditions applicable to the policy. Should you require any change to the insurance, please contact us immediately. Otherwise, any change will not be covered under the policy.</p> <p>The Company may cancel this cover by notice in writing and the insurance will be terminated and a proportionate part of the annual premium for the insurance will be charged for the time the Company has been on risk.</p>			
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189) MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960 ROAD TRANSPORT ACT, 1987 (MALAYSIA) MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)			
<b>CERTIFICATE OF INSURANCE</b>			
I/We hereby certify that this cover note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)			

Issued at SINGAPORE

AIG ASIA PACIFIC INSURANCE PTE. LTD.

**IMPORTANT NOTICE**  
THIS COVER NOTE IS VALID FOR  
60 DAYS FROM THE FIRST DAY OF  
THE POLICY PERIOD.

  
Authorised Representative

SSPYTP

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	778Z
Vehicle Details	
Vehicle No.:	GBD6912J
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Feb 2020
Vehicle Make:	CITROEN
Vehicle Model:	DISPATCH 2.0 HDI MT6
Primary Colour:	White
Manufacturing Year:	2014
Engine No.:	10DYZG4090357
Chassis No.:	VF7XSAHZ8EZ012466
Maximum Power Output:	-
Open Market Value:	\$23,966.00
Original Registration Date:	26 Mar 2015
First Registration Date:	26 Mar 2015
Transfer Count:	0
Actual ARF Paid:	\$1,199.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	25 Mar 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$59,999.00
COE Rebate Amount:	\$30,693.00
<b>Total Rebate Amount:</b>	<b>\$30,693.00</b>

The information contained herein is correct as at 13 Feb 2020

OK

## Exclusive 10% OFF on Videos

HD videos starting at \$63/clip. Over 11 million SD, HD, and 4K video clips. Shutterstock.com

**Post an Advertisement**  
Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

New 5 Years Renewal COE Toyota Altis 1.6A



2.98% P.A. 0 down, 0 down,  
monthly \$488, 2 Years Warranty  
Engine & Gearbox  
GV Credit Standard



Browse by Category ▾

Sort by Date Posted ▾ 20 results/page ▾

1 vehicles

DISPATCH 2.0

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	DISPATCH 2.0		Any	Any	2015	Any	Any	Any	Available
	Citroen	Dispatch 2.0A	\$42,800	\$7,820 /yr	04-Aug-2015	1,997 cc	66,521 km	Van	Available
<b>Fuel Type: Diesel</b> Looking For A Vehicle With Good Fuel Consumption Vehicle? No Matter Which Engine You Go For, The Citroen Dispatch Offers Impressive Fuel Consumption For This Class. Try This Spacious Very Good Condition Citroen Dispatch 2.0A. Fuel Consumption At Only 17.5 Km/L. L... Motor-Way Credit Pte Ltd Posted: 16-Jan-2020           Tags: 2015 Citroen Dispatch, 2015 citroen dispatch, Citroen Dispatch, citroen dispatch, Citroen, Dispatch, dispatch, Used Citroen									

Save this search criteria, to get email alerts whenever a match is found.

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
For old advertisements, view <b>Expired ads</b>									20 results/page

[Home](#)
[New Cars](#)
[Used Cars](#)
[Sell My Car](#)
[Directory](#)
[Products](#)
[Insurance](#)
[Article](#)
[Forum](#)
[Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used DISPATCH 2.0, DISPATCH 2.0 Singapore, used DISPATCH 2.0 Singapore, used DISPATCH 2.0, used vehicles Singapore or even buy used DISPATCH 2.0 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

[About Us](#)
[Careers](#)
[Contact Us](#)
[Sitemap](#)
[Terms of Service](#)
[Privacy Policy](#)
[Personal Data Protection Statement](#)

©2004-2020 sgCarMart. All rights reserved.



# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD.

78 SHENTON WAY #07-16  
AIG BUILDING  
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT

TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :

CLAIM TYPE : OWN DAMAGE

ACCIDENT DATE : 13/01/2020

## ESTIMATE

NO : QUOT202002-000010(00)

DATE : 12/02/2020

POLICY NO : 999995580

VEH REG NO : GBD6912J

MAKE/MODEL : CITROEN DISPATCH 2.0 HDI  
MT6

CHASSIS NO : VF7XSAHZ8EZ012466

ENGINE NO : 10DYZG4090357

REG. DATE : 2014

*Not withain  
Resurvey B&Pain*

*6 days  
Rear oil*

## Estimate Repair Cost to Vehicle No : GBD6912J

Description	Quantity	Unit Price	Amount
		<u>S\$</u>	<u>S\$</u>
<b>PARTS</b>			
1 Rear fender - RH	1	1,850.00	1,850.00
2 Taillamp assy - RH	1	250.00	250.00
3 Rear door - RH	1	980.00	980.00
4 Rear door hinges - RH	2	220.00	440.00
5 Rear door hinge cover - RH	2	120.00	240.00
6 Rear bumper	1	680.00	680.00
7 Rear bumper side retainer - RH	1	38.00	38.00
			4,478.00
		Add 10%	447.80
			4,925.80
<b>SPECIAL NET</b>			
8 Rear door '70km/h' sticker - RH	1	25.00	25.00
9 Rear door '6pax' sticker - RH	1	25.00	25.00
			50.00
<b>LABOUR</b>			
10 To transfer RH rear door interior mechanism to new door	1	120.00	120.00
11 To check and rectify wiring system	1	80.00	80.00
12 To panel beat RH rear door pillar, RH taillamp panel, RH rear fender inner panel, to cut & weld RH rear fender, including replacement of parts and align where necessary, to refit and adjust the same	1	1,500.00	1,500.00
13 To putty and spray paint on affected areas	1	1,200.00	1,200.00
14 To supply artwork & paste sticker on RH rear door and RH body panel	1	1,800.00	1,800.00
			4,700.00

TOTAL S\$ 9,675.80

ADD GST @ 7% 677.31

GRAND TOTAL S\$ 10,353.11

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

SINGAPORE DOLLAR TEN THOUSAND THREE HUNDRED FIFTY-THREE AND CENTS ELEVEN ONLY

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : AIG ASIA PACIFIC INSURANCE PTE. LTD. 13/2/20  
78 SHENTON WAY #07-16  
AIG BUILDING  
SINGAPORE 079120

ATTN : MOTOR CLAIM DEPT  
TEL : 6419 3000

FAX : 6415 3723

YOUR REF NO :  
CLAIM TYPE : OWN DAMAGE  
ACCIDENT DATE : 13/01/2020

Not Notation  
Return Repair

6 days  
Rear oil

## ESTIMATE

NO : QUOT202002-000010(00)  
DATE : 12/02/2020  
POLICY NO : 999995580  
VEH REG NO : GBD6912J  
MAKE/MODEL : CITROEN DISPATCH 2.0 HDI  
MT6  
CHASSIS NO : VF7XSAHZ8EZ012466  
ENGINE NO : 10DYZG4090357  
REG. DATE : 2014

## Estimate Repair Cost to Vehicle No : GBD6912J

Description	Quantity	Unit Price	Amount
		S\$	S\$
<b>PARTS</b>			
1 Rear fender - RH	1-R	500/1,850.00	1,850.00 ✓
2 Taillamp assy - RH	1-R	250.00	250.00 ✓
3 Rear door - RH	1-R	250/980.00	980.00 ✓
4 Rear door hinges - RH	2	220.00	440.00 X R
5 Rear door hinge cover - RH	2	120.00	240.00 ✓
6 Rear bumper	1	680.00	680.00 ✓
7 Rear bumper side retainer - RH	1	38.00	38.00 ✓
			4,478.00
		Add 10%	447.80
			4,925.80
<b>SPECIAL NET</b>			
8 Rear door '70km/h' sticker - RH	1	25.00	25.00 15m
9 Rear door '6pax' sticker - RH	1	25.00	25.00 15m
			50.00 15m
<b>LABOUR</b>			
10 To transfer RH rear door interior mechanism to new door	1	120.00	120.00 60
11 To check and rectify wiring system	1	80.00	80.00 20
12 To panel beat RH rear door pillar, RH taillamp panel, RH rear fender inner panel, to cut & weld RH rear fender, including replacement of parts and align where necessary, to refit and adjust the same	1	1,500.00	1,500.00 800
13 To putty and spray paint on affected areas	1	1,200.00	1,200.00 600
14 To supply artwork & paste sticker on RH rear door and RH body panel	(Bill) 1	1,800.00	1,800.00 2
			4,700.00 2380
		TOTAL	S\$ 9,675.80
		ADD GST @ 7%	677.31
		GRAND TOTAL	S\$ 10,353.11

SINGAPORE DOLLAR TEN THOUSAND THREE HUNDRED FIFTY-THREE AND CENTS ELEVEN ONLY

3,305.02

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE



VINYL STICKERS . SIGNAGE . GARMENTS

DFM PTE LTD  
No. 53 Ubi Ave 1  
#03-45 Paya Ubi Industrial Park  
Singapore 408934  
Tel: (65) 6841 4295  
Fax: (65) 6842 3262  
www.dfm.com.sg

Operating Hours:  
10.30am ~ 8pm  
Mon ~ Sat  
Closed on Sunday & P.H

## Cash Sale

Business Reg. No. 200711120W

Cash Sale No: 9220

Date: 5/3/20

Signages ☐ Vinyls ☐ Others ☐  
Garments ☐ Prints ☐

Sold to: TONG LUCK AUTO P/L

Ordered By: YU CHING

ITEM	DESCRIPTION	QTY	UNIT PRICE	TOTAL
1	JUNGHEINRICH CITROEN DISPATCH			\$950
	STICKER REPAIR			
	* REAR RIGHT + DRIVER SIDE			
	* GBD 6412J			

Paid by cash / cheque: \_\_\_\_\_

Sub Total:

Total:

\$950/-

E. & O.E.

For DFM PTE LTD

Received the goods in good  
order & conditions

Goods sold are not refundable. Thank you for your business.





日美汽車私人有限公司

**JAE AUTO PTE LTD**

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

  
HOLDSCREEN GLASS  
Dept Direct: 6417 9781 / 6745 9929

Arrange By

Driver

*mm*



Dept Direct: 6306 8610

Dept Direct: 6205 9641

Dept Direct: 6417 9782



Dept Direct: 6417 9784

Dept Direct: 6417 9785

Dept Direct: 6417 9786

Dept Direct: 6417 9783

Wiper blade: NWB (Nippon Wiper blade), Selenia (Made in Korea)

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TONG LUCK AUTO PTE LTD

**CASH**

ATTN :

160 SIN MING DRIVE #07-01 SIN MING AUTOCITY

TAX INVOICE : AR202002-14960  
DATE : 28/02/2020  
CUSTOMER ID : CAS001  
VEH REG. NO. : GBD6912J  
TERMS : CASH  
PO NO. :  
PAGE NO. : Page 1 of 1  
CURR : SGD

SQ	STOCK ID	DESCRIPTION	QTY	U/PRICE	AMOUNT
1.	7410 AS DISPATCH 3	REAR BUMPER	1	680.00	680.00
2.	6350 AH DISPATCH 3	TAILLAMP RH	1	250.00	250.00
3.	8716 68 DISPATCH 3	HINGE MOULDING RH	2	120.00	240.00
4	7414 RJ DISPATCH 3	BUMPER BRACKET RR RH	1	38.00	38.00

SUB-TOTAL : 1,208.00  
ADD GST 7.00 % 84.56

E & OE

TOTAL AMOUNT SGD : 1,292.56

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : HUA

This is computer generated document.

No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Jan 2020		13 Feb 2020 14:39 <a href="#">Edit Adj Rpt</a>	<b>S\$4,488.80</b> <a href="#">Edit Estimates</a>	<b>S\$4,488.80</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
Insured:	<b>DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD.</b> , Co. Reg. No.: 199803778Z								
Vehicle Reg. No.:	<b>GBD6912J</b>	Date of Loss:	13/01/2020 22:00 - :59 <b>[57 Months and 18 Days From LTA Reg Date (Man Yr)]</b>						
Claim Type:	<b>OD / 4853558256SG</b>	Policy/Cover Note No.:	0999993937 (Comprehensive)						
		Excess:	S\$1,400.00						
Repairer:	<b>Tong Luck Auto Pte Ltd (HQ)</b> 160 Sin Ming Drive, #07-01 Sin Ming AutoCity, 575722 Sin Ming - Tel: 6250 0088								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (SG)</b> - Tel: 65-6419-3000 ... [Handled by <b>Chan, Yoke Shi</b> ] yokeshi.chan@aig.com								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>KENNETH KONG</b> ] ... <b>[Final Rpt due 24/02/2020]</b>								
Driver/Custodian:	MOHAMED ALI MUHAMMAD FAISAL (29 / Male), NRIC: S9082382E, Tel: +6596563758 Email: NOEMAIL								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
<ul style="list-style-type: none"> <li>AIG_SG (19/02/2020): Alert - Adj Mandate Approved (S\$5951.80) - GBD6912J - Claim Handler: Chan, Yoke ...</li> <li>AIG_SG (19/02/2020): GBD6912J / OD / 13/01/2020 / Coverage &amp; Excess update</li> </ul>									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									





## Claim Documents

\*GBD6912J (4853558256SG)

OD

Jan 13 2020 10:00PM


[DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD]

Tong Luck Auto Pte Ltd












<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a> <a href="#">Upload Video</a> <a href="#">Upload Audio</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/02/20 15:09	Adjuster Immediate Advice		Load HTM
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/02/20 09:03	General View		Load JPG
2	14/02/20 09:03	General View		Load JPG
3	14/02/20 09:03	General View		Load JPG
4	14/02/20 09:03	General View		Load JPG
5	14/02/20 09:03	General View		Load JPG
6	14/02/20 09:03	General View		Load JPG
7	14/02/20 09:03	General View		Load JPG
8	14/02/20 09:03	General View		Load JPG
9	14/02/20 09:03	General View		Load JPG
10	14/02/20 09:03	General View		Load JPG
11	14/02/20 09:03	General View		Load JPG
12	14/02/20 09:03	General View		Load JPG
13	14/02/20 09:03	General View		Load JPG
14	14/02/20 09:03	General View		Load JPG
15	14/02/20 09:03	General View		Load JPG
16	14/02/20 09:03	Odometer Reading		Load JPG
17	14/02/20 09:03	Chassis Number		Load JPG
18	12/03/20 14:26	BEFORE PAINT PHOTO		Load JPG
19	12/03/20 14:26	BEFORE PAINT PHOTO		Load JPG
20	12/03/20 14:26	Photo After Spray		Load JPG
<b>Documentation</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	18/02/20 14:22	Undertaking letter		Load JPG
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/02/20 15:04	USED CAR ADVERTISEMENT		Load PDF
2	13/02/20 15:04	Log card (if available)		Load PDF
3	17/02/20 11:37	ESTIMATE		Load PDF
4	12/03/20 16:11	PARTS INVOICE		Load PDF

## Linked Accident Report Documents






<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a> <a href="#">Upload Video</a> <a href="#">Upload Audio</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	14/01/20 18:05	Accident Statement	 Load HTM	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	14/01/20 18:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	14/01/20 18:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	14/01/20 18:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	14/01/20 18:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	14/01/20 18:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	14/01/20 18:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	14/01/20 18:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	14/01/20 18:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	14/01/20 18:05	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	14/01/20 18:05	Identification Card	 Load JPG	<input checked="" type="checkbox"/>
11	14/01/20 18:05	Driving License	 Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Ajax Mars Pte Ltd (Bukit Merah)	Thumbnail	Print
1	14/01/20 18:04	Sketch Plan	 Load TIF	
2	14/01/20 18:04	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>
3	14/01/20 18:04	Sketch Plan #3	 Load JPG	<input checked="" type="checkbox"/>
4	14/01/20 18:04	Sketch Plan #4	 Load JPG	<input checked="" type="checkbox"/>
5	14/01/20 18:04	Sketch Plan #5	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b> <span>Reset</span> <span>Save</span> <span>Print</span>
There are no document checklists configured.
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #08-16  
Singapore 079120

Our File No: CS/AIG20002533/KQD3S2  
Date: 12/03/2020

## REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD  
Date of Loss: 13/01/2020

Policy No: 0999993937  
Nature of Claim: OD Claim No: 4853558256SG

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	GBD6912J	Engine No:	10DYZG4090357
Make & Model:	CITROEN DISPATCH, 2.0 D I HDI AT (M)	Chassis No:	VF7XSAHZ8EZ012466
Reg. Date:	26/03/2015 (Man. Year: 2014)	Odometer:	125323 km
Colour:	White		
Engine Capacity:	1997 cc		
Market Value/New Car Price:	S\$41,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

## CONDITION OF TYRES

Front Tyre Size:	205/65 R16	Rear Tyre Size:	205/65 R16
Front Left Side:	Yokohama 8 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 8 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,975.80	2,108.80	2,867.00	57.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,700.00	2,380.00	2,320.00	49.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,675.80</b>	<b>4,488.80</b>	<b>5,187.00</b>	<b>53.61</b>
<b>- Excess (S\$)</b>	<b>1,400.00</b>	<b>1,400.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>8,275.80</b>	<b>3,088.80</b>	<b>5,187.00</b>	<b>62.68</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>579.31</b>	<b>216.22</b>	<b>363.09</b>	<b>62.68</b>
<b>Nett Amount (S\$)</b>	<b>8,855.11</b>	<b>3,305.02</b>	<b>5,550.09</b>	<b>62.68</b>

## INSPECTION

Date of Assignment:	13/02/2020		Tong Luck Auto Pte Ltd (HQ)
Date Inspected:	13/02/2020	Inspected At:	160 Sin Ming Drive, #07-01 Sin Ming AutoCity
Estimated Period of Repair:	6.0 days		Singapore 575722

Adjuster: KENNETH KONG

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILLAMP ASSY - RH (WCP)	Cracked	250.00 F	*250.00 F
2	2		*REAR DOOR HINGES - RH (WCP)	Repair	440.00 F	*- F
3	2		*REAR DOOR HINGES COVER - RH (WCP)	Dented / Missing	240.00 F	*240.00 F
4	1		*REAR BUMPER (WCP)	Cracked	680.00 F	*680.00 F
5	1		*REAR BUMPER SIDE RETAINER - RH (WCP)	Distorted	38.00 F	*38.00 F
6	1		*REAR DOOR - RH	Bent	1,078.00 FS	*250.00 FS
7	1		*REAR DOOR 70KM/H STICKER - RH	Necessary	25.00 FS	*15.00 FS
8	1		*REAR DOOR 6PAX STICKER - RH	Necessary	25.00 FS	*15.00 FS
9	1		*REAR FENDER - RH	Bent	2,035.00 FS	*500.00 FS
					<b>Sub Total (S\$)</b>	<b>4,811.00</b>
					<b>+ Margin on L,N Items 10.00/10.00% (S\$)</b>	<b>164.80</b>
					<b>Total Parts (S\$)</b>	<b>4,975.80</b>
						<b>1,988.00</b>
						<b>120.80</b>
						<b>2,108.80</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				0.00
1	1	*OD/TP Case (Insurer)	-	
Sub Total (S\$)			0.00	0.00

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO TRANSFER RH REAR DOOR INTERIOR MECHANISM TO NEW DOOR.	New	120.00	60.00
2	TO CHECK AND RECTIFY WIRING SYSTEM.	New	80.00	20.00
3	TO PANEL BEAT RH REAR DOOR PILLAR, RH TAILLAMP PANEL, RH REAR FENDER INNER PANEL, TO CUT & WELD RH REAR FENDER, INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME.	New	1,500.00	600.00
4	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS.	New	1,200.00	750.00
5	TO SUPPLY ARTWORK & PASTE STICKER ON RH REAR DOOR AND RH BODY PANEL.	New	1,800.00	950.00
Gross Labour Cost (S\$)			4,700.00	2,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >