

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd

Date: 12/02/2020

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLR2481u

CHASSIS NO : NSP1707060128

MAKE / MODEL : Toyota Sienta Hybrid1.5G CVT

DATE OF ACCIDENT : 13/01/2020

YOUR INSURED VEHICLE NUMBER :SLZ212B

MILEAGE : 235353 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	R/R door / DD	1PC	\$ 1,404.00	\$ 1,404.00
2	F/R door X R	1PC	\$ 1,840.00	\$ 1,840.00
3	R/R fender outer rubber moulding AP/SH	1PC	\$ 80.00	\$ 80.00
4	R/R door outer rubber moulding SCH	1PC	\$ 150.00	\$ 150.00
LIST TOTAL S\$:				\$ 3,474.00
25.00% DISCOUNT S\$:				\$ 868.50
				\$ 2,605.50

LABOUR CHARGES

1	To labour charge for removing R/R door and F/R door out to failitate replacement of damaged part.	\$ 1,000.00	400 450
2	To respray R/R fender, R/R door and F/R door	\$ 1,000.00	600
3	Transfer both doors mechanism	\$ 100.00	60
LABOUR TOTAL S\$:		\$ 2,100.00	
TOTAL S\$:		\$ 4,705.50	
7% GST		\$ 329.39	
GRAND TOTAL S\$:		\$ 5,034.89	

Repair day - 3 day.

P/P

before paint photo

Sun Pm (Lkl)

13/02/2020

TP with prejudice.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: