

NGS MOTORSPORT PTE LTD

Blk 10 Ang Mo Kio Industrial Park 2A #02-01 AMK AutoPoint Singapore 568047

Tel : 9695 5547 Fax: 6481 5727 e-mail : evelynnstrading@gmail.com

Reg No: 201812604N

14/02/2020

China Taiping Ins (S) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

Attn: Motor Claims Dept

RE: ACCIDENT ON 10/02/2020 @09:50HRS INVOLVING VEH NO: SKC385T & SLJ9660R
CLAIMS AGAINST SLJ9660R

We submit herewith our direct claim estimate quotation as follow:-
Replacement parts - Toyota Vios

1	Rear Boot Lid	/ BT	\$ 627.00	✓
1	Rear Bumper	/ n's	\$ 396.00	363.1
1	Rear Bumper Retainer Upp LH	/ ee.	\$ 42.50	✓
1	Rear Bumper Retainer Low LH		\$ 105.50	✓
1	Rear End Panel	/ Bue	\$ 577.50	✓
1	Rear End Panel Garnish	X NN	\$ 201.40	X
1	Luggage Compartment Panel	X repair.	\$ 639.50	X
1	Luggage Compartment Board	X NN	\$ 147.00	X
1	Cover, Room Partition	X	\$ 203.00	X
1	Board, Room Partition LH	/ CRA	\$ 154.50	✓
1	Weatherstrip, Trunk	/ Twi	\$ 133.00	✓
1	Striker, Luggage Compartment	X NN	\$ 23.00	X
2	Seal, Rear Bumper RH/LH	@\$49.00 NN X	\$ 98.00	X
1	Rear Fender LH	/ Bue	\$ 1,011.00	845.1
2	Rear Bumper Reflector RH/LH	@\$94.31 / n's	\$ 188.62	✓
1	Rear Fender Air Duct LH	/ ee.	\$ 49.50	✓
1	Rear Exhaust	X NN	\$ 399.50	X
2	Taillamp RH/LH	@\$243.20	\$ 486.40	243.2
2	Taillamp Gasket RH/LH	@\$28.50	\$ 57.00	20
			\$ 5,539.92	3349.52
			Less 25%	\$ 1,384.98
			\$ 4,154.94	2512.14

VEHICLE NO.: SKC385T

1	Reverse Sensor	/ MS	S.Nett	\$ 280.00	200
11	Clips, Luggage Compartment Trim @\$5.00	S.Nett	/ MS	\$ 55.00	20
4	Clips, Taillamp	/ MS	@\$4.50 S.Nett	\$ 18.00	9
1	Emblem "VIOS"	/ MS	S.Nett	\$ 54.80	36
1	RR Boot 'Badge'	/ MS	S.Nett	\$ 46.50	✓
2	Taillamp Clips RH/LH	X	@\$5.00 S.Nett	\$ 10.00	X
1	Rear No Plate c/w Casing	X MS	S.Nett	\$ 50.00	X
					311.5

To remove all damaged part with all necessary component/attachment
 Straighten chassis member, repair/reshape dented body panel..
 Replace damaged part. Refit into position.

\$ 1,500.00 1000

To transfer door mechanism

\$ 150.00 X NV

Remove/Replace fuel tank, to enable cut & weld rear fender LH

\$ 150.00 60

To spray painting

\$ 1,200.00 1000

Check wiring & light function

\$ 50.00 30

RR sealant 60 40

\$ 7,719.24
 7,899.24 2250

Any other parts which necessitate repair or renewal will incur additional charged.
 Please contact our Ms Evelyn @HP96955547 to arrange for survey. Thank you

Yours faithfully.

5073.64

NGS MOTORSPORT PTE LTD
 EVELYN NG

-20%: 4050

R & R windscreen 120

7 Days

Imp sum repair.

After repair photos.

Emo Qian - 82880282

14/2/2020.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: