

CS/TP 20002542/ Agf3n2

ASSIGNMENT

Smw 9632P

2019 Sept.

Controlled Code:

Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

CO / TP / W3 / TP RES / OO RES / EVA / RT / MV

Truck / Trailer ☐

To be used Vehicle No:

Make: Hyundai Avante Elite 1591

of Workshop no:

Colour: White AC Insured / Std / NI / NA

of

Sp Reading 7353 T/Radio: Insured / Std / NI / NA

Insured

Engine

Policy No:

C/No: KMHD841CML4977873.

Claims No:

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ Burnt

Is an insured:

Excess:

Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt ☐

(Client's Record)

Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt ☐

Make of Veli:

Modi: Nil ☒ (S/Rim) / ☐ STD A/Rim ☐

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Tyre Size F: 205/55R16 -

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kumho.

Est. or Market Value

Front

Rear

ICAC Accident Report Consistent? Yes or No

R/Bal 06 mm

R/Bal 06 mm

G/A / PR Seen Consistent? Yes or No

L/Bal 06 mm

L/Bal 06 mm

Est. Repair: 14 days Res: Yes or No

D.O.A. 13/02/20

Lien Sums: % Val: Yes or No

Survey held at CAS

CA / REV / REP. / 24 HRS

Des. of Damages ☒ (FR) / ☒ Rear / ☐ Q/S / ☐ N/S / ☐ U/C / ☐ Rooftop ☐

Date: Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Direct Asia Independent

SMW 9632P-X

US \$ 15100, 14 days (Red \$ 13040.63, 46%)

MV:

PV:

Nett:

RECEIVED 26 MAR 2020

Date/Time, File Path (C)



: Prel. Report

24/3/2020



: Final Report

Date/Time, File Path (C)

Days Of Repair: 14

Resurvey No. of Trip: 2

Survey Fee:

Transport:

Total Page:

☐ SBE log: 15☐ SBE log: 15☐ SBE log: 15☐ SBE log: 15

on behalf of

OSP

26/3/2020

Report Form:

Long Desc:

7P

15100

18x15=270

170+270

50

50+50

164

80

834

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/02/2020 11:44
Date Of Accident	12/02/2020 08:00
Exact Location Of Accident	MANDAI ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMN9632P
Insured/Policyholder	
Name Of Registered Owner	YEO BOON LENG MERVIN
NRIC No	SXXXX677I
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98768878
Alternative Phone No	OFFICE-98768878

Vehicle Particulars

Manufacturer	HYUNDAI
Model	AVANTE

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	P2333323
Cover Note Number	

Driver

Name of Driver	YEO BOON LENG MERVIN
NRIC No	SXXXX677I
Date Of Birth	09/12/1988
Occupation	INDOOR
Date Of Driving Pass	09/05/2012
Driving Experience	7 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98768878
Fax Number	
Contact Number	OFFICE-98768878
Email Address	NOEMAIL

Address	BLK 513B YISHUN ST 51 #12-363
Postcode	762513
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING STRAIGHT ON MANDAI ROAD. DUE TO THE HEAVY TRAFFIC, THE FRONT VEHICLE BRAKE AND STOPPED. I APPLIED MY BRAKE IMMEDIATELY AND MANAGED TO STOP IN TIME. SUDDENLY, I FELT A HUGE IMPACT FROM MY REAR WHICH CAUSED MY VEHICLE TO MOVE FORWARD AND HIT ONTO VEHICLE C.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLU4145L
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SMC5577A

Vehicle Make/Model/Colour

Details Of Properties

VEHICLE C

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Person's Signature
 Name:
 NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling straight on mandai road the
 to the heavy traffic the front vehicle brake and stopp I applied
 my brake immediately and managed to stop
 in time. Suddenly I felt a huge impact from
 my rear which caused my vehicle to move
 forward and hit onto vehicle C.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 Unit/Unit No.:

LETTER OF UNDERTAKING

I/We, Teo Boon Leng Merwin, the owner of vehicle no. SMMN9632P

My/Our Insurance is under M/s AXA Insurance Pte Ltd, I/we shall decide whether to claim under my/our Policy or against the Third Party and if the former shall submit such a claim to M/s AXA Insurance Pte Ltd with all relevant facts and documents within 14(fourteen) days of occurrence or discovery of damage.

My/Our Third Party claim is handle by my/our preferred workshop, Casgarage Pte Ltd

Signed and Acknowledge by:

S88A06713 UW
Nric no. & signature of policyholder

Company stamp

Date

**CAS GARAGE PTE LTD**

(Reg No: 201828067M)

1 KAKI BUKIT AVENUE 6, #02-22 AUTOBAY, SINGAPORE 417883

VEHICLE REPAIR ESTIMATE

Insurance Company: DIRECT ASIA INSURANCE

Xiao Chen.

Address: NO 20 ANSON ROAD
#08-01,S(079912)

Telephone: 65321818

Fax: 64231197

Email claim@directasia.com

Make/ Model : HYUNDAI AVANTE ELITE

Date: 12.02.2020

Chassis No : KMHD841CMLU977873

Vehicle No: SMN9632P

Date/Time of Accide 12.02.2020/0800

Date of Reg: 04.09.2019

Materials Cost/ Spare Parts Cost**TO BE COMPLETED BY SERVICE ADVISOR**

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$		FINAL PRICE \$
1	REAR BOOTLID <i>new</i>	1	\$ 1,853.60		\$ 1,853.60
2	REAR BOOTLID INNER LOCK <i>new</i>	1	\$ 185.70		\$ 185.70
3	REAR BOOTLID SMARTKEY ANTENNA <i>new</i>	1	\$ 197.50		\$ 197.50
4	REAR BOOTLID INNER TRIM <i>new</i>	1	\$ 195.80		\$ 195.80
5	REAR BOOTLID LATCH <i>new</i>	1	\$ 38.50		\$ 38.50
6	REAR BOOTLID LOGO	1	\$ 85.60		\$ 85.60
7	REAR NUMBER PLATE LAMPS <i>new</i>	2	\$ 98.70		\$ 197.40
8	REAR BOOTLID REFLECTORS <i>new</i>	2	\$ 498.70		\$ 997.40
9	REAR BOOTLID WEATHERSTRIP <i>new</i>	1	\$ 165.30		\$ 165.30
10	END PANEL <i>new</i>	1	\$ 657.80		\$ 657.80
11	END PANEL TOP GARNISH <i>new</i>	1	\$ 175.90		\$ 175.90
12	END PANEL BOOT RELEASE ANTENNA <i>new</i>	1	\$ 185.90		\$ 185.90
13	TAILAMPS <i>new</i>	2	\$ 758.60		\$ 1,517.20
14	TAILAMPS PANEL <i>new</i>	2	\$ 245.60		\$ 491.20
15	REAR BUMPER <i>Distorted</i>	1	\$ 659.49		\$ 659.49
16	REAR BUMPER NUMBER PLATE GARNISH <i>new</i>	1	\$ 98.50		\$ 98.50
17	REAR BLINDSPOT RADAR SENSOR LH <i>new</i>	2	\$ 1,245.80		\$ 2,491.60
18	REAR BUMPER LOWER <i>new</i>	1	\$ 496.30		\$ 496.30
19	REAR BUMPER LOWER COVER LH <i>new</i>	1	\$ 197.80		\$ 197.80
20	REAR BUMPER LOWER COVER RH <i>new</i>	1	\$ 156.30		\$ 156.30
21	REAR BUMPER RETAINERS <i>new</i>	2	\$ 85.90		\$ 171.80
22	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 256.80		\$ 513.60
23	REAR BUMPER REINFORCEMENT <i>new</i>	1	\$ 398.70		\$ 398.70
24	REINFORCEMENT BRACKETS(BOTTOM) <i>new</i>	3	\$ 76.80		\$ 230.40
25	REINFORCEMENT BRACKETS(TOP) <i>new</i>	2	\$ 76.80		\$ 153.60
26	REINFORCEMENT BRACKETS METAL <i>new</i>	2	\$ 198.80		\$ 397.60
27	REAR FENDER INNER TRIM <i>new</i>	2	\$ 238.70		\$ 477.40
28	REAR FENDER INNER COWLING <i>new</i>	1	\$ 165.90		\$ 165.90
29	REAR FENDER AIR DUCTS <i>new</i>	2	\$ 98.50		\$ 197.00
30	REAR SILENCER BOX <i>new</i>	1	\$ 756.20		\$ 756.20
31	SPARE TYRE TOP BOARD <i>new</i>	1	\$ 397.80		\$ 397.80

32	SPARE TYRE PANEL <i>Buckled</i>	1	\$ 798.60		\$ 798.60	✓
33	FRONT BUMPER <i>old</i>	1	\$ 785.80		\$ 785.80	✓
34	FRONT BUMPER NUMBER PLATE GARNISH	1	\$ 69.70		\$ 69.70	✓
35	FRONT BUMPER TOP BRACKET <i>old</i>	2	\$ 98.60		\$ 197.20	✓
36	FRONT BUMPER SIGNAL LAMP <i>new</i>	2	\$ 165.80		\$ 331.60	+
37	FRONT BUMPER RETAINER <i>new</i>	2	\$ 86.90		\$ 173.80	✓
38	FRONT BUMPER AIR GUIDE <i>new</i>	2	\$ 125.80		\$ 251.60	+
39	FRONT BUMPER SIDE STRIP <i>new</i>	2	\$ 92.60		\$ 185.20	+
40	FRONT BUMPER SIDE COVER <i>new</i>	2	\$ 98.60		\$ 197.20	+
41	FRONT BUMPER LOWER LIP <i>new</i>	1	\$ 265.20		\$ 265.20	+
42	FRONT ENGINE UNDER COVER <i>new</i>	1	\$ 356.80		\$ 356.80	+
43	FRONT BUMPER SPONGE <i>new</i>	1	\$ 225.60		\$ 225.60	✓
44	FRONT BUMPER LOWER STIFFENER <i>old</i>	1	\$ 175.20		\$ 175.20	✓
45	FRONT BUMPER REINFORCEMENT <i>old</i>	1	\$ 589.50		\$ 589.50	✓
46	FRONT BUMPER RADIATOR GRILLE <i>new</i>	1	\$ 798.50		\$ 798.50	✓
47	FRONT SUPPORT PANEL TOP GARNISH <i>old</i>	1	\$ 202.50		\$ 202.50	✓
48	FRONT HEADLAMP <i>new</i>	2	\$ 3,034.90		\$ 6,069.80	✓
49	FRONT HEADLAMP BRACKET <i>new</i>	2	\$ 98.60		\$ 197.20	+
50	FRONT FENDER INNER COWLING <i>Not New</i>	2	\$ 187.50		\$ 375.00	+
Total List Price Cost					\$ 27,150.79	
					\$ 21,720.63	

17942.79

1435423

PARTS DISCOUNT 20%

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$		FINAL PRICE \$	
1	REVERSE SENSORS <i>new</i>	1 SET	\$ 250.00		\$ 250.00	200
2	REAR NUMBER PLATE WITH CASING <i>new</i>	1 SET	\$ 50.00		\$ 50.00	✓
3	REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00		\$ 30.00	✓
4	END PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 30.00		\$ 30.00	10
5	REAR BOOTLID INNER TRIM CLIPS <i>new</i>	1 SET	\$ 30.00		\$ 30.00	+
6	END PANEL SEALANT <i>new</i>	2	\$ 80.00		\$ 80.00	60
7	REAR FENDER INNER TRIM CLIPS <i>new</i>	2 SET	\$ 60.00		\$ 60.00	+
8	REAR FENDER INNER COWLING CLIPS <i>new</i>	2 SET	\$ 60.00		\$ 60.00	+
9	REAR BUMPER LOWER COVER CLIPS <i>new</i>	1 SET	\$ 30.00		\$ 30.00	20
10	FRONT NUMBER PLATE WITH CASING <i>new</i>	1 SET	\$ 50.00		\$ 50.00	✓
11	FRONT BUMPER CLIPS <i>new</i>	1 SET	\$ 30.00		\$ 30.00	✓
12	FRONT BUMPER UNDERCOVER CLIPS <i>new</i>	1 SET	\$ 30.00		\$ 30.00	+
13	FRONT SUPPORT PANEL GARNISH CLIPS <i>new</i>	4 SET	\$ 30.00		\$ 30.00	20
Total Special Nett Items					\$ 620.00	

470

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS	\$ 2,200.00
1820	
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 2,200.00
1400	
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 200.00
TO CONDUCT WIRING CHECK ON THE REAR TAILLAMPS	\$ 120.00
TO CONDUCT WIRING CHECK ON THE FRONT HEADLAMPS	\$ 120.00
TO REMOVE/ REFIT & REPLACE REAR SENSORS AND DISTANCE SETTLING	\$ 180.00
TO REMOVE/ REFIT REAR INTERIOR UPHOLSTERY	\$ 180.00
TO CONDUCT WATER LEAKAGE TEST	\$ 120.00
TO REMOVE /REFIT AND REPLACE REAR SILENCER	\$ 150.00
TO APPLY UNDERCOATING TO THE AFFECTED AREAS	\$ 180.00
TO REMOVE AND REPLACE BOOTLID MECHANISM	\$ 150.00
Total Others Cost	\$ 1,400.00
3920	
GRAND TOTAL	\$ 28,140.63
28280.63	

CAS GARAGE PTE LTD

Person Incharge: Allan
Direct Contact: +65 8782 7171
Email: allan@casgarage.sg
Fax: +65 6509 9501

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lj
L/S 13/02/20

14 Days

total: 18744.23

L/S 15K

15K

15100



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CAS GARAGE PTE LTD			Ref : CS/TP20002542/Aqf3n2	
1 KAKI BUKIT AVENUE 6 #02-22 AUTOBAY @ KAKI BUKIT SINGAPORE 417883			Date : 30-03-2020	
ON BEHALF OF YEO BOON LENG MERVIN			Code : TP516	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.		Veh. Inspected		SMN 9632P
Policy No.		Coverage (\$)		0.00
Claim No.		Excess (\$)		0.00
Assign From		Assign Date		13/02/2020
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI AVANTE ELITE	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	KMHD841CMLU977873	Colour	WHITE	
Odometer	7353	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	KUMHO	6 mm	
L/H Front Tyre	205/55 R16	KUMHO	6 mm	
R/H Rear Tyre	205/55 R16	KUMHO	6 mm	
L/H Rear Tyre	205/55 R16	KUMHO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/02/2020	Inspection Date	13/02/2020	
Survey held at	CAS GARAGE PTE LTD NO. 1 KAKI BUKIT AVE 6. #02-22 AUTOBAY 417883 KAKI BUKIT			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		14 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMN 9632P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOTLID	NOT NECESSARY	1,853.60	-
1	REAR BOOTLID INNER LOCK	NOT NECESSARY	185.70	-
1	REAR BOOTLID SMARTKEY ANTENNA	NOT NECESSARY	197.50	-
1	REAR BOOTLID INNER TRIM	NOT NECESSARY	195.80	-
1	REAR BOOTLID LATCH	NOT NECESSARY	38.50	-
1	REAR BOOTLID LOGO	NOT NECESSARY	85.60	-
2	REAR NUMBER PLATE LAMPS @\$98.70	NOT NECESSARY	197.40	-
2	REAR BOOTLID REFLECTORS @\$498.70	NOT NECESSARY	997.40	-
1	REAR BOOTLID WEATHERSTRIP	NOT NECESSARY	165.30	-
1	END PANEL	DENTED	657.80	657.80
1	END PANEL TOP GARNISH	DEFORMED	175.90	175.90
1	END APNEL BOOT RELEASE ANTENNA	CRACKED	185.90	185.90
2	TAILLAMPS @\$758.60	CRACKED	1,517.20	1,517.20
2	TAILLAMPS PANEL @\$245.60	TO REPAIR SEE LABOUR	491.20	-
1	REAR BUMPER	DISTORTED	659.49	659.49
1	REAR BUMPER NUMBER PLATE GARNISH	DEFORMED	98.50	98.50
2	REAR BLINDSPOT RADAR SENSOR @\$1245.80	N/S CRACKED	2,491.60	1,245.80
1	REAR BUMPER LOWER	DEFORMED	496.30	496.30
1	REAR BUMPER LOWER COVER LH	DEFORMED	197.80	197.80
1	REAR BUMPER LOWER COVER RH	NECESSARY	156.30	156.30
2	REAR BUMPER RETAINERS @\$85.90	NECESSARY	171.80	171.80
2	REAR BUMPER REFLECTOR @\$256.80	CRACKED	513.60	513.60
1	REAR BUMPER REINFORCEMENT	CRACKED	398.70	398.70
3	REINFORCEMENT BRACKETS (BOTTOM) @\$76.80	DAMAGED	230.40	230.40
2	REINFORCEMENT BRACKETS (TOP) @\$76.80	DAMAGED	153.60	153.60
2	REINFORCEMENT BRACKETS METAL @\$198.80	BENT	397.60	397.60
2	REAR FENDER INNER TRIM @\$238.70	NOT NECESSARY	477.40	-
1	REAR FENDER INNER COWLING	NOT NECESSARY	165.90	-
2	REAR FENDER AIR DUCTS @\$98.50	NOT NECESSARY	197.00	-
1	REAR SILENCER BOX	BENT	756.20	756.20
1	SPARE TYRE TOP BOARD	NOT NECESSARY	397.80	-
1	SPARE TYRE PANEL	BUCKLED	798.60	798.60
1	FRONT BUMPER	DEFORMED	785.80	785.80

Report Ref No. CS/TP20002542/Aqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER NUMBER PLATE GARNISH	CRACKED	69.70	69.70
2	FRONT BUMPER TOP BRACKET @\$98.60	DEFORMED	197.20	197.20
2	FRONT BUMPER SIGNAL LAMP @\$165.80	NOT NECESSARY	331.60	-
2	FRONT BUMPER RETAINER @\$86.90	NECESSARY	173.80	173.80
2	FRONT BUMPER AIR DUCT @\$125.80	NOT NECESSARY	251.60	-
2	FRONT BUMPER SIDE STRIP @\$92.60	NOT NECESSARY	185.20	-
2	FRONT BUMPER SIDE COVER @\$98.60	NOT NECESSARY	197.20	-
1	FRONT BUMPER LOWER LIP	NOT NECESSARY	265.20	-
1	FRONT ENGINE UNDER COVER	NOT NECESSARY	356.80	-
1	FRONT BUMPER SPONGE	CRACKED	225.60	225.60
1	FRONT BUMPER LOWER STIFFENER	DEFORMED	175.20	175.20
1	FRONT BUMPER REINFORCEMENT	BENT	589.50	589.50
1	FRONT BUMPER RADIATOR GRILLE	CRACKED	798.50	798.50
1	FRONT SUPPORT PANEL TOP GARNISH	DEFORMED	202.50	202.50
2	FRONT HEADLAMP @\$3034.90	CRACKED	6,069.80	6,069.80
2	FRONT HEADLAMP BRACKET @\$98.60	NOT NECESSARY	197.20	-
2	FRONT FENDER INNER COWLING @\$187.50	NOT NECESSARY	375.00	-
	LESS 20% DISCOUNT		-5,430.16	-3,619.82
			21,720.63	14,479.27
	SPECIAL NETT ITEMS			
1	SET REVERSE SENSORS (SN)	DAMAGED	250.00	200.00
1	SET REAR NUMBER PLATE WITH CASING (SN)	BENT	50.00	50.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET END PANEL TOP GARNISH CLIPS (SN)	NECESSARY	30.00	10.00
1	SET REAR BOOTLID INNER TRIM CLIPS (SN)	NOT NECESSARY	30.00	-
2	END PANEL SEALANT (SN)	NECESSARY	80.00	60.00
2	SET REAR FENDER INNER TRIM CLIPS (SN)	NOT NECESSARY	60.00	-
2	SET REAR FENDER INNER COWLING CLIPS (SN)	NOT NECESSARY	60.00	-
1	SET REAR BUMPER LOWER COVER CLIPS (SN)	NECESSARY	30.00	20.00
1	SET FRONT NUMBER PLATE WITH CASING (SN)	BENT	50.00	50.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	30.00	30.00
1	SET FRONT BUMPER UNDERCOVER CLIPS (SN)	NOT NECESSARY	30.00	-
1	SET FRONT SUPPORT PANEL GARNISH CLIPS (SN)	NECESSARY	30.00	20.00
			760.00	470.00

Report Ref No. CS/TP20002542/Aqf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS, INCLUSIVE OF THE REPAIR OF TAILLAMPS PANEL.		2,200.00	1,800.00
	TO RESPRAY AFFECTED AREAS.		2,200.00	1,400.00
	TO TUFFCOAT AFFECTED AREA.		200.00	100.00
	TO CONDUCT WIRING CHECK ON THE REAR TAILLAMPS.		120.00	30.00
	TO CONDUCT WIRING CHECK ON THE FRONT HEADLAMPS.		120.00	30.00
	TO REMOVE/REFIT & REPLACE REAR SENSORS AND DISTANCE SETTLING.		180.00	60.00
	TO REMOVE/REFIT REAR INTERIOR UPHOLSTERY.		180.00	150.00
	TO CONDUCT WATER LEAKAGE TEST.		120.00	30.00
	TO REMOVE/REFIT AND REPLACE REAR SILENCER.		150.00	100.00
	TO APPLY UNDERCOATING TO THE AFFECTED AREAS.		180.00	120.00
	TO REMOVE AND REPLACE BOOTLID MECHANISM.		150.00	100.00
			5,800.00	3,920.00
	GRAND TOTAL		28,280.63	18,869.27
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			15,100.00

Report Ref No. CS/TP20002542/Aqf3n2

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.