

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHD 9166E - AIG

Andrea

6/11/14
 Lump Sum - \$3300 / 3 Pays

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD 9166E - Andrea
KL1LA69RJBB058006*
CHEVROLET
CHEVROLET EPICA 2.0
04.11.2014
AIG

		PART	LIST	
1	1	Rear Door RH ✓ Int	\$	1,133.00
2	1	Rear Door outer weatherstrip moulding RH ✓ suc	\$	85.00
3	1	Rear Fender RH X repair	\$	1,145.00
4	1	Rear Fender Inner Cowling RH ✓ suc	\$	76.60
5	1	Side Rocker Panel Garnish RH ✓ suc	\$	236.40
6	1	Rear Tail Lamp RH ✓ suc	\$	479.30
7	1	Rear Bumper ✓ Deformed	\$	1,202.00
8	1	Rear Bumper Side Retainer RH ✓ crn	\$	68.76
9	1	Rear Bumper Reflectors RH X suc	\$	119.74
			TOTAL	\$ 4,545.80
			10%	\$ 454.58
				\$ 4,091.22

2161.78

Special Nett

1Set	Rear Bumper Fastener Clip ✓ suc	\$	35.00
1 Set	Rear Fender Inner Cowling Clip ✓ suc crn	\$	60.00
1Set	Rear Bumper Parking Sensor ✓ shaded	\$	300.00
1	Door Sticker "6555-3333" ✓ suc	\$	80.00
2	Rear Windscreen Sealant X suc crn	\$	80.00
1	Rear Windscreen Inner Sponge Seal X suc crn	\$	100.00
1	Rear Tyre RH X suc	\$	360.00
1	Rear Wheel Rim RH X repair	\$	254.00
1	Hub Cup Rim X suc	\$	35.00

TOTAL \$ 1,304.00

417

TOTAL PARTS \$ 5,395.22

Panel Beating, Knocking And Straightening The
 Necessary Portion, Remove And Renewal Of
 Parts, Adjust And Realign The Same

\$

800
 2,800.00

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHD 9166E - AIG

Andrea

To Rust-Proofing Of The Affected Areas.	\$	220.00 ⁶⁰
Putty and Spray Painting Of The Affected	\$	2,700.00 ⁶⁰
To Check Electrical Lighting Concerned.	\$	170.00 x ⁶⁰
To Remove And Refit Rear W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00 x
To check steering geometry and computer wheel alignment	\$	220.00 x
To transfer of tire, rim and on wheel balancing.	\$	170.00 x
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00 x
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00 x
TOTAL	\$	6,790.00 ¹⁵²⁰
Over All Total	\$	12,185.22

REPAIR DAYS

10 DAYS

1/Calua (LKK)
 11 5/11/14 1525hrs.
 3 Repair Days.
 Longman Repair
 After repair photo