

INS. CASE OWNER:

1/1/15 CC 3/III150 20588 / Kwb3/

LKK:
IDAC:

Surveyor: Kenneth DOI: 1/22/2015 Date / Time: 1/12/2015
Registered in Merimen: 3/10/2015

Pre-assign / CCU / FTE




Insured Vehicle No. : SDQ 79004
Name of Insured : Chang Yu Hwa
Insured Tel No. : _____ HP: 90029281
Excess Sec II :SS _____ D.O.A: 1/12/2015

Claim No. : 2015/3273/KL
Policy No. : M474691
Make / Model : MERCEDES
Place of Accident : LOYANG AVE / PASIR RIS

Is driver the owner? (YES / NO) Nature of Accident : _____
If NO, Driver Name / Age : Gay Peng Rend OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO
Driver Tel No. : 83329168 (VL: YES / NO) Insured Liability : % Final ? Yes / No

SHC 5408P



INSRS: trans
WSP: cab
Tel : _____
Liability : _____
RMKS: _____



INSRS: _____
WSP: _____
Tel : _____
Liability : _____
RMKS: _____



INSRS: _____
WSP: _____
Tel : _____
Liability : _____
RMKS: _____



INSRS: _____
WSP: _____
Tel : _____
Liability : _____
RMKS: _____

Date/ Time		STAGE	DATE / PIC
7/12/15	SHC 5408P - CC 3/III15016683/Kwb3/ D.O.A = 1/10/15	Non-Reporting ltr (1st):	
11/12/15	SDQ 79004 - X	Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
9/12/15	seek 50% liability via merimen	Notification ltr (if non-pickup):	
14/12/15	liability 50% via merimen.	Call OI:	
28/12/15	Email to III to temp close FIP.	After call ltr to OI:	
		Documentation Check List: Handler Typist	
		Notification ltr (if non-pickup)	<input type="checkbox"/>
		After call ltr to OI:	<input type="checkbox"/>
		Authorisation To Act:	<input type="checkbox"/>
		Release Voucher:	<input type="checkbox"/>
		Final Repair Bill:	<input type="checkbox"/>
		Car Rental Invoice:	<input type="checkbox"/>
		Towing Invoice	<input type="checkbox"/>
		LTA / GIA :	<input type="checkbox"/>
		Medical Bill:	<input type="checkbox"/>
		PIR:	<input type="checkbox"/>
		Mandate/Reject Instruction:	<input type="checkbox"/>
		LOD	<input type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/>
		Post-Repair Photos:	<input type="checkbox"/>
		Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____
Repair Cost: S\$ _____ (_____ days) Reduction: _____ % Email Call

FINAL SETTLEMENT Date/Time: _____ Confirm with: _____ Email Call
Final Liability: % 50 (Agreed / Assessed) BOLA S/N No. : NOIC
Repair Cost: S\$ _____
Loss of Rental (LOR): S\$ _____ (_____ days)
Loss of Use (LOU): S\$ _____ (\$ x _____ days)
Loss of Income (LOI): S\$ _____ (\$ x _____ days)
LOR only LOU only LOR + LOU LOR + LOI [Tick only one]
GIA/LTA Search: S\$ _____
Medical: S\$ _____
Disbursement: S\$ _____ (e.g. Tow/ Independent)
Legal Cost: S\$ _____
Total: S\$ _____ Global Sum S\$: _____
1) Claim status: Normal/Reject/Private Settle
2) Report Format: temp close WIP
3) Survey fee: \$ 450.00

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call
Payee 1: S\$ _____ Name 1: _____
Payee 2: (Strike if N.A.) S\$ _____ Name 2: _____
Payee 3: (Strike if N.A.) S\$ _____ Name 3: _____

ASS. REC. BY:

REF: TE /

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Trans Cab

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 02 days Res.: Yes or No

Lum Sum: 1.84 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SHC 5408P Yr Regn: 11, 14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Renault Latitude c.c. 1995

Colour A. white/Red A/C: Insured / Std / NI / NA

Sp. Reading 100460 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: VIF1ABL154UC 279611

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NII / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Renold

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 9 mm

L/Bal. 7 mm L/Bal. 9 mm

D.O.A. 1/12/15 D.O.I. 1/12/15

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>1/12</u>	<u>Est not ready</u>
<u>3/12</u>	<u>8:1944.66 Faxed</u>
<u>4</u>	<u>File sent to Customer</u>
<u>31/3</u>	<u>8:1944.66 Car Insured Jarnine (2x 132.68 + 80.00)</u>
	<u>(Red-# 1666.98)</u>
	<u>89%</u>

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:	
Transportation:	
\$ + RS. SI	
Photos	
Others	
TOTAL	

Report Format: _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CC3/III15020588/Kwb3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 03-12-2015	
		Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SDQ 7900U	Veh. Inspected	SHC 5408P
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	03/12/2015
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	01/12/2015	Inspection Date	01/12/2015
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO. 42 SUNGEI KADUT ST 1 SINGAPORE 729346		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHC 5408P - III

Not Authored
1-B1
B1944.66
Resin B4 paint
ROEL

Vehicle No.: **SHC 5408P - ROEL**
 Chassis No.: VF1ABL15AUC279611
 Vehicle Make: RENAULT
 Vehicle Model: LATITUDE
 Date of Accident : 01.12.15
 Third Party Insurer : **III**

		PART		LIST
1	1	BUMPER COVER REAR	\$	<i>Bul/lat</i> 852.66 ✓
2	1	BUMPER LOWER REAR	\$	<i>Del/lat</i> 591.41 ✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sm</i> 87.29 X
4	1	BUMEPR BRACKET SIDE RH REAR(Taillamp lower)	\$	<i>Sm</i> 104.59 X
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sm</i> 34.61 X
6	1	BUMPER REFLECTOR RH	\$	<i>See</i> 33.55 X
7	1	BUMEPR BRACKET SIDE LH REAR(Taillamp lower)	\$	<i>Sm</i> 104.59 X
8	1	BUMEPR RETAINER LH REAR	\$	<i>Sm</i> 34.61 X
9	1	BUMPER REFLECTOR LH	\$	<i>Sm</i> 33.55 X
10	1	BUMPER BEAM REAR	\$	<i>R</i> 598.09 X
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 173.81 X
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 173.81 X
13	1	BOOT REAR	\$	<i>R</i> 2,209.75 X
14	1	BOOT FINISHER (Moulding)	\$	<i>Sm</i> 429.90 X
15	1	BOOT WHEATERSTRIP	\$	<i>Sm</i> 248.50 X
16	1	BOOT REFLECTOR LAMP RH	\$	<i>Sm</i> 379.50 X
17	1	BOOT REFLECTOR LAMP LH	\$	<i>Sm</i> 379.50 X
18	1	BOOT BADGE 'RENAULT'	\$	<i>Sm</i> 173.35 X
19	1	BOOT BADGE	\$	<i>Sm</i> 173.35 X
20	1	BOOT SWITCH	\$	<i>See</i> 107.78 X
21	1	BOOT LOCK	\$	<i>R</i> 155.90 X
22	1	BOOT LOCK CATCH	\$	<i>R</i> 72.00 X
23	1	TAILLAMP RH	\$	<i>Sm</i> 425.04 X
24	1	TAILLAMP LH	\$	<i>Sm</i> 425.04 X
25	1	OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,132.13 X
26	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sm</i> 311.20 X
27	1	EXHAUST REAR	\$	<i>R</i> 5,760.00 X
28	1	EXHAUST CAP REAR	\$	<i>R</i> 177.30 X

TOTAL	\$	15,382.81
10%	\$	1,538.28
	\$	13,844.53

Special Nett

1	ISET	PARKING AID	\$	Sw	600.00 X
2	ISET	REAR BUMPER CLIP	\$	Sw	66.00
3	ISET	BUMPER BRACKET CTR CLIP	\$	Sw	33.00
4	ISET	BUMEPR BRACKET SIDE CLIP RH RR	\$	Sw	10.00 X
5	ISET	BUMEPR RETAINER RH CLIP RR	\$	Sw	20.00 X
6	ISET	BUMEPR BRACKET SIDE CLIP LH RR	\$	Sw	10.00 X
7	ISET	BUMEPR RETAINER CLIP LH RR	\$	Sw	20.00 X
8	ISET	BUMPER LOWER REAR CLIP	\$	Sw	66.00
9	1	EXHAUST MOUNTING REAR	\$	Sw	17.82 X
10	ISET	OUTER PANEL REAR (End Panel)TRIM CLIP	\$	Sw	30.00 X
11	ISET	BOOT FINISHER CLIP	\$	Sw	24.20 X
12	1	BOOT STICKER "Trans-cab"	\$	Sw	30.00 X
13	1	BOOT STICKER "6555-3333"	\$	Sw	30.00 X

TOTAL	\$	957.02
TOTAL PARTS	\$	14,801.55

Putty And Spray Painting Of The Affected Portion. \$ 1,500.00 *2000*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same \$ 1,400.00 *2000*

To Rust-Proofing Of The Affected Areas. \$ *Sw* 170.00 X

To reinstall rear bumper parking sensor. \$ 170.00 *600*

To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe. \$ *Sw* 170.00 X

TOTAL	\$	3,410.00
Over All Total	\$	18,211.55

LKK Auto Consultants hence
 the Repairer of the following
 • To resurvey before/after spray painting
 • To display damaged part(s) during
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice"
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

(PARTS BY PARTS)
Repair Days

Acknowledged by Repairer
 Signature:
 Date:

5 Days

2 days

View Received Message

This mail is associated with :

***SHC5408P (MC2015/3633/KL)**
[SDQ7900U]

TP
TRANS-CAB SERVICES PTE LTD
Dec 1 2015 9:00AM

[-]
Trans-cab Auto Services Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on **10/12/2015 16:09 PM**.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$0.00) - SHC5408P - Claim Handler: Lalitha Krishhan

Approved:0.00:Versions by drivers conflicting: ID claim TP reversed and TP claim Head to rear collision. We agree to direct settlement at liability of 50%

DOCUMENTS SUMMARY

There are no documents.

Vivian Lau (LKKAuto)

From: Vivian Lau (LKKAuto)
Sent: Tuesday, 28 February, 2017 7:31 PM
To: 'Lalitha Krishnan - III'
Cc: 'Motor Claim - III'; Zayyer (LKKAuto)
Subject: PODS III Ref: MC2015/3633/KL LKK Ref: CC3/III15020588/Kwb3 Accident on 01/12/2015 involving SDQ 7900U (India) and SHC 5408P (TP)

PODS III Ref: MC2015/3633/KL LKK Ref: CC3/III15020588/Kwb3 Accident on 01/12/2015 involving SDQ 7900U (India) and SHC 5408P (TP)

Dear Lalitha,

We refer to the above matter.

Be informed that till date TP's repairer had finalised with our surveyor since 01/12/2015 after inspection .

TP's repairer did not submit the LOD until now. In view of no further development, we will proceed to temporary close the file and submit the report to your office.

If any new development in future, we will keep you informed for an update and follow up the matter accordingly.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	03 Dec 2015 Edit Reg		01 Dec 2015 00:00 Edit Adj Rpt	S\$1,944.66 Edit Estimates	S\$1,944.66 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All																				
CLAIM SUBFOLDER DETAILS				[Created by adjuster]																				
Insured:	CHANG YU HWA, Co. Reg. No.: S2204885F																							
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K																							
Vehicle Reg. No.:	SHC5408P	Date of Loss:	01/12/2015 09:00 - :59																					
Claim Type:	TP / MC2015/3633/KL	Policy/Cover Note No.:	M474641																					
Vehicle Reg. No. (Insured):	SDQ7900U	Policy No. (Claimant):	VPX/P1680520																					
		Excess:																						
Repairer:	Trans-cab Auto Services Pte Ltd (HQ) No. 42 Sungei Kadut St 1, 729346 Sungei Kadut - Tel: 62876666																							
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Lalitha Krishnan - 6347 6139]																							
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288																							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 14/12/2015]																							
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail																			
<ul style="list-style-type: none"> III_SG (10/12/2015): Alert - Adj Mandate Approved (S\$0.00) - SHC5408P - Claim Handler: Lalitha Krishh... 																								
<div style="border: 1px solid black; padding: 5px;"> <p>ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete</p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th>Due Date</th> <th>Priority</th> <th>Type</th> <th>Task Group</th> <th>Subject</th> <th>Handler</th> <th>Assigned By</th> <th>Completed On</th> <th>Created On</th> <th>Done?</th> </tr> </thead> <tbody> <tr> <td colspan="10">No results.</td> </tr> </tbody> </table> </div>					Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	No results.									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?															
No results.																								

Claim Documents

***SHC5408P (MC2015/3633/KL)**
[SDQ7900U]
TP
TRANS-CAB SERVICES PTE LTD
Dec 1 2015 9:00AM
[CHANG YU HWA]
Trans-cab Auto Services Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View Use Viewer ▼	
Photos/Images						3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	01/03/17 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
2	01/03/17 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
3	01/03/17 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
4	01/03/17 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
5	01/03/17 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
6	01/03/17 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
7	01/03/17 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
8	01/03/17 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
9	01/03/17 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
10	01/03/17 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
11	01/03/17 12:08	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>		
12	01/03/17 12:08	General View		Load JPG	<input checked="" type="checkbox"/>		
13	01/03/17 12:08	Chassis Number		Load JPG	<input checked="" type="checkbox"/>		
Documentation						1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print		
1	03/12/15 14:24	TP ESTIMATE- MARKED		Load PDF			
2	03/12/15 14:30	TP GIA REPORT		Load PDF			
3	28/02/17 19:31	Email to III to temporary close 28.2.17 SHC 5408P		Load PDF			
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print		
1	04/12/15 15:56	Singapore Accident Statement -0 IV		Load PDF			

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
<div style="border: 1px solid gray; width: 100%; height: 100%;"></div>	
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III15020588/KWB3Q2

Date: 02/03/2017

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	M474641
Claimant Vehicle No :	SHC5408P	Insured Vehicle No :	SDQ7900U
Date of Loss:	01/12/2015	Nature of Claim:	TP
		Claim No:	MC2015/3633/KL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC5408P	Engine No:	M9R8839C002045
Make & Model:	RENAULT LATITUDE, 2.0 D dCi (A)	Chassis No:	VF1ABL15AUC279611
Reg. Date:	04/11/2014 (Man. Year: 2014)	Odometer:	100460 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Rovelo 7 mm	Rear Left Side:	Rovelo 9 mm
Front Right Side:	Rovelo 7 mm	Rear Right Side:	Rovelo 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	14,801.55	1,464.66	13,336.89	90.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,410.00	480.00	2,930.00	85.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	18,211.55	1,944.66	16,266.89	89.32
+ GST 7.00/7.00% (S\$)	1,274.81	136.13	1,138.68	89.32
Nett Amount (S\$)	19,486.36	2,080.79	17,405.57	89.32

INSPECTION

Date of Assignment:	01/12/2015	
Date Inspected:	01/12/2015	Inspected At: Trans-cab Auto Services Pte Ltd (HQ) No. 42 Sungei Kadut St 1 Singapore 729346
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 02 Mar 2017)
Parts: 143	RENAULT LATITUDE 2.0 D dCi (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHC5408P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled / Dented	852.66 FL	*852.66 FL
2	1		*BUMPER LOWER REAR	Dented / Cut	591.41 FL	*591.41 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	87.29 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR (TAILLAMP LOWER)	Serviceable	104.59 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	34.61 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	33.55 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR (TAILLAMP LOWER)	Serviceable	104.59 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	34.61 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	33.55 FL	*- FL
10	1		*BUMPER BEAM REAR	Repair	598.09 FL	*- FL
11	1		*BUMPER BEAM BRACKET LH REAR	Repair	173.81 FL	*- FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	173.81 FL	*- FL
13	1		*BOOT REAR	Repair	2,209.75 FL	*- FL
14	1		*BOOT FINISHER (MOULDING)	Serviceable	429.90 FL	*- FL
15	1		*BOOT WEATHERSTRIP	Serviceable	248.50 FL	*- FL
16	1		*BOOT REFLECTOR LAMP RH	Serviceable	379.50 FL	*- FL
17	1		*BOOT REFLECTOR LAMP LH	Serviceable	379.50 FL	*- FL
18	1		*BOOT BADGE RENAULT	Not Necessary	173.35 FL	*- FL
19	1		*BOOT BADGE	Not Necessary	173.35 FL	*- FL
20	1		*BOOT SWITCH	Serviceable	107.78 FL	*- FL
21	1		*BOOT LOCK	Repair	155.90 FL	*- FL
22	1		*BOOT LOCK CATCH	Repair	72.00 FL	*- FL
23	1		*TAILLAMP RH	Serviceable	425.04 FL	*- FL
24	1		*TAILLAMP LH	Serviceable	425.04 FL	*- FL
25	1		*OUTER PANEL REAR (END PANEL)	Repair	1,132.13 FL	*- FL
26	1		*OUTER PANEL REAR (END PANEL) TRIM	Serviceable	311.20 FL	*- FL
27	1		*EXHAUST REAR	Repair	5,760.00 FL	*- FL
28	1		*EXHAUST CAP REAR	Repair	177.30 FL	*- FL
29	1		*SET PARKING AID	Serviceable	600.00 FS	*- FS
30	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
31	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
32	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
33	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
34	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
35	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
36	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
37	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
38	1		*SET OUTER PANEL REAR (END PANEL) TRIM CLIP	Not Necessary	30.00 FS	*- FS
39	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
40	1		*BOOT STICKER TRANS-CAB	Not Necessary	30.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
41	1		*BOOT STICKER 6555-3333	Not Necessary	30.00 FS	*- FS	
			F=Franchise part, S=SpcNett, L=ListItemDisc				
					Sub Total (S\$)	16,339.83	1,609.07
					- List Item Discount on L Items 10.00/10.00% (S\$)	1,538.28	144.41
					Total Parts (S\$)	14,801.55	1,464.66

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,500.00	220.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	1,400.00	200.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO DROP REAR EXHAUST BOX ,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
Gross Labour Cost (\$\$)			3,410.00	480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >