

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHC 5408P - III

Not Autho **ROEL**
1-B1
81944.66
Resurvey B4 paint

Vehicle No.: **SHC 5408P - ROEL**
 Chassis No.: VF1ABL15AUC279611
 Vehicle Make: RENAULT
 Vehicle Model: LATITUDE
 Date of Accident : 01.12.15
 Third Party Insurer : **III**

		PART		LIST
1	1	BUMPER COVER REAR	\$	<i>Bul/nt</i> 852.66 ✓
2	1	BUMPER LOWER REAR	\$	<i>nd/nt</i> 591.41 ✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>sn</i> 87.29 X
4	1	BUMEP R BRACKET SIDE RH REAR(Taillamp lower)	\$	<i>sn</i> 104.59 X
5	1	BUMEP R RETAINER RH REAR	\$	<i>sn</i> 34.61 X
6	1	BUMPER REFLECTOR RH	\$	<i>see</i> 33.55 X
7	1	BUMEP R BRACKET SIDE LH REAR(Taillamp lower)	\$	<i>sn</i> 104.59 X
8	1	BUMEP R RETAINER LH REAR	\$	<i>sn</i> 34.61 X
9	1	BUMPER REFLECTOR LH	\$	<i>sn</i> 33.55 X
10	1	BUMPER BEAM REAR	\$	<i>R</i> 598.09 X
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 173.81 X
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 173.81 X
13	1	BOOT REAR	\$	<i>R</i> 2,209.75 X
14	1	BOOT FINISHER (Moulding)	\$	<i>sn</i> 429.90 X
15	1	BOOT WHEATERSTRIP	\$	<i>sn</i> 248.50 X
16	1	BOOT REFLECTOR LAMP RH	\$	<i>sn</i> 379.50 X
17	1	BOOT REFLECTOR LAMP LH	\$	<i>sn</i> 379.50 X
18	1	BOOT BADGE 'RENAULT'	\$	<i>sn</i> 173.35 X
19	1	BOOT BADGE	\$	<i>sn</i> 173.35 X
20	1	BOOT SWITCH	\$	<i>see</i> 107.78 X
21	1	BOOT LOCK	\$	<i>R</i> 155.90 X
22	1	BOOT LOCK CATCH	\$	<i>R</i> 72.00 X
23	1	TAILLAMP RH	\$	<i>sn</i> 425.04 X
24	1	TAILLAMP LH	\$	<i>sn</i> 425.04 X
25	1	OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,132.13 X
26	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>sn</i> 311.20 X
27	1	EXHAUST REAR	\$	<i>R</i> 5,760.00 X
28	1	EXHAUST CAP REAR	\$	<i>R</i> 177.30 X
TOTAL			\$	15,382.81
10%			\$	1,538.28
			\$	13,844.53

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHC 5408P - III

ROEL

Special Nett

1	1SET	PARKING AID	\$	Sm 600.00 X
2	1SET	REAR BUMPER CLIP	\$	nn 66.00 ✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	nn 33.00 ✓
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	nn 10.00 X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	nn 20.00 X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	nn 10.00 X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	nn 20.00 X
8	1SET	BUMPER LOWER REAR CLIP	\$	nn 66.00 ✓
9	1	EXHAUST MOUNTING REAR	\$	Sm 17.82 X
10	1SET	OUTER PANEL REAR (End Panel)TRIM CLIP	\$	nn 30.00 X
11	1SET	BOOT FINISHER CLIP	\$	nn 24.20 X
12	1	BOOT STICKER "Trans-cab"	\$	nn 30.00 X
13	1	BOOT STICKER "6555-3333"	\$	nn 30.00 X

TOTAL	\$	957.02
TOTAL PARTS	\$	14,801.55

Putty And Spray Painting Of The Affected Portion. \$ 1,500.00 *2200*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same \$ 1,400.00 *2000*

To Rust-Proofing Of The Affected Areas. \$ *nn* 170.00 X

To reinstall rear bumper parking sensor. \$ 170.00 *600*

To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe. \$ *nn* 170.00 X

TOTAL	\$	3,410.00
Over All Total	\$	18,211.55

5 Days

LKK Auto Consultants henceforth the Repairer of the following

- To resurvey before/after spray painting
- To display damaged part(s) during
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

(PARTS BY PARTS) Repair Days

Acknowledged by Repairer
 Signature:
 Date: