

6 AIG

Not Authorized
2/1/2020
960/3 days



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring
#08-1339 Singapore 470130
Tel: 9450 7920
zoomautowerks@gmail.com

Car Number: SKQ7188B

Date: 13/02/2020

Model : OPEL INSIGNIA

Damaged Area: (Front RH Portion Damaged)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

S.N-600

L-360

960

Parts / Material :

	Quantity			
1 Front Bumper		\$	11	2,860.00 X
2 Front Bumper Fog Lamp Bracket RH		\$	11	180.00 X
3 Front Bumper Fog Lamp RH		\$	11	380.00 X
4 Front Bumper Garnish RH		\$	11	270.00 X
5 Front Bumper Inner Sponge		\$	11	280.00 X
6 Front Bumper Lower Arm		\$	11	240.00 X
7 Front Bumper Lower Centre Grille		\$	11	320.00 X
8 Front Bumper Reinforcement		\$	11	850.00 X
9 Front Bumper Retainer RH		\$	11	150.00 X
10 Front Bumper Tow Hook Garnish		\$	11	68.00 X
11 Front Bumper Clips		\$	11	60.00 X
12 Front Fender RH		\$	11	1,480.00 X
13 Front Fender Inner Shield RH		\$	11	320.00 X
14 Front Fender Inner Shield Clips		\$	11	60.00 X
15 Front Fender Lamp RH		\$	11	140.00 X
16 Front Fender Bracket RH		\$	11	110.00 X
17 Front Headlamp RH		\$	11	2,680.00 X
18 Front Support Panel		\$	11	1,450.00 X
19 Front Door RH		\$	11	Repair X

Parts : \$ 11,898.00

Less Parts 10% : \$ 1,189.80

Total Parts : \$ 10,708.20

Special Net Items :

Front Rim RH	\$	car/tyr	1,680.00 600 S.N
Front Tyre RH	\$	11	650.00 X
Front Sensor RH	\$	11	420.00 X
Front Angle Sensor RH	\$	11	370.00 X
Radiator Coolant	\$	11	180.00 X

Total S/N Parts : \$ 3,300.00

Labour :

To Remove, Repair & Renew Affected Accident Areas	\$	1,200.00 100
To Putty, Spray Paint on Affected Accident Areas	\$	1,100.00 200
To Check & Re-Connect all electrical wiring	\$	11 50.00 X
To Remove, Install & Conduct Radiator Pressure Leakage Test	\$	11 200.00 X
To Remove, Install AC Condenser & Top Up Gas	\$	11 200.00 X
To Conduct Wheel Alignment	\$	150.00 60

To Conduct Diagnostic & Reset Engine Mangement
To Re-position Front Sensor & Angle Sensor
To Rust Proof Affected Areas

\$	17	450.00	X
\$	17	200.00	X
\$	17	150.00	X
Total Labour :		\$	3,700.00

TOTAL PARTS : \$ 10,708.20
TOTAL SPECIAL NET ITEM : \$ 3,300.00
TOTAL LABOUR : \$ 3,700.00
TOTAL REPAIR COST : \$ 17,708.20

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM :

RECOMMENDED NUMBER OF DAYS :

SURVEY BY / SURVEYOR FIRM :

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :

FINALISED AMOUNT :

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: