

ASSIGNMENT

From: _____ Date: 17/11/2020

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SCX 7973J

at Workshop m/s Comfortdeligno

of 320 ulbi Road 3

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: 3.00p.m to 4.00p.m

Veh No: SCX 7973J Yr Regn: 18/110/2003

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: T. wish c.c. 1774

Colour: silver A/C: Insured / Std / NI / NA

Sp. Reading: 275758/1 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2NE100084363

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or _____

Brake: Inorder / Jammed / Leaked / Burnt or _____

Modi: Nil / S/Rim / STD A/Rim or _____

Tyre Size: F: 195/65/15

R: 1 1

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front Rear

R/Bal. 6 Firestone mm R/Bal. 6 Firestone mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 8/2/20 D.O.I. 17/2/20

Survey held at comfortdeligno

Des. of Damages: (Fr) / Rear / (O/S) / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Bal. or Market Value: _____

IDAC Accident Rport: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS imp'

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
	<u>tinien@sparkcarcare * DO DINT hv Estimate case</u>
	<u>Tinie 6848 5726 Hack Ann</u>
	<u>Shon 6848 5725 PLS check parts prices.</u>
	<u>MV - 3/000 L/S \$ 1,550.00/3 DAYS, FINALIZED WITH TINIE 19/08/20</u>
	<u>PV - 77996 (\$ 2,761.30 RED - 64%) Celine 19/08/2020</u>
	<u>NV - 3000</u>

Date/Time, File Pass to? 19/08/2020

1) TYPIST : Preli. Report : Final Report

Date/Time, File Return to? _____

2) _____

Days Of Repair: 3

Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Survey Fee:	
Transportation:	
S + RS, SI	
Photos	
Others	
TOTAL	

Report Format : _____

Lump sum / I.B.I: (\$ L/S \$ 1,550.00)

19/2

2223



ComfortDelGro Engineering

320 UBI ROAD 3 SINGAPORE 408649

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TP

Vehicle No. : SCX7973J

Make & Model : TOYOTA WISH

Year of Manufacture : 2003

Chassis No. : ZNE100084363

Ins Company : _____

Engine No. : 1ZZ1554370

Excess : _____

Policy No. : _____

Date of Accident : 08/02/2020

Time of Accident : 23.00

Suggested Days of Repair : _____

In-house Vehicle Assessor

Repair Estimates

Case Owner : _____

Signature : _____

Parts (a) Cost / List Price Items \$ 3,548.41

Contact No

Plus/Less 25% \$ 887.10

68485725 - JOHARI

Total of Cost / List \$ 2,661.30

(b) Nett Price Items \$ -

Less _____

Total of Nett Item _____

(c) Special Nett Items \$ -

Total Parts Cost (Appendix A) \$ 2,661.30

Labour (Appendix B) \$ 1,650.00

Total Repair Cost \$ 4,311.30

The above total will be subjected to 7% G.S.T.

Name of Surveyor : _____

Company : _____

Survey conducted on : _____ at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : _____ day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : _____ Date: _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
TEL :68438723/68438736 Fax:67436072

Spare Parts

Vehicle No : SCX7973J Case Owner : JOHARI

Make & Model : TOYOTA WISH Year Manufacture : 2003

Chassis No : ZNE100084363 Engine No : 1ZZ1554370

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N
1	RH HEADLAMP ✓ <i>CR4</i>	1		\$ 930.55	<i>798</i>	
2	RH HEADLAMP LOWER BRACKET X (<i>not use</i>)	1				
3	FRONT BUMPER ✓ <i>CR4</i>	1		\$ 1,878.79	<i>565</i>	
4	FRONT BUMPER CLIP'S ✓ <i>new</i>	<i>15</i> / <i>1 set</i>		\$ 60.00	<i>25</i>	
5	FRONT BUMPER SIDE RETAINER RH ?	1		\$ 79.78	✓ <i>CR4</i>	<i>4/18/20</i>
6	FRONT BUMPER REINFORCEMENT X (<i>R</i>)	1		\$ 395.15		<i>CR4</i>
7	FRONT BUMPER SPONGE X (<i>svc</i>)	1		\$ 162.14		<i>CR4</i>
8	FOG LAMP COVER RH ✓ <i>CR3</i>	1		\$ 42.00	✓	
9						
10						
11					<i>1,509.78</i>	
12					<i>- 25%</i>	
13					<i>1,132.34</i>	
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

Spark Car Care

ComfortDelGro Engineering Pte Ltd

320 UBI ROAD 3 SINGAPORE 408649

Tel: 68438723/68438736 FAX : 67436072

Labour

Vehicle No. : SCX7973J Case Owner : JOHARI
 Make & Model : TOYOTA WISH Year of Manufacture : 2003

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING , WIRE SOCKET ETC , REMOVE AND REINSTALL DAMAGE PARTS , TEST AND RETIFY FOR PROPER FUNCTIONING .	\$100.00	30
2	TO KNOCK & REPAIR RH FENDER INNER PANEL , FRONT BONNET , RADIATOR SUPPORT PANEL AND AFFECTED AREA.	\$550.00	300 400
3	TO PUTTY & SPRAY PAINT RH FENDER , INNER PANEL , FRONT BONNET , RADIATOR SUPPORT PANEL , FRONT BUMPER AND AFFECTED AREA .	\$1,000.00	400
			830
	<i>1/3 repair with pigments respray after paint</i>		
	<i>respray 3 days (11hrs)</i>		
	<i>H. ANN (11hrs)</i>		
	<i>853/1883</i>		
	<i>17/2/03 4:15pm</i>		
	<i>Handwritten signature</i>		
			1,132.34
			830
			1,962.34
			20%
			1,569.87
	I KK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	4/5	
	Acknowledged by Repairer	\$1,550	
	Signature:		
	Date:		

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.