

LIM POH YIAN
46 CANBERRA DRIVE
#08-11
SINGAPORE 768436

File No :
Date : 13-February-2020

Estimated cost of repair for vehicle no : **SLH2772H Mazda 3**
Accident involving vehicle no: **SLH2772H & SLW2303A** on **22.01.2020**

Description	Quantity	Cost Price
Front RH fender	1	\$ <i>R</i> 433.90 <i>X</i>
Front RH fender cowling	1	\$ <i>h</i> 97.00 <i>X</i>
Front RH fender cowling clips @ set	1	\$ <i>nn</i> 22.00 <i>X</i>
Front bumper	1	\$ <i>Bu</i> 1,080.50 ✓
Front bumper RH retainer	1	\$ <i>sn</i> 28.70 <i>X</i>
Front bumper RH fog lamp cover	1	\$ <i>sn</i> 197.00 ✓
Front bumper RH fog lamp cover chrome rim	1	\$ <i>sn</i> 225.00 <i>X</i>
Front RH headlamp	1	\$ <i>cm</i> 2,357.00 ✓
		\$ 4,441.10
	Less 10%	\$ 444.11
		\$ 3,996.99
To spray paint affected front and inner damaged portion inclusive of preparatory works and material		
		\$ 450.00 <i>400</i>
To remove front damaged parts, to jack out front fender, panel, front body, and cut out damaged parts, reinstall front fender and inner panel, head lamp inner panel, front support panel, front chassis member and adjust body panel alignment		
		\$ 420.00 <i>300</i>
To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp		
		\$ 25.00 <i>20</i>
		\$ 4,891.99

*Not withheld
Returning B&P*

T/Party: AIG Asia Pacific Insurance Pte Ltd

3 days
LKK Auto Consultants hereby notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Page 1 of 1

Acknowledged by Repairer
Signature:

Date: