



LIM POH YIAN
46 CANBERRA DRIVE
#08-11
SINGAPORE 768436

File No :
Date : 13-February-2020

Estimated cost of repair for vehicle no : SLH2772H Mazda 3
Accident involving vehicle no: SLH2772H & SLW2303A on 22.01.2020

Description	Quantity	Cost Price
Front RH fender	1	\$ 433.90 X
Front RH fender cowl	1	\$ 97.00 X
Front RH fender cowl clips @ set	1	\$ 22.00 X
Front bumper 1031.70	1	\$ Bu 1,080.50 ✓
Front bumper RH retainer	1	\$ 28.70 X
Front bumper RH fog lamp cover 165.	1	\$ 197.00 ✓
Front bumper RH fog lamp cover chrome rim	1	\$ 225.00 X
Front RH headlamp 2357	1	\$ CM 2,357.00 ✓
	20%	\$ 4,441.10
	Less 10%	\$ 444.11
		\$ 3,996.99

To spray paint affected front and inner damaged portion inclusive of preparatory works and material \$ 450.00 400

To remove front damaged parts, to jack out front fender, panel, front body, and cut out damaged parts, reinstall front fender and inner panel, head lamp inner panel, front support panel, front chassis member and adjust body panel alignment \$ 420.00 300

To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp \$ 25.00 20

\$ 4,891.99

T/Party: AIG Asia Pacific Insurance Pte Ltd

Not withheld
Returning B&P

3 days

83742.96