

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

MR.YAM CON PENG BERNABD
 BLK 342C YISHUN RING ROAD #02-1946
 SINGAPORE 763342

TP 1st Cop
 Jasper

ESTIMATE

Repair Code : CLM16044

Date in : 13/02/2020

Vehicle Num. : SMM5611G

Model : TOYOTA NOAH HYBRID 1.8X CVT

Chassis/Eng# : ZWR800375019/2ZR2C98009

Contact : 85117238

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Del d</i>	1	972.25	✓ 972.25
REAR BUMPER SIDE RETAINER L/R <i>Her</i>	2	171.70	256 343.40
REAR BUMPER TOW HOOK COVER <i>Not Her</i>	1	121.10	X 121.10
REAR END PANEL <i>Dented</i>	1	781.90	1 781.90
REAR END PANEL INNER TOP GARNISH <i>Del d</i>	1	375.85	✓ 375.85
REAR RH BUMPER REFLECTOR <i>cracked</i>	1	181.90	6870 181.90
REAR RH BUMPER UPPER GARNISH <i>Repair</i>	1	372.80	235 372.80
REAR RH BUMPER UPPER GARNISH BRACKET <i>Her</i>	1	185.10	X 185.10
REAR TAILGATE <i>Dented</i>	1	1715.85	✓ 1,715.85
REAR TAILGATE 'HYBRID SYNERGY DRIVE' EMBLEM <i>Her</i>	1	50.00	✓ 50.00
REAR TAILGATE GUIDE RUBBER STOPPER L/R <i>Her</i>	2	43.70	X 87.40
REAR TAILGATE INNER PULL HANDLE <i>Her</i>	1	45.00	X 45.00
REAR TAILGATE INNER TRIM GARNISH <i>cracked</i>	1	781.90	495 781.90
REAR TAILGATE WEATHER STRIP <i>Her</i>	1	374.70	X 374.70
REAR TAILGATE WINDSCREEN MOULDING L/R <i>Her</i>	2	175.45	185 350.90

*** This is a computer-generated document which requires no signature.***

51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

MR.YAM CON PENG BERNABD
BLK 342C YISHUN RING ROAD #02-1946
SINGAPORE 763342

Contact : 85117238

ESTIMATE

Repair Code : CLM16044
Date in : 13/02/2020
Vehicle Num. : SMM5611G
Model : TOYOTA NOAH HYBRID 1.8X CVT
Chassis/Eng# : ZWR800375019/2ZR2C98009

Subtotal before discount		6,740.05
Percentage discount 25%		1,685.01
Sub-total 1		5,055.04
REAR BUMPER CLIPS - SET	1	80.00
REAR BUMPER REVERSE SENSOR	1	350.00
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET	1	50.00
REAR TAILGATE WINDSCREEN SEALANT	1	80.00
Subtotal before discount		560.00
Percentage discount 0%		0.00
Sub-total 2		560.00
Parts-total		5,615.04

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	50	100.00
To remove, reinstall tailgate windscreen	120	150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	50	140.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	700	1,000.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	700	1,000.00
To apply anti-rust chemical on repaired and replaced panel.	40	120.00
To remove, reinstall tailgate mechanism and check for function	✓	80.00
Labour Total		2,590.00
Parts & Labour Total		8,205.04

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total 5629.77
4/5 4.5K.
OB Dwp.