

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd

Date: 12/02/2020

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: ~~SLR2481H~~ → **SLR9056A**

CHASSIS NO : NSP1707060128

MAKE / MODEL : Toyota Sienta Hybrid1.5G CVT

DATE OF ACCIDENT : ~~12/01~~ **11/02** /2020

YOUR INSURED VEHICLE NUMBER : ~~SLZ212B~~ **SDX899A**

MILEAGE : 235353 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>	
1	F/R fender ✓ <i>h n</i>	1PC	\$ 750.00	\$ 750.00	550
2	F/R fender Hybrid emblem ✓ <i>Nec</i>	1PC	\$ 84.00	\$ 84.00	✓
3	F/R fender inner liner <i>X SVC</i>	1PC	\$ 187.50	\$ 187.50	X
4	F/R door ✓ <i>DR</i>	1PC	\$ 1,840.00	\$ 1,840.00	1,237
5	R/R door <i>X R</i>	1PC	\$ 1,404.00	\$ 1,404.00	X
LIST TOTAL S\$:				\$ 4,265.50	1,867
25.00% DISCOUNT S\$:				\$ 1,066.38	-25%
				\$ 3,199.13	1,400.25

LABOUR CHARGES

1	To labour charge for removing R/R door, F/R fender and F/R door out to facilitate replacement of damaged part.	\$ 1,000.00	500
2	To respray R/R fender, R/R door, F/R fender and F/R door ✓	\$ 1,000.00	600
3	Transfer both doors mechanism / <i>front door</i>	\$ 100.00	60
LABOUR TOTAL S\$:		\$ 2,100.00	1,160
TOTAL S\$:		\$ 5,299.13	
7% GST		\$ 370.94	
GRAND TOTAL S\$:		\$ 5,670.06	

Repair day - 3 days

Lump Sum

After paint photo.

Sun Pm CLKb7

13/02/2020

TP without prejudice

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P=1,400.25
L=1,160
2,560.25
-20%
2,048.2

45
\$2,050
3 days