BIFROST AUTO PTE LTD

REPAIR ESTIMATE

-	-		_	_	
\Box	Λ	П	П		
$\mathbf{\nu}$		U		_	

12-Feb-20

INSURANCE:

AlG.

MODEL:

HYUNDAI 140

VEHICLE NO.: SHA9980L

DESCRIPTION	QTY	LIST PRICE	AMOUNT
BONNET / NU	1	\$2,265.90	\$2,265.90
BONNET RUBBER (LH) HIL	1	\$15.70	\$15.70
BONNET RUBBER (RH) MILL	1	\$6.20	\$6.20
BONNET HINGE (LH/RH)	2	\$82.00	\$164.00
BONNET LOCK SVZ	1	\$42.40	\$42.40
BONNET ABSORBER (LH ONLY) トル	1	\$61.60	\$61.60
BONNET INSULATOR HA	1	\$202.50	\$202.50
BONNET SEAL HA	1	\$31.90	\$31.90
BONNET INSULATOR CLIPS 서니	1	\$7.00	\$7.00
RADIATOR GRILLE / DR	1	\$1,480.00	\$1,480.00
FRONT BUMPER COVER / AR	1	\$1,052.20	\$1,052.20
FRONT BUMPER SPONGE / JK	1	\$99.20	\$99.20
FRONT BUMPER REINFORCEMENT / 10	1	\$438.40	\$438.40
FRONT BUMPER GRILLE (LH/RH) 44	2	\$49.20	\$98.40
FRONT BUMPER CENTRE GRILLE	1	\$114.00	\$114.00
FRONT BUMPER BRACKET TOP (LH/RH)	2	\$44.80	\$89.60
FRONT BUMPER CENTRE GRILLE TOP GARNISH (140) 🛶 🕏	1	\$32.00	\$32.00
FRONT BUMPER BRACKET (LH/RH) 44	2	\$49.20	\$98.40
FRONT BUMPER SIDE BRACKET	2	\$14.60	\$29.20
FRONT BUMPER RETAINER MOUNTING HA	2	\$18.00	\$36.00
FRONT BUMPER GRILLE AIR DUCT HA	1	\$26.20	\$26.20
HEADLAMP SUPPORT PANEL ASSY / 1/1	1 /	\$907.40	\$907.40
HEADLAMP (LH/RH) / BR	2	\$2,776.00	\$5,552.00
HEADLAMP SUPPORT TOP COVER MA	1	\$222.60	\$222.60
RADIATOR / JT	1	\$708.50	\$708.50
RADIATOR FAN BLADE, COWLING, MOTOR ASSY	SVC 1	\$792.95	\$792.95
RADIATOR BRACKET (LH/RH) H4	1	\$5.40	\$5.40
RADIATOR GUARD HH	1	\$35.00	\$35.00
HORN UNIT (LH/RH)	2	\$72.30	\$144.60
HORN WIRE Nム	1	\$156.60	\$156.60
AIRCON CONDENSER / Ø0	1	\$947.80	\$947.80
AIRCON RECEIVER HALL	1	\$59.60	\$59.60
AIRCON SUCTION & LIQUID HOSE HL	1	\$549.10	\$549.10
AIRCON DISCHARGE HOSE HL	1	\$194.40	\$194.40
OIL COOLER-ASSY MS	1	\$222.60	\$222.60
NTER COOLER / 00	1	\$1,032.50	\$1,032.50
NTER COOLER MOUNTING (2 PCS) HA	1	\$25.90	\$25.90
HOSE B TO INTER COOLER HL	1	\$229.70	\$229.70
HOSE C TO INTER COOLER INLET HA	1	\$294.50	\$294.50
			040 474 67
SUB TOTAL			\$18,471.95
LESS 20%			\$3,694.39

DISCOUNTED TOTAL			\$14,777.56
DISCOUNTED TOTAL			
FRONT NUMBER PLATE / BK SN	1	\$25.00	\$25.00
FRONT NO. PLATE TRIM COVER SN	1	\$30.00	\$30.00
SUB TOTAL			\$55.00
SUB TOTAL			
Labour Charge		A4 000 00	04 200 08
Panel Beating	1	\$1,200.00	\$1,200.00
Spray Painting Charge	1	\$1,000.00	\$1,000.00
Wiring Charge	1	\$150.00	\$150.00
Tuff Kote	1	\$100.00	\$100.00
Towing Charge	1	\$50.00	\$50.00
Remove/Refix Radiator	1	\$90.00	50 - \$90.00
Remove/Refix Aircon & Refill Gas	1	\$130.00	\$130.00
TOTAL LABOUR			\$2,720.00
ESTIMATE TOTAL			\$17,552.56

Sten (tkk)

14/02/2020 @ 1200m NA Adm 2 from 4 days.

1 KK Ando

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: