



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2005257
INV Date 28/07/2020
Reference CC4/FCI20002568/Gba3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SKE 5151H
Insured Veh. SHA 7758B
Claim No. D20000917MFSH
Policy No. D-20094922MFSH
Accident Date 07/02/2020
Inspection Date 14/02/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC4/FCI20002568/Gba3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 28-07-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7758B	Veh. Inspected	SKE 5151H	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20000917MFSH	Excess (\$)	0.00	
Assign From	RACHEL WU	Assign Date	13/02/2020	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ E250	c.c	1796	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WDD2120472A168143	Colour	BLACK	
Odometer	287672	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/45Z R17	KAPSEN	6 mm	
L/H Front Tyre	245/45Z R17	KAPSEN	6 mm	
R/H Rear Tyre	245/45Z R17	KAPSEN	6 mm	
L/H Rear Tyre	245/45Z R17	KAPSEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/02/2020	Inspection Date	14/02/2020	
Survey held at	SUCCESS UNITED PTE LTD 2 KAKI BUKIT AVE 2 #01-33 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKE 5151H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRT SPORT RIM RH	NOT NECESSARY	625.00	-
1	FRT FENDER RH	BUCKLED	1,185.00	1,185.00
1	FRT FENDER 'BLUEEFFICIENCY' EMBLEM RH	NECESSARY	85.00	55.00
	LESS 10% DISCOUNT		-189.50	-124.00
			1,705.50	1,116.00
	<u>LABOUR</u>			
	TO REMOVE ,REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT .		250.00	100.00
	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA.		250.00	200.00
			500.00	300.00
	GRAND TOTAL		2,205.50	1,416.00
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,100.00

Report Ref No. CC4/FCI20002568/Gba3q2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKE 5151H

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKE 5151H

RE-INSPECTION

