



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 4404L

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|----------------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | REAR BUMPER | DENTED / DEFORMED | 708.00 | 708.00 |
| 10 | REAR BUMPER CLIPS | NECESSARY | 40.00 | 40.00 |
| 1 | REAR BUMPER RH RED REFLECTOR | NOT NECESSARY | 25.00 | - |
| 1 | REAR END PANEL | TO REPAIR SEE LABOUR | 402.00 | - |
| 1 | BOOTLID | DENTED | 828.00 | 792.00 |
| 1 | BOOTLID BADGE | NECESSARY | 41.00 | 41.00 |
| 1 | BOOTLID ATTRAGE EMBLEM | NECESSARY | 25.00 | 25.00 |
| 1 | BOOTLID MIVEC EMBLEM | NECESSARY | 48.00 | 48.00 |
| 1 | BOOTLID LOCK | TWISTED | 206.00 | 206.00 |
| 1 | NUMBER PLATE LAMP CHROME GARNISH | CRACKED | 318.00 | 318.00 |
| 1 | RH LICENCE LAMP | NOT NECESSARY | 48.00 | - |
| 1 | TAILLAMP | NOT NECESSARY | 276.00 | - |
| | LESS 10% DISCOUNT | | -296.50 | -217.80 |
| | | | 2,668.50 | 1,960.20 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | NUMBER PLATE (SN) | SERVICEABLE | 40.00 | - |
| 1 | SET REVERSE SENSOR (SN) | SHORTED | 280.00 | 200.00 |
| | | | 320.00 | 200.00 |
| <u>LABOUR</u> | | | | |
| | REMOVE AND RENEW SENSOR . | | 80.00 | 50.00 |
| | TUFF COAT. | | 80.00 | 30.00 |
| | TO REMOVE AND RENEW REAR PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL . | | 980.00 | 300.00 |
| | WIRING CHECK (REAR). | | 30.00 | 20.00 |
| | SPRAY PAINTING. | | 980.00 | 400.00 |
| | | | 2,150.00 | 800.00 |
| GRAND TOTAL | | | 5,138.50 | 2,960.20 |



| | | | |
|---|--|--|-----------------|
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | 2,350.00 |
|---|--|--|-----------------|

Report Ref No. CC4/FCI20002569/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.