

# Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

*not allowed  
ok  
2/55  
3 days.  
17/2/20  
check amount*

Name of Insurance Company: M/S INDIA INSURANCE

DATE OF ACCIDENT : 07/02/2020

VEHICLE NO : SLL4404L

DEAR SIR / MADAM

NO	QTY	DESCRIPTION		
1	1 PC	REAR BUMPER	2/pc	\$ 708.00 ✓
2	10 PC	REAR BUMPER CLIPS	per	\$ 40.00 ✓
3	1 PC	REAR BUMPER RH RED REFLECTOR	1/1	\$ 25.00 X
4	1 PC	REAR END PANEL	1	\$ 402.00 X
5	1 PC	BOOTLID ?	ce	\$ 828.00 ✓
6	1 PC	BOOTLID BADGE	per	\$ 41.00 ✓
7	1 PC	BOOTLID ATTRAGE EMBLEM	per	\$ 25.00 ✓
8	1 PC	BOOTLID MIVEC EMBLEM	ALL	\$ 48.00 ✓
9	1 PC	BOOTLID LOCK	tw	\$ 206.00 ✓
10	1 PC	NUMBER PLATE LAMP CHROME GARNISH	cm	\$ 318.00 ✓
11	1 PC	RH LICENCE LAMP	1/1	\$ 48.00 X
12	1 PC	TAILLAMP	1/1	\$ 276.00 X
				\$ 2,965.00
		LESS 10%		\$ (296.50)
				\$ 2,668.50
13	1 PC	NUMBER PLATE	stg	\$ 40.00 X
14	1 PC	REVERSE SENSOR	stg	\$ 280.00 200
15		REMOVE AND RENEW SENSOR		\$ 80.00 50
16		TUFF COAT		\$ 80.00 30
17		TO REMOVE AND RENEW REAR PARTS		\$ 980.00 300
18		WIRING CHECK (REAR )		\$ 30.00 20
19		SPRAY PAINTING		\$ 980.00 400
				\$ 5,138.50

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: