

KIANG MOTOR

Block 25 Kaki Bukit Road 4 #08-26 Synergy@KB Singapore 417800
HP: 92712214 Fax: (65) 69664526

11th FEBRUARY 2020

STRAITS RENTAL PTE LTD
25 KAKI BUKIT ROAD4
08-26 SYNERGY @KB
Singapore 417800

TP China
Jia te. GPT2004030

Accident date: 01st FEBRUARY 2020
Estimated repair costs for vehicle no: SJG9988K Honda Shuttle 2019

S/n	Qty	Items	U/price	Amount
1	1	Rear boot lid Distorted.		\$1,250.00 ✓
2	1	Rear boot lid rubber <i>ok</i>		\$205.00 ✓
3	1	Rear Boot Lid inner trim <i>cracked</i>		\$680.00 385
4	1	boot lid inner lock <i>Damaged</i>		\$203.10 ✓
5	8	Rear boot lid center garnish clips } <i>NEC</i>	\$5.50	\$44.00 ✓
6	1	Rear boot lid centre garnish } <i>NEC</i>		\$285.10 ✓
7	1	Rear boot lid emble logo } <i>NEC</i>		\$60.00 ✓
8	1	Rear Boot Lid SHUTTE logo } <i>NEC</i>		\$40.00 ✓
9	1	Rear Boot Lid Hybrid logo } <i>NEC</i>		\$48.00 ✓
10	1	boot lid centre moulding } <i>NEC</i>		\$385.20 ✓
11	1	boot lid centre moulding clips } <i>NEC</i>		\$80.00 ✓
12	2	Rear Boot Lid side reflector } <i>NEC</i>	\$375.00	\$750.00 ✓
13	2	Rear Number Plate lamp } <i>NEC</i>	\$58.00	\$116.00 ✓
14	1	Rear Number Plate <i>Bent</i>		\$50.00 ✓
15	2	Rear Bumper side reflector } <i>NEC</i>	\$65.00	\$130.00 ✓
16	1	Rear bumper towing cover } <i>NEC</i>		\$64.00 ✓
17	1	Rear bumper <i>Deformed</i>		\$1,080.00 ✓
18	2	Rear bumper side bracket } <i>NEC</i>	\$85.20	\$170.40 ✓
19	8	Rear bumper clips } <i>NEC</i>	\$5.00	\$40.00 ✓
20	2	Rear tail lamp } <i>NEC</i>	\$558.00	\$1,116.00 ✓
21	1	Rear end panel <i>Repair</i>		\$740.00 ✓
22	1	Rear end Panel top garnish <i>Deformed</i>		\$384.00 ✓
23	1	Spare Tyre Panel top cover } <i>NEC</i>		\$385.00 ✓
24	1	Rear spare tyre panel sealant } <i>NEC</i>		\$280.00 ✓
			Subtotal :-	\$8,585.80

Labour charges

Remove / refix rear windscreen

gum

remove / refix rear cushion

Remove / refix rear reverse camera

Remove and refix rear exhaust

Tuff kote

To Check Wiring System

Panel beating

Spray painting charges

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total

\$120.00 ✓

\$50.00 ✓

\$120.00 60

\$100.00 50

\$220.00 X

\$120.00 50

\$60.00 30

\$800.00 600

\$800.00 600

\$2,390.00

\$10,975.80

total: 450320
4/5: 3.6k
05 Days.