

Attn: Adv

MODERN AUTOMOT
BLK 3023A UBI RO
SINGAPORE

Tel : 6748 4422/ 6745 4422 Fax : 67

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

Tel : 6389 - 6111

Fax : 6224 - 7478 / 7175

Khanchan

Attn : Motor Claim Dept (Pls arrange vehicle

RE : ESTIMATE FOR ACCIDENT REPAIR SLK2825Z

Item	Description
<u>NO</u>	<u>LIST ITEMS</u>
1	Rear Bumper <i>Distorted</i>
2	Rear Bumper Clips <i>new</i>
3	Rear Bumper Side Holder - LH & RH <i>new</i>
4	Rear Bumper Lower Garnish <i>new</i>
5	Rear Bumper Side Cover - LH & RH <i>new</i>
6	Rear Bumper Towing Cover <i>Missing</i>
7	Rear End Panel <i>Dented</i>
8	Rear End Panel Top Garnish <i>reborn</i>
9	Tail Lamp - LH & RH <i>ut</i>
10	Bootlid <i>Dented</i>
11	Bootlid Lock <i>new</i>
12	Bootlid Weatherstripe <i>ut</i>
13	Bootlid Reflector - LH & RH <i>new</i>
14	Bootlid Outer Garnish <i>new</i>
15	Bootlid Outer Garnish Clips <i>new</i>
16	Bootlid Hinges - LH & RH <i>new</i>
17	Bootlid Hinges Cover - LH & RH <i>new</i>
18	Honda Logo <i>?</i>
19	Civic Wording <i>new</i>
20	i-vtec Wording <i>new</i>
21	Rear Buzzer <i>new</i>
22	Rear Lock Antenna <i>new</i>
23	Spare Tyre Panel Top Cover <i>new</i>

Less 20%

S/NET ITEMS

0
 668.2+
 30.4
 49.4
 275.3+
 22.1+
 385.7+
 98.4+
 546.2+
 572.1+)
 74.3+
 79.4 c
 102.7+
 22.4
 53.9+
 46.2+
 48.9+
 46.4
 45.4
 =
 3,165.*
 3,165.* x
 80.%
 2,532.* 8.20 ✓
 0.* 1.00 ✓
 0.* 1.00 ✓
 0.* 0.30 ✓
 280.+ 60 ✓
 60.+ 10 ✓
 = 70 ✓
 340.* 40 ✓
 0.* 10 ✓
 0.* 0 ✓
 800.+ 0 ✓
 950.+ 1 ✓
 30.+ 1 X
 60.+ 1 ✓
 50.+ 1 ✓
 80.+ +
 60.= +
 2,330.*
 0.*
 2,532.+
 340.+
 2,330.=
 4,922.*
 4,902.* x
 80.%
 3,921.6*

4/5 = \$3900