

Attn: Advian

MODERN AUTOMOTIVE PTE LTD  
BLK 3023A UBI ROAD 1 # 01-61  
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road #16-00  
Springleaf Tower  
Singapore 079909  
Tel : 6389 - 6111  
Fax : 6224 - 7478 / 7175

Khanchan

Quotation

DATE : 12.02.2020  
VEH NO : SLK2825Z  
MODEL : Honda Civic  
D O A : 11.02.2020  
YR REF : GBH5946Y

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLK2825Z (HONDA CIVIC)

Item	Description	Qty	Amt
<b>NO</b>	<b>LIST ITEMS</b>		
1	Rear Bumper <i>Distorted</i>	1	668.20 ✓
2	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
3	Rear Bumper Side Holder - LH & RH <i>new</i>	2	49.00 ✓
4	Rear Bumper Lower Garnish <i>Distorted</i>	1	275.30 ✓
5	Rear Bumper Side Cover - LH & RH <i>new</i>	2	156.60 ✓
6	Rear Bumper Towing Cover <i>Missing</i>	1	22.10 ✓
7	Rear End Panel <i>Dented</i>	1	385.70 ✓
8	Rear End Panel Top Garnish <i>reborned</i>	1	98.40 ✓
9	Tail Lamp - LH & RH <i>lt</i>	2	546.20 ✓
10	Bootlid <i>Dented</i>	1	572.10 ✓
11	Bootlid Lock <i>2nd</i>	1	74.30 ✓
12	Bootlid Weatherstripe <i>lt</i>	1	79.00 ✓
13	Bootlid Reflector - LH & RH <i>new</i>	2	237.40 ✓
14	Bootlid Outer Garnish <i>could</i>	1	102.70 ✓
15	Bootlid Outer Garnish Clips <i>on</i>	1 set	22.00 ✓
16	Bootlid Hinges - LH & RH <i>? new</i>	2	124.20 ✓
17	Bootlid Hinges Cover - LH & RH	2	76.40 ✓
18	Honda Logo <i>? new</i>	1	53.90 ✓
19	Civic Wording <i>? new</i>	1	46.20 ✓
20	i-vtec Wording <i>? new</i>	1	48.90 ✓
21	Rear Buzzer <i>Damaged</i>	1	46.00 ✓
22	Rear Lock Antenna <i>could</i>	1	45.00 ✓
23	Spare Tyre Panel Top Cover <i>new</i>	1	246.20 ✓
			\$ 4,005.80
Less 20%			(801.16)
			\$ 3,204.64

S/NET ITEMS

RE: ESTIMATE FOR ACCIDENT REPAIR SLK2825Z (HONDA CIVIC)

1	Reverse Sensor	<i>Pay d</i>	1	<del>380.00</del> <i>280.</i>
2	Rear End Panel Sealant	<i>New</i>	1	60.00 ✓
3	Rear Camera	<i>None</i>	1	480.00 +

\$ 920.00

Total parts

\$ 4,124.64

LABOUR CHARGE

1	To knocking out rear portion & renew above parts	\$ 1,200.00 <i>800</i>
2	To putty & spray up paint works	\$ 1,200.00 <i>950.</i>
3	To check wiring system	\$ 50.00 <i>30</i>
4	To remove reverse sensor	\$ 100.00 <i>60.</i>
5	To remove rear camera	\$ 100.00 <i>50</i>
6	To transfer bootlid fittings	\$ 150.00 <i>80</i>
7	To remove upholstery	\$ 150.00 <i>60</i>

Total Labour

\$ 2,950.00

Grand Total

\$ 7,074.64

GST Will be reflected in the final bills

NOTE: -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Total: 4902*

*4/s: 3.9k.*

*06 Days*