

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

Email : Mg3solution@gmail.com

TO	: AIG ASIA PACIFIC INSURANCE	DATE	: 07/02/2020
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: GBE5192X	Vic	
MODEL	: TOYOTA DYNA 150 MANUAL 3SEATER		
CHASSIS NO		KDY2318022144	
<u>ACCIDENT DETAILS</u>		DATE	: 27-Jan-20
		TIME	: 15:00HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT WIPER PANEL <i>Regis</i>	1	\$ 1,250.00	\$ 1,250.00
2	FRONT WIPER PANEL GARNISH <i>at</i>	1	\$ 356.00	\$ 356.00
3	FRONT CENTRE PANEL <i>Dented</i>	1	\$ 1,254.40	\$ 1,254.40
4	FRONT CORNER PANEL RH <i>new</i>	1	\$ 320.60	\$ 320.60
5	FRONT BUMPER <i>Best</i>	1	\$ 826.40	\$ 826.40
6	FRONT BUMPER REINFORCEMENT <i>new</i>	1	\$ 354.00	\$ 354.00
7	FRONT BUMPER BRACKET <i>Best -</i>	2	\$ 89.20	\$ 178.40
8	FRONT RADIATOR GRILLE <i>crushed</i>	1	\$ 415.00	\$ 415.00
9	FRONT RADIATOR GRILLE LOGO <i>new</i>	1	\$ 69.50	\$ 69.50
10	HEAD LAMP RH <i>crushed</i>	1	\$ 1,124.85	\$ 1,124.85
11	WINDSCREEN RUBBER <i>new</i>	1	\$ 289.00	\$ 289.00
12	FRONT DOOR RH <i>Regis</i>	1	\$ 1,322.50	\$ 1,322.50

TOTAL PRICE \$ 7,760.65

MINUS 25% \$ 1,940.16

SUB TOTAL PRICE \$ 5,820.49

4120.30

3090.22

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT NUMBER PLATE <i>Beat</i>	1	\$ 50.00	\$ 50.00 30
2	FRONT GRILLE CLIP(SET) <i>ker</i>	1	\$ 22.00	\$ 22.00 10
3	COMPANY STICKER 'SAM LAIN' <i>ker</i>	1	\$ 350.00	\$ 350.00 100
4	COMPANY ADDRESS STICKER <i>ker</i>	1	\$ 50.00	\$ 50.00 30

170

TOTAL \$ 472.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (F&R)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	TO PANEL BEAT, WELD ,CUT, ADJUST, KNOCK	\$ 1,800.00	800	
2	TO PUTTY, SPRAY PAINT, POLISH WAX	\$ 1,800.00	800	
3	TO SPRAY TUFF COAT	\$ 250.00	60	
4	WIRING, BULB CHECKING	\$ 60.00	30	
5	TO REMOVE AND REFIX FRONT DASHBOARD	\$ 350.00	X	
6	REMOVE AND REFIX B/D EXHAUST PIPE , TEMPERATURE SENSOR PIPE AND AIR FUEL SENSOR	\$ 550.00	X	
7	REMOVE AND REFIX FRONT WINDSCREEN	\$ 180.00	120	

TOTAL \$ 4,990.00

18/0

ESTIMATE REPORT

TOTAL PARTS COST : \$ 6,292.49

TOTAL LABOUR COST : \$ 4,990.00

TOTAL REPAIR COST : \$ 11,282.49

EXCESS :

NO. OF DAYS :

RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :

SURVEYED BY :

CONTACT NUMBER :

FAX NUMBER :

Adrian Lj
A/S 07/02/20.

06 Days.

total: 5070.22

A/S: AK ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: