LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd. 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

From: LKK Auto Consultants Pte Ltd

Attn: Date: 17 Feb 2020

Preliminary Advice

Insured Vehicle No : SGU800P

TP Vehicle No : SJR173X Accident Date : 10/02/2020

Make : TOYOTA VIOS Assignment Date : 14/02/2020

Date of Inspection : 14/02/2020 Est. Duration of Repair : 8.00

Inspection At : KAI MOTOR TRADING (HQ)

BLK 3007 UBI ROAD 1, #01-440

SINGAPORE 408701

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front & rear portion and parts claimed are consistent to the accident.

| Repairer's Estimate (Gross) | :S\$ | 11,314.34 |
|-----------------------------|------|-----------|
| Revised Amount | :S\$ | 5,303.96 |
| Check Items (Estimated) | :S\$ | 3,727.87 |
| Total | :S\$ | 9,031.83 |

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :\$\$
Pre-Accident Value :\$\$
COE / PARF Rebate :\$\$
Salvage Value :\$\$
Margin for Repair :\$\$

Remarks

| (|) | The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. |
|---|---|--|
| | | Kindly let us have your authorisation. |
| | | |

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: TP: WP