| ASS. REC. BY: | REF: (| s(smo 2 | 100万千年 | infact sp | ecial Instruction | r | |
|---|--------------------------|----------------|--------------|------------|-------------------|----------------|--------|
| Surveyor: Steve | | | ENT (Office) | | | U61 | |
| From (Person); GNA U | TO O | of S | mo | | Date/Time: | 14.2.2000 | 9.494. |
| Estimated Cost: | | | Bill to: | | | | |
| To Inspect Vehicle No: | SHA 20 | INVIMVI 9BE | CS | _ Insured: | GB | (3700D 2187 | |
| of BIK 9 Sector (| | Sin Ming | Glate. | Tel: | 9641 | 7187 | 2 |
| Policy No: | | | Claim No: | CMITID. | 2000709 | 1/544 | |
| Sum Insured: | | | Excess: | | | 2 | |
| Make of Veh: | | | | | D.O.A. | 1.2.7020 | |
| CA / REV / REP. / RED. | V 24 HRS 10-300-mpers | hp' | ms Lu | | H.O.D. End | korsement: | |
| | raction (V | | | | | | |
| | Thun - X | 1/NCF60 | 15587 / KING | 112 | 2614 - N | W107/2013 | |
| 18/2/20 Email | preli ro | vised to | shiring ! | Yi | | | |

| SS, REC. BY: STEVE | EF: S740 | | |
|--|-------------------|-----------------------------------|---|
| | ASSI | GNMENT | and the second |
| From: Date: | 14121 2020 | Veh No: SHA 2098 | E Yr Regn: 15/6/17 |
| stimated Cost: | | Type: M.Car / M.Cycle / Bus / Va | n / Lorry (Tax) / Prime Mover / |
| DITTE DWS / TP RES / OD RES / EVA / IN | NV / MV | Truck / Trailer or | |
| o Inspect Vehicle No: SHA 20 | 93E | Make: Toyala Privs | c.c 179 N |
| t Workshop m/s Br Frost | | Colour Aluc | A/C: Insured / Std / NI / NA |
| 1 BIK 9 Sever C # 01-4 | +2 Sn Ming | Sp.Reading 466/30 | T/Radio: Insured / Std / NI / NA |
| nsured: | / | Eng/No: | |
| olicy No. | | C/No: JTD KB3 | F4 703558764 |
| Naims No. | | Gen. Cond: Good / Fair / Poor / I | |
| Sum Insured: Exces | SS: | Steering: Injorder / Jammed / Les | aked / Burnt or |
| (Client's Record) | | Brake: Inder / Jammed / Les | aked / Burnt or |
| Make of Veh: | | Modi: NII / S/R m / STD A/R | im or |
| MEMPAGNI SANTI | 0.04.050 | Tyre Size: F: 19 | 5/65R15 |
| (Dallas Castellan) | PART I | R: | 1 |
| (Policy Condition) Remark: The veh had commenced its | N/S O/S | | LIZA / MIC / OHTSU / PIR / SUMI / |
| repair at the time of inspection. | | TOYO/YOKO or | DAVANTI |
| Bal. or Market Value: | | Front | Rear |
| | nt? : Yes or No | R/Bal. 5 mm | R/Bal. C mm |
| THE POST OF THE PARTY OF THE PA | nt? : Yes or No | L/Bai. 5 mm | L/Bal. C mm |
| 5th / 110 555th | s.: Yes or No | D.O.A. 11/2/20 | D.O.L 17/2/29 |
| Lot Hapairo | /al.: Yes or No | 1/1/2/1/ | I fost Auto |
| Lum Sum: % 3 V | we" | | O/S / N/S / U/C / Rooftop or |
| CA / REV / REP. / 24 HRS | Vehicle: IN / OUT | FM L | |
| Date: Person Contacted: | venide: IN / OUT | | Body Structure affected due to collision |
| Date / Time Action / Instruction | | 1110 010 7 0110010 1111110 7 | |
| 81918 |) | | |
| | Pls checks | 2000 ETYDG | |
| 25/2/20 Finalize \$11,790 (| a deal At the | \ , | $\Delta \Delta $ |
| 95/2/90 Finalize \$11,799 (| T DYD AN THE | (Red 28, 873.90, 718) | Myserth |
| | | | Hail |
| * | RECEIVED 2 | FEB 2020 | 18/2 |
| | RECEIVED | | |
| | | | |
| | eport | Days Of Repair: 9 | |
| Date/Time, File Pass to7 : Prell. Re | | 24 | - Personne |
| H | | Resurvey No. of Trip: 2 | Survey Fee: LGO |
| i) : Final Re | | Resurvey No. of Trip: | Survey Fee: LIGO Transportation: |
| n) : Final Re | | | |
| t) : Final Re | eport | | Transportation: |
| Dete/Time, File Return to? | eport | 9: Site Insp (\$ | Transportation: S + RSSt |
| t) : Final Re | eport | : Site Insp (\$ | Transportation:)S + RS,St) Photos |

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Tuesday, 18 February 2020 10:12 AM 'Teo, Grace'; SUR; 'Hwang, Shiang Yi'

To:

IVe Vens Vens Mehini

Subject:

'Ye, Yong Kang Melvin'
RE: CMTD2000709/SYH - LKK/ GBC3700D & SHA2098E ACC on 11.02.2020.

Attachments:

SHA 2098E PRELI ADVISED.pdf

Dear Shiang Yi,

Enclosed preliminary revised of vehicle SHA 2098E

Date of survey: 17/2/2020

Number of days (estimated): 9 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>

Sent: Friday, 14 February 2020 10:27 AM

To: 'Teo, Grace' <grace.teo@sompo.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com> Cc: 'Hwang, Shiang Yi' <shiangyi.hwang@sompo.com.sg>; 'Assessment' <claims@bifrostauto.com>; 'Regina' <assessment_ltc@bifrostauto.com>; 'Claims Dept' <claims_ltv@bifrostauto.com>; claims_ltr@bifrostauto.com; 'Ye,

Yong Kang Melvin' <melvin.ye@sompo.com.sg>

Subject: RE: CMTD2000709/SYH - LKK/ GBC3700D & SHA2098E ACC on 11.02.2020.

Dear Sir/Madam,

Thank you for the assignment.

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue

1, #02-25 | S(408933)

From: Teo, Grace <grace.teo@sompo.com.sg>

Sent: Friday, 14 February, 2020 9:49 AM

To: Claims Dept <claims Itm@bifrostauto.com>; 'admin-d@lkkauto.com' <admin-d@lkkauto.com'>;

'assignments@lkkauto.com' <assignments@lkkauto.com>; sur@lkkauto.com

Cc: Hwang, Shiang Yi <shiangyi.hwang@sompo.com.sg>; Assessment <claims@bifrostauto.com>; Regina

<assessment Itc@bifrostauto.com>; Claims Dept <claims Itv@bifrostauto.com>; claims Itr@bifrostauto.com; Ye,

Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: CMTD2000709/SYH - LKK/ GBC3700D & SHA2098E ACC on 11.02.2020.

Our Reference: CMTD2000709/SYH

Your Reference: SHA2098E

Date: 14/02/2020

Without Prejudice EMAIL ONLY

OUR Email: motorsurvey@sompo.com.sg

Attention:

M/S BIFROST AUTO PTE LTD

Dear Ms. Lim,

ACCIDENT INVOLVING GBC3700D & SHA2098 ON 11.02.2020

We refer to your email reply of 13.02.20.

We will appoint LKK Auto to conduct the survey.

Hi LKK Auto,

Please make the arrangement to survey for SHA2098E on a without prejudice and any admission of liability basis.

Please be informed that Ms. Hwang Shiang Yi is the handler of this case who can be contacted at 63295 205/ shiangyi.hwang@sompo.com.sg.

Please revert your report upon completion of survey to my colleague, Ms. Shiang Yi.

Thank you.

Best Regards Grace Teo Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg




SOMPO A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG







Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: Claims Dept <claims ltm@bifrostauto.com>

Sent: Thursday, February 13, 2020 5:04 PM To: Teo, Grace <grace.teo@sompo.com.sg>

Cc: Hwang, Shiang Yi <shiangyi.hwang@sompo.com.sg>; Assessment <claims@bifrostauto.com>; Regina

<assessment ltc@bifrostauto.com>; Claims Dept <claims ltv@bifrostauto.com>; claims ltr@bifrostauto.com; Ye,

Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: Re: CMTD2000709/SYH - PRI/ GBC3700D & SHA2098E ACC on 11.02.2020.

WITHOUT PREJUDICE

Hi,

We selected LKK.

Pls assign asap.

Ms Lim (96412187) Thanks & Regards, Bifrost Auto Pte Ltd Accident Claims Dept

On Thu, 13 Feb 2020 at 16:42, Teo, Grace <grace.teo@sompo.com.sg> wrote:

Our Reference: CMTD2000709/SYH

Your Reference: SHA2098E

Without Prejudice

Date: 13/02/2020 EMAIL ONLY

OUR Email: motorsurvey@sompo.com.sg

Attention:

M/S BIFROST AUTO PTE LTD

Dear Ms. Lim,

ACCIDENT INVOLVING GBC3700D & SHA2098 ON 11.02.2020

We refer to your Notice of Accident dated 13/02/2020.

Please be informed that Ms. Hwang Shiang Yi is the handler of this case who can be contacted at 63295 205/ shiangyi.hwang@sompo.com.sg .

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

| | Tre-Kepan Survey | | Selection (Indicate as |
|---|----------------------|------------------------------|------------------------|
| | Motor Surveyor | Surveyor | tick) |
| 1 | Raleigh Services | Andrew Ow Yong | |
| | | Vincent Ng | |
| 2 | LKK Auto Consultants | Kenneth Kong (North area) | |
| | | Marcus Chua (East area) | |
| | | Mohd Rasul (West area) | |
| | • | Mohd Taufikh (West area) | |
| 3 | Priority Services | Jimmy Lee | |
| | | Lawrence Ng | |
| | | Jeffrey Ong | |

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sq | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @





¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: Claims Dept <claims ltm@bifrostauto.com>

Sent: Thursday, February 13, 2020 3:18 PM

To: Claims - Motor Survey < Motor Survey@sompo.com.sg >

Cc: Assessment <claims@bifrostauto.com>; Regina <assessment ltc@bifrostauto.com>; Claims Dept

<claims ltv@bifrostauto.com>; claims ltr@bifrostauto.com

Subject: Re: PRS for our client's vehicle SHA 2098 E and your insured's vehicle GBC 3700 D on 11.02.2020.

Without Prejudice

Dear Sir/ Mdm,

We refer to the above matter. We represent our client, Tan Tong Neng, to notify you of the aforesaid accident involving our client's vehicle SHA 2098 E and your insured's vehicle GBC 3700 D on 11.02.2020. Please find enclose our client's GIA report for your necessary action. This serves as a NOTICE that we are claiming against GBC 3700 D for damages, costs and disbursements. Please let us know within 2 working days from today, your client's and your intention to conduct a pre-repair survey of our client's vehicle. PLEASE LET US HAVE A LIST OF YOUR EXTERNAL SURVEYORS FOR OUR SELECTION AS A SINGLE JOINT EXPERT. If we do not receive any reply from you within the stipulated timeline, we shall proceed to appoint our own surveyor and proceed with the necessary repair for our client's vehicle without further reference to your insured or you. Premises for the Pre-repair inspection: Blk 9 Sector C #01-42, Sin Ming Industrial Estate, Singapore 575644 Contact Person: Ms Lim / Ms Lee Contact Email: claims | Itv@bifrostauto.com / claims | Itm@bifrostauto.com : 13.02.2020 VEH IN (Date & Time)

: AS SOON AS POSSIBLE

PRS ARRANGEMENT (Date & Time)

Kindly cc a copy of this letter to your insured for his/her acknowledgement.

We look forward to hearing from you soon.

To avoid incurrence of any unnecessary cost on both our end, kindly confirm liability status within 7 days from this to minimize time wastage and incurrence of any unnecessary cost(s) on both our end, we seek your kind advice, within 7 days working days, on liability status for subject claim. If we do not hear from you within the stipulated period, we shall proceed with the purchase of your insured GIA report and this cost or any other cost incurred for confirmation of liability status shall be included in our LOD for reimbursement purpose.

Thank you.

You can protect our environment. Think before you print.

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential.

The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Ms Lim (96412187)

Thanks & Regards,

Bifrost Auto Pte Ltd

Accident Claims Dept -



51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX: (065) 62564315

Your Ref: CMTD2000709/SYH

Our ref: CS/SMO20002577/Evf3

Date: 18/2/2020

The Motor Claims Department
M/s SOMPO INSURANCE SINGAPORE PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.SHA 2098E

We thank you for your instruction on 14/2/2020

Please be informed that we had conducted the inspection of the above mentioned vehicle on 17/2/2020 at the premises of M/s BIFROST AUTO PTE LTD and have the following to report:-

| Workshop Estimate Amount | : S\$36,094.62 |
|--------------------------|----------------|
| Revised Estimate Amount | : S\$9,899.84 |
| "Check" Items Amount | : S\$ |
| Market Value | : S\$ |
| LTA Reimbursement Value | : S\$ |
| Nett Value | : S\$ |

Description of Damage: The vehicle sustained damage

The vehicle sustained damages at the

front n/s portion.

nearside

offside

rear

Comments/Present Status: Damages Consistent

Yours faithfully,

CHEN TSUE YEE
Automotive Assessor

Nivitha (LKK Auto)

From:

Teo, Grace < grace.teo@sompo.com.sg>

Sent:

Friday, 14 February 2020 9:49 AM

To:

Claims Dept; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com';

sur@lkkauto.com

Cc:

Hwang, Shiang Yi; Assessment; Regina; Claims Dept; claims_ltr@bifrostauto.com; Ye,

Yong Kang Melvin

Subject:

CMTD2000709/SYH - LKK/ GBC3700D & SHA2098E ACC on 11.02.2020.

Attachments:

SHA 2098E - GIA Report (1).pdf

Our Reference: CMTD2000709/SYH

Your Reference: SHA2098E

Date: 14/02/2020

Without Prejudice EMAIL ONLY

OUR Email: motorsurvey@sompo.com.sg

Attention:

M/S BIFROST AUTO PTE LTD

Dear Ms. Lim,

ACCIDENT INVOLVING GBC3700D & SHA2098 ON 11.02.2020

We refer to your email reply of 13.02.20.

We will appoint LKK Auto to conduct the survey.

Hi LKK Auto,

Please make the arrangement to survey for SHA2098E on a without prejudice and any admission of liability basis.

Please be informed that Ms. Hwang Shiang Yi is the handler of this case who can be contacted at 63295 205/ shiangyi.hwang@sompo.com.sg.

Please revert your report upon completion of survey to my colleague, Ms. Shiang Yi.

Thank you.

Best Regards Grace Teo Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission1 & Product Purchase2 via Sompo SG

Download now @





¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: Claims Dept <claims_ltm@bifrostauto.com>

Sent: Thursday, February 13, 2020 5:04 PM To: Teo, Grace <grace.teo@sompo.com.sg>

Cc: Hwang, Shiang Yi <shiangyi.hwang@sompo.com.sg>; Assessment <claims@bifrostauto.com>; Regina <assessment_ltc@bifrostauto.com>; Claims Dept <claims_ltv@bifrostauto.com>; claims_ltr@bifrostauto.com; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: Re: CMTD2000709/SYH - PRI/ GBC3700D & SHA2098E ACC on 11.02.2020.

WITHOUT PREJUDICE

Hi.

We selected LKK.

Pls assign asap.

Ms Lim (96412187) Thanks & Regards, Bifrost Auto Pte Ltd Accident Claims Dept

On Thu, 13 Feb 2020 at 16:42, Teo, Grace <grace.teo@sompo.com.sg> wrote:

Our Reference: CMTD2000709/SYH

Your Reference: SHA2098E

Without Prejudice

| Date: 13/02/2020 | EMAIL ONLY |
|------------------|------------|
| | |

Attention:

OUR Email: motorsurvey@sompo.com.sg

| M/S BIFROST AUTO PTE LTD |
|---|
| |
| |
| Dear Ms. Lim, |
| |
| ACCIDENT INVOLVING GBC3700D & SHA2098 ON 11.02.2020 |
| |
| We refer to your Notice of Accident dated 13/02/2020. |

Please be informed that Ms. Hwang Shiang Yi is the handler of this case who can be contacted at 63295 205/ shiangyi.hwang@sompo.com.sg .

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

| T | | * | E7 | |
|-------|------|----|-----|------|
| Pre-F | tens | ur | SIL | rvev |

| | Matan Survey | S.,,,,,,,,,, | Selection (Indicate as tick) |
|---|----------------------|------------------------------|------------------------------|
| | Motor Surveyor | Surveyor | tick) |
| 1 | Raleigh Services | Andrew Ow Yong | |
| | | Vincent Ng | |
| 2 | LKK Auto Consultants | Kenneth Kong (North area) | |
| | | Marcus Chua (East area) | |
| | | Mohd Rasul (West area) | |
| | | Mohd Taufikh (West area) | |
| 3 | Priority Services | Jimmy Lee | |
| | | Lawrence Ng | |
| | | Jeffrey Ong | |

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623 Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission1 & Product Purchase2 via Sompo SG







¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click here for our Privacy Policy

From: Claims Dept <<u>claims_ltm@bifrostauto.com</u>>

Sent: Thursday, February 13, 2020 3:18 PM

| Cc: Assessment < <u>claims@bifrostauto.com</u> >; Regina < <u>assessment ltc@bifrostauto.com</u> >; Claims Dept < <u>claims ltv@bifrostauto.com</u> >; <u>claims ltr@bifrostauto.com</u> Subject: Re: PRS for our client's vehicle SHA 2098 E and your insured's vehicle GBC 3700 D on 11.02.2020. |
|--|
| Without Prejudice |
| Dear Sir/ Mdm, |
| We refer to the above matter. |
| We represent our client, Tan Tong Neng, to notify you of the aforesaid accident involving our client's vehicle SHA 2098 E and your insured's vehicle GBC 3700 D on 11.02.2020. |
| Please find enclose our client's GIA report for your necessary action. |
| This serves as a NOTICE that we are claiming against GBC 3700 D for damages, costs and disbursements. |
| Please let us know within 2 working days from today, your client's and your intention to conduct a pre-repair survey of our client's vehicle. |
| PLEASE LET US HAVE A LIST OF YOUR EXTERNAL SURVEYORS FOR OUR SELECTION AS A SINGLE JOINT EXPERT. |
| If we do not receive any reply from you within the stipulated timeline, we shall proceed to appoint our own surveyor and proceed with the necessary repair for our client's vehicle without further reference to your insured or you. |
| Premises for the Pre-repair inspection: Blk 9 Sector C #01-42, Sin Ming Industrial Estate, Singapore 575644 |
| Contact Person: Ms Lim / Ms Lee |
| Contact Email: claims Itv@bifrostauto.com / claims Itm@bifrostauto.com |

Kindly cc a copy of this letter to your insured for his/her acknowledgement.

We look forward to hearing from you soon.

To avoid incurrence of any unnecessary cost on both our end, kindly confirm liability status within 7 days from this to minimize time wastage and incurrence of any unnecessary cost(s) on both our end, we seek your kind advice, within 7 days working days, on liability status for subject claim. If we do not hear from you within the stipulated period, we shall proceed with the purchase of your insured GIA report and this cost or any other cost incurred for confirmation of liability status shall be included in our LOD for reimbursement purpose.

Thank you.

You can protect our environment. Think before you print.

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential.

The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it.

If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Ms Lim (96412187)

Thanks & Regards,

Bifrost Auto Pte Ltd

Accident Claims Dept

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

| Owner ID Type: | Company |
|--|--------------------------------------|
| Owner ID: Vehicle Details | 821R |
| Vehicle No.: | SHA2098E |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 17 Feb 2020 |
| Vehicle Make: | TOYOTA |
| Vehicle Model: | PRIUS HYBRID 1.8 CVT |
| Primary Colour: | Blue |
| Manufacturing Year: | 2017 |
| Engine No.: | 2ZRS048527 |
| Chassis No.: | JTDKB3FU703558764 |
| Maximum Power Output: | 90.0 kW (120 bhp) |
| Open Market Value: | \$29,007.00 |
| Original Registration Date: | 15 Jun 2017 |
| First Registration Date: | 15 Jun 2017 |
| Transfer Count: | 0 |
| Actual ARF Paid: Intended PARF Rebate Details | \$5,000.00 |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 14 Jun 2025 |
| PARF Rebate Amount: Intended COE Rebate Details | \$3,750.00 |
| COE Expiry Date: | 14 Jun 2025 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 8 |
| PQP Paid: | \$40,500.00 |
| COE Rebate Amount: | \$26,965.00 |
| Total Rebate Amount: Message | \$30,715.00 |

COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier. The information contained herein is correct as at 17 Feb 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

| | ACCIDENT STATEMENT | |
|----------------------------|--------------------|--|
| Date Of Report | 12/02/2020 11:21 | |
| Date Of Accident | 11/02/2020 15:00 | |
| Exact Location Of Accident | SENOKO ROAD | |
| Country/State of Loss | SINGAPORE | |

| DETAI | LS OF | OWN | VEH | CLE |
|-------|-------|-----|----------|-----|
| | | | April 64 | |

Vehicle Registration Number SHA2098E

Insured/Policyholder

Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD

Co Reg No 1XXXXX821R

Email Address FLEETSAFETY@CDGTAXI.COM.SG

Mobile Phone No

Alternative Phone No OFFICE-65508768

Vehicle Particulars

Manufacturer TOYOTA

Model PRIUS HYBRID 4G

Exact Purpose for which vehicle was being used at

time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY

Vehicle Category

TAX

Insurance Company

Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD

Type Of Coverage THIRD PARTY FIRE AND/OR THEFT

Fleet Policy YES

Policy Number D-18088936MFSH

Cover Note Number

Driver

Name of Driver TAN TONG NENG

 NRIC No
 SXXXX182Z

 Date Of Birth
 25/09/1981

 Occupation
 OUTDOOR

 Date Of Driving Pass
 13/10/2011

Driving Experience 8 YEARS AND 3 MONTHS

Gender MALE

Mobile Number (LOCAL) +65-97689841

Fax Number

Contact Number

EMail Address TONY_TAN512@HOTMAIL.COM

-Address

BLK 524A PASIR RIS ST 51

#09-625

Postcode

511524

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - TAXI DRIVER

Vehicle Registration Number of Driver's Own

Vehicle

-

Insurance Company of Driver's Own Vehicle

.

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles (including own vehicle)

2

involved in the accident

YES

Was any body injured in the Accident?
Was any injured conveyed to hospital by

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s)

cie:

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

1

Details of Police Action

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

REFER ATTACHED

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons

Was there any audio recorded?

NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

GBC3700D

Vehicle Make/Model/Colour

MITSUBISHI LORRY

Details Of Properties

Vehicle Category

COMMERCIAL VEHICLE

Name of Driver

BALU BABU

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

LH REAR

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name

- Approximate Age

Injuries Sustain

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

TAN TONG NENG

CHEST

SHA2098E

YES

NO

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/iaw firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD CO. REG. NO. 199303821R

> Policyholder's Signature Date & Time:

Driver's Signature (If driver is not the policyholder)


Date & Time: 12.02.2020

@ 11:00 hrs

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

| On 11.02.2020 at about 1 | 15:00 hours I was travelling along Senoko Road With no passenge |
|-------------------------------|---|
| onboard . | |
| While I was travelling strain | ght , suddenly veh B (GBC 3700D) dash out without giving way to |
| me and collided into my taxi | A - Front Left Portion . |
| After the accident I suffere | ed pain at my chest area , will consult doctor later on . |
| I have company video and | photos at scene to support my claims . |
| Veh B (GBC 3700D) - Mr | Balu Babu |
| | |
| | |
| | |
| | |

DECLARATION

COMFORY TRANSPORTATION PTE LTD

CO. REG. NO. 199303821R

Policyholder's Signature Date & Time:

CAMIC Intention for the CVI

Driver's Signature

(If driver is not the policyholder)

Date & Time: 12.02.2020

@ 11:00 hrs

Reporting Centre Personnel's Signature

Name: NRIC/FIN No.:

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

| - | | | - | | |
|---|----|----|---|---|-----|
| • | ъ. | м. | п | - | 200 |
| | 34 | м. | | | - |
| | | | | | |

13-Feb-20

INSURANCE:

MODEL:

TOYOTA PRIUS

VEHICLE NO .:

SHA2098E

| DESCRIPTION | QTY | LIST PRICE | AMOUNT |
|--|-----|------------|------------|
| BONNET / DI) | 1 | \$950.50 | \$950.50 |
| INSULATOR, HOOD X /M/ | 1 | \$398.10 | \$398.10 |
| INSULATOR CLIPS X MAI | 1 | \$3.60 | \$3.60 |
| BONNET RUBBER × MM | 1 | \$35.50 | \$35.50 |
| BONNET HINGE (RH) / IT | 1 | \$57.70 | \$57.70 |
| BONNET HINGE (LH) / JT | 1 | \$57.70 | \$57.70 |
| BONNET LOCK X NN | 1 | \$132.60 | \$132.60 |
| RADIATOR GRILLE X MI | 1 | \$438.00 | \$438.00 |
| RADIATOR GRILLE EMBLEM / / | 1 | \$88.00 | \$88.00 |
| FRONT BUMPER COVER / | 1 | \$499.90 | \$499.90 |
| FRONT BUMPER REINFORCEMENT X NA | 1 | \$696.40 | \$696.40 |
| FRONT BUMPER REINFORCEMENT ABSORBER × NN | 1 | \$115.70 | \$115.70 |
| FT BUMPER LOWER REINFORCEMENT BRACKET NA | 1 | \$330.00 | \$330.00 |
| FRONT BUMPER SPONGE | 1 | \$78.80 | \$78.80 |
| FRONT BUMPER CENTRE GRILLE X MN | 1 | \$301.90 | \$301.90 |
| FRONT BUMPER LOWER GRILLE X /V/N | 1 | \$148.60 | \$148.60 |
| LAMP ASSY, FOG, LH X ///N | 1 | \$920.00 | \$920.00 |
| FRONT BUMPER CLIPS / //C | 1 | \$22.00 | \$22.00 |
| FRONT BUMPER SIDE RETAINER / /// | 1 | \$77.00 | \$77.00 |
| COVER, FRONT BUMPER HOLE, LH X //// | 1 | \$28.38 | \$28.38 |
| REINFORCEMENT, FRONT BUMPER LOWER X MAI | 1 | \$236.10 | \$236.10 |
| BRACKET FT BUMPER EXTENSION MOUNTING X MV | 1 | \$110.40 | \$110.40 |
| SUPPORT FR BUMPER, LH X N/I | 1 | \$81.70 | \$81.70 |
| FRONT BUMPER CENTRE FRAME X NIII | 1 | \$236.90 | \$236.90 |
| BRACKET, FRONT BUMPER SIDE, LH X NN | 1 | \$82.30 | \$82.30 |
| BRACKET, FRONT BUMPER MOUNTING VINI | 1 | \$29.60 | \$29.60 |
| BRACKET, FRONT BUMPER MOUNTING, NO. 2 VINI | 1 | \$97.80 | \$97.80 |
| ABSORBER, FRONT BUMPER, LOWER X NA | 1 | \$127.70 | \$127.70 |
| JNIT ASSY, HEADLAMP, LH (LED) | - 1 | \$3,455.00 | \$3,455.00 |
| HEAD LAMP PANEL (LH) ✓ □ | 1 | \$240.10 | \$240.10 |
| TOP PANEL CENTRE / DIJ | 1 | \$364.98 | \$364.98 |
| TOP PANEL SIDE (01) | 1 | \$145.90 | \$145.90 |
| BRACE PANEL X N/I | 1 | \$75.20 | \$75.20 |
| BRACKET, HEADLAMP MOUNTING, LH X MAI | 1 | \$25.50 | \$25.50 |
| HEADLAMP BULB / ()K | 1 | \$34.30 | \$34.30 |
| RADIATOR ASSY X JUNI | 1 | \$1,841.80 | \$1,841.80 |
| RADIATOR FAN MOTOR ASSY X NAI | 1 | \$661.30 | \$661.30 |
| STAY, RADIATOR SUPPORT, LH X NA | 1 | \$65.70 | \$65.70 |
| DEFLECTOR, RADIATOR SIDE, LH X [V/II] | 1 | \$83.50 | \$83.50 |
| CONDENSER ASSY, W/RECEIVER / / 00 | 1 | \$1,336.60 | \$1,336.60 |
| AIRCON DISCHARGE HOSE X NAI | 1 | \$386.90 | \$386.90 |

| \$945.30 | \$945.30 |
|------------|---|
| \$945.26 | \$945.26 |
| \$198.50 | \$198.50 |
| \$14.90 | \$14.90 |
| \$86.50 | \$86.50 |
| \$100.00 | \$100.00 |
| \$44.50 | \$44.50 |
| \$47.20 | \$47.20 |
| \$46.10 | \$46.10 |
| \$34.90 | \$34.90 |
| \$138.40 | \$138.40 |
| \$82.30 | \$82.30 |
| \$208.60 | \$208.60 |
| \$339.56 | \$339.56 |
| \$82.30 | \$82.30 |
| \$71.00 | \$71.00 |
| \$131.80 | |
| \$1,570.55 | \$131.80 \$1,570.55 |
| \$175.80 | |
| | \$175.80 |
| \$559.94 | \$559.94 |
| \$631.90 | \$631.90 |
| \$398.20 | \$398.20 |
| \$196.20 | \$196.20 |
| \$1,764.00 | \$1,764.00 |
| \$1,621.30 | \$1,621.30 |
| \$352.40 | \$352.40 |
| \$196.80 | \$196.80 |
| \$580.80 | \$580.80 |
| \$549.70 | \$549.70 |
| \$159.30 | \$159.30 |
| \$382.70 | \$382.70 |
| \$174.63 | \$174.63 |
| \$207.20 | \$207.20 |
| \$450.70 | \$450.70 |
| \$8,450.50 | \$8,450.50 |
| | ********* |
| | \$37,039.40 |
| | \$7,407.88 |
| | \$29,631.52 |
| \$87.10 | \$87.10 |
| \$216.00 | \$216.00 |
| 3213100 | 42.0.00 |
| | \$303.10 |
| | |
| £4 000 00 | 64 000 00 |
| | \$1,800.00 |
| | \$1,200.00 |
| | \$200.00 |
| | \$150.00 \$50.00 |
| _ | \$1,800.00 \$1,200.00 \$200.00 \$150.00 \$50.00 |

10,573.90 -35% 778042

1400 ×

| ESTIMATE TOTAL | | | \$36,094.62 |
|--|---|----------|---------------------|
| TOTAL LABOUR | | | \$6,160.00 |
| | | \$330.00 | 7,15,15,15,17,17,17 |
| Remove/Refix Air Bag/Steering Wheel/Dashboard/Seat | 1 | \$550.00 | \$550.00 |
| Remove/Refix Front Windscreen Glass | 1 | \$120.00 | \$120.00 |
| Remove/Refix Fuse Box | 1 | \$180.00 | \$180.00 |
| Remove/Refix Dashboard | 1 | \$450.00 | \$450.00 |
| Remove/Refix Engine | 1 | \$500.00 | \$500.00 |
| Remove/Refix Aircon & Refill Gas | 1 | \$150.00 | \$150.00 |
| Remove/Refix Radiator | 1 | \$90.00 | \$90.00 |
| Rear Wheel Alignment | 1 | \$120.00 | \$120.00 |
| Remove/Refix Undercarriage (Frt) | 1 | \$200.00 | \$200.00 |
| Front Chassis Alignment Charge | 1 | \$400.00 | \$400.00 |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance

tene CLKK) WIL III-83228613 17/2/20, 2-30pm L/S Ry AL SY 9 dys

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

40, 573.90

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

| _ | 8. | - | _ |
|---|----|---|---|
| | - | | - |
| _ | _ | | _ |

13-Feb-20

INSURANCE:

MODEL:

TOYOTA PRIUS

VEHICLE NO .:

SHA2098E

| DESCRIPTION | QTY | LIST PRICE | AMOUNT |
|--|-----|------------|------------|
| BONNET / 01) | 1 | \$950.50 | \$950.50 |
| INSULATOR, HOOD X | 1 | \$398.10 | \$398.10 |
| INSULATOR CLIPS X | 1 | \$3.60 | \$3.60 |
| BONNET RUBBER X | 1 | \$35.50 | \$35.50 |
| BONNET HINGE (RH) / JT | 1 | \$57.70 | \$57.70 |
| BONNET HINGE (LH) / ÎT | 1 | \$57.70 | \$57.70 |
| BONNET LOCK X | 1 | \$132.60 | \$132.60 |
| RADIATOR GRILLE X | 1 | \$438.00 | \$438.00 |
| RADIATOR GRILLE EMBLEM / // | 1 | \$88.00 | \$88.00 |
| FRONT BUMPER COVER / BR | 1 | \$499.90 | \$499.90 |
| FRONT BUMPER REINFORCEMENT X | 1 | \$696.40 | \$696.40 |
| FRONT BUMPER REINFORCEMENT ABSORBER X | 1 | \$115.70 | \$115.70 |
| FT BUMPER LOWER REINFORCEMENT BRACKET | 1 | \$330.00 | \$330.00 |
| FRONT BUMPER SPONGE / DR | 1 | \$78.80 | \$78.80 |
| FRONT BUMPER CENTRE GRILLE | 1 | \$301.90 | \$301.90 |
| FRONT BUMPER LOWER GRILLE | 1 | \$148.60 | \$148.60 |
| LAMP ASSY, FOG, LH X | 1 | \$920.00 | \$920.00 |
| FRONT BUMPER CLIPS / 1/C | 1 | \$22.00 | \$22.00 |
| FRONT BUMPER SIDE RETAINER / 🌃 | 1 | \$77.00 | \$77.00 |
| COVER, FRONT BUMPER HOLE, LH X | 1 | \$28.38 | \$28.38 |
| REINFORCEMENT, FRONT BUMPER LOWER X | 1 | \$236.10 | \$236.10 |
| BRACKET FT BUMPER EXTENSION MOUNTING X | 1 | \$110.40 | \$110.40 |
| SUPPORT FR BUMPER, LH 🗵 | 1 | \$81.70 | \$81.70 |
| FRONT BUMPER CENTRE FRAME X | 1 | \$236.90 | \$236.90 |
| BRACKET, FRONT BUMPER SIDE, LH | 1 | \$82.30 | \$82.30 |
| BRACKET, FRONT BUMPER MOUNTING | 1 | \$29.60 | \$29.60 |
| BRACKET, FRONT BUMPER MOUNTING, NO. 2 | 1 | \$97.80 | \$97.80 |
| ABSORBER, FRONT BUMPER, LOWER | 1 | \$127.70 | \$127.70 |
| UNIT ASSY, HEADLAMP, LH (LED) / IIK | 1 | \$3,455.00 | \$3,455.00 |
| HEAD LAMP PANEL (LH) | 1 | \$240.10 | \$240.10 |
| TOP PANEL CENTRE / DÛ | 1 | \$364.98 | \$364.98 |
| TOP PANEL SIDE / 00 | 1 | \$145.90 | \$145.90 |
| BRACE PANEL X | 1 | \$75.20 | \$75.20 |
| BRACKET, HEADLAMP MOUNTING, LH × | 1 | \$25.50 | \$25.50 |
| HEADLAMP BULB / []R | 1 | \$34.30 | \$34.30 |
| RADIATOR ASSY X | 1 | \$1,841.80 | \$1,841.80 |
| RADIATOR FAN MOTOR ASSY X | 1 | \$661.30 | \$661.30 |
| STAY, RADIATOR SUPPORT, LH X | 1 | \$65.70 | \$65.70 |
| DEFLECTOR, RADIATOR SIDE, LH X | 1 | \$83.50 | \$83.50 |
| CONDENSER ASSY, W/RECEIVER 15 Phones | 1 | \$1,336.60 | \$1,336.60 |
| AIRCON DISCHARGE HOSE X | 1 | \$386.90 | \$386.90 |

| NDER SUB-ASSY, FRONT LH 00 | 1 | \$945.30 | \$945.30 |
|--|-----|------------|--------------|
| RONT HOUSING ASSY / III | 1 | \$945.26 | |
| FRONT FENDER SHIELD TAI | 1 | \$198.50 | |
| FRONT FENDER SHIELD CLIP / //C | 1 | \$14.90 | |
| FRONT FENDER HYBRID EMBLEM, LH / I/C | 1 | \$86.50 | |
| FRONT FENDER ADVERTISEMENT LOGO (LH) Nett | 1 | \$100.00 | |
| BRACKET, FRONT SIDE PANEL, LH / /// | 1 | \$44.50 | |
| EXTENSION, FRONT FENDER, LH X | | \$47.20 | |
| PROTECTOR, FRONT FENDER UPPER, LH X | 1 | | |
| GUSSET, FRONT FENDER APRON, LOWER LH | - 1 | \$46.10 | |
| MEMBER, FRONT APRON TO COWL SIDE, UPPER LH X | - 1 | \$34.90 | |
| FRONT APRON TO COWL SIDE, LOWER FRT LH | - 1 | \$138.40 | |
| EPONT WINDSCOPERN OF ACCUMENTS | | \$82.30 | |
| FRONT WINDSCREEN GLASS MOULDING | 1 | \$208.60 | |
| FUSE BOX TOP COVER / CPM | 1 | \$339.56 | \$339.56 |
| FUSE BOX BOTTOM COVER X | 1 | \$82.30 | \$82.30 |
| FUSE BOX ASSY X | 1 | \$71.00 | \$71.00 |
| | 1 | \$131.80 | \$131.80 |
| | 1 | \$1,570.55 | \$1,570.55 |
| FRONT WHEEL HUB CAP X | 1 | \$175.80 | \$175.80 |
| FRONT WHEEL HUB BEARING X | 1 | \$559.94 | \$559.94 |
| FRONT SUSPENSION LOWER ARM (LH) X | 1 | \$631.90 | \$631.90 |
| FRONT SHOCK ABSORBER (LH) | 1 | \$398.20 | \$398.20 |
| ABSORBER TOP MOUNTING | - 1 | \$196.20 | \$196.20 |
| FRONT DRIVE SHAFT (LH) | 1 | \$1,764.00 | \$1,764.00 |
| RACK & PINION ASSY × | 1 | \$1,621.30 | \$1,621.30 |
| BAR, STABILIZER X | 1 | \$352.40 | \$352.40 |
| LINK ASSY, FRONT STABILIZER, LH X | 1 | \$196.80 | \$196.80 |
| KNUCKLE, STEERING, LH | 1 | \$580.80 | \$580.80 |
| HUB SUB-ASSY, FRONT AXLE, RH/LH X | 1 | \$549.70 | \$549.70 |
| END SUB-ASSY, TIE ROD, LH | 1 | \$159.30 | \$159.30 |
| ENGINE MOUNTING (LH/RH) | 1 | \$382.70 | \$382.70 |
| ENGINE MTG (FRONT) | 1 | \$174.63 | \$174.63 |
| ENGINE ROOM WIR FRT FOR FUSE BOX | 1 | \$207.20 | \$207.20 |
| FRONT BRAKE ABS SENSOR ONLY | 1 | \$450.70 | \$450.70 |
| WIRING FRONT | 1 | \$8,450.50 | \$8,450.50 |
| | | 40,100.00 | 40,100.00 |
| SUB TOTAL | | | \$37,039.40 |
| LESS 20% 25% | | | \$7,407.88 |
| DISCOUNTED TOTAL | | | \$29,631.52 |
| | | | \$20,00 1.02 |
| FRONT BUMPER LOGO X Nett | 1 | \$87.10 | \$87.10 |
| FRONT TYRE (LH/RH) X Nett | 11 | \$216.00 | \$216.00 |
| 1 1 2 | | \$210.00 | \$210.00 |
| SUB TOTAL | | | \$303.10 |
| | | | \$303.10 |
| Labour Charge | | | |
| Panel Beating | - | 04 000 00 | |
| Spray Painting Charge | 1 | \$1,800.00 | \$1,800.00 |
| Wiring Charge | 1 | \$1,200.00 | \$1,200.00 |
| Tuff Kote | 1 | \$200.00 | \$200.00 |
| | 11 | \$150.00 | \$150.00 |
| Towing Charge | 1 | \$50.00 | \$50.00 |

0,373.90 -757. 780.42

400 00

| ESTIMATE TOTAL | | | \$36,094.62 |
|--|----|----------|-------------|
| TOTAL LABOUR | | | \$6,160.00 |
| | | \$550.00 | \$550.00 |
| Remove/Refix Air Bag/Steering Wheel/Dashboard/Seat | 1 | \$550.00 | \$550.00 |
| Remove/Refix Front Windscreen Glass | 1 | \$120.00 | \$120.00 |
| Remove/Refix Fuse Box | 1 | \$180.00 | \$180.00 |
| Remove/Refix Dashboard | 1 | \$450.00 | \$450.00 |
| Remove/Refix Engine | 1 | \$500.00 | \$500.00 |
| Remove/Refix Aircon & Refill Gas | 1 | \$150.00 | \$150.00 |
| Remove/Refix Radiator | 1 | \$90.00 | \$90.00 |
| Rear Wheel Alignment | 1 | \$120.00 | \$120.00 |
| kemove/Refix Undercarriage (Frt) | 11 | \$200.00 | \$200.00 |
| ont Chassis Alignment Charge | 1 | \$400.00 | \$400.00 |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance

Steve CLKK) ML A:L 83218613 17/2/20, 2-30pm L/S Ry AL SY 9 dys Suppl Headlyp RH

P-7789.42 L-2659 SYM-4174.32 14,694-74 L/S-11,683.79 = 11,790.90

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

| DATE: | 18-Feb-20 | | |
|--------------|--------------|------------|--|
| MODEL: | TOYOTA PRIUS | INSURANCE: | |
| VEHICLE NO.: | SHA2098E | | |

SHA2098E

| DESCRIPTION | QTY | LIST PRICE | AMOUNT |
|--|-----|------------|-------------|
| UNIT ASSY, HEADLAMP, RH (LED) money are | 1 | \$3,455.00 | \$3,455.00 |
| FRONT FENDER TOP GARNISH LEFT AND SHOULD | 1 | \$148.00 | \$148.00 |
| FRONT WINDSCREEN GLASS CANC | 1 | \$1,627.30 | \$1,627.30 |
| FRONT WINDSCREEN GLASS MOULDING LOWER ~~ | 1 | \$268.80 | \$268.80 |
| | | | |
| SUB TOTAL | | | \$5,499.10 |
| LESS 20% 25% | | | \$1,099.82 |
| DISCOUNTED TOTAL | | | \$4,399.28 |
| FRONT WINDSCREEN GLASS SEALANT New SN | 2 | \$40.00 | \$80.00 |
| | | | |
| | | | |
| SUB TOTAL | | | \$ 80.00 |
| ESTIMATE TOTAL | | | \$ 4,479.28 |

P- 4174-32 N- 50 4174-32



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale | Des Experts En Automobile |
|---|---------------------------|
|---|---------------------------|

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20002577/Evf3e2

50 RAFFLES PLACE

#05-01/06

Date: 27-02-2020

SINGAPORE LAND TOWERSINGAPORE 048623

| 200 | | | | - |
|------|----|------|------|---|
| - 11 | шш | 1000 | 100 | ш |
| - 11 | | | | ш |
| - 11 | шш | | | ш |
| - 11 | шш | | | ш |
| - 11 | шш | | | ш |

| 1. | | Policy Particul | ars :- THIRD PARTY CLA | JM. |
|-----|----------------|---|------------------------|------------------|
| | Insured Veh. | GBC 3700D | Veh. Inspected | SHA 2098E |
| | Policy No. | | Coverage (\$) | 0.00 |
| | Claim No. | CMTD2000709/SYH | Excess (\$) | 0.00 |
| | Assign From | GRACE TEO | Assign Date | 14/02/2020 |
| 2. | | Vehicle P | articulars & Condition | |
| | Make & Model | TOYOTA PRIUS | c.c | 1798 |
| | Engine No. | HIDDEN | Year of Reg. | 2017 |
| | Chassis No. | JTDKB3FU703558764 | Colour | BLUE |
| | Odometer | 466130 | Steering | IN ORDER |
| | Brakes | IN ORDER | Modification | SPORTS RIM |
| | General | GOOD | | |
| 3. | | Con | ditions of Tyres | |
| | | Size | Make | Balance |
| | R/H Front Tyre | 195/65 R15 | DAVANTI | 5 mm |
| | L/H Front Tyre | 195/65 R15 | DAVANTI | 5 mm |
| | R/H Rear Tyre | 195/65 R15 | DAVANTI | 5 mm |
| | L/H Rear Tyre | 195/65 R15 | DAVANTI | 5 mm |
| 4. | | Descr | iption of Damages | DA HOUSE LINES |
| | THE VEHICLE SU | STAINED DAMAGES AT THE | FRONT N/S PORTION. | |
| | DAMAGES SEE D | ETAILS. | | |
| 5. | | Gen | eral Information | |
| | Accident Date | 11/02/2020 | Inspection Date | 17/02/2020 |
| | Survey held at | BLK 9 SECTOR C #01-42 S | IN MING ESTATE | |
| | Repairer | BIFROST AUTO PTE LTD | | |
| 5a. | | THE PERSON OF | Remarks | TO THE RESIDENCE |
| | | ON WAS CONDUCTED ON A' CE TO YOUR INSTRUCTION: | | |
| 5b. | | Estim | ate Days of Repair | |
| | ESTIMATED NOR | MAL PERIOD FOR REPAIR: | 9 Working Da | ys |



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 2098E

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---------------------------------------|---------------|-------------------------------|----------------------|
| | REPLACEMENT OF PARTS | | | 1 |
| 1 | BONNET | DENTED | 950.50 | 950.50 |
| 1 | INSULATOR, HOOD | NOT NECESSARY | 398.10 | |
| 1 | INSULATOR CLIPS | NOT NECESSARY | 3.60 | |
| 1 | BONNET RUBBER | NOT NECESSARY | 35.50 | |
| 1 | BONNET HINGE (RH) | BENT | 57.70 | 57.70 |
| 1 | BONNET HINGE (LH) | BENT | 57.70 | 57.70 |
| 1 | BONNET LOCK | NOT NECESSARY | 132.60 | |
| 1 | RADIATOR GRILLE | NOT NECESSARY | 438.00 | 9 |
| 1 | RADIATOR GRILLE EMBLEM | NECESSARY | 88.00 | 88.00 |
| 1 | FRONT BUMPER COVER | BROKEN | 499.90 | 499.90 |
| 1 | FRONT BUMPER REINFORCEMENT | NOT NECESSARY | 696.40 | 9 |
| 1 | FRONT BUMPER REINFORCEMENT ABSORBER | NOT NECESSARY | 115.70 | 9 |
| 1 | FT BUMPER LOWER REINFORCEMENT BRACKET | NOT NECESSARY | 330.00 | |
| 1 | FRONT BUMPER SPONGE | BROKEN | 78.80 | 78.80 |
| 1 | FRONT BUMPER CENTRE GRILLE | NOT NECESSARY | 301.90 | |
| 1 | FRONT BUMPER LOWER GRILLE | NOT NECESSARY | 148.60 | |
| 1 | LAMP ASSY, FOG, LH | NOT NECESSARY | 920.00 | |
| 1 | FRONT BUMPER CLIPS | NECESSARY | 22.00 | 22.00 |
| 1 | FRONT BUMPER SIDE RETAINER | BROKEN | 77.00 | 77.00 |
| 1 | COVER, FRONT BUMPER HOLE, LH | NOT NECESSARY | 28.38 | 3 |
| 1 | REINFORCEMENT, FRONT BUMPER LOWER | NOT NECESSARY | 236.10 | , |
| 1 | BRACKET FT BUMPER EXTENSION MOUNTING | NOT NECESSARY | 110.40 | 3 |
| 1 | SUPPORT FR BUMPER, LH | NOT NECESSARY | 81.70 | |
| 1 | FRONT BUMPER CENTRE FRAME | NOT NECESSARY | 236.90 | |
| 1 | BRACKET, FRONT BUMPER SIDE, LH | NOT NECESSARY | 82.30 | |
| 1 | BRACKET, FRONT BUMPER MOUNTING | NOT NECESSARY | 29.60 | 5 |
| 1 | BRACKET, FRONT BUMPER MOUNTING, NO.2 | NOT NECESSARY | 97.80 | |
| 1 | ABSORBER, FRONT BUMPER, LOWER | NOT NECESSARY | 127.70 | 1 |
| 1 | UNIT ASSY, HEADLAMP, LH (LED) | BROKEN | 3,455.00 | 3,455.00 |
| 1 | HEAD LAMP PANEL (LH) | DENTED | 240.10 | 240.10 |
| 1 | TOP PANEL CENTRE | DENTED | 364.98 | 364.98 |

Report Ref No. CS/SMO20002577/Evf3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 4

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|---------------|-------------------------------|----------------------|
| 1 | TOP PANEL SIDE | DENTED | 145.90 | 145.90 |
| 1 | BRACE PANEL | NOT NECESSARY | 75.20 | |
| 1 | BRACKET, HEADLAMP MOUNTING, LH | NOT NECESSARY | 25.50 | 9 |
| 1 | HEADLAMP BULB | BROKEN | 34.30 | 34.30 |
| 1 | RADIATOR ASSY | NOT NECESSARY | 1,841.80 | 9 |
| 1 | RADIATOR FAN MOTOR ASSY | NOT NECESSARY | 661.30 | |
| 1 | STAY, RADIATOR SUPPORT, LH | NOT NECESSARY | 65.70 | ā |
| 1 | DEFLECTOR, RADIATOR SIDE, LH | NOT NECESSARY | 83.50 | 3 |
| 1 | CONDENSER ASSY, W/RECEIVER | DENTED | 1,336.60 | 1,336.60 |
| 1 | AIRCON DISCHARGE HOSE | NOT NECESSARY | 386.90 | 3 |
| 1 | FENDER SUB-ASSY, FRONT LH | DENTED | 945.30 | 945.30 |
| 1 | FRONT HOUSING ASSY | DENTED | 945.26 | 945.26 |
| 1 | FRONT FENDER SHIELD | TORN | 198.50 | 198.50 |
| 1 | FRONT FENDER SHIELD CLIP | NECESSARY | 14.90 | 14.90 |
| 1 | FRONT FENDER HYBRID EMBLEM, LH | NECESSARY | 86.50 | 86.50 |
| 1 | FRONT FENDER ADVERTISEMENT LOGO (LH) | NECESSARY | 100.00 | 100.00 |
| 1 | BRACKET, FRONT SIDE PANEL, LH | DENTED | 44.50 | 44.50 |
| 1 | EXTENSION, FRONT FENDER, LH | NOT NECESSARY | 47.20 | 3 |
| 1 | PROTECTOR, FRONT FENDER UPPER, LH | NOT NECESSARY | 46.10 | |
| 1 | GUSSET, FRONT FENDER APRON, LOWER LH | NOT NECESSARY | 34.90 | |
| 1 | MEMBER, FRONT APRON TO COWL SIDE, UPPER LH | NOT NECESSARY | 138.40 | |
| 1 | FRONR APRON TO COWL SIDE, LOWER FRT LH | NOT NECESSARY | 82.30 | 3 |
| 1 | FRONT WINDSCREEN GLASS MOULDING | NECESSARY | 208.60 | 208.60 |
| 1 | FRONT WINDSCREEN GLASS PILLAR | BROKEN | 339.56 | 339.56 |
| 1 | FUSE BOX TOP COVER | CRUSHED | 82.30 | 82.30 |
| 1 | FUSE BOX BOTTOM COVER | NOT NECESSARY | 71.00 | |
| 1 | FUSE BOX ASSY | NOT NECESSARY | 131.80 | |
| 1 | FRONT WHEEL RIM | NOT NECESSARY | 1,570.55 | |
| 1 | FRONT WHEEL HUB CAP | NOT NECESSARY | 175.80 | , |
| 1 | FRONT WHEEL HUB BEARING | NOT NECESSARY | 559.94 | |
| 1 | FRONT SUSPENSION LOWER ARM (LH) | NOT NECESSARY | 631.90 | , |
| 1 | FRONT SHOCK ABSORBER (LH) | NOT NECESSARY | 398.20 | |
| -2 | ABSORBER TOP MOUNTING | NOT NECESSARY | 196.20 | |

Report Ref No. CS/SMO20002577/Evf3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 3 of 4

| ty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|----|--|---------------|-------------------------------|----------------------|
| 1 | FRONT DRIVE SHAFT (LH) | NOT NECESSARY | 1,764.00 | |
| 1 | RACK & PINION ASSY | NOT NECESSARY | 1,621.30 | |
| 1 | BAR, STABILIZER | NOT NECESSARY | 352.40 | i i |
| 1 | LINK ASSY, FRONT STABILIZER, LH | NOT NECESSARY | 196.80 | |
| 1 | KNUCKLE, STEERING, LH | NOT NECESSARY | 580.80 | |
| 2 | HUB SUB-ASSY, FRONT AXLE, RH / LH | NOT NECESSARY | 549.70 | |
| 1 | END SUB-ASSY, TIE ROD, LH | NOT NECESSARY | 159.30 | |
| 2 | ENGINE MOUNTING (LH/RH) | NOT NECESSARY | 382.70 | |
| 1 | ENGINE MTG (FRONT) | NOT NECESSARY | 174.63 | i . |
| 1 | ENGINE ROOM WIR FRT FOR FUSE BOX | NOT NECESSARY | 207.20 | |
| 1 | FRONT BRAKE ABS SENSOR ONLY | NOT NECESSARY | 450.70 | 9 |
| 1 | WIRING FRONT | NOT NECESSARY | 8,450.50 | |
| 1 | UNIT ASSY, HEADLAMP, RH (LED) (ADDITIONAL) | MTG CRACKED | 3,455.00 | 3,455.00 |
| 1 | FRONT FENDER TOP GARNISH LEFT (ADDITIONAL) | DISLODGE | 148.00 | 148.00 |
| 1 | FRONT WINDSCREEN GLASS (ADDITIONAL) | CRACKED | 1,627.30 | 1,627.30 |
| 1 | FRONT WINDSCREEN GLASS MOULDING LOWER (ADDITIONAL) | NECESSARY | 268.80 | 268.80 |
| | LESS 20% DISCOUNT | | -8,507.70 | 9 |
| | LESS 25% DISCOUNT | | - | -3,968.25 |
| | | | 34,030.80 | 11,904.75 |
| | SPECIAL NETT ITEMS | | | |
| 1 | FRONT BUMPER LOGO (SN) | NOT NECESSARY | 87.10 | |
| 2 | FRONT TYRE (LH/RH) (SN) | NOT NECESSARY | 216.00 | |
| 2 | FRONT WINDSCREEN GLASS SEALANT @\$40.00 (SN) (ADDITIONAL) | NECESSARY | 80.00 | 50.00 |
| | LABOUR | | 383.10 | 50.00 |
| | | | | 4.400.00 |
| | PANEL BEATING | | 1,800.00 | 1,400.00 |
| | SPRAY PAINTING CHARGE. | 1) | 1,200.00 | 800.00 |
| | WIRING CHARGE. | | 200.00 | 30.00 |
| | TUFF KOTE. | | 150.00 | 50.00 |
| | TOWING CHARGE | MOT MEGEORIES | 50.00 | 50.00 |
| | FRONT CHASSIS ALIGNMENT CHARGE | NOT NECESSARY | 400.00 | |

Report Ref No. CS/SMO20002577/Evf3e2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|---------------|-------------------------------|----------------------|
| | REMOVE / REFIX UNDERCARRIAGE (FRT). | NOT NECESSARY | 200.00 | |
| | REAR WHEEL ALIGNMENT. | NOT NECESSARY | 120.00 | 9 |
| | REMOVE / REFIX RADIATOR. | | 90.00 | 50.00 |
| | REMOVE / REFIX AIRCON & REFILL GAS. | | 150.00 | 120.00 |
| | REMOVE / REFIX ENGINE. | NOT NECESSARY | 500.00 | 8- |
| | REMOVE / REFIX DASHBOARD. | NOT NECESSARY | 450.00 | |
| | REMOVE / REFIX FUSE BOX. | | 180.00 | 30.00 |
| | REMOVE / REFIX FRONT WINDSCREEN GLASS. | | 120.00 | 120.00 |
| | REMOVE / REFIX AIR BAG / STEERING WHEEL / DASHBOARD / SEAT. | NOT NECESSARY | 550.00 | 5= |
| | | | 6,160.00 | 2,650.00 |
| | GRAND TOTAL | | 40,573.90 | 14,604.75 |

| RECOMMENDED COST OF LUMP SUM REPAIRS | 11,700.00 |
|--------------------------------------|-----------|
| (TO ITS PRE-ACCIDENT CONDITION) | |

Report Ref No. CS/SMO20002577/Evf3e2



CHEN TSUE YEE

Automotive Assessor

St. S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report. In whole or in part, does so at his or her own risk.