

AUTOLUTION INDUSTRIAL PTE LTD
1 UBI ROAD 4
SINGAPORE 108000
TEL: 6490 9999 FAX: 6490 9999

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0072/20
DATE : 11-FEB-2020

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63896111
FAX : 62247175

OWNER'S NAME : DREW & NAPIER LLC
ADDRESS : 10 COLLYER QUAY #10-01
OCEAN FINANCIAL CENTRE
S(049315)
TELEPHONE NO : 65312448/96960881

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 2100266922-08
VEHICLE NO : SDF1889S
MODEL CODE : TDBARTWE52ED8-----
MODEL/YEAR : ELGRAND QR25DE 250 2WD HIGHWAY STAR 8PAX (PI)
ENGINE NO : QR25175765B
CHASSIS NO : TE52011125
MILEAGE : 167455 KM
DATE IN : 11/02/2020
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER
ACCIDENT DATE : 11/02/2020

*not Authorized
when received
18/2/20
The phd Repairing
3 days*

LIK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- This part survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

- 9645 0084 elmur@fanchong.com

LIK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- This part survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SDF1889S

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOR CHARGES TO REPAIR RH QUARTER PANEL,RH RR SIGHT SHIELD RENEW RH SLIDING DOOR	1560.00	390
2 ZZ/002	CHARGES TO SPRAY PAINTING SAME	800.00	750
3 ZZ/003	REMOVE AND TRANSFER RH SLIDING DOOR MECHANISM	80.00	✓
4 ZZ/004	APPLY SEALANT TO RH SLIDING DOOR	100.00	✓
TOTAL LABOUR CHARGES		2540.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SDF1889S

DAMAGED PARTS & PRICES				
S/NO PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT REMARKS
1 RH SLIDING DOOR LOWER MOULDING	82870-1JB0B	5 cr 694.10	✓	
2 RH SLIDE DOOR INNER RR SASH TAPE	82814-1JA1D	nel 32.50	✓	
3 RH SLIDING DOOR RR SASH TAPE	82816-1JA0A	nel 19.50	✓	
4 RH SLIDING DOOR FRT SASH TAPE	82814-1JA0B	nel 39.30	✓	
5 RH SLIDING DOOR	H210M-1JAAB	10/21 1420.90	✓	
6 SUNDRIES	NPN			50.00 ?
SUB TOTAL		2206.30	0.00	50.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		441.26	0.00	0.00
GRAND TOTAL		1765.04	0.00	50.00
OVERALL TOTAL		1815.04		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SDF1889S

TOTAL LABOUR CHARGES	2540.00
TOTAL SPARE PARTS CHARGES	1815.04

GRAND TOTAL	4355.04 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.