0.1.000	MS1 (1) Date/Time: 14.1. 2000 11 26 0. 60
Estimated Cost:	Bill to:
OD / TP / WS / TP RES / OD RES / EVA / INV / MT To Inspect Vehicle No: SD V 45562 at Workshop m/s Bi fros?	10 Insured: PBG 97627 Tel: 97921327
of Blk 9 sector C #01-42 Sin Ming	1
Policy No: MSC/V20-000740	Claim No: MSD/VMS/19-998230_NIT
Sum Insured:	Excess:
Make of Veh:	D.O.A. 16. 1. 20 70
CA / REV / REP. / REV 24 HRS  Date/Time: 14 mm 11-44 n Person Contact	MS Le Vehicle IN LOUT
Date/Time Action/Instruction ( V ) Estin	nute.
5DV 45562 -X	
PBG 9762P - X	
19/1/2001.50 an verised to 1	nene Tan via Merrimen.

3.	ASS, REC. BY: REF: MSG			
*		SIGNMENT		
	Erom: Date: 18 127070	Veh No: SOV 4556 7	Yr Regn:	10
		Type: M.Car M.Cycle / Bus / Van / Lorry		
	Estimated Cost:	Truck / Trailer or		
	OD/TP/WS/TP RES/OD RES/EVA/INV/MV	1- 2	C.C	1588
	To Inspect Vehicle No: SDV 45562	1 0	A/C: Insured / Std	
	at Workshop m/s Lim Tan (Bifnost)	086.12	T/Radio: Insured / Sto	
	of \$103-09 Six ming Autolore	_ Sp.Reading	(Madio, Modrod Co.	
	Insured:	Eng/No: TN 6BL 10	21.101	5 158=
	Policy No.		THOIS	1773
	Claims No.	Gen. Cond: 2000 Fair / Poor / Burnt	77V225777	
	Sum Insured: Excess:	Steering: Inorder? Jammed / Leaked / Br		
	(Client's Record)	Brake: Inerder / Jammed / Leaked / Br	urnt or	
	Make of Veh:	Modi: Nil / S/Rim / STE AJRim or	5/2000	
		Tyre Size: F: 20	5/55R16	
	(Policy Condition)	R:		e Latine
	Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / M	IIC / OHTSU / PIR / S	UMI /
	repair at the time of inspection.	TOYO / YOKO or		
	Bal, or Market Value:	Front 0	Rear	D
	IDAC Accident Rport: Consistent? : Yes or No	R/Bal. mm	R/Bal. O	mm
	GIA / PR Seen: Consistent? : Yes or No	L/Bal. P mm	L/Bal.	mm
	Est. Repairs: \$5 days Res.: Yes or No	D.O.A. 16/1/20	D.O.I. 181	12/20
	Lum Sum: 20 % 3 Val.: Yes or No	Survey held at		
	moil	Des. of Damages : Frt Rear / O/S /	N/S / U/C / Roofto	p or
	CA / REV / REP. / 24 HRS Vehicle: IN / C	DUT		
	Date: Person Contacted:	The U/C / Chassis frame / Body	Structure affected du	e to collision.
	Date / Time Action / Instruction			
	DE(	FIVER 1.2 MAR 2020		
	KEA	O E I V E D . Z		
	de .			
	- E			
	GLEENING .	Days Of Repair:		
	Date/Time, File Pass to? : Prell. Report		[	
	1)(23 MMM : Final Report	Resurvey No. of Trip: 2	Survey Fee:	150
	Date/Time, File Return to?	F	Transportation:	11
	2) Add	Fee: Site Insp (\$	_)S+RS,SI	•1
	¥	: Interview (\$	_) Photos	
	Report Format: MENTI Lump Sum / I.B.K. (\$ 3550 )	: Tech. Invs (\$	Others	
	Lump Sum / I.B.F. (\$ 3550 )	:Weekend (\$	_)	7/
			TOTAL	161

### Note: This document has not been finalised.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:

MSIG Insurance (Singapore) Pte. Ltd.

4 Shenton Way #21-01 SGX Centre 2 Singapore 068807

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn:

Irene Tan Gek Ing

Date:

19 Feb 2020

### **Preliminary Advice**

Insured Vehicle No : FBG9762P

TP Vehicle No

: SDV4556Z

Accident Date

: 16/01/2020

Make

: MAZDA 3

Assignment Date

: 14/02/2020

Date of Inspection

: 18/02/2020

Est. Duration of Repair

: 5.00

Inspection At

: BIFROST AUTO PTE LTD (SIN MING) (HQ)

BLK 9 SECTOR C, #01-42 SIN MING INDUSTRIAL ESTATE

SINGAPORE 575644

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,217.84
Revised Amount	:S\$	2,841.68
Check Items (Estimated)	:S\$	2,317.68
Total	:S\$	5,159.36

:S\$ Lump Sum Repair

#### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

#### Remarks

						the second secon		
1	fo: 9	The	vehicle	is econ	omical/not	economical	tor re	pair.

The above survey was conducted on a 'without prejudice' basis.

### Nivitha (LKK Auto)

From:

Crystal Lee <crystal\_lee@sg.msig-asia.com>

Sent:

Friday, 14 February 2020 11:26 AM Admin-D (LKKAuto); assignments

To: Cc:

Ong Zi Hui

Subject:

Survey Request - Manual Assigned

Attachments:

SDV 4556Z - GIA REPORT.PDF

### PRS F of Our client vehicle SDV4556Z and your insured's vehicle FBG9762P (MSIG) on 16.01.2020

#### Manual Assigned

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you & Best regards, Crystal Lee Admin Officer, Claims Services (In-House Survey) D: +65 6594 2535 | F: +65 6643 1349 | crystal\_lee@sg.msig-asia.com



### MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg









A Member of MS&AD INSURANCE GROUP

From: Helene Phua <helene\_phua@sg.msig-asia.com>

Sent: Friday, 14 February 2020 10:56 AM

To: Crystal Lee <crystal\_lee@sg.msig-asia.com>; Ong Zi Hui <zihui\_ong@sg.msig-asia.com>

Subject: FW: PRS F of Our client vehicle SDV4556Z and your insured's vehicle FBG9762P (MSIG) on 16.01.2020 Car in

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene\_phua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg





A Member of MS&AD INSURANCE GROUP

From: Helene Phua

Sent: Friday, 14 February 2020 10:55 AM

To: 'Claims Dept' < claims | Itv@bifrostauto.com>

Cc: Winnie Chua <pingping chua@sg.msig-asia.com>

Subject: RE: PRS F of Our client vehicle SDV4556Z and your insured's vehicle FBG9762P (MSIG) on 16.01.2020 Car in

Hi,

Thank you for your selection.

We will proceed to assign LKK Auto Consultants Pte Ltd via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion. Any arrangement or appointment of surveyor must come from MSIG.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Have a great week ahead!

#### Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene\_phua@sg.msig-asia.com



### MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg





A Member of MS&AD INSURANCE GROUP

From: Claims Dept <claims Itv@bifrostauto.com>

Sent: Thursday, 13 February 2020 5:27 PM

To: Helene Phua < helene phua@sg.msig-asia.com > Cc: Winnie Chua <pingping chua@sg.msig-asia.com>

Subject: Re: PRS F of Our client vehicle SDV4556Z and your insured's vehicle FBG9762P (MSIG) on 16.01.2020 Car in

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Without Prejudice

Dear Helene,

We select LKK Auto Consultants Pte Ltd

Premises for the Pre-repair inspection: Blk 176 Sin Ming Drive #03-09, Sin Ming Autocare, Singapore 575721

BBC	0	0
11/12	-6	E

Bifrost Auto Pte Ltd

Accident Claims Department

+65 9792 1329 (Mobile)

On Thu, 13 Feb 2020 at 17:22, Helene Phua < helene phua@sg.msig-asia.com > wrote:

Hi,

We refer to your email dated 13/02/2020.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Formteam Consultancy Pte Ltd
- 3) A-Pac Adjusters & Surveyors Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) Appraisal VP Pte Ltd
- 6) AutoProbe Consultants
- 7) MSIG In-House Surveyors

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

<sup>\*</sup>This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor\*

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1. Xing Guo Qiang	6) Chow Bo Xiong	
2. Kenneth Kong	7) Siew Meng Hui	
3. Marcus Chua	8) Daniel Chan	
4. Ng You Han	9) Victor Png	
5. Gary Soon	10) Samuel Phun	

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB:

- a. \*Fast lane settlement is not applicable for cases that liability is in dispute\*
- b. If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: <a href="mailto:motorsurvey@sg.msig-asia.com">motorsurvey@sg.msig-asia.com</a>

Have a great week ahead!

#### Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene\_phua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg 🕡 🎯 🕼 🕒 A Member of MS&AD INSURANCE GROUP From: Claims Dept [mailto:claims | Itv@bifrostauto.com] Sent: Thursday, 13 February 2020 5:01 PM To: Winnie Chua <pingping chua@sg.msig-asia.com> Cc: Assessment <<u>claims@bifrostauto.com</u>>; Regina <<u>assessment ltc@bifrostauto.com</u>>; Accident Claims Dept <claims ltr@bifrostauto.com>; Ms Lim <claims ltm@bifrostauto.com> Subject: RE: PRS F of Our client vehicle SDV 4556 Z and your insured's vehicle FBG 9762 P on 16.01.2020 EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s). Without Prejudice Dear Sir/ Mdm, We refer to the above matter. We represent our client, WENDY MARILYN KHOO GEOK, to notify you of the aforesaid accident involving our

client's vehicle SDV 4556 Z and your insured's vehicle FBG 9762 P on 16/01/2020.

Please find enclose our client's GIA report for your necessary action.

This serves as a NOTICE that we are claiming against FBG 9762 P for damages, costs and disbursements.

Please let us know within 2 working days from today, your client's and your intention to conduct a pre-repair survey of our client's vehicle.

PLEASE LET US HAVE A LIST OF YOUR EXTERNAL SURVEYORS FOR OUR SELECTION AS A SINGLE JOINT EXPERT. WE HEREBY GIVING YOU OUR CLIENT'S LIST OF SURVEYOR AS STATED BELOW. OUR CLIENT DO NOT AGREE THE VEHICLE TO BE SURVEYED BY YOUR IN-HOUSE.

- 1] LKK AUTO CONSULTANTS
- 2] FORMTEAM ADJUSTERS PTE LTD
- 3] AUTOPROBE CONSULTANTS
- 4] APPRAISALS ASSOCIATES PTE LTD

If we do not receive any reply from you within the stipulated timeline, we shall proceed to appoint our own surveyor and proceed with the necessary repair for our client's vehicle without further reference to your insured or you.

Premises for the Pre-repair inspection: Blk 9 Sector C #01-42, Sin Ming Industrial Estate, Singapore 575644

Contact Person: Ms Lim / Ms Lee

Contact Email: claims | Itv@bifrostauto.com / claims | Itm@bifrostauto.com

VEH IN (Date & Time) : 13/02/2020

PRS ARRANGEMENT (Date & Time) : AS SOON AS POSSIBLE

Kindly cc a copy of this letter to your insured for his/her acknowledgement.

We look forward to hearing from you soon.

To avoid incurrence of any unnecessary cost on both our end, kindly confirm liability status within 7 days from this to minimize time wastage and incurrence of any unnecessary cost(s) on both our end, we seek your kind advice, within 7 days working days, on liability status for subject claim. If we do not hear from you within the stipulated period, we shall proceed with the purchase of your insured GIA report and this cost or any other cost incurred for confirmation of liability status shall be included in our LOD for reimbursement purpose.

Thank you.

You can protect our environment. Think before you print.

#### CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential.

The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Ms Lee

Bifrost Auto Pte Ltd

Accident Claims Department

+65 9792 1329 (Mobile)

# > Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	000 000 000 000 000 000 000 000 000 00	
Owner ID Type:	Singapore NRIC	
Owner ID: Vehicle Details	812D	
Vehicle No.:	SDV4556Z	
Vehicle to be Exported:	Yes	
Intended Deregistration Date:	17 Jan 2020	
Vehicle Make:	MAZDA	
Vehicle Model:	MAZDA3 1.6L SDN	
Primary Colour:	Red	
Manufacturing Year:	2010	
Engine No.:	Z6864167	
Chassis No.:	JM6BL10Z1A0151595	
Maximum Power Output:	77.0 kW (103 bhp)	
Open Market Value:	\$19,342.00	
Original Registration Date:	17 Sep 2010	
First Registration Date:	17 Sep 2010	
Transfer Count:	0	
Actual ARF Paid: Intended PARF Rebate Details	\$19,342.00	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	16 Sep 2020	
PARF Rebate Amount: Intended COE Rebate Details	\$9,671.00	
COE Expiry Date:	16 Sep 2020	
COE Category:	A - Car (1600cc & below)	
COE Period(Years):	10	
QP Paid:	\$33,089.00	
COE Rebate Amount:	\$2,201.00	
Total Rebate Amount:	\$11,872.00	

The information contained herein is correct as at 17 Jan 2020

# > Back to OneMotoring

Land Transport Authority

Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time:

21 Jan 2020 / 15:29:09

Receipt Date/Time: 21 Jan 2020 / 15:29:09

### Tax Invoice/Receipt

Receipt No.: ITNET-00000-200121-002450

Bravious Receipt No :

Previo	ous Receipt No. :			CCT	Amount
S/N	Item Description/ Business Transaction Reference No.		Amount Before GST (S\$)	GST Amount (S\$)	After GST (S\$)
As at	ilt of Insurance Enquiry - FBG9762P t 16 Jan 2020/18:10:00 rance Co: MSIG INSURANCE (SINGA)	PORE) PTE LTD			
1	Insurance Enquiry - FBG9762P Enquiry Fee 20200121152709741011		7.00	0.49	7.49
	20200121102100141011	Sub-Total	7.00	0.49	7,49
		Total Before Rounding	7.00	0.49	7.49
		Rounding Difference			0.04
		Total Amount Payable			7.45
		Paid By			
		xxxxxxxxxxxx7458	Credit Card: Visa/MasterCard	í	7.45
		Total			7.45
		Cash Change			0.00
		Tendered Amount			7.45
		Excess Refundable Amount			0.00

#### THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

# BIFROST AUTO PTE LTD

### REPAIR ESTIMATE

6-Feb-20 DATE:

INSURANCE: MSIG

MODEL:

MAZDA 3 1.6

Presery Afte Paint

Not Nothank

VEHICLE NO .:

SDV 4556 Z

ESCRIPTION		QTY	UNIT PRICE	LIST PRICE
EAR BUMPER		1	Bu	\$1,102.30
REAR BUMPER RETAINER		2	\$38.90	Su \$77.80
REAR BUMPER REINFORCE	MENT	1		\$556.10
REAR BUMPER CLIPS,		10	\$4.00	Ma \$40.00
EAR BUMPER REFLETOR	ols	mem 2	\$62.20	\$124.40
REAR BUMPER NO PLATE L	AMP	1	Ch	\$163.40
REAR END PANEL		1	1	\$421.80
REAR END PANEL GARNISH	1	1	Mg pro	\$203.00
REAR BOOT LID	1092	1	R	Section Control Control Control
REAR BOOT LOCK		1		m \$177.00
REAR BOOT RUBBER		1		In \$147.80
REAR BOOT 3RD BRAKE LA	MP	1		In \$514.20
REAR BOOT MAZDA EMBLE	M	1		در \$39.20
REAR BOOT 3 EMBLEM		1		\$25.80
REAR BOOT CENTRE EMBL	.EM	1		\$74.50
REAR BOOT REFLECTOR		2		m \$674.20
TAIL LAMP		Su 2	\$1,174.30	\$2,348.60
SUB TOTAL				\$7,909.80
LESS 20%				\$1,581.96
DISCOUNTED TOTAL				\$6,327.84
			0	
REAR BUMPER SENSOR		1	R	
REAR NUMBER PLATE		111		<b>3</b> \$40.00
-1.				\$240.00
SUB TOTAL	LKK Auto Consultants hence notif the Repairer of the religiousses			\$240.00
		<i>y</i>		
	To      To			
Labour Charge	To Same Processor Survey pointing     To Same Processor     Page Processor		0700.00	6700.00
Labour Charge Panel Beating	• To display the SUIVy Pouriting.	1	\$700.00	
	• To display the SUIVy Pouriting.	1	\$800.00	\$800.00
Panel Beating	• To display the SUIVy Pouriting.	1 Sand 1	\$800.00 \$30.00	\$800.00 \$30.00
Panel Beating Spray Painting Charge	• To display the SUIVy Pouriting.	1	\$800.00	\$800.00 \$30.00
Panel Beating Spray Painting Charge Wiring Charge	• To display the SUIVy Pouriting.	1 Sand 1	\$800.00 \$30.00	\$800.00 \$30.00

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG20002584/KQF3N2

Date:

16/03/2020

REFERENCE

MSIG Insurance (Singapore) Pte.

Policy No:

MSD/VMS/19-998230-

Handling Insurer:

Ltd.

Claimant Vehicle

Insured Vehicle No

FBG9762P

No:

SDV4556Z

Date of Loss:

16/01/2020

Nature of Claim:

TP

Claim No:

MSC/V/20-000240

JM6BL10Z1A0151595

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

Colour:

SDV4556Z

Make & Model:

MAZDA 3, 1.6 (A)

17/09/2010 (Man. Year: 2010)

Engine No: Chassis No:

Odometer:

Z6864167

88462 km

Reg. Date:

Metallic Red

Engine Capacity:

1598 cc N/A

Market Value/New Car Price: Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Engine Modification: Yes

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

205/55 R16

Rear Tyre Size:

205/55 R16

Front Left Side:

Yokohama 8 mm

Rear Left Side:

Yokohama 8 mm

Front Right Side:

Yokohama 8 mm

Rear Right Side:

Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,567.84	3,205.84	3,362.00	51.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,650.00	1,280.00	370.00	22.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,217.84	4,485.84	3,732.00	45.41
Approved Total (Overridden) (S\$)		3,550.00		
(S\$)	8,217.84	3,550.00	4,667.84	56.80
+ GST 7.00/7.00% (S\$)	575.25	248,50	326.75	56.80
Nett Amount (S\$)	8,793.09	3,798.50	4,994.59	56.80

INSPECTION

Date of Assignment:

14/02/2020

Date Inspected:

18/02/2020 Inspected At:

Bifrost Auto Pte Ltd (sin Ming) (HQ)

Blk 9 Sector C, #01-42 Sin Ming Industrial Estate

Singapore 575644

Estimated Period of Repair:

5.0 days

Adjuster: KENNETH KONG Manager:

SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

### REPAIR DETAILS

Reference

Version: 1.0 (Last Synchronised: 16 Mar 2020) Part Source: MRM-SG

MAZDA 3 1.6 (A) (Catalogue:Merimen Singapore 1.0) 144 Parts:

(Price-denominated Standard List) Repairer's Labour:

Print Code: (Unsubmitted, no print-code for SDV4556Z)

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with Validity:

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

Recommended	<b>Parts</b>
-------------	--------------

	Commender Qty Part No.		Condition	Repairer's	Amount
		*REAR BUMPER	Buckled	1,102.30 FL	*1,102.30 FL
1	1	*REAR BUMPER RETAINER	Serviceable	77.80 FL	*-FL
2	1	*REAR BUMPER REINFORCEMENT	Bent	556.10 FL	*556.10 FL
3	250	*REAR BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
4	10	*REAR BUMPER REFLECTOR	O/s Mtg Cracked	124,40 FL	*62.20 FL
5	1	*REAR BUMPER NO PLATE LAMP	Missing	163.40 FL	*163.40 FL
6	1	*REAR END PANEL	Bent	421.80 FL	*421.80 FL
7	1	*REAR END PANEL GARNISH	Mtg Distorted	203.00 FL	*203.00 FL
8	1	*REAR BOOT LID	Bent	1,219.70 FL	*1,092.00 FL
9	1	*REAR BOOT LOCK	Cracked	177.00 FL	*177.00 FL
10		*REAR BOOT RUBBER	Serviceable	147.80 FL	*-FL
11	1	*REAR BOOT 3RD BRAKE LAMP	Serviceable	514.20 FL	*-FL
12		*REAR BOOT MAZDA EMBLEM	Necessary	39.20 FL	*39.20 FL
13	1	*REAR BOOT 3 EMBLEM	Necessary	25.80 FL	*25.80 FL
14	1	*REAR BOOT CENTRE EMBLEM	Necessary	74.50 FL	*74.50 FL
15	1	*REAR BOOT REFLECTOR	Serviceable	674.20 FL	*- FL
16	2	*TAIL LAMP	Serviceable	2,348.60 FL	*-FL
17	2	*REAR BUMPER SENSOR	Serviceable	200.00 FS	*- FS
18	_1	*REAR NUMBER PLATE	Bent	40.00 FS	*40.00 FS
19	1		-	2290-00431 - 69	
F=FI	ranchise part. 5=5pt	Nett, L=ListItemDisc.	Sub Total (S\$)	8,149.80	3,997.30
		- List Item Discount	on L Items 20.00/20.00% (S\$)	1,581.96	791.46
			Total Parts (S\$)	6,567.84	3,205.84

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Re	commended Labour	0.000	B i de	Amount
No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items	200	700.00	600.00
1	PANEL BEATING	New		100000
2	SPRAY PAINTING CHARGE	New	800.00	600.00
3	WIRING CHARGE	New	30.00	20.00
4	TUFF KOTE	New	120.00	60.00
	Cortic di cassilla colonia	Gross Labour Cost (S\$)	1,650.00	1,280.00
_	Descri	t was unsubmitted during this print-out.		
	Repor	t was unsubmitted during this print out.		

< END OF ESTIMATES >