

REF: EST/III 20002602/ KV d3 <sup>n2</sup>

Special Endorsement:

Divisions: LI (MUT)Name: menmenASSIGNMENT (Office)From (Person): Gabriel weeof IIIDate/Time: 11/2/2020

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMN 3538T

Insured:

SH 9421 S

at Workshop n/a:

GM Solution

Tel:

6456 0226

of

160 Sin Ming Drive # 03-18/19

Policy No:

mcom0015

Claim No:

MCT20020212

Sum Insured:

Excess:

Make of Veh:

D.O.A. 10/02/2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

<sup>1up</sup>

H.O.D. Endorsement:

Date/Time: 9:50am @ 14/2/2020

Person Contacted:

BernardVehicle IN OUT

Date/Time	Action/Instruction
	<u>Estimate 1</u> ✓
	<u>SMN 3538T - X</u>
	<u>SHD 2878 C - X</u>
<u>27/2</u>	<u>LI Sing @ 510d. confirm (Real 6700-50, 561)</u>
	<u>RECEIVED 27 FEB 2020</u>

ASS. REC. BY:

REF: 711 /

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

04

days

Res.: Yes or No

Lum Sum: \_\_\_\_\_

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No: \_\_\_\_\_

SMN 3538T

Yr Regn: \_\_\_\_\_

09, 10

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: \_\_\_\_\_

M/C180 Komp.c

1597

Colour: \_\_\_\_\_

White

A/C: Insured / Std / Nil / NA

Sp. Reading \_\_\_\_\_

132160

T/Radio: Insured / Std / Nil / NA

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

W0802040452A426721

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: \_\_\_\_\_

F: \_\_\_\_\_

R: \_\_\_\_\_

225/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) / SUMI /  
TOYO / YOKO or

Front

R/Bal. \_\_\_\_\_

9

mm

Rear

R/Bal. \_\_\_\_\_

9

mm

L/Bal. \_\_\_\_\_

9

mm

L/Bal. \_\_\_\_\_

9

mm

D.O.A. \_\_\_\_\_

10/2/20

D.O.I. \_\_\_\_\_

17/2/2020

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S R

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

0.57/2 - typist

Report Format: \_\_\_\_\_

Lump Sum / I.B.I. (\$) \_\_\_\_\_

merimen

5100/2

Days Of Repair: \_\_\_\_\_

4

Resurvey No. of Trip: \_\_\_\_\_

2

Add Fee: \_\_\_\_\_

☐

: Site Insp (\$) \_\_\_\_\_

☐

: Interview (\$) \_\_\_\_\_

☐

: Tech Invs (\$) \_\_\_\_\_

☐

: Weekend (\$) \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S - RS \$ \_\_\_\_\_

F - RS \_\_\_\_\_

Others \_\_\_\_\_

TOTAL

350

11

361

**Nivitha (LKK Auto)**

---

**From:** Motor Claim - III <motorclaim@iii.com.sg>  
**Sent:** Tuesday, 11 February 2020 5:19 PM  
**To:** Sally Chong; 'sur@lkkauto.com'; Admin-D (LKKAuto)  
**Cc:** 'EM Solution Pte Ltd'; Zuhaidah Samsuri  
**Subject:** RE: OUR REF.: E21-112871.20 (SMN 3538T @ 10/02/2020) III'S REF NO : SH 9421S  
**Attachments:** SKU5513M.PDF

P: Bernard  
T: 9.52am 11/2/20  
V: Out  
E: ✓

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SHD2878E and let us have your report urgently.

This claim will be handled by Ms Sherini.

\*Kindly upload this survey request email to merimen.

\*We started using audatex since 1<sup>st</sup> dec 2019. Please do adjustments throught Audatex and upload the report onto Merimen.

Thank You.

Best Regards,  
**Gabriel Wee**



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext - 248

**From:** Sally Chong [mailto:sallychong@visionlawllc.com]  
**Sent:** 11 February, 2020 4:52 PM  
**To:** Motor Claim - III <motorclaim@iii.com.sg>; Zuhaidah Samsuri <aida@iii.com.sg>; Gabriel Wee <Gabriel@iii.com.sg>  
**Cc:** 'EM Solution Pte Ltd' <emautosolution@singnet.com.sg>; Andrew Lim <Andrew@iii.com.sg>; derekkeh@singnet.com.sg; Tanvin13@yahoo.com.sg  
**Subject:** RE: OUR REF.: E21-112871.20 (SMN 3538T @ 10/02/2020) III'S REF NO : SH 9421S  
**Importance:** High

**URGENT**

Dear Gabriel,

**NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES**  
**CLAIMANT: DERRICK CHOO CHEE WEE**

ACCIDENT INVOLVING SMN 3538T & SH 9421S ON 10 FEB 2020 ALONG BUKIT MERAH ROAD/BUKIT MERAH CENTRAL AT ABOUT 16:02 HRS

We refer to your email of even date below and your list of surveyors therein.

Our client now confirms the appointment of KENNETH KONG- LKK Auto Consultants Pte Ltd as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at :

Venue : E M SOLUTION PTE LTD  
160, Sin Ming Drive, #03-18/19, Sin Ming Autocity,  
Singapore 575722  
Contact : Mr. Bernard (Tel: 6456-0226 / 9101-8302)

If you fail to conduct the pre-repair survey within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Thank you.

*Sally Chong*

(Secretary)

VISION LAW LLC

133 NEW BRIDGE ROAD,

#18-01/02, CHINATOWN POINT,

SINGAPORE 059413

TEL: 6534-2811 (ext 115)

FAX : 6535-6802

---

**From:** Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

**Sent:** Tuesday, 11 February, 2020 2:48 PM

**To:** Sally Chong; Zuhaidah Samsuri; Gabriel Wee

**Cc:** 'EM Solution Pte Ltd'; Andrew Lim

**Subject:** RE: OUR REF.: E21-MISC.20 (SMN 3538T @ 10/02/2020) III'S REF NO : SH 9421S

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

We started using audatex since 1<sup>st</sup> dec 2019. Please submit your estimate/quotation through Audatex so that our surveyors can make the adjustments according.

Best Regards,  
**Gabriel Wee**



64 Cecil Street; #05 - IOB Building  
Singapore 049711  
Tel: 6347 6100, Ext - 248

**From:** Sally Chong [mailto:sallychong@visionlawllc.com]

**Sent:** 11 February, 2020 1:34 PM

**To:** Motor Claim - III <motorclaim@iii.com.sg>; Zuhaidah Samsuri <aida@iii.com.sg>; Gabriel Wee <Gabriel@iii.com.sg>

**Cc:** 'EM Solution Pte Ltd' <emautosolution@singnet.com.sg>; Andrew Lim <Andrew@iii.com.sg>

**Subject:** OUR REF.: E21-MISC.20 (SMN 3538T @ 10/02/2020) III'S REF NO : SH 9421S

## VERY URGENT

Dear Sir,

**NOTICE TO INSURERS TO CONDUCT PRE-REPAIR SURVEY WITHIN 2 WORKING DAYS PURSUANT TO PARAGRAPH 2 OF PRE-ACTION PROTOCOL FOR NIMA CASES**

**CLAIMANT: DERRICK CHOO CHEE WEE**

**ACCIDENT INVOLVING SMN 3538T & SH 9421S ON 10 FEB 2020 ALONG BUKIT MERAH ROAD/BUKIT MERAH CENTRAL AT ABOUT 16:02 HRS**

We are instructed by DERRICK CHOO CHEE WEE to notify you of a road traffic accident ON 10 FEB 2020 ALONG BUKIT MERAH ROAD/BUKIT MERAH CENTRAL AT ABOUT 16:02 HRS involving our client's vehicle registration number SMN 3538T and vehicle registration number SH 9421S driven by you/your insured at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client shall proceed to repair the vehicle without reference to you.

Thank you.

*Sally Chong*

(Secretary)

VISION LAW LLC

133 NEW BRIDGE ROAD,

#18-01/02, CHINATOWN POINT,

SINGAPORE 059413

TEL.: 6534-2811 (ext 115)

FAX : 6535-6802

C.c.: VEHICLE OWNER OF SH 9421S

COMFORT TRANSPORTATION PTE LTD

383, Sin Ming Drive,

GAS BUILDING,

Singapore 575717

---

**VISION LAW LLC**

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Address : 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

---

**DISCLAIMER:**

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

---

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

---

**VISION LAW LLC**

Advocates & Solicitors

(Incorporated with limited liability)

Unique Entity No. 200721148H

Address : 133 New Bridge Road #18-01/02 Chinatown Point, Singapore 059413

---

**DISCLAIMER:**

The contents of this email (including any attachments) are confidential and privileged and only intended for the recipient(s) addressed above. If you received this email by error, please notify the sender immediately and destroy it (and all attachments) without reading, storing and/or disseminating any of its contents (in any form) to any person. Email communication is not secure. Vision Law LLC is not liable for any losses arising out of any errors or omissions in the contents resulting from email transmission or any illegal or unauthorised usage or tampering of its email system.

---

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

**DISCLAIMER:**

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	337F
<b>Vehicle Details</b>	
Vehicle No.:	SMN3538T
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Feb 2020
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C180K
Primary Colour:	Blue
Manufacturing Year:	2010
Engine No.:	27191031330928
Chassis No.:	WDD2040452A426721
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$31,893.00
Original Registration Date:	22 Sep 2010
First Registration Date:	22 Sep 2010
Transfer Count:	2
Actual ARF Paid:	\$31,893.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Sep 2020
PARF Rebate Amount:	\$15,946.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	31 Aug 2029
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
PQP Paid:	\$29,328.00
COE Rebate Amount:	\$27,956.00
<b>Total Rebate Amount:</b>	<b>\$43,902.00</b>

The information contained herein is correct as at 19 Feb 2020

OK



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	11/02/2020 13:06
Date Of Accident	10/02/2020 16:00
Exact Location Of Accident	BUKIT MERAH ROAD / BUKIT MERAH CENTRAL
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMN3538T
<b>Insured/Policyholder</b>	
Name Of Registered Owner	DERRICK CHOO CHEE WEE
NRIC No	SXXXX337F
Email Address	KTNCPROPERTIES@GMAIL.COM
Mobile Phone No	(LOCAL) +65-82828319
Alternative Phone No	OTHERS-82828319

### Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C180 KOMPRESSOR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5112019418
Cover Note Number	

### Driver

Name of Driver	DERRICK CHOO CHEE WEE
NRIC No	SXXXX337F
Date Of Birth	13/08/1958
Occupation	INDOOR
Date Of Driving Pass	18/11/1980
Driving Experience	39 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-82828319
Fax Number	
Contact Number	OTHERS-82828319
Email Address	KTNCPROPERTIES@GMAIL.COM

Address	BLK 315 SERANGOON AVE 2 #04-210
Postcode	550315
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	VIDEO IS WITH OWNER
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SH9421S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/TIN No.:



**E M SOLUTION PTE LTD**

**160, Sin Ming Drive, #03-18/19, Sin Ming Autocity, Singapore 575722**

**Tel: 64560226**

**Fax: 64584500**

**Registration No: 201016308K**

12.02.2020

Derrick Choo Chee Wee

12.02.2020  
Not written  
6/100 @ 5100h  
Resurvey After Paint 6/100h

## REPAIR ESTIMATE FOR MERCEDES C180 - SMN 3538 T

QTY	DESCRIPTION	UNIT PRICE	TOTAL PRICE	REMARKS
1 pc	front bumper	1,376.00	1,376.00	
2 pcs	front bumper side chrome mouldings	196.00	392.00	
1 pc	RH front bumper fog lamp	310.00	310.00	X
1 pc	RH front bumper fog lamp grille	103.00	103.00	X
1 pc	front bumper tow hood cover	36.00	36.00	X
2 pcs	front bumper side retainers	44.00	88.00	LT
1 pc	front bumper reinforcement	406.00	406.00	X
2 pcs	front bumper brackets	66.00	132.00	X
1 pc	front bumper inner foam	153.00	153.00	X
1 pc	RH headlamp assy	1,245.00	1,245.00	
1 pc	RH headlamp panel	284.00	284.00	X
1 pc	RH front fender	891.00	891.00	X
1 pc	RH front fender inner shield	232.00	232.00	X
1 pc	RH front fender badge	56.00	56.00	
1 pc	RH front fender chrome moulding	55.00	55.00	
1 pc	RH front shock absorber	598.00	598.00	
1 pc	RH front top arm	339.00	339.00	X
1 pc	RH front lower arm	475.00	475.00	
1 pc	RH front knuckle arm	862.00	862.00	
1 pc	RH front wheel hub w bearing	465.00	465.00	
1 pc	front stabilizer bar	285.00	285.00	X
2 pcs	front stabilizer bar linkages	56.00	112.00	X
			8,895.00	
	Less 10%		889.50	
			8,005.50	
1 set	front bumper clips	45.00	45.00	SN ✓
1 set	RH front fender inner shield clips	30.00	30.00	SN X
1 pc	RH front sport rim	680.00	680.00	SN ✓
1 pc	RH front tyre	360.00	360.00	SN X
1)	Check electrical wirings.	60.00	60.00	201
2)	Repair accident damages and renew above parts.	880.00	880.00	4001
3)	Spray paint on accident affected portions.	880.00	880.00	4401
4)	Lower front suspension to facilitate repair	350.00	350.00	1801
5)	Computerize wheel alignment	100.00	100.00	601
6)	Tuff kote on affected portions.	60.00	60.00	X
7)	Computerize vehicle system reset	350.00	350.00	X
			\$ 11,800.50	



Mercedes-Benz : 204 (C Class 2007-15) : without 4MATIC : Sedan/Wagon Standard Suspension Europe version/USA : 02/2008-  
4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-0°53'	-0°53'	-0°48' -0°05'
10°13'	10°13'	
-0°03'	-0°03'	0°00' 0°10'
13°37'	13°37'	
12°45'	12°45'	
		-2°12' -1°12'

Camber  
Caster  
Toe  
SAI  
Included Angle  
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-2°06'	-2°07'	-0°48' -0°05'
10°17'	10°17'	
-0°14'	-0°15'	0°00' 0°10'
14°58'	14°59'	
12°52'	12°52'	
		-2°12' -1°12'

Front

Cross Camber  
Cross Caster  
Cross SAI  
Total Toe  
Cross Turn Diff.

Actual	Before	Specified Range
1°13'	1°15'	-0°24' 0°24'
-0°04'	-0°04'	-0°30' 0°30'
-1°20'	-1°22'	
-0°18'	-0°18'	0°00' 0°20'

Rear : Left

Actual	Before	Specified Range
-0°56'	-0°56'	-1°34' -0°34'
0°04'	0°04'	0°05' 0°19'

Camber  
Toe

Rear : Right

Actual	Before	Specified Range
-1°14'	-1°14'	-1°34' -0°34'
0°12'	0°12'	0°05' 0°19'

Rear

Cross Camber  
Total Toe  
Thrust Angle

Actual	Before	Specified Range
0°18'	0°18'	-0°30' 0°30'
0°16'	0°16'	0°17' 0°31'
-0°04'	-0°04'	-0°15' 0°15'



SMN3538T

Mercedes-Benz : 204 (C Class)  
4-Wheel Total Alignment

Front : Left

Actual	Before	Specified Range
-0°48'	-1°02'	-0°48' -0°05'
10°09'	10°09'	
0°06'	0°24'	0°00' 0°10'
13°43'	13°58'	
12°55'	12°55'	
		-2°12' -1°12'

Camber  
Caster  
Toe  
SAI  
Included Angle  
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°39'	-0°40'	-0°48' -0°05'
10°31'	10°31'	
0°04'	0°40'	0°00' 0°10'
13°36'	13°38'	
12°58'	12°58'	
		-2°12' -1°12'

Front

Cross Camber  
Cross Caster  
Cross SAI  
Total Toe  
Cross Turn Diff.

Actual	Before	Specified Range
-0°08'	-0°22'	-0°24' 0°24'
-0°22'	-0°22'	-0°30' 0°30'
0°06'	0°20'	
0°11'	1°04'	0°00' 0°20'

Rear : Left

Actual	Before	Specified Range
-0°55'	-1°05'	-1°34' -0°34'
0°11'	0°06'	0°05' 0°19'

Camber  
Toe

Rear : Right

Actual	Before	Specified Range
-1°12'	-1°02'	-1°34' -0°34'
0°10'	0°09'	0°05' 0°19'

Rear

Cross Camber  
Total Toe  
Thrust Angle

Actual	Before	Specified Range
0°17'	-0°04'	-0°30' 0°30'
0°21'	0°16'	0°17' 0°31'
0°00'	-0°02'	-0°15' 0°15'

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III20002602/KVD3N2  
Date: 28/02/2020

## REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015  
Claimant Vehicle No: SMN3538T Insured Vehicle No: SH9421S  
Date of Loss: 10/02/2020 Nature of Claim: TP Claim No: MCT20020212

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No: SMN3538T  
Make & Model: MERCEDES-BENZ C180, 1.6 Kompressor (A) Engine No: 27191031330928  
Reg. Date: 22/09/2010 (Man. Year: 2010) Chassis No: WDD2040452A426721  
Colour: White Odometer: 132160 km  
Engine Capacity: 1597 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): Market Value/New Car Price

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size: 225/45R17 Rear Tyre Size: 225/45R17  
Front Left Side: Pirelli 9 mm Rear Left Side: Pirelli 9 mm  
Front Right Side: Pirelli 9 mm Rear Right Side: Pirelli 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,120.50	5,330.95	3,789.55	41.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,680.00	1,100.00	1,580.00	58.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>11,800.50</b>	<b>6,430.95</b>	<b>5,369.55</b>	<b>45.50</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>5,100.00</b>		
<b>(S\$)</b>	11,800.50	5,100.00	6,700.50	56.78
<b>+ GST 7.00/7.00% (S\$)</b>	826.04	357.00	469.04	56.78
<b>Nett Amount (S\$)</b>	<b>12,626.54</b>	<b>5,457.00</b>	<b>7,169.54</b>	<b>56.78</b>

## INSPECTION

Date of Assignment: 11/02/2020  
Date Inspected: 17/02/2020 Inspected At: Em Solution Pte Ltd (160 Sin Ming) (HQ)  
160 Sin Ming Drive, #03-19 Sin Ming Autocity  
Singapore 575722  
Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

## Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Feb 2020)

Parts: 143 MERCEDES-BENZ C180 1.6 Kompressor (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMN3538T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Mtg Cracked	1,376.00 FL	*1,315.32 FL
2	2		*FRONT BUMPER SIDE CHROME MOULDINGS	Necessary	392.00 FL	*304.00 FL
3	1		*RH FRONT BUMPER FOG LAMP	Serviceable	310.00 FL	*- FL
4	1		*RH FRONT BUMPER FOG LAMP GRILLE	Serviceable	103.00 FL	*- FL
5	1		*FRONT BUMPER TOW HOOD COVER	Serviceable	36.00 FL	*- FL
6	1		*FRONT BUMPER SIDE RETAINERS	O/s Distorted	88.00 FL	*44.00 FL
7	1		*FRONT BUMPER REINFORCEMENT	Repair	406.00 FL	*- FL
8	2		*FRONT BUMPER BRACKETS	Repair	132.00 FL	*- FL
9	1		*FRONT BUMPER INNER FOAM	Serviceable	153.00 FL	*- FL
10	1		*RH HEADLAMP ASSY	Mtg Cracked	1,245.00 FL	*1,245.00 FL
11	1		*RH HEADLAMP PANEL	Repair	284.00 FL	*- FL
12	1		*RH FRONT FENDER	Repair	891.00 FL	*- FL
13	1		*RH FRONT FENDER INNER SHIELD	Not Necessary	232.00 FL	*- FL
14	1		*RH FRONT FENDER BADGE	Necessary	56.00 FL	*56.00 FL
15	1		*RH FRONT FENDER CHROME MOULDING	Necessary	55.00 FL	*55.00 FL
16	1		*RH FRONT SHOCK ABSORBER	Bent	598.00 FL	*598.00 FL
17	1		*RH FRONT TOP ARM	Serviceable	339.00 FL	*- FL
18	1		*RH FRONT LOWER ARM	Distorted	475.00 FL	*438.00 FL
19	1		*RH FRONT KNUCKLE ARM	Bent	862.00 FL	*675.00 FL
20	1		*RH FRONT WHEEL HUB W BEARING	Bent	465.00 FL	*387.40 FL
21	1		*FRONT STABILIZER BAR	Serviceable	285.00 FL	*- FL
22	2		*FRONT STABILIZER BAR LINKAGES	Serviceable	112.00 FL	*- FL
23	1		*SET FRONT BUMPER CLIPS	Necessary	45.00 FS	*45.00 FS
24	1		*SET RH FRONT FENDER INNER SHIELD CLIPS	Not Necessary	30.00 FS	*- FS
25	1		*RH FRONT SPORT RIM	Dented	680.00 FS	*680.00 FS
26	1		*RH FRONT TYRE	Serviceable	360.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>10,010.00</b>	<b>5,842.72</b>
<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>889.50</b>	<b>511.77</b>
<b>Total Parts (\$\$)</b>	<b>9,120.50</b>	<b>5,330.95</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK ELECTRICAL WIRINGS	New	60.00	20.00
2	REPAIR ACCIDENT DAMAGES AND RENEW ABOVE PARTS	New	880.00	400.00
3	SPRAY PAINT ON ACCIDENT AFFECTED PORTIONS	New	880.00	440.00
4	LOWER FRONT SUSPENSION TO FACILITATE REPAIR	New	350.00	180.00
5	COMPUTERIZE WHEEL ALIGNMENT	New	100.00	60.00
6	TUFF ON AFFECTED PORTIONS	New	60.00	0.00
7	COMPUTERIZE VEHICLE SYSTEM RESET	New	350.00	0.00
Gross Labour Cost (S\$)			2,680.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >