

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

**WIP : 11552**

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/OD/1079/2019/NS  
**Date** : 14-Feb-20

**Vehicle NOT IN workshop. Please arrange for survey**

### **AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way  
#07-16 AIG Building  
Singapore 079120

**Attn: Motor Claims Dept**  
**Tel: Fax 6338 1504**

**Owner's Name** : Mr Chittaranjaneshwar Jha  
**Address** : 18 Simei Street 1  
#10-13  
Singapore 529943  
**Telephone** : HP +65 93832737  
**Type of Claim** : Own Damage Claim  
**Policy No.** : 2100387227-04  
**Vehicle No** : **SKP 6078 Y**  
**Model Code** : Audi A4 1.8T FSI MU 8K203  
**Model / Year** : Sep-14  
**Engine No** : CJE 083506  
**Chassis No** : WAUZZZ8KXEA158707  
**Mileage** :  
**Date In** :  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 5-Sep-19  
**Place of Accident** : Melville Park Car Entrance

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SKP 6078 Y

| S/N                         | Nature of Jobs                                                                                                                                        | Estimated Charges    | Surveyor's Recommendation |
|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|---------------------------|
| 1                           | To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy.                           | S/N \$ 360.00 ✓      |                           |
| 2                           | To dismantle and renew front bumper, lhs front fender and lhs wing mirror assy. Re-organise crash management components. Reinstall all parts removed. | \$ 2,800.00 1000     |                           |
| 3                           | To respray front bumper and lhs front fender, lhs front door and lhs wing mirror cover.                                                               | \$ 3,200.00 1100     |                           |
| 4                           | To renew lhs front rim and carry out wheel alignment.                                                                                                 | S/N \$ 280.00 X      |                           |
| 5                           | To carry out diagnostic checks.                                                                                                                       | S/N \$ 192.00 ✓      |                           |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                       | <b>: \$ 6,832.00</b> |                           |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SKP 6078 Y

| S/N                   | Parts Description                              | Damage Parts & Prices |         |
|-----------------------|------------------------------------------------|-----------------------|---------|
|                       |                                                | S/NETT                | REMARKS |
| 1                     | FRONT BUMPER / <i>DD</i>                       | \$ 2,100.00           |         |
| 2                     | FRONT BUMPER FIXING PARTS ?                    | \$ 234.00             |         |
| 3                     | FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE X  | \$ 207.00             |         |
| 4                     | FRONT BUMPER AIR GUIDE GRILLE - LH X           | \$ 123.00             |         |
| 5                     | FRONT WHEEL SPOILER - LH ?                     | \$ 45.00              |         |
| 6                     | FRONT BUMPER FOAM FILLER PIECE X               | \$ 113.00             |         |
| 7                     | FRONT BUMPER SIDE REINFORCEMENT X              | \$ 802.00             |         |
| 8                     | FRONT BUMPER GUIDE SECTION - LH ?              | \$ 33.00              |         |
| 9                     | FRONT BUMPER SUPPORT ?                         | 2 \$ 23.00            |         |
| 10                    | FRONT FENDER - LH / <i>DD</i>                  | \$ 904.00             |         |
| 11                    | FRONT FENDER ATTACHMENT PARTS ?                | \$ 52.00              |         |
| 12                    | FENDER BRACKET - LH FRONT ?                    | \$ 48.00              |         |
| 13                    | FENDER DEFORMATION ELEMENT BRACKET - LH REAR ? | \$ 45.00              |         |
| 14                    | FRONT FENDER BRACE - LH LOWER ?                | \$ 107.00             |         |
| 15                    | FRONT FENDER WHEEL HOUSING LINER ?             | \$ 223.00             |         |
| 16                    | WHEEL HOUSING LINER ATTACHMENT PARTS ?         | \$ 41.00              |         |
| 17                    | HEADLAMP BRACE - LH ?                          | \$ 41.00              |         |
| 18                    | MAIN BEAM HEADLIGHT MOUNTING - LH ?            | \$ 107.00             |         |
| 19                    | HEADLAMP BRACKET - LH ?                        | \$ 96.00              |         |
| 20                    | GAS DISCHARGE LAMP HEAD LIGHT - LH ?           | \$ 2,152.00           |         |
| SUB TOTAL SPARE PARTS |                                                | <u>\$ 7,496.00</u>    |         |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Material List for Accident Vehicle Regn No. SKP 6078 Y

| S/N                  | Parts Description                            | Damage Parts & Prices |         |
|----------------------|----------------------------------------------|-----------------------|---------|
|                      |                                              | S/NETT                | REMARKS |
| 21                   | HEADLIGHT WASHER SYSTEM LIFT CYLINDER - LH X | \$ 192.00             |         |
| 22                   | HALOGEN FOG LAMP - LH X                      | \$ 242.00             |         |
| 23                   | EXTERIOR MIRROR MOUNTING - LH X              | \$ 1,226.00           |         |
| 24                   | MIRROR CAP - LH X                            | \$ 522.00             |         |
| 25                   | TURN SIGNAL INDICATOR X                      | \$ 92.00              |         |
| 26                   | MIRROR GLASS X                               | \$ 209.00             |         |
| 27                   | FRONT ALUMINIUM RIM - LH X                   | \$ 666.00             |         |
| 28                   | ALUMINIUM RIM RUBBER VALVE X                 | 4 \$ 13.00            |         |
| 29                   | SUNDRIES                                     | \$ 300.00             |         |
| TOTAL SPARE PARTS    |                                              | \$ 10,958.00          |         |
| TOTAL LABOUR CHARGES |                                              | \$ 6,832.00           |         |
| GRAND TOTAL          |                                              | \$ 17,790.00          |         |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name

:

Surveyed Date

:

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

:

14/2/20, 11.30am

SKK (LKK) 9D - Mr Anthony (Car)

EXCESS - ?

P/P

Ry RL sy

5 dys

## Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
- For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

**LKK Auto Consultancy** hereby notify  
the Repairer of the following:  
• To resurvey the vehicle after painting  
• To display damaged parts for resurvey  
• Parts prices are subject to confirmation  
• Third party claims on a "without Prejudice" basis  
• No illegal claims are allowed  
• Supplemental claims are resurveyed and  
is subject to the relevant Insurance Company

Acknowledged: \_\_\_\_\_

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant