

ASS. REC. BY:

REF:

es/11420002612/ kg d3

Special Instruction:

Surveyor: Gnnmth

ASSIGNMENT (Office)

From (Person): minimn Hor Yinnul

of

AluDate/Time: 14/2/2020 @ 2.11pm

Estimated Cost:

Bill to:

OD TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PC 7636P

Insured:

GBJ 9483D

at Workshop m/s

Yee Auto

Tel:

6457 5768

of

160 Sin Ming Ave # 02-17

Policy No:

1900230409

Claim No:

1631382953SG

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/02/2020

CA / REV / REP. / REV 24 HRS

lup1

H.O.D. Endorsement:

Date/Time:

3.08pm @ 14/2/2020

Person Contacted:

Mr. Chan

Vehicle IN/OUT

Date/Time	Action/Instruction
	<u>Estimate ✓</u>
	<u>PC 7636P-X</u>
	<u>GBJ 9483D-X</u>
	<u>Kenneth confirmed LS \$4700, 4 days. (Red \$10557.90, 69%)</u>

ASS. REC. BY:

REF:

A61

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

04 days

Res.: Yes or No

Lum Sum: \_\_\_\_\_

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: \_\_\_\_\_

PC 7638P

Yr Regn: \_\_\_\_\_

10, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: \_\_\_\_\_

Toyota Perios

c.c

2882

Colour

M. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

82433

T/Radio:

Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

K01A201 0174288

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: \_\_\_\_\_

R: \_\_\_\_\_

195R15X8

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. \_\_\_\_\_

9

mm

R/Bal. \_\_\_\_\_

9

mm

L/Bal. \_\_\_\_\_

9

mm

L/Bal. \_\_\_\_\_

9

mm

D.O.A. \_\_\_\_\_

11/2/20

D.O.I. \_\_\_\_\_

19/3/2020

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

15/05 Typist

Date/Time, File Return to?

☐

: Prell. Report

☐

: Final Report

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S - RS - SI

Fees:

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

MER-TP

Lump Sum / +B+ (\$

4700

**PRE-REPAIR INSPECTION REQUEST – PC7636P vs GBJ9483D (OI) on D.O.A.: 11/02/2020**

From: Hor, Yinrul  
To: Admin A (admin-a@lkkauto.com), 'assignments@lkkauto.com'  
Cc: Lim, Kok-Chong, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Hor, Yinrul, Subramaniam, Divyashni, Teo, Ericweihong  
Sent: 2/14/2020 2:11:17 PM  
Attachments:  YeeAuto-PC7636P.LTA.pdf  YeeAuto-PC7636P.LTA.pdf

---

Hi,

Please refer to the enclosed request from **BONNIE KWOK LLC**.  
Kindly carry out Policy coverage verification **first** before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Thanks & Regards,

Hor Yin Rul (Viviane)  
AIG  
FNOL Adjuster I  
Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.

Tel: 8001206556 | Ext: 1002208  
[Yinrul.Hor@aig.com](mailto:Yinrul.Hor@aig.com) | [www.aig.sg](http://www.aig.sg)

**From:** bonnie kwok <litigation@bonniekwok.com>  
**Sent:** Friday, February 14, 2020 11:47 AM  
**To:** Hor, Yinrul <Yinrul.Hor@aig.com>  
**Cc:** Lim, Kok-Chong <Kok-Chong.Lim@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Subramaniam, Divyashni <Divyashni.Subramaniam@aig.com>; Teo, Ericweihong <Ericweihong.Teo@aig.com>; yeeauto pteltd <yeeautopteltd@gmail.com>  
**Subject:** [EXTERNAL] Re: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBJ9483D AND PC7636P ON 11/02/2020

**This message is from an external sender; be cautious with links and attachments.**

Dear Sirs,

Our client agrees to LKK Auto Consultants Pte Ltd as the Single Joint Expert (SJE).

Please let us have their report in due course.

Kindly request for the SJE to contact the repairers, M/s Yee Auto Pte Ltd at 6457 5768 to make the necessary arrangements.

Regards,  
ST

--

**BONNIE KWOK LLC**  
Advocates & Solicitors  
101A Upper Cross Street  
#08-12 People's Park Centre

Singapore 058358  
TEL: 6536 6026  
FAX: 6536 2279  
email : [litigation@bonniekwok.com](mailto:litigation@bonniekwok.com)  
GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 8.45 a.m. to 5.45 p.m. and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

On Fri, 14 Feb 2020 at 09:20, Hor, Yinrul <[Yinrul.Hor@aig.com](mailto:Yinrul.Hor@aig.com)> wrote:



This is a secure, encrypted message. To read it, open the attachment.

Este es un mensaje cifrado y seguro. Para leerlo, abra el archivo adjunto.

Esta é uma mensagem criptografada segura. Para lê-lo, abra o anexo.

Ceci est une sécurité, un message crypté. Pour le lire, ouvrez la pièce jointe.

これは暗号化された電子メールです。閲覧には添付ファイルを開いてください。

[Click here](#) by 2020-02-20 19:20 CST to read your message.  
After that, open the attachment.

[More Info](#)

**Disclaimer:** This email and its content are confidential and intended solely for the use of the addressee. Please notify the sender if you have received this email in error or simply delete it.

Secured by Proofpoint Encryption, Copyright © 2009-2019 Proofpoint, Inc. All rights reserved.

---

**From:** Yinrul.Hor@aig.com  
**To:** [litigation@bonniekwok.com](mailto:litigation@bonniekwok.com)  
**Cc:** Kok-Chong.Lim@aig.com , Lee-Ying.Chin@aig.com , NoorMariesa.AbuKassim@aig.com , Yinrul.Hor@aig.com

,Divyashni.Subramaniam@aig.com ,Ericweihong.Teo@aig.com

**Subject:** aigencrypt PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE GBJ9483D AND PC7636P ON 11/02/2020

**Date:** Fri, 14 Feb 2020 01:20:09 +0000

Without Prejudice

Your Reference : YeeAuto-PC 7636 P

Our Reference : GBJ9483D

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert:

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Hor Yin Rul (Viviane)

AIG

FNOL Adjuster I

Auto Claims | AIG Asia Pacific Insurance Pte. Ltd.

Tel: 8001206556 | Ext: 1002208

[Yinrul.Hor@aig.com](mailto:Yinrul.Hor@aig.com) | [www.aig.sg](http://www.aig.sg)

**From:** bonnie kwok [<mailto:litigation@bonniekwok.com>]

**Sent:** Thursday, February 13, 2020 2:31 PM

**To:** AIG SGP, Claims-Survey

**Subject:** [EXTERNAL] Urgent: Pre-Repair Inspection: Your Vehicle: GBJ 9483 D; Our Ref: YeeAuto-PC 7636 P; Accident Involving PC 7636 P & GBJ 9483 D on 11 February 2020

**This message is from an external sender; be cautious with links and attachments.**

**Urgent**

Dear Sirs,

We refer to the above matter.

We hereby give you 2 days' notice to conduct a pre-repair inspection of vehicle no. PC 7636 P at M/s Yee Auto Pte Ltd, Block 160 Sin Ming Drive #02-17 Sin Ming Autocity Singapore 575722.

Regards,

ST

--

**BONNIE KWOK LLC**

Advocates & Solicitors

101A Upper Cross Street

#08-12 People's Park Centre

Singapore 058358

TEL: 6536 6026

FAX: 6536 2279

email : [litigation@bonniekwok.com](mailto:litigation@bonniekwok.com)

GST Reg. No.: 201203547Z

We do not accept service of documents by facsimile or email. Our business hours are from Mondays to Fridays from 8.45 a.m. to 5.45 p.m. and we are closed on Saturday, Sundays and Public Holidays.

-- Email Disclaimer --

This message contains information that may be privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this message is strictly prohibited. If you have received this message in error, please delete it from your system and notify the sender. You are advised to carry out your own checks on this message for computer viruses and other defects. Please note that we disclaim liability for any loss or damage caused by computer viruses and/or other defects.

# Yee Auto Pte Ltd

160 Sin Ming Dr #02-17 / #07-12 Sin Ming Autocity Singapore 575722

TEL: 6457 5768 FAX: 6252 8459 Email: yeeautopte ltd@gmail.com

GST:201719251W RCB NO:201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16

Singapore 079120

Estimate No: ES2000033

Date: 19 Mar 2020

Policy No:

Veh Reg No: PC7636P

Make/Model: TOYOTA REGIUS ACE  
GL 3.0 DIESEL A/T 2WD

Chassis No: KDH2010174298

Engine No: 1KD2545475

Reg. Date: 16/10/2015

ATTN: Motor Claim Department

Your Ref No: -

Claim Type: Third Party

Accident Date: 11/02/2020

TP Veh Reg No: GBJ9483D

*Not with mark*

*1/1mg &*

*Resurvey After Repair*

*4 days*

## Estimate Repair Cost to Vehicle No :PC7636P

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
<b>Net Price</b>				
1 FRONT NUMBER PLATE	50.00	1 PC	<i>Sm</i> 50.00	X 50.00
<b>Spare Parts</b>				
2 AIRCON CONDENSER	1,080.50	1 PC	<i>Sm</i> 1,080.50	X
3 COOLER CONDENSER	920.10	1 PC	<i>Sm</i> 920.10	X
4 FRONT BONNET	856.70	1 PC	<i>By</i> 856.70	✓
5 FRONT BONNET EMBLEM	130.00	1 PC	<i>Sm</i> 130.00	✓
6 FRONT BONNET LOCK	180.00	1 PC	<i>Sm</i> 180.00	X
7 FRONT BUMPER	572.80	1 PC	572.80	?
8 FRONT BUMPER CLIPS	60.00	1 SET	60.00	?
9 FRONT BUMPER LAMP - LH	310.50	1 PC	<i>Sm</i> 310.50	X
10 FRONT BUMPER LAMP - RH	310.50	1 PC	<i>Sm</i> 310.50	X
11 FRONT BUMPER LOWER SPOILER	320.00	1 PC	<i>Sm</i> 320.00	X
12 FRONT BUMPER REINFORCEMENT	280.00	1 PC	280.00	?
13 FRONT BUMPER SIDE RETAINER - LH	137.20	1 PC	<i>Sm</i> 137.20	X
14 FRONT BUMPER SIDE RETAINER - RH	137.20	1 PC	<i>Sm</i> 137.20	X
15 FRONT GRILLE	420.00	1 PC	<i>CM</i> 420.00	✓
16 FRONT GRILLE INNER GARNISH	320.00	1 PC	320.00	?
17 FRONT GRILLE CHROME 'TOP'	380.00	1 PC	380.00	?
18 FRONT GRILLE CHROME 'BOTTOM'	450.00	1 PC	<i>CM</i> 450.00	✓
19 FRONT GRILLE CLIPS	20.00	1 SET	<i>Sm</i> 20.00	✓
20 FRONT GRILLE LOWER COVER GARNISH	180.00	1 PC	<i>Sm</i> 180.00	X
21 FRONT HEADLAMP (HID) - LH	2,606.20	1 PC	2,606.20	?
22 FRONT HEADLAMP (HID) - RH	2,606.20	1 PC	2,606.20	?
23 FRONT SUPPORT PANEL 'TOP'	280.00	1 PC	<i>Sm</i> 280.00	X
24 RADIATOR SPARE TANK	180.00	1 PC	<i>Sm</i> 180.00	X
25 WASHING TANK	220.00	1 PC	<i>Sm</i> 220.00	X
			12,957.90	12,957.90
<b>Labour</b>				
26 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	1,000.00	1 JOB	1,000.00	<i>400</i>
27 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,000.00	1 JOB	1,000.00	<i>400</i>
28 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	120.00	1 JOB	120.00	<i>30</i>
29 TO CHECK WIRING FUNCTIONS.	50.00	1 JOB	50.00	<i>20</i>



# Yee Auto Pte Ltd

160 Sin Ming Dr #02-17 / #07-12 Sin Ming Autocity Singapore 575722  
TEL: 6457 5768 FAX: 6252 8459 Email: yeeautopteltd@gmail.com  
GST:201719251W RCB NO:201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way  
#07-16  
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -  
Claim Type: Third Party  
Accident Date: 11/02/2020  
TP Veh Reg No: GBJ9483D

Estimate No: ES2000033  
Date: 19 Mar 2020  
Policy No:  
Veh Reg No: PC7636P  
Make/Model: TOYOTA REGIUS ACE  
GL 3.0 DIESEL A/T 2WD  
Chassis No: KDH2010174298  
Engine No: 1KD2545475  
Reg. Date: 16/10/2015

## Estimate Repair Cost to Vehicle No :PC7636P

Description	U/Price	Quantity	List Price	Amount
30 AIRCON JOB AND REFILL GAS	80.00	1 JOB	<del>80.00</del> <u>SS</u>	<u>SS</u>
			2,250.00	2,250.00
Total				SS 15,257.90
Add GST @ 7%				1,068.05
Total Amount Payable				SS 16,325.95

TOTAL: SINGAPORE DOLLAR SIXTEEN THOUSAND THREE HUNDRED TWENTY FIVE AND CENTS NINETY FIVE ONLY

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No repair modification(s) is allowed
- Supplementary part(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:  
Signature:  
Date: