

FTA PERFORMANCE PTE LTD

Co Reg/ GST No: 201600708N
8 Kaki Bukit Avenue 4, #07-26, Singapore 415875
Tel: +65 6384 0123

REPAIR ESTIMATE

Date: _____

Name: Ismail Bin Sahul Hameed

Bike No.: FBP7371A

HP No.: 82883211

Bike Model/Make: BMW R1200GS K25

WB1045004 CZX45882

Parts S/No.	Quantity	Description	Price (SGD)	
1	1	V/cover gasket set (RHS & LHS) ✓	\$ 143.75	71.88
2	1	Cylinder head cover R/H only ✓	\$ 362.50	✓
3	2	Screw with bush ✓	\$ 47.50	✓
4	1	Front wheel cover ✓	\$ 218.75	✓
5	1	Fuel tank panel (middle) X (sve)	\$ 306.25	X
6	1	RR footrest RHS ✓	\$ 91.25	✓
7	1	Headlight support ? / BT	\$ 475.00	✓
8	1	Oil cooler ✓	\$ 643.75	✓
9	1	Hose clamp (21.3mm) ✓	\$ 1.87	✓
10	1	Oil cooler pipe outlet X (sve)	\$ 237.50	X BT
11	1	Oil cooler pipe inlet X (sve)	\$ 243.75	X
12	1	Handlebar ? / BT	\$ 450.00	✓
13	1	Handguard RHS ✓	\$ 87.50	✓
14	2	Screw M12x1.5x8 R/H only ✓	\$ 30.00	15
15	2	Bush R/H only ✓	\$ 17.50	8.75
16	1	Slider tube LHS X (sve)	\$ 1,175.00	X
17	1	Slider tube RHS ? X R	\$ 1,175.00	X SCR
18	4	Fork Guide bush ? / Nec	\$ 165.00	✓
19	2	Fork Gasket ring ? / Nec	\$ 62.50	✓
20	2	Fork Dust cover R/H ? / CRU	\$ 67.50	✓
21	1	Fork mount, bottom ? X SVC	\$ 862.50	X
22	1	Fork mount, upper X (sve)	\$ 875.00	X
23	1	Fork Ball joint ? X SVC	\$ 225.00	X
24	1	Fork Collar nut ? X SVC	\$ 9.37	X
25	1	Joint link ? RH / Nec	\$ 287.50	143.75
26	1	Snap ring ? / Nec	\$ 5.00	2.5
27	1	Upper fork brace bearing 47x20x20 X (sve)	\$ 106.25	X
28	2	Fork Stanchion R/H ? X SVC	\$ 1,575.00	X
29	1	Front spoke rim X (sve)	\$ 2,062.50	X
30	1	pt Axle shaft ? X SVC	\$ 200.00	X
31	2	Front brake disc X (sve)	\$ 650.00	X
32	10	Screw X (sve)	\$ 25.00	X
33	1	Fairing bracket X (R)	\$ 900.00	X
34	10	C clip X (sve)	\$ 31.25	X
35	1	Cylinder head protector set ✓	\$ 368.75	✓

36	1	Engine protector bar set <i>R/H ✓</i>	\$ 662.50
37	1	Headlamp guard <i>✓ SCN</i>	\$ 118.75
38	1	<i>Fit</i> Signal holder RR <i>✓ LRA</i>	\$ 28.75
Subtotal			\$ 14,994.99
-10%			\$ 13,495.49

4,093.15
-10%
3,684.38

Accessories and Workshop Services			
S/No.	Quantity	Description	Price (SGD)
1	1	<i>wing Arm</i> Gear box sliders <i>R/H ✓ SCN</i>	\$ 85.00
2	1	Fog light <i>✓ LRA R/H</i>	\$ 550.00
3	1	Headlight ? <i>R/H XSC</i>	\$ 550.00
4	1	Top protector bar <i>✓ SCN R/H</i>	\$ 680.00
5	1	Amber camera <i>X (SC)</i>	\$ 450.00
6	1	Towing <i>✓</i>	\$ 120.00
7	2 <i>lit</i>	Fork oil <i>✓</i>	\$ 80.00
8	1	Removing and installation	\$ 800.00
9	1	Diagnostics and safety testing	\$ 100.00
10	1	Wiring check	\$ 80.00
11	1	Brake bleeding ?	\$ 80.00
12	1	Fairing spray <i>✓</i>	\$ 600.00
Subtotal			\$ 4,175.00

1,315

665

Total:	\$ 17,670.49
GST (7%)	\$ 1,236.93
Grand total:	\$ 18,907.43

We are happy to provide you with any further information necessary and trust that you will call on us to fill your enquiries and orders.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Signature / Date

15/2/20
L/S repair
with payment
4 days
H-ANN
85311883
Resurvey after paint
17/2/20 3:30pm
Ann ANN@lkkauto.com

3,684.38
1,315
665
5,664.38
-20%
4,531.56

L/S
\$4,550
4 days