

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle SMF 7650 S

<u>S/N</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's Recommendations</u>
1	To remove and reinstall rear carpet to facilitate the repair.	S/N	\$ 480.00 ✓	✓
2	To dislodge and renew underbody trims. To renew breather line and air line for activated charcoal container	S/N	\$ 600.00 ✓	✓
3	To repair and weld the bottom plate.		\$ <del>1,050.00</del> 550 ✓	✓
4	To respray bottom plate.		\$ <del>1,200.00</del> 500 ✓	✓
5	To carry out diagnostic check.	S/N	\$ 192.00 ✓	
<b>TOTAL LABOUR CHARGES</b>			<b>: <u>\$ 3,522.00</u></b>	

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
 Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SMF 7650 S

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	AIR LINE ?	\$ 37.00	X SVC
2	BREATHER LINE cut ✓	\$ 109.00	X SVC
3	UNDER BODY TRIM ms ✓	\$ 305.00	243.60
4	SUNDRIES ?	\$ 200.00	1.36
<b>TOTAL SPARE PARTS CHARGES</b>		<b>: \$ 651.00</b>	
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 3,522.00</b>	
<b>GRAND TOTAL</b>		<b>: \$ 4,173.00</b>	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.