

### ESTIMATE

Our Ref: AC2020008/OD/SGD333K-07.02.2020

Vehicle number: SGD333K

Vehicle Made & Model: PORSCHE CAYENNE TURBO

Items	Qty	Items	Cost \$
1	1	Front bonnet ✓ BT	✓ 4,200.00
2	1	Front bonnet badge ✓ new	✓ 220.00
3	1	Front bonnet lock X (R)	✓ 185.00
4	2	Front bonnet dampers - L/R @ 120 R/H only ✓ Jm 2/H X (SVC) 4X SVC	✓ 240.00 120
5	2	Front bonnet hinges - L/R @ 160 R/H only ✓ CRM 2/H X (LR) 1 PC	✓ 320.00
6	1	Front bumper ✓ CRA	✓ 980.00
7	1	Front bumper lower guard ✓ CRA	✓ 960.00
8	1	Front bumper fog lamp - RH - Lower ✓ mis	✓ 580.00
9	1	Front bumper side grille ✓ mis R/H X SVC	✓ 250.00
10	1	Front bumper side cover ✓ mis R/H	✓ 250.00
11	1	Front bumper L.E.D light ✓ CRA	✓ 750.00
12	1	Front bumper CTR grille X (SVC) X SVC	✓ 330.00 X
13	1	Front bumper side pad X (SVC)	✓ 160.00
14	1	Front bumper frame pad X (SVC) X SVC	✓ 295.00 X
15	1	Front bumper side holder X (SVC) / BR	✓ 60.00 ✓
16	1	Front bumper side bracket ✓ BT R/H	✓ 120.00
17	1	Front bumper side retainer ✓ CRM R/H	✓ 65.00
18	1	Front bumper tow cover ✓ R/H mis	✓ 95.00
19	2	Front bumper PDC sensors @ 285 ✓ R/H (mis)	✓ 570.00 \$ 285
20	1	Front bumper PDC sensor wire harness ✓ CRA	✓ 670.00
21	1	Front bumper top beam X (SVC) X SVC	✓ 180.00 X
22	1	Front bumper reinforcement X (R) XR	✓ 750.00 X
23	1	Front bumper top guide (supp top garnish) ✓ CRA	✓ 230.00
24	1	Front bumper stay X (SVC) X SVC	✓ 120.00 X
25	1	Front fender - RH ✓ cut	✓ 1,500.00
26	1	Front fender wheel arch garnish ✓ mis R/H	✓ 430.00
27	1	Front fender inner shield ✓ CRA R/H	✓ 350.00
28	10	Front fender inner shield clips @ 6 ✓ new X SVC	✓ 60.00 X
29	1	Front fender inner top cover ✓ SCR R/H	✓ 310.00
30	1	Front fender inner panel ✓ cut R/H	1265.00 ✓ 1,800.00
31	1	Front fender wheel housing X (R) X R	✓ 3,200.00 X
32	1	Front fender wheel housing extension X (R) XR	✓ 450.00 X
33	1	Front headlamp - RH ✓ CRA	✓ 5,200.00 complete
34	1	Front headlamp seal ✓ new R/H	✓ 220.00
35	1	Front headlamp lower bracket ✓ CRA	✓ 185.00

36	1	Front headlamp bulb	X SVC	X	650.00
37	1	Front headlamp bulb cover	/ CR4	X	120.00
38	1	Front headlamp control unit - No. 1	/ CR4	X	600.00
39	1	Front headlamp control unit - No. 2	/ CR4	X	1,150.00
40	1	Front headlamp spray nozzle pen	✓ CRA	✓	280.00
41	1 set	Front headlamp kit	X (SVC)	X	250.00
42	1	Front support panel	X (A) / CRA	✓	750.00
43	1	Front support top garnish	X (AFT) Repeat Item 23	✓	210.00
44	20	Front support top garnish clips @ 6	✓ all X SVC	X	120.00
45	1	Front shock absorber assy - RH	X (SVC) X SVC	✓	3,500.00
46	1	Front sub frame assy	X (SVC)	X	3,200.00
47	1	Front sport wheel - RH	✓ (CR) R/H outly	✓	4,200.00
48	1	Front top arm	X (SVC) X SVC	✓	980.00
49	1	Front lower arm	X (SVC) X SVC	✓	1,550.00
50	1	Front knuckle arm	? X SVC	✓	1,200.00
51	1	Front wheel hub bearing	? / Jam	✓	750.00
52	1	Washer tank	✓ CRA	✓	280.00
53	1	Washer tank neck	✓ CRA	✓	95.00
54	1	Washer tank motor	X (SVC) X SVC	✓	195.00
55	1	Air cleaner box assy	R/H ✓ CRA	✓	780.00
56	1	Air cleaner duct - Inlet	? R/H / CR4	✓	180.00
57	1	Air cleaner duct - Outlet	? R/H / CR4	✓	180.00
58	1	Air intercooler	✓ CRA R/H	✓	2,600.00
59	1	Air intercooler intake duct	? R/H / CR4	✓	210.00
60	1	Air intercooler hose - Inlet	? R/H / CR4	✓	450.00
61	1	Air intercooler hose - Outlet	? R/H / CR4	✓	450.00
62	1	Air con condenser	X (SVC)	X	1,600.00
63	1	Air con condenser intake duct	X (SVC)	X	280.00
64	1	Radiator assy	X (SVC) X SVC	✓	1,200.00
65	1	Front windshield assy	✓ CRA	✓	1,250.00
66	2	Front windshield side mouldings - L/R @ 180	X (SVC)	X	360.00
67	1	Steering wheel	X (SVC)	X	4,500.00
68	1	Steering wheel S.R.S	R/H ✓ (BUS)	✓	3,500.00
69	1	Steering wheel clock sensor	✓ Jam R/H	✓	750.00
70	1	Passenger S.R.S	✓ R/H (BUS)	✓	3,600.00
71	1	Dashboard assy	✓ CRA	✓	8,300.00
72	1	S.R.S control unit	✓ all	✓	2,600.00
73	2	Front safety belts @ 850	✓ Jam	✓	1,700.00
74	2	Rear safety belts @ 850	✓ Jam	✓	1,700.00

Sub-total	82,555.00
Additional 10%	8,255.50
<b>Total List</b>	<b>90,810.50</b>

**Special Nett Items**

75	1 set	Front windscreen sealant	✓	80.00	50
76	1	Front tyre - RH	X (SVC) X SVC	2 PCS 760.00	1,200.00
77	1	I.U bracket	✓ all	30.00	10
78	1 bot	Brake fluid	✓ all	50.00	20

Total Special Nett

1,360.00

Labour charges

79	To check front electrical wiring ✓		180.00	30
80	Towing charges ✓		200.00	70
81	To remove, refix front undercarriage ? photo	200.00 ✓	650.00	?
82	To check wheel alignment <del>and</del> ? Align report	40.00 ✓	120.00	60?
83	To remove, reinstall & reset A.B.S brake systems ✓		200.00	40
84	To remove, refix front A/C condenser & refill A/C gas R134A	80.00 ✓	180.00	80?
85	To remove, refix front dashboard ✓		450.00	180
86	To diagnos, erase fault memory after repair		450.00	250
87	To remove, refix & reset S.R.S systems ✓		580.00	
88	To respray painting and etc		2,000.00	1000
89	Panel beating, cut, weld remove & replacing above parts		3,000.00	300
			<hr/>	
<b>Total Labour</b>			<b>8,010.00</b>	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

100,180.50

\*Hidden, inaccessible damage parts shall be submitted through supplementary

Not Authorized  
 need to check (m.v)  
 Excess \$3000  
 Home ANN (IKK)  
 67418434 / 8531893  
 Reming before paint / arrange after paint  
 P/P repair / H/s report  
 without production  
 12/2/20  
 need to Rivert #  
 6:15 pm

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:



Automobile Integrated Management Pte Ltd

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Automobile Integrated Management Pte Ltd  
 Co. & G.S.T. Reg no. 201605297G  
 Office: 28 Sin Ming Lane #07-147 Midview City Singapore 573972  
 Workshop: 23 Kaki Bukit Ave 5 #04-01 (South Wing) Singapore 415933  
 Email: automim.claim@gmail.com Tel: 9119 8371

Acknowledged by Repairer

Signature:

Date: 07.02.2020

**ESTIMATE**

Our Ref: AC2020008/OD/SGD333K

Vehicle number: SGD333K

Vehicle Made & Model: PORSCHE CAYENNE TURBO

Items	Qty	Supplementary Items	Cost \$
1	1	Front bonnet badge base set ? photo / BR	40.00 ✓
2	1	Front bumper side moulding - RH - TOP ✓ CAA	80.00 ✓
3	1	Front bumper side moulding - RH - CTR ✓ CAA	85.00 ✓
4	1	Front bumper side moulding - RH - LOWER ✓ CAA	85.00 ✓
5	1	Front bumper lower seal cover - RH ✓ CAA	70.00 ✓
6	1	Front bumper fog lamp cover - RH ✓ mis	60.00 ✓
7	1	Front headlamp spray nozzle cover - RH ✓ CR4	185.00 ✓
8	1	Front headlamp spray nozzle bracket ✓ BR	95.00 ✓
9	1	Front headlamp spray nozzle joint ✓ BR	60.00 ✓
10	1 set	Front headlamp wire harness ✓ CAA	202.00 ✓ 850.00
11	1	Air intercooler intake duct - RH - Rear ✓ CAA	380.00 ✓
12	1	Horn high tone ✓ ser	150.00 ✓
13	1	Horn low tone ✓ CAA	150.00 ✓
14	1	Radiator air guide ✓ CAA	320.00 ✓
15	1	Radiator top pin ✓ m	10.00 ✓
16	1	Radiator top stopper ✓ m	15.00 ✓
17	1	Radiator top bushing ✓ m	20.00 ✓
18	1	Radiator top bracket ✓ m	30.00 ✓
19	1	Turbo cut off valve - RH ✓ CAA	180.00 ✓
20	1	Turbo cut off valve hose ✓ CAA	200.00 ✓
21	1	R.H. Front fender protector (lower) mis ✓	180.00 ✓
22	1 set	Front fender wheel arch garnish clip ✓ m	50.00 ✓ 50.00 25
23	1	Washer tank neck seal ✓ m	15.00 ✓
24	1	Washer tank cap x (svc) / NEC	25.00 ✓
25	1	Crash sensor ? photo / NEC	380.00 ✓
26	1	Sun visor - LH ✓ CAA	750.00 ✓
27	1	Battery terminal ✓ 3 short	150.00 ✓
28	1	Battery fuse ✓	450.00 ✓
		<b>Sub-total</b>	<b>5,065.00</b>
		<b>Additional 10%</b>	<b>506.50</b>
		<b>Total List</b>	<b>5,571.50</b>

Revised by  
 H-ANN (1/1/20)  
 17/3/20 4:30 pm

5065  
 + 506.5  
 5571.50  
 4575  
 4575  
 5052.50



Automobile Integrated Management Pte Ltd  
 Co. & G.S.T. Reg no. 201605297G  
 Office: 28 Sin Ming Lane #07-147 Midview City Singapore 573972  
 Workshop: 23 Kaki Bukit Ave 5 #04-01 (South Wing) Singapore 415933  
 Email: automim.claim@gmail.com Tel: 9119 8371

## Estimate

Our Ref: AC2020008/OD/SGD333K-07.02.2020

Vehicle number: SGD333K      Vehicle Made & Model: PORSCHE CAYENNE TURBO

<u>Items</u>	<u>Qty</u>	<u>Supplementary Items</u>	<u>Cost \$</u>
1	2	Front bonnet logo base nut @ 5 <i>New</i>	✓ 10.00 ✓
2	1	Front wheel hub - RH <i>Damaged</i>	✓ 500.00 ✓
3	1	Front headlamp control unit - RH <i>Malfunction</i>	✓ 400.00 ✓
4	1	Front headlamp control unit cover <i>Del'd</i>	✓ 40.00 ✓
5	1	Front headlamp fan motor - RH <i>Malfunction</i>	✓ 350.00 ✓
6	1	Front headlamp fan motor cover <i>Del'd</i>	✓ 40.00 ✓
7	1	Front headlamp back cover - RH <i>Del'd</i>	✓ 40.00 ✓
8	1	Front wiper neck cap <i>Missing</i>	✓ 20.00 ✓
9	1	Air cleaner hose lower joint - RH <i>Del'd</i>	✓ 120.00 ✓
10	1	Turbo pressure hose <i>Del'd</i>	✓ 320.00 ✓
11	1	Air pressure hose	✓ 130.00 ✓
12	1	Air pressure pipe <i>Bent</i>	✓ 125.00 ✓
13	1	Air bag wire <i>Adjusted</i>	✓ 185.00 ✓
14	1	Battery fuse <i>Damaged</i>	✓ 55.00 ✓
Sub-Total			2,335.00
Additional 10%			233.50
Total			2,568.50

\*Hidden, inaccessible damage parts shall be submitted through supplementary

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

14/07/20



Automobile Integrated Management Pte Ltd  
Co. & G.S.T. Reg no. 201605297G  
Office: 28 Sin Ming Lane #07-147 Midview City Singapore  
573972  
Workshop: 23 Kaki Bukit Ave 5 #04-01 (South Wing) Singapore  
415933  
Email: automim.claim@gmail.com Tel: 9119 8371

## Estimate

Our Ref: AC2020008/OD/SGD333K-07.02.2020

Vehicle number: SGD333K      Vehicle Made & Model: PORSCHE CAYENNE TURBO

<u>Items</u>	<u>Qty</u>	<u>Supplementary Items</u>	<u>Cost \$</u>
1	1	Air intercooler intake duct <i>X SVC</i>	210.00
		Sub-Total	210.00
		Additional 10%	21.00
		Total	231.00

**\*Hidden, inaccessible damage parts shall be submitted through supplementary**