



Automobile Integrated Management Pte Ltd  
 Co. & G.S.T. Reg no. 201605297G  
 Office: 28 Sin Ming Lane #07-147 Midview City Singapore  
 S73972  
 Workshop: 23 Kaki Bukit Ave 5 #04-01 (South Wing)  
 Singapore 415933  
 Email: automim.claim@gmail.com Tel: 9119 8371

**ESTIMATE**

Our Ref: AC2020008/OD/SGD333K-07.02.2020

Vehicle number: SGD333K      Vehicle Made & Model: PORSCHE CAYENNE TURBO

Items	Qty	Items	Cost \$
1	1	Front bonnet ✓ BT	✓ 4,200.00
2	1	Front bonnet badge ✓ new	✓ 220.00
3	1	Front bonnet lock X (R)	✓ 185.00
4	2	Front bonnet dampers - L/R @ 120 R/H only ✓ Jm 2/H X (SVC) 4 X SVC	✓ 240.00 120
5	2	Front bonnet hinges - L/R @ 160 R/H only ✓ CRU 2/H X (R) 1 PC	✓ 320.00
6	1	Front bumper ✓ CRA	✓ 980.00
7	1	Front bumper lower guard ✓ CRA	✓ 960.00
8	1	Front bumper fog lamp - RH - Lower ✓ mis	✓ 580.00
9	1	Front bumper side grille ✓ mis R/H X SVC	✓ 250.00
10	1	Front bumper side cover ✓ mis R/H	✓ 250.00
11	1	Front bumper L.E.D light ✓ CRA	✓ 750.00
12	1	Front bumper CTR grille X (SVC) / CRU	✓ 330.00
13	1	Front bumper side pad X (SVC)	X 160.00
14	1	Front bumper frame pad X (SVC) X SVC	295.00 X
15	1	Front bumper side holder X (SVC) / BR	✓ 60.00 ✓
16	1	Front bumper side bracket ✓ BT R/H	✓ 120.00
17	1	Front bumper side retainer ✓ CRU R/H	✓ 65.00
18	1	Front bumper tow cover ✓ R/H mis	✓ 95.00
19	2	Front bumper PDC sensors @ 285 ✓ R/H (mis)	\$ 285 ✓ 570.00
20	1	Front bumper PDC sensor wire harness ✓ CRA	✓ 670.00
21	1	Front bumper top beam X (SVC) X SVC	✓ 180.00 X
22	1	Front bumper reinforcement X (R) / CRU	✓ 750.00
23	1	Front bumper top guide (support top bracket) ✓ CRA	✓ 230.00
24	1	Front bumper stay X (SVC) X SVC	✓ 120.00 X
25	1	Front fender - RH ✓ int	✓ 1,500.00
26	1	Front fender wheel arch garnish ✓ mis R/H	✓ 430.00
27	1	Front fender inner shield ✓ CRA R/H	✓ 350.00
28	10	Front fender inner shield clips @ 6 ✓ new X SVC	✓ 60.00 X
29	1	Front fender inner top cover ✓ serv R/H	✓ 310.00
30	1	Front fender inner panel ✓ int R/H	1265.00 ✓ 1,800.00
31	1	Front fender wheel housing X (R) X R	X 3,200.00 X
32	1	Front fender wheel housing extension X (R) X R	X 450.00 X
33	1	Front headlamp - RH ✓ CRA	✓ 5,200.00 complete
34	1	Front headlamp seal ✓ new R/H	✓ 220.00
35	1	Front headlamp lower bracket ✓ CRA	✓ 185.00

36	1	Front	headlamp bulb	X SVC		X	650.00	
37	1	Front	headlamp bulb cover	/ CRU		✓	120.00	
38	1	Front	headlamp control unit - No. 1	/ CRU		✓	600.00	
39	1	Front	headlamp control unit - No. 2	/ CRU		✓	1,150.00	
40	1	Front	headlamp spray nozzle pen	✓ CRA		✓	280.00	
41	1 set	Front	headlamp kit	X (SVC)		X	250.00	
42	1	Front	support panel	X (A) / CRA		✓	750.00	
43	1	Front	support top garnish	X (AFT) Repeat Item 23		✓	210.00 X	
44	20	Front	support top garnish clips @ 6	✓ new X SVC		X	120.00 X	
45	1	Front	shock absorber assy - RH	X (SVC) / BT		✓	3,500.00	
46	1	Front	sub frame assy	X (SVC)		X	3,200.00	
47	1	Front	sport wheel - RH	✓ (SVC) R/H only		✓	4,200.00	
48	1	Front	top arm	X (SVC) X SVC		✓	980.00 X	
49	1	Front	lower arm	X (SVC) / BT		✓	1,550.00	
50	1	Front	knuckle arm ?	X SVC		✓	1,200.00 X	
51	1	Front	wheel hub bearing ?	/ Sam		✓	750.00	
52	1		Washer tank	✓ CRA		✓	280.00	
53	1		Washer tank neck	✓ CRA		✓	95.00	
54	1		Washer tank motor	X (SVC) X SVC		✓	195.00 X	
55	1		Air cleaner box assy	R/H ✓ CRA		✓	780.00	
56	1		Air cleaner duct - Inlet ?	R/H / CRU		✓	180.00	
57	1		Air cleaner duct - Outlet ?	R/H / CRU		✓	180.00	
58	1		Air intercooler	✓ CRA R/H		✓	2,600.00	
59	1		Air intercooler intake duct ?	R/H / CRU		✓	210.00	
60	1		Air intercooler hose - Inlet ?	R/H / CRU		✓	450.00	
61	1		Air intercooler hose - Outlet ?	R/H / CRU		✓	450.00	
62	1		Air con condenser	X (SVC)		X	1,600.00	
63	1		Air con condenser intake duct	X (SVC)		X	280.00	
64	1		Radiator assy	X (SVC) / CRA		✓	1,200.00	
65	1	Front	windshield assy	✓ CRA		✓	1,250.00	
66	2	Front	windshield side mouldings - L/R @ 180	X (SVC)		X	360.00	
67	1		Steering wheel	X (SVC)		X	4,500.00	
68	1		Steering wheel S.R.S	R/H ✓ (BUS)		✓	3,500.00	
69	1		Steering wheel clock sensor	✓ Jim R/H		✓	750.00	
70	1		Passenger S.R.S	✓ R/H (BUS)		✓	3,600.00	
71	1		Dashboard assy	✓ CRA		✓	8,300.00	
72	1		S.R.S control unit	✓ new		✓	2,600.00	
73	2	Front	safety belts @ 850	✓ Jim		✓	1,700.00	
74	2	Rear	safety belts @ 850	✓ Jim		✓	1,700.00	
							Sub-total	82,555.00
							Additional 10%	8,255.50
							Total List	90,810.50

**Special Nett Items**

75	1 set	Front	windscreen sealant	✓			80.00 50
76	1	Front	tyre - RH	X (SVC) X SVC RH / Cut			1,200.00 380.00
77	1		I.U bracket	✓ new			30.00 / 0
78	1 bot		Brake fluid	✓ new			50.00 20

Total Special Nett 1,360.00

Labour charges

79	To check front electrical wiring ✓		180.00	30
80	Towing charges ✓		200.00	70
81	To remove, refix front undercarriage ? photo	200.00 ✓	650.00	?
82	To check wheel alignment ✓ ? Align report	40.00 ✓	120.00	60?
83	To remove, reinstall & reset A.B.S brake systems ✓		200.00	40
84	To remove, refix front A/C condenser & refill A/C gas R134A	80.00 ✓	180.00	80?
85	To remove, refix front dashaboard ✓		450.00	180
86	To diagnos, erase fault memory after repair		450.00	250
87	To remove, refix & reset S.R.S systems ✓		580.00	
88	To respray painting and etc		2,000.00	1000
89	Panel beating, cut, weld remove & replacing above parts		3,000.00	300
<b>Total Labour</b>			<u>8,010.00</u>	

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ ~~100,100.50~~ 108,551.50

\*Hidden, inaccessible damage parts shall be submitted through supplementary

*Not Authorized  
 need to check (m.v)  
 Excess \$3000  
 Hook A/NW (1K12)  
 674/8434 / 853/1893  
 Runny before paint / arrange after paint  
 P/P repair / 4/5 repair  
 without purchase  
 12/2/20 6:15 pm  
 need to Airport #*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: 17/02/2020

Automobile Integrated Management Pte Ltd  
Co. & G.S.T. Reg no. 201605297G  
Office: 28 Sin Ming Lane #07-147 Midview City Singapore 573972  
Workshop: 23 Kaki Bukit Ave S #04-01 (South Wing) Singapore 415933  
Email: automim.claim@gmail.com Tel: 9119 8371

**ESTIMATE**

Our Ref: AC2020008/OD/SGD333K-07.02.2020

Vehicle number: SGD333K      Vehicle Made & Model: PORSCHE CAYENNE TURBO

Items	Qty	Supplementary Items	Cost \$
1	1	Front bonnet badge base set ? photo / BR ✓	40.00 ✓
2	1	Front bumper side moulding - RH - TOP ✓ CRA	80.00 ✓
3	1	Front bumper side moulding - RH - CTR ✓ CRA	85.00 ✓
4	1	Front bumper side moulding - RH - LOWER ✓ CRA	85.00 ✓
5	1	Front bumper lower seal cover - RH ✓ CRA	70.00 ✓
6	1	Front bumper fog lamp cover - RH ✓ mis	60.00 ✓
7	1	Front headlamp spray nozzle cover - RH ✓ CRA	185.00 ✓
8	1	Front headlamp spray nozzle bracket ✓ BR	95.00 ✓
9	1	Front headlamp spray nozzle joint ✓ BR	60.00 ✓
10	1 set	Front headlamp wire harness ✓ CRA	202.00 ✓ 850.00
11	1	Air intercooler intake duct - RH - Rear ✓ CRA	380.00 ✓
12	1	Horn high tone ✓ CRA	150.00 ✓
13	1	Horn low tone ✓ CRA	150.00 ✓
14	1	Radiator air guide ✓ CRA	320.00 ✓
15	1	Radiator top pin ✓ m	10.00 ✓
16	1	Radiator top stopper ✓ m	15.00 ✓
17	1	Radiator top bushing ✓ m	20.00 ✓
18	1	Radiator top bracket ✓ m BT	30.00 ✓
19	1	Turbo cut off valve - RH ✓ CRA	180.00 ✓
20	1	Turbo cut off valve hose ✓ CRA	200.00 ✓
21	1	R/L Front fender protector (lower) mis ✓	180.00 ✓
22	1 set	Front fender wheel arch garnish clip ✓ m	50.00 ✓ 50.00 25
23	1	Washer tank neck seal ✓ m	15.00 ✓
24	1	Washer tank cap x (svc) / NEC ✓	25.00 ✓
25	1	Crash sensor ? photo / NEC ✓	380.00 ✓
26	1	Sun visor - LH ✓ <del>CRA</del> NN X	750.00 ✓
27	1	Battery terminal ✓ 3 short	150.00 ✓
28	1	Battery fuse ✓	450.00 ✓
Sub-total			5,065.00
Additional 10%			506.50
Total List			5,571.50

Revised total  
H-ANN (1/1/20)  
17/3/20 4:30 pm

5015  
+ 501.5  
4515  
4515  
5016.50



Automobile Integrated Management Pte Ltd  
 Co. & G.S.T. Reg no. 201605297G  
 Office: 28 Sin Ming Lane #07-147 Midview City Singapore  
 573972  
 Workshop: 23 Kaki Bukit Ave 5 #04-01 (South Wing) Singapore  
 415933  
 Email: automim.claim@gmail.com Tel: 9119 8371

**Estimate**

Our Ref: AC2020008/OD/SGD333K-07.02.2020

Vehicle number: SGD333K      Vehicle Made & Model: PORSCHE CAYENNE TURBO

<u>Items</u>	<u>Qty</u>	<u>Supplementary Items</u>	<u>Cost \$</u>
1	2	Front bonnet logo base nut @ 5 <i>New</i>	✓ 10.00 ✓
2	1	Front wheel hub - RH <i>Damaged</i>	✓ 500.00 ✓
3	1	Front headlamp control unit - RH <i>Malfunction</i>	✓ 400.00 ✓
4	1	Front headlamp control unit cover <i>Defect</i>	✓ 40.00 ✓
5	1	Front headlamp fan motor - RH <i>Malfunction</i>	✓ 350.00 ✓
6	1	Front headlamp fan motor cover <i>Defect</i>	✓ 40.00 ✓
7	1	Front headlamp back cover - RH <i>Defect</i>	✓ 40.00 ✓
8	1	Front wiper neck cap <i>Missing</i>	✓ 20.00 ✓
9	1	Air cleaner hose lower joint - RH <i>Defect</i>	✓ 120.00 ✓
10	1	Turbo pressure hose <i>Defect</i>	✓ 320.00 ✓
11	1	Air pressure hose	✓ 130.00 ✓
12	1	Air pressure pipe <i>Best</i>	✓ 125.00 ✓
13	1	Air bag wire <i>Activated</i>	✓ 185.00 ✓
14	1	Battery fuse <i>Damaged</i>	✓ 55.00 ✓
Sub-Total			2,335.00
Additional 10%			233.50
Total			2,568.50

\*Hidden, inaccessible damage parts shall be submitted through supplementary

14/07/20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_



Automobile Integrated Management Pte Ltd  
Co. & G.S.T. Reg no. 201605297G  
Office: 28 Sin Ming Lane #07-147 Midview City Singapore  
573972  
Workshop: 23 Kaki Bukit Ave 5 #04-01 (South Wing) Singapore  
415933  
Email: automim.claim@gmail.com Tel: 9119 8371

## Estimate

Our Ref: AC2020008/OD/SGD333K-07.02.2020

Vehicle number: SGD333K      Vehicle Made & Model: PORSCHE CAYENNE TURBO

<u>Items</u>	<u>Qty</u>	<u>Supplementary Items</u>	<u>Cost \$</u>
1	1	Air intercooler intake duct <i>X SVC</i>	210.00✕
		Sub-Total	210.00
		Additional 10%	21.00
		Total	231.00

**\*Hidden, inaccessible damage parts shall be submitted through supplementary**