



Automobile Integrated Management Pte Ltd
 Co. & G.S.T. Reg no. 201605297G
 Office: 28 Sin Ming Lane #07-147 Midview City Singapore
 573972
 Workshop: 23 Kaki Bukit Ave 5 #04-01 (South Wing) Singapore
 415933
 Email: automim.claim@gmail.com Tel: 9119 8371

Estimate

Our Ref: AC2020008/OD/SGD333K-07.02.2020

Vehicle number: SGD333K Vehicle Made & Model: PORSCHE CAYENNE TURBO

<u>Items</u>	<u>Qty</u>	<u>Supplementary Items</u>	<u>Cost \$</u>
1	2	Front bonnet logo base nut @ 5 <i>New</i>	10.00 ✓
2	1	Front wheel hub - RH <i>Damaged</i>	500.00 ✓
3	1	Front headlamp control unit - RH <i>Malfunction</i>	400.00 ✓
4	1	Front headlamp control unit cover <i>Del'd</i>	40.00 ✓
5	1	Front headlamp fan motor - RH <i>Malfunction</i>	350.00 ✓
6	1	Front headlamp fan motor cover <i>Del'd</i>	40.00 ✓
7	1	Front headlamp back cover - RH <i>Del'd</i>	40.00 ✓
8	1	Front wiper neck cap <i>Missing</i>	20.00 ✓
9	1	Air cleaner hose lower joint - RH <i>Del'd</i>	120.00 ✓
10	1	Turbo pressure hose <i>? Del'd</i>	320.00 ✓
11	1	Air pressure hose	130.00 ✓
12	1	Air pressure pipe <i>Bent</i>	125.00 ✓
13	1	Air bag wire <i>Adjusted</i>	185.00 ✓
14	1	Battery fuse <i>Damaged</i>	55.00 ✓
Sub-Total			2,335.00
Additional 10%			233.50
Total			2,568.50

*Hidden, inaccessible damage parts shall be submitted through supplementary

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

14/07/20