

22/03/2002

ASS. REC. BY:

REF: CS/MSG 20002657/ETf3⁸²

Special Instruction:

Surveyor: Steve

ASSIGNMENT (Office)

From (Person): Crystal Lee

of

MSIG

Date/Time: 14.2.2020 5.09p.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SH 690IT

Insured:

SLM 5831A

at Workshop m/s

Bifrost

Tel:

97921329

of BIK 9 Secur (#01-42 sn mng

Policy No: 29141713MKF

Claim No:

619669

Sum Insured:

Excess:

Make of Veh:

D.O.A. 8.2.2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

17/1/2020 9.44a.m

Person Contacted:

Ms Lee

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SH 690IT - X

SLM 5831A - X

19/2-

Pensed prev advise.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	13 Feb 2020		17 Feb 2020 09:46 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G			
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R			
Vehicle Reg. No.:	SH6901T	Date of Loss:	08/02/2020 17:00 - :59 [1 Months and 7 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 619669	Policy/Cover Note No.:	29141713MKF (Comprehensive) Coverage: 01/02/2020 - 31/12/2020	
Vehicle Reg. No. (Insured):	SLM5831A	Policy No. (Claimant):		
		Excess:		
Repairer:	Bifrost Auto Pte Ltd (sin Ming) (HQ) Blk 9 Sector C, #01-42 Sin Ming Industrial Estate, 575644 Sin Ming - Tel:			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]			
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 18/02/2020]			
Driver/Custodian (Insured):	TAN KIAP TECK (), NRIC: S1505309G, Tel: +6594575786 Email:			
Adj Asg. Remarks:	on WP. Manual assigned to LKK via email on 14/02/2020, (Manual Assign). OI:Grab, Liab: clear, Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Ms Lee @ 9792 1329.			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Summer Lee (LKK Auto)

From: Crystal Lee <crystal_lee@sg.msig-asia.com>
Sent: Friday, 14 February, 2020 5:09 PM
To: Admin-D (LKKAuto); assignments
Cc: Ong Zi Hui
Subject: Survey Request - Manual Assigned

PRS for Our client vehicle SH6901T and your insured's vehicle SLM5831A (GRAB) on 08.02.2020

Manual Assigned

Dear LKK,

Refer to the email below, please arrange survey the vehicle.

We'll assign via Merimen once we receive the assignment from Motor Team.

Please contact us ASAP if you cannot attend this assignment.

Thank you & Best regards,

Crystal Lee

Admin Officer, Claims Services (In-House Survey)

D: +65 6594 2535 | F: +65 6643 1349 | crystal_lee@sg.msig-asia.com



MSIG

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Winnie Chua <pingping_chua@sg.msig-asia.com>
Sent: Friday, 14 February 2020 5:08 PM
To: Crystal Lee <crystal_lee@sg.msig-asia.com>
Cc: Ong Zi Hui <zihui_ong@sg.msig-asia.com>
Subject: FW: PRS F of Our client vehicle SH6901T and your insured's vehicle SLM5831A (GRAB) on 08.02.2020

From: Helene Phua
Sent: Friday, 14 February 2020 4:55 PM
To: Claims Dept <claims_ltv@bifrostauto.com>
Cc: Winnie Chua <pingping_chua@sg.msig-asia.com>
Subject: RE: PRS F of Our client vehicle SH6901T and your insured's vehicle SLM5831A (GRAB) on 08.02.2020

Hi,

Thank you for your selection.

We will proceed to assign **LKK Auto Consultants Pte Ltd** via Merimen at our end and update you upon confirmation.

Please do not contact them directly to prevent confusion. Any arrangement or appointment of surveyor must come from MSIG.

Please be informed that our surveyor will also be conducting a post repair inspection within the stipulated timeline under the protocol.

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Claims Dept <claims_ltv@bifrostauto.com>

Sent: Friday, 14 February 2020 4:44 PM

To: Helene Phua <helene_phua@sg.msig-asia.com>

Subject: Re: PRS F of Our client vehicle SH6901T and your insured's vehicle SLM5831A (GRAB) on 08.02.2020

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Without Prejudice

Dear Sir/ Mdm,

We select LKK Auto Consultants Pte Ltd

Ms Lee

Bifrost Auto Pte Ltd

Accident Claims Department

+65 9792 1329 (Mobile)

On Fri, 14 Feb 2020 at 16:38, Helene Phua <helene_phua@sg.msig-asia.com> wrote:

Hi,

We did not received your email dated 11/02/2020.

Please choose one surveyor from the list that you wish for us to appoint to conduct the pre-repair inspection:

- 1) LKK Auto Consultants Pte Ltd
- 2) Forrnteam Consultancy Pte Ltd
- 3) A-Pac Adjusters & Surveyors Pte Ltd
- 4) STA Inspection Pte Ltd
- 5) Appraisal VP Pte Ltd
- 6) AutoProbe Consultants
- 7) **MSIG In-House Surveyors**

This Fast-Lane settlement option is for clear-cut liability which MSIG will expedite offer @ 100% with express payment. Priority will be given to those opted for our in-house surveyor

To facilitate an expeditious claim settlement, we hope you are agreeable for the above surveyor to be the SJE (Single Joint Expert).

If not, you may wish to nominate any of the 10 surveyors listed below as the SJE, depending on their availability:

1. Xing Guo Qiang	6) Chow Bo Xiong
2. Kenneth Kong	7) Siew Meng Hui
3. Marcus Chua	8) Daniel Chan
4. Ng You Han	9) Victor Png
5. Gary Soon	10) Samuel Phun

In your response, please also provide us a list of 10 surveyors as your nominated SJE, regardless of whether you agree or disagree to our above nominated SJE. We may consider appointing one of your nominated SJE in case of any of our nominated SJE is not available.

NB:

- a. ***Fast lane settlement is not applicable for cases that liability is in dispute***
- b. If both of us could not agree with each other's list of nominated SJE, we may still proceed to appoint a motor surveyor to conduct a pre repair survey & post repair inspection within the timeline stipulated under the NIMA protocol.

We have created a dedicated motor survey mailbox for your motor survey request and pre-repair inspection. Please contact us (MSIG) by clicking this link: motorsurvey@sg.msig-asia.com

Have a great week ahead!

Helene Phua

Admin Assistant, Claims Services

D: +65 6594 2493 | F: +65 6225 7402 | helene_phua@sg.msig-asia.com



MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of **MS&AD** INSURANCE GROUP

From: Claims Dept [mailto:claims_ltv@bifrostauto.com]

Sent: Friday, 14 February 2020 4:06 PM

To: Winnie Chua <pingping_chua@sg.msig-asia.com>

Cc: Assessment <claims@bifrostauto.com>; Regina <assessment_ltc@bifrostauto.com>; Accident Claims Dept

<claims_ltr@bifrostable.com>; Ms Lim <claims_ltm@bifrostable.com>

Subject: Re: PRS F of Our client vehicle SH 6901 T and your insured's vehicle SLM 5831 A on 08.02.2020

EXTERNAL EMAIL: Be careful when you click any links or open any attachment(s).

Without Prejudice

Dear Sir/ Mdm,

This case nobody reply me.

Pls assign survey ASAP.

Ms Lee

Bifrost Auto Pte Ltd

Accident Claims Department

+65 9792 1329 (Mobile)

On Tue, 11 Feb 2020 at 15:02, Claims Dept <claims_ltv@bifrostable.com> wrote:

Without Prejudice

Dear Sir/ Mdm,

We refer to the above matter.

We represent our client, Cher Han Sin, to notify you of the aforesaid accident involving our client's vehicle SH 6901 T and your insured's vehicle SLM 5831 A on 08.02.2020.

Please find enclosed our client's GIA report for your necessary action.

This serves as a **NOTICE** that we are claiming against SLM 5831 A for damages, costs and disbursements.

Please let us know within **2 working days** from today, your client's and your intention to conduct a pre-repair survey of our client's vehicle.

PLEASE LET US HAVE A LIST OF YOUR EXTERNAL SURVEYORS FOR OUR SELECTION AS A SINGLE JOINT EXPERT.

If we do not receive any reply from you within the stipulated timeline, we shall proceed to appoint our own surveyor and proceed with the necessary repair for our client's vehicle without further reference to your insured or you.

Premises for the Pre-repair inspection: Blk 9 Sector C #01-42, Sin Ming Industrial Estate, Singapore 575644

Contact Person: Ms Lim / Ms Lee

Contact Email: claims_ltv@bifrotauto.com / claims_ltm@bifrotauto.com

VEH IN (Date & Time) : **11/02/2020**

PRS ARRANGEMENT (Date & Time) : **AS SOON AS POSSIBLE**

Kindly cc a copy of this letter to your insured for his/her acknowledgement.

We look forward to hearing from you soon.

To avoid incurrence of any unnecessary cost on both our end, kindly confirm liability status within 7 days from this to minimize time wastage and incurrence of any unnecessary cost(s) on both our end, we seek your kind advice, within 7 days working days, on liability status for subject claim. If we do not hear from you within the stipulated period, we shall proceed with the purchase of your insured GIA report and this cost or any other cost incurred for confirmation of liability status shall be included in our LOD for reimbursement purpose.

Thank you.

You can protect our environment. Think before you print.

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential.

The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it.

If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Ms Lee

Bifrost Auto Pte Ltd

Accident Claims Department

+65 9792 1329 (Mobile)

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 19 Feb 2020

Preliminary Advice

Insured Vehicle No	: SLM5831A	Accident Date	: 08/02/2020
TP Vehicle No	: SH6901T	Assignment Date	: 17/02/2020
Make	: HYUNDAI I40	Est. Duration of Repair	: 7.00
Date of Inspection	: 17/02/2020		
Inspection At	: BIFROST AUTO PTE LTD (SIN MING) (HQ) BLK 9 SECTOR C, #01-42 SIN MING INDUSTRIAL ESTATE SINGAPORE 575644		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front, rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,355.72
Revised Amount	:S\$	8,440.44
Check Items (Estimated)	:S\$	4,433.28
Total	:S\$	12,873.72
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	10/02/2020 14:14
Date Of Accident	08/02/2020 17:25
Exact Location Of Accident	ALONG PIE TOWARDS WOODLANDS AFTER EXIT 17
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH6901T
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	1XXXXX821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	

Driver

Name of Driver	CHER HAN SIN
NRIC No	SXXXX647E
Date Of Birth	03/05/1976
Occupation	OUTDOOR
Date Of Driving Pass	07/05/2015
Driving Experience	4 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94788884
Fax Number	
Contact Number	
Email Address	CHER_HS@YAHOO.COM.SG

Address	896 12-886 TAMPINES ST 81
Postcode	520896
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	5
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : - GENDER: : MALE
Passenger 2	NAME: : - GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

SEE ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	-
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLM5831A
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode
Insurance Company Name
Nature Of Damage FRT & REAR
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SHA9232M
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category TAXI
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage NOT SURE
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SFK5033T
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage FRT
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number
Vehicle Make/Model/Colour
Details Of Properties UNKNOWN
Vehicle Category NA/UNKNOWN
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage NOT SURE
No. Of Passenger (Including Driver)

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by Insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**


I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

09 FEB 2020

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Statement as per attached.

1

Describe Circumstances of the Accident.

On the 08/02/2020@ about 17:25hrs, I was driving along PIE towards Woodlands direction

With 2 passenger on board my taxi.

As I was driving the front City Cab slow down ^{and e-brake} ~~to stop~~ so I stop as well when suddenly there's

an impact from behind my taxi which resulted my taxi to surged forward and collided onto

the front City Cab of SHA9232M rear portion. I step out to check and found a vehicle of

SLM5831A front portion had collided onto my taxi rear portion. There's another 2 vehicle

involved in this chain collision.

No injury at the point of accident.

Declaration

I/We declare the foregoing particulars are true in every respect.

JMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 189303821R

Policyholder's Signature/Date &
Time

Driver's Signature(if driver is not the policyholder)/Date
& Time

Olivia Wendy

Witnessed by Reporting
Centre Personnel

09 FEB 2020

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SH6901T
Vehicle to be Exported:	No
Intended Deregistration Date:	17 Feb 2020
Vehicle Make:	HYUNDAI
Vehicle Model:	I40 1.7 CRDI F/L AT ABS AIRBAG 4DR
Primary Colour:	Blue
Manufacturing Year:	2015
Engine No.:	D4FDFU596452
Chassis No.:	KMHLB41UMGU085569
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$20,856.00
Original Registration Date:	17 Mar 2016
First Registration Date:	17 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$21,199.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Mar 2024
PARF Rebate Amount:	\$15,899.00
Intended COE Rebate Details	
COE Expiry Date:	16 Mar 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$39,633.00
COE Rebate Amount:	\$20,200.00
Total Rebate Amount:	\$36,099.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 17 Feb 2020

OK

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 11-Feb-20

INSURANCE: _____

MODEL: HYUNDAI I40

VEHICLE NO.: SH6901T

DESCRIPTION	QTY	LIST PRICE	AMOUNT	
BOOTLID / 00	1	\$2,174.90	\$2,174.90	1949.50
BOOTLID RUBBER / TAN	1	\$96.50	\$96.50	/
BOOTLID HINGE (LH/RH) X R	2	\$284.60	\$569.20	X
BOOTLID LOCK UPPER / CUT	1	\$114.90	\$114.90	/
BOOTLID 'H' EMBLEM / MC	1	\$22.70	\$22.70	/
BOOTLID CRDI PLATE / MC	1	\$27.90	\$27.90	/
BOOTLID LAMP (LH/RH) / BR	1	\$565.60	\$565.60	/
BOOTLID TRIMBOARD X MM	1	\$143.90	\$143.90	X
BOOTLID TRIMBOARD CLIPS (11 PCS) X / MC	1	\$11.00	\$11.00	/
BOOTLID I40 EMBLEM (I40) / MC	1	\$27.90	\$27.90	/
BOOTLID LOWER GARNISH (I40) / BR	1	\$227.90	\$227.90	/
REAR BUMPER / BR	1	\$1,106.00	\$1,106.00	553
REAR BUMPER REINFORCEMENT BRACKET ? X MM	1	\$160.60	\$160.60	X
REAR BUMPER REINFORCEMENT ? X MM	1	\$428.40	\$428.40	X
REAR BUMPER CLIP / MC	1	\$22.00	\$22.00	/
REAR BUMPER SPONGE ? X MM	1	\$119.50	\$119.50	X
REAR BUMPER UNDER COVER / CUT	1	\$228.00	\$228.00	/
REAR BUMPER REFLECTOR LAMP (I40) X MM	1	\$32.00	\$32.00	X
TAIL LAMP (LH/RH) / BR	1	\$697.80	\$697.80	/
TAIL LAMP QUARTER PANEL (LH/RH) X MM	1	\$453.00	\$453.00	X
REAR PANEL / 00	1	\$526.70	\$526.70	/
REAR PANEL GARNISH / CR4	1	\$57.70	\$57.70	/
SPARE TYRE HOLDER 2 X MM	1	\$223.10	\$223.10	X
TAIL LAMP PANEL TOP (LH/RH) X MM	1	\$189.10	\$189.10	X
SPARE TYRE PANEL 2 X MM	1	\$852.80	\$852.80	X
SPARE TYRE PANEL CUSHION 2 X MM	1	\$223.10	\$223.10	X
REAR TOWING HOOK X MM	1	\$94.60	\$94.60	X
EXHAUST SILENCER X MM	1	\$1,935.40	\$1,935.40	X
EXHAUST PIPE HANGER X MM	1	\$117.10	\$117.10	X
EXHAUST PIPE CENTRE X MM	1	\$730.10	\$730.10	X
RADIATOR GRILLE H EMBLEM X ? / MC	1	\$39.50	\$39.50	/

RADIATOR GRILLE ? / DR 1110 /	1	\$1,480.00	\$1,480.00	/
FRONT BUMPER COVER / DR	1	\$1,052.20	\$1,052.20	/
FRONT BUMPER SPONGE ? / TM	1	\$99.20	\$99.20	/
FRONT BUMPER REINFORCEMENT ? / DO	1	\$438.40	\$438.40	/
FRONT BUMPER GRILLE (LH/RH) X NM	1	\$49.20	\$49.20	X
FRONT BUMPER BRACKET TOP (LH/RH) X NM	1	\$44.80	\$44.80	X
FRONT BUMPER CENTRE GRILLE TOP GARNISH (I40) X NM	1	\$32.00	\$32.00	X
FRONT BUMPER BRACKET (LH/RH) X NM	1	\$49.20	\$49.20	X
FRONT BUMPER SIDE BRACKET X NM	1	\$4.60	\$4.60	X
FRONT BUMPER RETAINER MOUNTING X NM	1	\$8.00	\$8.00	X
FRONT BUMPER GRILLE AIR DUCT X NM	1	\$26.20	\$26.20	X
HEADLAMP SUPPORT PANEL ASSY & / DR	1	\$907.40	\$907.40	/
HEADLAMP (LH/RH) (LH) / DR (RH) & / DR	1	\$2,776.00	\$2,776.00	/
HEADLAMP SUPPORT TOP COVER X NM	1	\$222.60	\$222.60	X
FRONT FENDER (LH/RH) X NM	1	\$566.30	\$566.30	X
FRONT FENDER SHIELD (LH/RH) X NM	1	\$174.90	\$174.90	X
FRONT FENDER MUDFLAP (LH/RH) X NM	1	\$13.50	\$13.50	X
FRONT FENDER RETAINER X NM	1	\$13.00	\$13.00	X
		11,551.80		
		-7%		
SUB TOTAL		9241.44	\$20,176.40	
LESS 20%			\$4,035.28	
DISCOUNTED TOTAL			\$16,141.12	
REAR BUMPER RESERVE SENSOR / SL SN	1	\$118.00	\$118.00	/
REAR BUMPER RUBBER MAT / I40 PLATE / NC SN	1	\$50.00	\$50.00	/
BOOTLID COMFORT LOGO & TEL NO. STICKER / NC SN	1	\$16.60	\$16.60	/
				184.60
SUB TOTAL			\$184.60	
Labour Charge				1200
Panel Beating	1	\$1,600.00	\$1,600.00	800
Spray Painting Charge	1	\$1,600.00	\$1,600.00	800
Wiring Charge	1	\$180.00	\$180.00	30
Tuff Kote	1	\$180.00	\$180.00	50
Towing Charge	1	\$50.00	\$50.00	/
Remove/Refix Reverse Sensor	1	\$120.00	\$120.00	30
Remove/Refix Exhaust Pipe	1	\$80.00	\$80.00	X
Remove/Refix Radiator	1	\$90.00	\$90.00	X
Remove/Refix Aircon & Refill Gas	1	\$130.00	\$130.00	X
TOTAL LABOUR			\$ 4,030.00	
ESTIMATE TOTAL			\$ 20,355.72	2169

20380.724

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

[Signature]
19/2/2020

Steve (LKK) W/L H/L
8322 8813 17/2/20, 3:30pm
L/S
Ry AL sy
9 d/s

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 9241.44
AI- 184.60
L - 2160
Supp - 25
11,611.04
L/S - 9,288.83
= 9,300

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 11-Feb-20

INSURANCE: _____

MODEL: HYUNDAI I40

VEHICLE NO.: SH6901T

DESCRIPTION	QTY	LIST PRICE	AMOUNT
BOOTLID / DD	1	\$2,174.90	\$2,174.90
BOOTLID RUBBER / TN	1	\$96.50	\$96.50
BOOTLID HINGE (LH/RH) X R	2	\$284.60	\$569.20
BOOTLID LOCK UPPER / CUT	1	\$114.90	\$114.90
BOOTLID 'H' EMBLEM / MC	1	\$22.70	\$22.70
BOOTLID CRDI PLATE / MC	1	\$27.90	\$27.90
BOOTLID LAMP (LH/RH) / BR	1	\$565.60	\$565.60
BOOTLID TRIMBOARD X	1	\$143.90	\$143.90
BOOTLID TRIMBOARD CLIPS (11 PCS) X / MC	1	\$11.00	\$11.00
BOOTLID I40 EMBLEM (I40) / MC	1	\$27.90	\$27.90
BOOTLID LOWER GARNISH (I40) / BR	1	\$227.90	\$227.90
REAR BUMPER / BR	1	\$1,106.00	\$1,106.00
REAR BUMPER REINFORCEMENT BRACKET 4 H4	1 X	\$160.60	\$160.60
REAR BUMPER REINFORCEMENT 2 Bumper 2 H4	X 1	\$428.40	\$428.40
REAR BUMPER CLIP / MC	1	\$22.00	\$22.00
REAR BUMPER SPONGE 2 H4	X 1	\$119.50	\$119.50
REAR BUMPER UNDER COVER / CUT	1	\$228.00	\$228.00
REAR BUMPER REFLECTOR LAMP (I40) X	1	\$32.00	\$32.00
TAIL LAMP (LH/RH) / BR	1	\$697.80	\$697.80
TAIL LAMP QUARTER PANEL (LH/RH) X	1	\$453.00	\$453.00
REAR PANEL / DD	1	\$526.70	\$526.70
REAR PANEL GARNISH / CR4	1	\$57.70	\$57.70
SPARE TYRE HOLDER 2 X	1	\$223.10	\$223.10
TAIL LAMP PANEL TOP (LH/RH) X	1	\$189.10	\$189.10
SPARE TYRE PANEL 2 X	1	\$852.80	\$852.80
SPARE TYRE PANEL CUSHION 2 X	1	\$223.10	\$223.10
REAR TOWING HOOK X	1	\$94.60	\$94.60
EXHAUST SILENCER X	1	\$1,935.40	\$1,935.40
EXHAUST PIPE HANGER X	1	\$117.10	\$117.10
EXHAUST PIPE CENTRE X	1	\$730.10	\$730.10
RADIATOR GRILLE H EMBLEM X 2 H4	1	\$39.50	\$39.50

RADIATOR GRILLE <i>2 money broken</i>	1 ✓	\$1,480.00	\$1,480.00
FRONT BUMPER COVER <i>1 OR</i>	1	\$1,052.20	\$1,052.20
FRONT BUMPER SPONGE <i>2 torn</i>	1 ✓	\$99.20	\$99.20
FRONT BUMPER REINFORCEMENT <i>2 Dashed</i>	1 ✓	\$438.40	\$438.40
FRONT BUMPER GRILLE (LH/RH) <i>X</i>	1	\$49.20	\$49.20
FRONT BUMPER BRACKET TOP (LH/RH) <i>X</i>	1	\$44.80	\$44.80
FRONT BUMPER CENTRE GRILLE TOP GARNISH (I40) <i>X</i>	1	\$32.00	\$32.00
FRONT BUMPER BRACKET (LH/RH) <i>X</i>	1	\$49.20	\$49.20
FRONT BUMPER SIDE BRACKET <i>X</i>	1	\$4.60	\$4.60
FRONT BUMPER RETAINER MOUNTING <i>X</i>	1	\$8.00	\$8.00
FRONT BUMPER GRILLE AIR DUCT <i>X</i>	1	\$26.20	\$26.20
HEADLAMP SUPPORT PANEL ASSY <i>2 broken</i>	1 ✓	\$907.40	\$907.40
HEADLAMP (LH/RH) <i>(LH) / OR (RH) 2 money broken</i>	1 ✓	\$2,776.00	\$2,776.00
HEADLAMP SUPPORT TOP COVER <i>X</i>	1	\$222.60	\$222.60
FRONT FENDER (LH/RH) <i>X</i>	1	\$566.30	\$566.30
FRONT FENDER SHIELD (LH/RH) <i>X</i>	1	\$174.90	\$174.90
FRONT FENDER MUDFLAP (LH/RH) <i>X</i>	1	\$13.50	\$13.50
FRONT FENDER RETAINER <i>X</i>	1	\$13.00	\$13.00
SUB TOTAL			\$20,176.40
LESS 20%			\$4,035.28
DISCOUNTED TOTAL			\$16,141.12
REAR BUMPER RESERVE SENSOR <i>1 SL</i>	SN 1	\$118.00	\$118.00
REAR BUMPER RUBBER MAT / I40 PLATE <i>1 PC</i>	SN 1	\$50.00	\$50.00
BOOTLID COMFORT LOGO & TEL NO. STICKER <i>1 PC</i>	SN 1	\$16.60	\$16.60
SUB TOTAL			\$184.60
Labour Charge			
Panel Beating	1	\$1,600.00	\$1,600.00
Spray Painting Charge	1	\$1,600.00	\$1,600.00
Wiring Charge	1	\$180.00	\$180.00
Tuff Kote	1	\$180.00	\$180.00
Towing Charge	1	\$50.00	\$50.00
Remove/Refix Reverse Sensor	1	\$120.00	\$120.00
Remove/Refix Exhaust Pipe	1	\$80.00	\$80.00
Remove/Refix Radiator	1	\$90.00	\$90.00
Remove/Refix Aircon & Refill Gas	1	\$130.00	\$130.00
TOTAL LABOUR			\$ 4,030.00
ESTIMATE TOTAL			\$ 20,355.72

1790
800

30
50
30
X
X
X

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Steve (LKK) WPL MIL
8322 8813 17/2/20, 3:30pm
L/S
Ry AL Ry
P dyp

20380.72

REPAIR ESTIMATE

INSURANCE: _____

Supplementary

VEHICLE NO.: SH6901T

2, your
2 K/L Andu

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Feb 2020		17 Feb 2020 09:46 Edit Adj Rpt	S\$9,300.00 Edit Estimates	S\$9,300.00 View Rpt		Pending for Survey Report Cancel Case


































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS			[Created by insurer]						
Insured:	GRAB RENTALS PTE LTD , Co. Reg. No.: 201617200G								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SH6901T	Date of Loss:	08/02/2020 17:00 - :59 [46 Months and 22 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 619669	Policy/Cover Note No.:	29141713MKF (Comprehensive) Coverage: 01/02/2020 - 31/12/2020						
Vehicle Reg. No. (Insured):	SLM5831A	Policy No. (Claimant):							
		Excess:							
Repairer:	Bifrost Auto Pte Ltd (sin Ming) (HQ) Blk 9 Sector C, #01-42 Sin Ming Industrial Estate, 575644 Sin Ming - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 18/03/2020]								
Driver/Custodian (Insured):	TAN KIAP TECK (), NRIC: S1505309G, Tel: +6594575786 Email:								
Adj Asg. Remarks:	on WP. Manual assigned to LKK via email on 14/02/2020. (Manual Assign). OI:Grab. Liab: clear. Agree on SJE. Assign: LKK Auto Consultants Pte Ltd. Contact: Ms Lee @ 9792 1329.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

Claim Documents

*SH6901T (619669)
 [SLM5831A]
 TP
 COMFORT TRANSPORTATION PTE LTD
 Feb 8 2020 5:00PM
 [GRAB RENTALS PTE LTD]
 Bifrost Auto Pte Ltd (sin Ming)

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	19/02/20 09:33	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
2	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
3	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
4	17/02/20 19:42	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
5	17/02/20 19:42	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
6	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
7	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
8	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
9	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
10	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
11	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
12	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
13	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
14	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
15	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
16	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
17	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
18	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
19	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
20	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
21	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
22	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
23	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
24	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
25	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
26	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
27	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
28	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
29	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
30	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
31	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>
32	17/02/20 19:42	General View	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
34	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
35	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
36	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
37	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
38	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
39	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
40	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
41	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
42	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
43	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
44	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
45	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
46	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
47	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
48	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
49	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
50	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
51	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
52	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
53	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
54	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
55	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
56	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
57	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
58	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
59	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
60	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
61	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
62	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
63	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
64	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
65	17/02/20 19:42	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	15/02/20 10:03	PRI	Load PDF	
2	15/02/20 10:03	TP GIA	Load PDF	
3	17/02/20 09:29	Agree on SJE	Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	17/02/20 09:43	Survey Request - Manual Assigned	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/03/20 09:06	SUPPLEMENTARY	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20002657/ETF3S2

Date: 02/03/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29141713MKF

Claimant Vehicle No : SH6901T

Insured Vehicle No : SLM5831A

Date of Loss: 08/02/2020

Nature of Claim: TP

Claim No: 619669

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SH6901T

Make & Model: HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)

Engine No: D4FDFU596452

Reg. Date: 17/03/2016 (Man. Year: 2015)

Chassis No: KMHLB41UMGU085569

Colour: Blue

Odometer: 404365 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size:

205/60 R16

Front Left Side: Hankook 5 mm

Rear Left Side:

Hankook 5 mm

Front Right Side: Hankook 5 mm

Rear Right Side:

Hankook 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,350.72	9,451.04	6,899.68	42.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,030.00	2,160.00	1,870.00	46.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,380.72	11,611.04	8,769.68	43.03
Approved Total (Overridden) (S\$)		9,300.00		
(S\$)	20,380.72	9,300.00	11,080.72	54.37
+ GST 7.00/7.00% (S\$)	1,426.65	651.00	775.65	54.37
Nett Amount (S\$)	21,807.37	9,951.00	11,856.37	54.37

INSPECTION

Date of Assignment: 17/02/2020

Date Inspected: 17/02/2020 Inspected At:

Blk 9 Sector C, #01-42 Sin Ming Industrial Estate
Singapore 575644

Repairer: Bifrost Auto Pte Ltd

Estimated Period of Repair: 9.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 02 Mar 2020)

Parts: 143 HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SH6901T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented	2,174.90 FL	*1,949.50 FL
2	1		*BOOTLID RUBBER	Torn	96.50 FL	*96.50 FL
3	2		*BOOTLID HINGE (LH/RH)	Repair	569.20 FL	*- FL
4	1		*BOOTLID LOCK UPPER	Cut	114.90 FL	*114.90 FL
5	1		*BOOTLID H EMBLEM	Necessary	22.70 FL	*22.70 FL
6	1		*BOOTLID CRDI PLATE	Necessary	27.90 FL	*27.90 FL
7	1		*BOOTLID LAMP (LH/RH)	Broken	565.60 FL	*565.60 FL
8	1		*BOOTLID TRIMBOARD	Not Necessary	143.90 FL	*- FL
9	11		*BOOTLID TRIMBOARD CLIPS	Necessary	11.00 FL	*11.00 FL
10	1		*BOOTLID I40 EMBLEM (I40)	Necessary	27.90 FL	*27.90 FL
11	1		*BOOTLID LOWER GARNISH (I40)	Broken	227.90 FL	*227.90 FL
12	1		*REAR BUMPER	Broken	1,106.00 FL	*553.00 FL
13	1		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	160.60 FL	*- FL
14	1		*REAR BUMPER REINFORCEMENT	Not Necessary	428.40 FL	*- FL
15	1		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
16	1		*REAR BUMPER SPONGE	Not Necessary	119.50 FL	*- FL
17	1		*REAR BUMPER UNDER COVER	Cut	228.00 FL	*228.00 FL
18	1		*REAR BUMPER REFLECTOR LAMP (I40)	Not Necessary	32.00 FL	*- FL
19	1		*TAIL LAMP (LH/RH)	Broken	697.80 FL	*697.80 FL
20	1		*TAIL LAMP QUARTER PANEL (LH/RH)	Not Necessary	453.00 FL	*- FL
21	1		*REAR PANEL	Dented	526.70 FL	*526.70 FL
22	1		*REAR PANEL GARNISH	Crushed	57.70 FL	*57.70 FL
23	1		*SPARE TYRE HOLDER	Not Necessary	223.10 FL	*- FL
24	1		*TAIL LAMP PANEL TOP (LH/RH)	Not Necessary	189.10 FL	*- FL
25	1		*SPARE TYRE PANEL	Not Necessary	852.80 FL	*- FL
26	1		*SPARE TYRE PANEL CUSHION	Not Necessary	223.10 FL	*- FL
27	1		*REAR TOWING HOOK	Not Necessary	94.60 FL	*- FL
28	1		*EXHAUST SILENCER	Not Necessary	1,935.40 FL	*- FL
29	1		*EXHAUST PIPE HANGER	Not Necessary	117.10 FL	*- FL
30	1		*EXHAUST PIPE CENTRE	Not Necessary	730.10 FL	*- FL
31	1		*RADIATOR GRILLE H EMBLEM	Necessary	39.50 FL	*39.50 FL
32	1		*RADIATOR GRILLE	Broken	1,480.00 FL	*1,110.00 FL
33	1		*FRONT BUMPER COVER	Broken	1,052.20 FL	*1,052.20 FL
34	1		*FRONT BUMPER SPONGE	Torn	99.20 FL	*99.20 FL
35	1		*FRONT BUMPER REINFORCEMENT	Dented	438.40 FL	*438.40 FL
36	1		*FRONT BUMPER GRILLE (LH/RH)	Not Necessary	49.20 FL	*- FL
37	1		*FRONT BUMPER BRACKET TOP (LH/RH)	Not Necessary	44.80 FL	*- FL
38	1		*FRONT BUMPER CENTRE GRILLE TOP GARNISH (I40)	Not Necessary	32.00 FL	*- FL
39	1		*FRONT BUMPER BRACKET (LH/RH)	Not Necessary	49.20 FL	*- FL
40	1		*FRONT BUMPER SIDE BRACKET	Not Necessary	4.60 FL	*- FL
41	1		*FRONT BUMPER RETAINER MOUNTING	Not Necessary	8.00 FL	*- FL
42	1		*FRONT BUMPER GRILLE AIR DUCT	Not Necessary	26.20 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	907.40 FL	*907.40 FL
44	1		*HEADLAMP (LH/RH)	Broken	2,776.00 FL	*2,776.00 FL
45	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*- FL
46	1		*FRONT FENDER (LH/RH)	Not Necessary	566.30 FL	*- FL
47	1		*FRONT FENDER SHIELD (LH/RH)	Not Necessary	174.90 FL	*- FL
48	1		*FRONT FENDER MUDFLAP (LH/RH)	Not Necessary	13.50 FL	*- FL
49	1		*FRONT FENDER RETAINER	Not Necessary	13.00 FL	*- FL
50	1		*REAR BUMPER REVERES SENSOR	Shorted	118.00 FS	*118.00 FS
51	1		*REAR BUMPER RUBBER MAT / I40 PLATE	Necessary	50.00 FS	*50.00 FS
52	1		*BOOTLID COMFORT LOGO & TEL NO. STICKER	Necessary	16.60 FS	*16.60 FS
53	1		*REAR NO. PLATE	Cracked	25.00 FS	*25.00 FS
					Sub Total (S\$)	20,386.00
					- List Item Discount on L Items 20.00/20.00% (S\$)	4,035.28
					Total Parts (S\$)	16,350.72
						9,451.04

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING.	New	1,600.00	1,200.00
2	SPRAY PAINTING CHARGE.	New	1,600.00	800.00
3	WIRING CHARGE.	New	180.00	30.00
4	TUFF KOTE.	New	180.00	50.00
5	TOWING CHARGE.	New	50.00	50.00
6	REMOVE / REFIX REVERSE SENSOR.	New	120.00	30.00
7	REMOVE / REFIX EXHAUST PIPE.	New	80.00	0.00
8	REMOVE / REFIX RADIATOR.	New	90.00	0.00
9	REMOVE / REFIX AIRCON & REFILL GAS.	New	130.00	0.00
Gross Labour Cost (S\$)			4,030.00	2,160.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >